

JHK AUTO SERVICES

BUSINESS REG NO: 52886790C

GST REG NO: M90360882G

ADDRESS: BLK 3014 UBI ROAD 1

#01-324 SINGAPORE 408702

TEL: 67432011 FAX: 67435234

KOO TEE ZHONG

BLK 3014 UBI ROAD 1

#01-324 SINGAPORE: 408702

Attention: Motor Claim Department

Contact: 67432011

Fax: 67435234

ESTIMATE: E18080005

DATE: 10/08/18

VEHICLE NO: SJY7765E

MAKE/MODEL: B.M.W. 520I 2.0L AT D/AB 2WD 4DR

CHASSIS/ENG#: WBAXG12040DX48298

ACCIDENT DATE: 30/07/2018

CLAIM NO:

REFERENCE: AXA DIRECT SETTLE

POLICY NO: GA117683/1

TPAXA
Joy

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:

1		FRONT BUMPER <i>Repair</i>	\$1,277.55	\$1,277.55*
2	10	FRONT BUMPER CLIPS <i>new</i>	\$5.00	\$50.00 <i>30</i>
3		FRONT SIDE RETAINER LH	\$19.45	\$19.45*
4		FRONT BUMPER SIDE RETAINER RH <i>new</i>	\$19.45	\$19.45*
5		FRONT BUMPER BRACKET LH	\$16.60	\$16.60*
6		FRONT BUMPER BRACKET RH	\$16.60	\$16.60*
7		FRONT BUMPER SENSOR LH <i>new</i>	\$236.85	\$236.85*
8		FRONT BUMPER REINFORCEMENT <i>new</i>	\$684.75	\$684.75*
9		FRONT BUMPER SPONGE <i>new</i>	\$48.00	\$48.00*
10		HEAD LAMP LH (HID) <i>new</i>	\$2,649.65	\$2,649.65*
11		HEAD LAMP BRACKET LH <i>new</i>	\$126.10	\$126.10*
12		FRONT FENDER LH <i>Painted</i>	\$863.35	\$863.35*
13		FRONT FENDER INNER SHIELD LH	\$256.40	\$256.40*
14	10	FRONT FENDER INNER SHIELD CLIPS LH <i>new</i>	\$5.00	\$50.00*
15		FRONT FENDER LAMP LH <i>at</i>	\$90.50	\$90.50*
16		FRONT WHEEL BEARING LH <i>new</i>	\$503.00	\$503.00*
17		FRONT KNUCKLE ARM LH <i>new</i>	\$579.65	\$579.65*
18		FRONT LOWER ARM LH <i>Best</i>	\$591.50	\$591.50*
19		FRONT UPPER ARM LH <i>Best</i>	\$542.20	\$542.20*
20		FRONT SHOCK ABSORBER LH <i>Best</i>	\$600.85	\$600.85*

LIST TOTAL S\$

5.00% DISCOUNT S\$

3221.40

3060.33

\$9,222.45

\$461.12

\$8,761.33



JHK AUTO SERVICES

The above estimate is derived from visual inspection only. You will be informed of additional damaged parts or additional during our course of repair if any. Item price are also subject to charges if any

JHK AUTO SERVICES

BUSINESS REG NO: 52886790C

GST REG NO: M90360882G

ADDRESS: BLK 3014 UBI ROAD 1

#01-324 SINGAPORE 408702

TEL: 67432011 FAX: 67435234

ESTIMATE: E18080005

KOO TEE ZHONG

BLK 3014 UBI ROAD 1

#01-324 SINGAPORE: 408702

Attention: Motor Claim Department

Contact: 67432011

Fax: 67435234

DATE: 10/08/18

VEHICLE NO: SJY7765E

MAKE/MODEL: B.M.W. 520I 2.0L AT D/AB 2WD 4DR

CHASSIS/ENG#: WBAXG12040DX48298

ACCIDENT DATE: 30/07/2018

CLAIM NO:

REFERENCE: AXA DIRECT SETTLE

POLICY NO: GA117683/1

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:

21		FRONT SHOCK ABSORBER MOUNTING LH <i>not in</i>	\$147.75	\$147.75 +
22		FRONT TIE ROD LH <i>not in</i>	\$352.90	\$352.90 +
23		FRONT TIE ROD END LH <i>not in</i>	\$211.90	\$211.90 +
24		FRONT ABS SENSOR LH <i>not in</i>	\$203.60	\$203.60 +
25		STEERING RACK AND PINION <i>not in</i>	\$4,610.65	\$4,610.65 +
26		FRONT DOOR LH <i>Dented</i>	\$1,731.25	\$1,731.25 ✓
27		REAR DOOR LH <i>Repair</i>	\$1,731.25	\$1,731.25 +
28		SIDE SKIRT LH <i>not in</i>	\$408.95	\$408.95 x

9775.20

9286.44

LIST TOTAL S\$

\$9,398.25

5.00% DISCOUNT S\$

469.91

\$8,928.34

SPECIAL NETT ITEMS :

29		FRONT SPORT RIM LH <i>1200</i>	\$2,800.00	
30		FRONT TYRE LH <i>not in</i>	\$380.00	

SPECIAL NETT TOTAL S\$

\$3,180.00



JHK AUTO SERVICES

The above estimate is derived from visual inspection only. You will be informed of additional damaged parts or additional during our course of repair if any. Item price are also subject to charges if any

JHK AUTO SERVICES

BUSINESS REG NO: 52886790C

GST REG NO: M90360882G

ADDRESS: BLK 3014 UBI ROAD 1

#01-324 SINGAPORE 408702

TEL: 67432011 FAX: 67435234

ESTIMATE: E18080005

KOO TEE ZHONG

BLK 3014 UBI ROAD 1

#01-324 SINGAPORE: 408702

Attention: Motor Claim Department

Contact: 67432011

Fax: 67435234

DATE: 10/08/18

VEHICLE NO: SJY7765E

MAKE/MODEL: B.M.W. 520I 2.0L AT D/AB 2WD 4DR

CHASSIS/ENG#: WBAXG12040DX48298

ACCIDENT DATE: 30/07/2018

CLAIM NO:

REFERENCE: AXA DIRECT SETTLE

POLICY NO: GA117683/1

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

31		TO PANEL BEAT AND RENEWAL OF ALL DAMAGED PARTS		
32		TO PUTTY & SPRAYPAINTING ON ACCIDENT DAMAGED PORTION		
33		TO REMOVE AND REFIT UNDERCARRIAGE		
34		TO PERFORM 4 WHEEL ALIGNMENT		
35		TO ALIGN HEAD LAMP	2310	
36		TO CHECK WIRING AND REWIRE		
37		TO ANTI RUST		

800
\$950.00
\$1,050.00
\$580.00
\$160.00
\$80.00
\$80.00
\$80.00

LABOUR TOTAL S\$

\$2,980.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyed by/Company :

Contact Number :

Date/Time :

Licensed Automotive Surveyor's Sign :

Adnan Lij
4/5 10/08/18

07 Days

total 1279644

4/5 10.2K



JHK AUTO SERVICES

The above estimate is derived from visual inspection only. You will be informed of additional damaged parts or additional during our course of repair if any. Item price are also subject to charges if any