

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

*LKK  
Kamoth  
Fri - 10/8  
1.30.*

*Not Authorized  
11 Sep @?  
Resurvey After Repair  
4 days*

06, August 2018

QBE Insurance (S) PL  
65 Chulia Street  
#36-01 OCBC Centre West Lobby  
S 049513

Attn: Motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: GBE3602T  
Accident involving vehicle no: GBE8247C/GBE3602T/YP2481B  
DOA: 02/08/2018 AT Hougang Ave 3 To Eunos Link

Dear officer incharge  
Re: Estimate cost of repair for vehicle no: GBE8247C  
To supply—

Description	Qty	Amount
Rear door, Lh	1	1,404.90 N ✓
Taillamp, Lh	1	203.30 N ✓
Rear bumper	1	740.00 N ✓
Rear door hinge @86.60N	2	173.20 N ✓
Rear door-dci emblem	1	163.50 N ✓
	Parts	2,684.90
	Nett parts less 10%	268.49
		2,416.41

Company sticker—rear door  
To transfer rear door glass, doorboard and all attachments to new door.  
To remove damaged parts and attachments.  
Repair/reshape dented areas.  
Replace/align all parts into position  
To spray paint.

*(Bul)* 450.00 ?  
150.00 600  
650.00 4000  
400.00 2500

4,066.41

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: