

Surveyor:

MARINE

DOI:

ASSIGNMENT

13/8/18

Date / Time:

13/8/18

Registered in Motorist:

13/8/18

Pre-assign / CCU / FTE

SLM 2207Y



Insured Vehicle No.

Name of Insured

Nha Ym Shing

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A :

11/8/18

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES/ NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

21085 04494

VA CERA To

PTE

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

Saw 1314J



INSRS:

WSP:

Tel:

Liability:

RMKS:

TAN LIM

9403J



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/8

8/9

Saw 1314J - X;

SLM 2207Y. CC6/A16 180 21085/Aud3: 0044/1418

21-8-18 @ 125 NO ANSWER.

2-10-18 FOR MANDATE

RECEIVED 08 OCT 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed)

BOLA S/N No.:

If NO or B 28, Ans. Lia: 0

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

Loss of Use (LOU):

S\$

Loss of Income (LOI):

S\$

LOR only

LOU only

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Payee 2: (Strike if N.A.)

S\$

Payee 3: (Strike if N.A.)

S\$

Name 1:

Name 2:

Name 3:

TAN LIM MOTOR PTE LTD.

X

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: SGW 1314J
 at Workshop n/a Tanhm
 of _____
 Insured S L M 22074
 Policy No: _____
 Claims No: _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 267

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen _____ Consistent?: Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGW1314J Yr Regn: 507
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota / Make: 1496
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 179305 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/N: N2E1416031368
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Mod: NI / Std / STD A/Rim or
 Tyre Size: F: _____ R: 185-70R14
 BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal: _____ mm R/Bal: _____ mm
 L/Bal: 6 mm L/Bal: 6 mm
 D.O.A. 11/8/18 D.O.J. 13/8/18
 Survey held at: _____
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Rear & R.
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	
	<u>30/4/2022</u>	
	<u>LTA 18654 3yrs. 8mth. net 7346</u>	<u>DUA - 11.6.18 21</u>
	<u>dep 7h</u>	<u>12 22</u>
<u>18-9-</u>	<u>7,800</u>	<u>DUA 13.5.18 23</u>
		<u>14 24</u>
		<u>15</u>
		<u>16</u>
		<u>17</u>
		<u>18</u>
		<u>19</u>
		<u>20</u>

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee:

Transportation:

6 + RS 80

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)

AI GAsia Insured's Veh No SLM2207Y

Date of Accident : 11 August 2018

TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216

Tel 68585151 (24 Hours) Fax 68580877

GST Regn. No. : M2-8922054-2

Mr Ang Eng Loo

Date 13 August 2018

Estimate To Repair SGW1314J - Toyota Corolla Axio 1.5X A

Chassis No NZE1416031368

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	bootlid <i>3uc</i>	\$ 720.00
02	1 pc	bootlid lock <i>tw</i>	\$ 99.50
03	1 pc	bootlid lock striker <i>11</i>	\$ 45.80
04	1 pc	bootlid Axio badge <i>all</i>	\$ 68.00
05	1 pc	bootlid X badge <i>all</i>	\$ 38.10
06	1 pc	bootlid weatherstrip <i>tw</i>	\$ 187.10
07	1 pc	bootlid outer garnish <i>2x1/2</i>	\$ 225.00
08	1 pc	bootlid outer garnish emblem badge <i>all</i>	\$ 45.60
09	2 ps	bootlid hinge @ \$69.00 <i>R</i>	\$ 138.00
10	4 ps	bootlid rubber stopper @ \$12.00 <i>11</i>	\$ 48.00
11	3 ps	bootlid lock cable clip @ \$3.00 <i>11</i>	\$ 9.00
12	1 pc	bootlid inner trim cover <i>11</i>	\$ 299.60
13	6 ps	bootlid inner trim cover clip @ \$3.00 <i>11</i>	\$ 18.00
14	1 pc	rear end panel <i>body</i>	\$ 599.80
15	1 pc	rear end panel inner trim <i>tw</i>	\$ 199.70
16	4 ps	rear end panel inner trim clip @ \$3.00 <i>11</i>	\$ 12.00
17	1 pc	rear bumper <i>211</i>	\$ 1,209.00
18	2 ps	rear bumper bracket @ \$98.50 <i>211</i>	\$ 197.00
19	2 ps	rear bumper side retainer @ \$54.60 <i>3x1</i>	\$ 109.20
20	2 ps	rear bumper side holder @ \$45.80 <i>11</i>	\$ 91.60
21	2 ps	rear bumper side bracket @ \$36.70 <i>11</i>	\$ 73.40
22	8 ps	rear bumper clip @ \$3.00 <i>all</i>	\$ 24.00
23	1 pc	rear bumper end splashshield cover <i>11</i>	\$ 45.60
24	6 ps	rear bumper end splashshield cover clip @ \$3.00 <i>11</i>	\$ 18.00
25	2 ps	rear lamp @ \$399.70 <i>11</i>	\$ 799.40
26	4 ps	rear lamp clip holder @ \$3.00 <i>11</i>	\$ 12.00
27	2 ps	rear licence plate lamp @ \$55.00 <i>11</i>	\$ 110.00
28	1 pc	rear luggage floor panel <i>11</i>	\$ 949.60
29	1 pc	rear luggage floor panel trimboard <i>11</i>	\$ 349.70
30	1 pc	rear fender RH <i>R</i>	\$ 848.60
31	2 ps	rear fender inner trim @ \$199.70 <i>2x1/2</i>	\$ 399.40
32	8 ps	rear fender inner trim clip @ \$3.00 <i>11</i>	\$ 24.00
33	1 pc	rear fender air vent RH <i>11</i>	\$ 42.80
34	1 pc	rear windscreen glass moulding <i>11</i>	\$ 121.60
35	1 pc	spare tyre clamp <i>11</i>	\$ 64.70
36	1 pc	rear exhaust box <i>R</i>	\$ 449.60
37	2 ps	rear exhaust box mount @ \$38.30 <i>11</i>	\$ 76.60
38	1 pc	rear exhaust box heat shield <i>R</i>	\$ 99.70
39	1 pc	bonnet <i>3uc</i>	\$ 897.00

Not Authorized
13/8/18
2/5 = 7800
Take photo after repair
12 only.

Log LUK - Marcus

13/8/18 C1320/1A



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No.: M2-8922054-2

AlGAsia Insured's Veh No: SLM2207Y

Date of Accident: 11 August 2018

Mr Ang Eng Loo

Date: 13 August 2018

Estimate To Repair SGW1314J - Toyota Corolla Axio 1.5X A

Chassis No: NZE1416031368

S/No	Quantity	Description	Amount
		LIST ITEMS	
40	2 ps	bonnet hinge @ \$66.00 <i>h</i>	\$ 132.00 <i>X</i>
41	1 pc	bonnet lock <i>tw</i>	\$ 89.50 <i>X</i>
42	2 ps	bonnet rubber stopper @ \$18.20 <i>nu</i>	\$ 36.40 <i>X</i>
43	1 pc	bonnet underseal weatherstrip <i>nu</i>	\$ 102.70 <i>X</i>
44	2 ps	headlamp @ \$843.90 <i>one</i>	\$ 1,687.80 <i>X</i>
45	2 ps	headlamp clip @ \$12.50 <i>11</i>	\$ 25.00 <i>X</i>
46	1 pc	radiator grille <i>510/14.5</i>	\$ 350.60 <i>X</i>
47	1 pc	radiator grille emblem badge <i>11.5</i>	\$ 54.60 <i>X</i>
48	1 pc	radiator grille brace panel <i>tw</i>	\$ 59.80 <i>X</i>
49	1 pc	front bumper <i>DS</i>	\$ 455.80 <i>X</i>
50	1 pc	front bumper reinforcement <i>but</i>	\$ 328.90 <i>X</i>
51	1 pc	front bumper absorber foam <i>20m</i>	\$ 95.00 <i>X</i>
52	2 ps	front bumper side retainer @ \$54.70 <i>but</i>	\$ 109.40 <i>X</i>
53	10 ps	front bumper clip @ \$3.00 <i>nu</i>	\$ 30.00 <i>X</i>
54	1 pc	front bumper lower splash cover <i>11</i>	\$ 199.00 <i>X</i>
55	4 ps	front bumper lower splash cover clip @ \$3.00 <i>11</i>	\$ 12.00 <i>X</i>
56	2 ps	horn @ \$68.50 <i>11</i>	\$ 137.00 <i>X</i>
57	1 pc	aircon condensor <i>11</i>	\$ 1,474.50 <i>X</i>
58	1 pc	radiator assy <i>11</i>	\$ 1,758.50 <i>X</i>
59	1 pc	radiator fan motor <i>11</i>	\$ 538.00 <i>X</i>
60	1 pc	radiator fan blade <i>11</i>	\$ 148.30 <i>X</i>
61	1 pc	radiator fan shroud <i>11</i>	\$ 216.50 <i>X</i>
62	2 ps	front fender @ \$738.00 <i>R</i>	\$ 1,476.00 <i>X</i>
63	2 ps	front fender inner trim @ \$166.20 <i>11</i>	\$ 332.40 <i>X</i>
64	6 ps	front fender inner trim clip @ \$3.50 <i>11</i>	\$ 21.00 <i>X</i>
		Less 25 %	\$ 19,636.40
			\$ 4,909.10
			\$ 14,727.30
		SPECIAL NETT ITEMS	
65	1 set	rear bumper parking sensor <i>shaf</i>	\$ 450.00 <i>200</i>
66	1 pc	rear licence plate <i>but</i>	\$ 80.00 <i>40</i>
67	1 pc	rear luggage floor panel insulation padding <i>nu</i>	\$ 150.00 <i>100</i>
68	1 pc	rear windscreen glass sealant <i>11</i>	\$ 200.00 <i>X</i>
69	1 pc	rear windscreen inner sponge seal <i>11</i>	\$ 100.00 <i>X</i>
70	1 pc	radiator coolant <i>11</i>	\$ 30.00 <i>X</i>
71	1 pc	front licence plate <i>11</i>	\$ 80.00 <i>40</i>
			\$ 1,090.00

8926.1
6692.82



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel: 68585151 (24 Hours) Fax: 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLM2207Y

Date of Accident : 11 August 2018

Mr Ang Eng Loo

Date : 13 August 2018

Estimate To Repair SGW1314J - Toyota Corolla Axio 1.5X A

Chassis No : NZE1416031368

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
01		Towing fees	\$ 120.00
02		To check electrical lighting concerned.	\$ 60.00
03		To rust-proofing of the affected areas.	\$ 280.00
04		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 111 550.00
05		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 220.00
07		To reinstall of rear bumper parking sensor.	\$ 150.00
08		To drop rear exhaust box and renew the same.	\$ 11 160.00
09		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 180.00
10		To remove and refit rear windscreen glass.	\$ 11 180.00
11		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,400.00
12		Putty and spray painting of the affected portion.	\$ 1,800.00
			\$ 6,250.00
		Total	\$ 22,067.30

LSF Auto Consultants hence notify the Insurer of the following:

- To remove, repair, alter, spray painting
- To supply damaged parts of during resurvey
- Repair work is subject to confirmation
- Third party survey if on a "Without Prejudice" basis
- No major modification is allowed
- Supplementary claims must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairs

Signature

Date

1076382
8611

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 8400J

Vehicle Details

Vehicle No.: SGW1314J
Vehicle to be Exported: No
Intended De-registration Date: 13 Aug 2018
Vehicle Make: TOYOTA
Vehicle Model: COROLLA AXIO 1.5X A
Primary Colour: Grey
Manufacturing Year: 2007
Engine No.: 1NZC584034
Chassis No.: NZE1416031368
Maximum Power Output: 81.0 kW (108 bhp)
Open Market Value: \$14,510.00
Original Registration Date: 04 May 2007
First Registration Date: 04 May 2007
Transfer Count: 1
Actual ARF Paid: \$15,961.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Apr 2022
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$25,115.00
COE Rebate Amount: \$18,654.00
Total Rebate Amount: \$18,654.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Aug 2018

OK



CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

Find out more



toyota corolla axio

Price Range

Depreciation

> 10 year(s)

Vehicle Type

Submit

Advanced Search

Home > Used Cars > Direct Owners > Toyota Corolla Axio 1.5A X (COE till 03/2022)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



1 x

Workspaces
that Inspire



Workspaces,
Community,
Events & Growth -
All under one roof

Toyota Corolla Axio 1.5A X (COE till 03/2022)

Overview Financial Accessories Similar Research Photos Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price **\$23,888**

Depreciation **\$6,590 /yr**

Reg Date **30-Mar-2007**
(3yrs 7mths 16days COE left)

Manufactured **2006**

Mileage **-**

Transmission **Auto**

Engine Cap **1,496 cc**

Road Tax **\$750 /yr**

Power **81.0 kW (108 bhp)**
View specs of the Toyota Corolla Axio (2007-2012)

Curb Weight **1,130 kg**

Features **1.5L 16 Valves 4 Cylinders VVTi DOHC Engine, Smooth CVT Auto Transmission, ABS, SRS Airbags, Immobilizer, Super Fuel Efficiency.**

Accessories **Leather Seats, Sports Rims, Reverse Sensors, Audio Player, Retractable Side Mirrors, Integrated Remote Key.**

Description **Super Fuel Efficient, Leather Seats, Non Smoker, STA Evaluated Cars, Tip Top Condition, Low Road Tax, Lady Careful Driver, Regular Car Service Maintenance, Original Paint, Spacious Interior And Excellent Condition. Don't Miss It, View To Believe It! No Dealers. Please. SMS/Call And Make An Appointment.**

COE **\$24,715**

OMV **\$17,660**

ARF **\$19,426**

Dereg Value **\$17,930 as of today (change)**

No. of Owners **2**

Type of Veh **Mid-Sized Sedan**

Category **COE Car, Direct Owner Sale**

Availability **Available**

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 13-Jun-2018 | Last Updated on: 09-Aug-2018

Tags: Toyota Corolla, 2007 Toyota Corolla, Toyota, Corolla, Used Toyota

Upfront Payment

< more Financial info



Seller Information

Contact Person(s) **Zane**

Contact No. **94778866**

Enquiry ☐ Contact Seller

USEFUL FORMS

- Indemnity form
- Receipt
- M01
- Sales agreement
- Hand-over form

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare



TAN LIM MOTOR PTE LTD

AlGAsia Insured's Veh No : SLM2207Y

Date of Accident : 11 August 2018

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Mr Ang Eng Loo

Date : 13 August 2018

Estimate To Repair SGW1314J - Toyota Corolla Axio 1.5X A

Chassis No : NZE1416031368

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	bootlid <i>Buc</i>	\$ 720.00
02	1 pc	bootlid lock <i>tw</i>	\$ 99.50
03	1 pc	bootlid lock striker <i>11</i>	\$ 45.80
04	1 pc	bootlid Axio badge <i>nu</i>	\$ 68.00
05	1 pc	bootlid X badge <i>nu</i>	\$ 38.10
06	1 pc	bootlid weatherstrip <i>tw</i>	\$ 187.10
07	1 pc	bootlid outer garnish <i>body line</i>	\$ 225.00
08	1 pc	bootlid outer garnish emblem badge <i>nu</i>	\$ 45.60
09	2 ps	bootlid hinge @ \$69.00 <i>R</i>	\$ 138.00
10	4 ps	bootlid rubber stopper @ \$12.00 <i>11</i>	\$ 48.00
11	3 ps	bootlid lock cable clip @ \$3.00 <i>11</i>	\$ 9.00
12	1 pc	bootlid inner trim cover <i>11</i>	\$ 299.60
13	6 ps	bootlid inner trim cover clip @ \$3.00 <i>11</i>	\$ 18.00
14	1 pc	rear end panel <i>body</i>	\$ 599.80
15	1 pc	rear end panel inner trim <i>tw</i>	\$ 199.70
16	4 ps	rear end panel inner trim clip @ \$3.00 <i>11</i>	\$ 12.00
17	1 pc	rear bumper <i>Dis \$66.10</i>	\$ 1,209.00
18	2 ps	rear bumper bracket @ \$98.50 <i>PD</i>	\$ 197.00
19	2 ps	rear bumper side retainer @ \$54.60 <i>But</i>	\$ 109.20
20	2 ps	rear bumper side holder @ \$45.80 <i>11</i>	\$ 91.60
21	2 ps	rear bumper side bracket @ \$36.70 <i>11</i>	\$ 73.40
22	8 ps	rear bumper clip @ \$3.00 <i>nu</i>	\$ 24.00
23	1 pc	rear bumper end splashshield cover <i>11</i>	\$ 45.60
24	6 ps	rear bumper end splashshield cover clip @ \$3.00 <i>11</i>	\$ 18.00
25	2 ps	rear lamp @ \$399.70 <i>11</i>	\$ 799.40
26	4 ps	rear lamp clip holder @ \$3.00 <i>11</i>	\$ 12.00
27	2 ps	rear licence plate lamp @ \$55.00 <i>11</i>	\$ 110.00
28	1 pc	rear luggage floor panel <i>11</i>	\$ 949.60
29	1 pc	rear luggage floor panel trimboard <i>11</i>	\$ 349.70
30	1 pc	rear fender RH <i>R</i>	\$ 848.60
31	2 ps	rear fender inner trim @ \$199.70 <i>Def/11</i>	\$ 399.40
32	8 ps	rear fender inner trim clip @ \$3.00 <i>11</i>	\$ 24.00
33	1 pc	rear fender air vent RH <i>11</i>	\$ 42.80
34	1 pc	rear windscreen glass moulding <i>11</i>	\$ 121.60
35	1 pc	spare tyre clamp <i>11</i>	\$ 64.70
36	1 pc	rear exhaust box <i>R</i>	\$ 449.60
37	2 ps	rear exhaust box mount @ \$38.30 <i>11</i>	\$ 76.60
38	1 pc	rear exhaust box heat shield <i>R</i>	\$ 99.70
39	1 pc	bonnet <i>Buc</i>	\$ 897.00

Not Authorized
13/8/18

2/5/5
Take photo After repair
9 day.

Reg: LUK - Mercedes

13/8/18 C1320/11R



TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLM2207Y

Date of Accident : 11 August 2018

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Mr Ang Eng Loo

Date : 13 August 2018

Estimate To Repair SGW1314J - Toyota Corolla Axio 1.5X A

Chassis No : NZE1416031368

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
40	2 ps	bonnet hinge @ \$66.00 <i>1</i>	\$ 132.00
41	1 pc	bonnet lock <i>1W1</i>	\$ 89.50
42	2 ps	bonnet rubber stopper @ \$18.20 <i>neu</i>	\$ 36.40
43	1 pc	bonnet underseal weatherstrip <i>neu</i>	\$ 102.70
44	2 ps	headlamp @ \$843.90 <i>one</i>	\$ 1,687.80
45	2 ps	headlamp clip @ \$12.50 <i>11</i>	\$ 25.00
46	1 pc	radiator grille <i>510/4.5</i>	\$ 350.60
47	1 pc	radiator grille emblem badge <i>4.5</i>	\$ 54.60
48	1 pc	radiator grille brace panel <i>1W1</i>	\$ 59.80
49	1 pc	front bumper <i>DS</i>	\$ 455.80
50	1 pc	front bumper reinforcement <i>but</i>	\$ 328.90
51	1 pc	front bumper absorber foam <i>20m</i>	\$ 95.00
52	2 ps	front bumper side retainer @ \$54.70 <i>but</i>	\$ 109.40
53	10 ps	front bumper clip @ \$3.00 <i>neu</i>	\$ 30.00
54	1 pc	front bumper lower splash cover <i>11</i>	\$ 199.00
55	4 ps	front bumper lower splash cover clip @ \$3.00 <i>11</i>	\$ 12.00
56	2 ps	horn @ \$68.50 <i>11</i>	\$ 137.00
57	1 pc	aircon condensor <i>11</i>	\$ 1,474.50
58	1 pc	radiator assy <i>11</i>	\$ 1,758.50
59	1 pc	radiator fan motor <i>11</i>	\$ 538.00
60	1 pc	radiator fan blade <i>11</i>	\$ 148.30
61	1 pc	radiator fan shroud <i>11</i>	\$ 216.50
62	2 ps	front fender @ \$738.00 <i>R</i>	\$ 1,476.00
63	2 ps	front fender inner trim @ \$166.20 <i>11</i>	\$ 332.40
64	6 ps	front fender inner trim clip @ \$3.50 <i>11</i>	\$ 21.00
			<i>8926.1</i>
			<i>6693.82</i>
Less 25 %			\$ 19,636.40
			\$ 4,909.10
			\$ 14,727.30
<u>SPECIAL NETT ITEMS</u>			
65	1 set	rear bumper parking sensor <i>shape</i>	\$ 450.00
66	1 pc	rear licence plate <i>but</i>	\$ 80.00
67	1 pc	rear luggage floor panel insulation padding <i>neu</i>	\$ 150.00
68	1 pc	rear windscreen glass sealant <i>11</i>	\$ 200.00
69	1 pc	rear windscreen inner sponge seal <i>11</i>	\$ 100.00
70	1 pc	radiator coolant <i>11</i>	\$ 30.00
71	1 pc	front licence plate <i>one</i>	\$ 80.00
			\$ 1,090.00



TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLM2207Y
Date of Accident : 11 August 2018

Mr Ang Eng Loo

Date : 13 August 2018

Estimate To Repair SGW1314J - Toyota Corolla Axio 1.5X A
Chassis No : NZE1416031368

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
01		Towing fees	\$ 120.00
02		To check electrical lighting concerned.	\$ 60.00
03		To rust-proofing of the affected areas.	\$ 280.00
04		To place vehicle on jig bench to obtain cross and parallel measurement and correct to manufacturer specification with hydraulic pneumatic jack.	\$ 550.00
05		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 150.00
06		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 220.00
07		To reinstall of rear bumper parking sensor.	\$ 150.00
08		To drop rear exhaust box and renew the same.	\$ 160.00
09		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 180.00
10		To remove and refit rear windscreen glass.	\$ 180.00
11		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,400.00
12		Putty and spray painting of the affected portion.	\$ 1,800.00
			\$ 6,250.00
		Total	\$ 22,067.30

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

1076582
8611.

10
30
120
X
60
80
50
X
100
X
1600
1600



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

Address: 51 Defu Lane 10 Singapore 539216

Tel: 6858 5151 Fax: 6858 0877

Our Ref : TP008082018

Date : 22.10.2018

Your Ref : CC6/AIG18014621/Uja3

WITHOUT PREJUDICE

Claims Department – **Motor Claims [AIG Asia Pacific Insurance]**

c/o LKK Consultants [Ms Joy Irene]

Dear Sir/Madam,

ACCIDENT INVOLVING SGW1314J & SLM2207Y ON 11.08.2018

We refer to the above accident.

It appears that the accident was caused by your insured. Enclosed documents to substantiate our client's property damaged claim as our client had authorized us to quantify, to act and to reach settlement within 6 weeks on their behalf: -

☐ Original survey report/_____ copies of photographs

☒ Original Tax-Invoice number

☒ Original rental invoice number

☒ SAS / AS & IS / police report

☐ police result

☐ Certificate Of Insurance

☒ Vehicle search result

☒ Authorisation To Act

☐ _____

*Survey under insurance instruction – LKK Consultants

a)	Cost of repair (inclusive GST)	\$ 8,346.00
b)	Survey fees / Photographs as per request	\$
c)	Vehicle Search fees / GIA fees / Police Report fees / Reporting fees	\$ 7.49
d)	Loss of hire / use / rental / earnings / rental fees	\$ 1,412.40
e)	Scene photographs	\$
f)	Administrative charges to negotiate settlement (Waive if 100% offer made within acknowledge timeframe)	\$
g)		\$
Total		\$ <u>9,765.89</u>

*** Driver's injury and other losses exclude in this claim.**

Please acknowledge receipt of this letter within 14 days.

If you are agreeable to the above, please forward discharge voucher for our client's signature and payment issued directly to "Tan Lim Motor Pte Ltd" within 28 days.

Yours faithfully,

Johnson Chua

Email: johnson.chua@tlmotor.com.sg

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."

Print Received Message

This mail is associated with :

***SGW1314J (3393787684SG)**
[SLM2207Y]
TP
ANG ENG LOO
Aug 11 2018 3:00PM
[NGO YUH SHING]
Tan Lim Motor Pte Ltd

From **AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS)**, sent on **28/11/2018 13:50 PM**.
To **LKK_HQ**
Subject **Alert - Adj Mandate Approved (S\$9637.49) - SGW1314J - Claim Handler: Kesaval, Jaclyn-M**

Approved:9637.49:COR - \$8,346.00 (\$7,800 +GST) LOR - \$1,284.00 (\$100/day for 12 days +GST) LTA - \$7.49

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 21 August 2018 1:30 PM
To: 'johnsonngo36@yahoo.com.sg'
Cc: Admin A
Subject: ACCIDENT INVOLVING SLM 2207Y / SGW 1314J / OTHERS ON 11.08.2018

Our ref: CC6/AIG18014621/Uja3

NGO YUH SHING

Policy Holder

Dear Sir,

ACCIDENT INVOLVING SLM 2207Y / SGW 1314J / OTHERS ON 11.08.2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being. Pending for final allocation of liability in settlement by our principal AIG Asia Pacific Insurance Pte Ltd.

Please call us if you have further queries.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Ang Eng Lou ("the third party claimant")
of Block 205 Tampines Street 21 #08-1299 (S) 520205 (address),
owner of SGW1314J (vehicle no.) hereby authorize
Tan Lim Motor Pte Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SGW1314J that was
damaged pursuant to the accident which occurred on 11/08/2018 (date) along
PIE towards Changi direction (location)
involving vehicle no/s SLM 2207Y ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 11 day of August (month) 20 18 (year)



Signed by "the third party claimant"



Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, TAN LIM MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$8,346.00 (Repair Cost), S\$1,284.00 (Loss of Use/Rental), S\$7.49 (Disbursement) for vehicle no. SGW 1314J that was damaged pursuant to the accident which occurred on 11/08/2018 (date) along PIE TOWARDS CHANGI (location) involving vehicle no/s SLM 2207Y. This is pursuant to the inspection conducted on 13/08/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner ANG ENG LOO ("the third party claimant") of vehicle no. SGW 1314J make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGW 1314J (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11th (day) of December (month) **2018** (year)



Signed by appointed surveyor

Signed by "the workshop" (with chop)

"The contents of this document apply to vehicle damages only. All personal injuries and damages arising therefrom are excluded from the ambit and application of this document."



TAX-INVOICE
NUMBER: TP0918/018

(Please quote our reference number TP008082018 for payment)

陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD


Ang Eng Loo

Date: 18/09/2018

Vehicle No: SGW1314J
Model: TOYOTA COROLLA AXIO

Description	Amount
To lump sum repair as recommended by surveyor.	\$7,800.00
Reimbursement of LTA search fees.	\$7.00

Sub Total	\$7,807.00
Add 7% GST	\$546.49
Total	\$8,353.49



Tan Lim Motor Pte Ltd

**GLOBAL ADVANCE LEASING**

Biz Reg: B52935825E
 GST Reg No: 200409785W
 C/o 51 Delta Lane 10 S1539216)
 Tel: 61000GAL

Agreement: 7079

Vehicle No <u>SJX 1842K</u>		Make & Model <u>7/1102</u>		Date <u>11.08.2018</u>
Hirer Name <u>Ang Eng Loo</u> Address <u>205 Tampines St. 21 #08-1299</u> <u>S(580205)</u> Contact Person _____ Tel <u>96617777</u>		Class 2 / 2A / 2B / 3 / 4 / 5 Check Out / Check In Date Out <u>11.08.2018</u> Time Out <u>1730 hrs</u> KM Out <u>125980</u> PETROL E 1/4 <u>1 1/2</u> 3/4 F Date In <u>24.08.2018</u> Time In <u>0940 hrs</u> KM In <u>126855</u> PETROL E 1/4 <u>1 1/2</u> 3/4 F		
1st Driver Name <u>Hong fangqi</u> Address <u>As above</u> (H/P) _____ (D) _____ (H) _____ Passport/NRIC No <u>S8123953C</u> Nationality <u>S'porean</u> Driving Licence No _____ Driving Exp <u>17 yrs</u> Country of Issue <u>S'pore</u> Expiry Date <u>Unlimited</u>		Mode of Payment Cash / Cheque / Company Billing / Credit Card / Others Cheque / Card Details: _____ Expiry Date: _____		
Additional Driver Name _____ Address _____ (H/P) _____ (D) _____ (H) _____ Passport/NRIC No _____ Nationality _____ Driving Licence No _____ Driving Exp _____ yrs Country of Issue _____ Expiry Date _____		Rental Charges 06 Day/s @ \$ <u>110.00</u> /day \$ <u>660.00</u> 01 Week/s @ \$ <u>660.00</u> /week \$ <u>660.00</u> _____ Month/s @ \$ _____ /month \$ _____ SUBTOTAL \$ _____ CDW @ \$ _____ \$ _____ PAI @ \$ _____ \$ _____ Petrol Top Up \$ _____ Delivery / Collection fee \$ _____ Misc \$ <u>90.40</u> Misc \$ _____ Less _____ Pre-Payment / Deposit (\$\$ _____) Misc (\$\$ _____) Total Due \$ <u>1412.40</u>		
Non Waiverable Excess The Hirer acknowledges a \$ <u>1500.00</u> collision damage excess per accident applies. <u>搭客</u> <u>Rong</u> X _____		Charges Subject to Final Audit Refundable Deposit Deposit \$ _____ Date of Refund _____ Refund Acknowledgement X _____		
Collision Damage Waiver (CDW) The Hirer may limit his liability for any damage arising from collision to \$ _____ by purchasing CDW and paying the specified sum. X _____		For Official Use Invoice No <u>17181254</u> Date <u>24.08.2018</u> Receipt No _____ Date _____		
Personal Accident Insurance (PAI) PAI may be purchased at a premium specified herein. The Hirer acknowledges that the insurance is written by an independent insurance company and acknowledges that he has received, read and understood the policy conditions relating to the same. X _____		Special Instructions _____ _____ _____		

Important Notes

- Rental Vehicle is strictly for Singapore use only and may not be driven out of Singapore without prior consent of the owner.
- Only persons authorised by Global Advance Leasing may drive the vehicle.
- All parking and traffic violations are the responsibility of the Hirer. An Administrative charge will be levied on any traffic violations redirected.
- The Hirer shall be liable for excess charges for any late return at the rate shown per hour or per day.
- In the event of accident, the Hirer shall report to the rental office immediately.

I/We have read and agreed to the terms and conditions as set out on both sides of the agreement and certify that the information given is true and correct. If I/we opt to pay by credit / charge card, I agree that all amounts payable under this agreement may be billed to the same account and my signature here will be deemed to have been made on the applicable credit card charge slip.

X 搭客
 (Hirer's signature)

X Rong
 (Additional Driver's signature)

X _____
 (Global Advance Leasing)

Bill To: ANG ENG LOO (C/O TAN LIM MOTOR PTE LTD)
BLK 205 TAMPINES STREET 21
#08-1299
SINGAPORE 520205

Tax Invoice : 17181254
Date : 24 AUG 2018
Agreement No. : ST7079

Vehicle No	Description	Total Amount
SJX1842K	Toyota Vios E Auto Rental Charges From 11-08-2018 to 24-08-2018 6.0 days @ \$110.00 per day	SGD 660.00
	1.0 week @ \$660.00 per week	SGD 660.00

PAID
31 AUG 2018
BY: 006187655

Sub-Total 1,320.00
Add: GST (7.00%) 92.40
Amount Payable (SGD) 1,412.40

SINGAPORE DOLLAR: ONE THOUSAND FOUR HUNDRED TWELVE AND CENTS FORTY ONLY.

Cheque should be crossed "A/C Payee Only" and made payable to GLOBAL ADVANCE LEASING
Please write your invoice number on the reverse side of the cheque.
Payment should be made within 7 days from invoice.
Interest at 24% per annum on overdue account.
For bill enquiry, please call 6100 0425 / 9018 0988

Enquire Vehicle & Owner Information (Vehicle No. SLM2207Y As At 11 Aug 2018 / 15:45:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: TLM(PAT.)SGW1314J

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S6862298J

Owner Name: NGO YUH SHING

Registered Address Type: HDB / HUDC

Registered Block/House No.: 151

Registered Street Name: SIMEI STREET 1

Registered Unit No.: # 04 - 27

Registered Building Name: -

Registered Postal Code: 520151

Current Vehicle Details

Vehicle No.: SLM2207Y

Make Description/Model: KIA / FORTE K3 1.6A

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane


















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2018 Edit Reg		13 Aug 2018 00:00 Edit Adj Rpt	\$47,800.00 Edit Estimates	\$47,800.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	NGO YUH SHING, ID: S6862298								
Main Claimant:	ANG ENG LOO, ID: S1128400J								
Vehicle Reg. No.:	SGW1314J	Date of Loss:	11/08/2018 15:00 - :59 [135 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3393787684SG	Policy/Cover Note No.:	2100504994 (Comprehensive) Coverage: 24/03/2018 - 23/03/2019						
Vehicle Reg. No. (Insured):	SLM2207Y	Policy No. (Claimant):	5090553919-01						
		Excess:							
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 23/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG_EXPRESS (28/11/2018): Alert - Adj Mandate Approved (\$49637.49) - SGW1314J - Claim Handler: Kesaval, Ja... AIG_SG (14/08/2018): Request To Upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGW1314J (3393787684SG)
[SLM2207Y]
TP
ANG ENG LOO
Aug 11 2018 3:00PM
[NGO YUH SHING]
Tan Lim Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	(Draft)		Third Party Express Settlement – Payment Breakdown													Edit				
															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print			
1	13/08/18 20:16		Chassis Number													Load JPG	<input checked="" type="checkbox"/>			
2	13/08/18 20:16		Odometer Reading													Load JPG	<input checked="" type="checkbox"/>			
3	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
4	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
5	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
6	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
7	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
8	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
9	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
10	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
11	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
12	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
13	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
14	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
15	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
16	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
17	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
18	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
19	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
20	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
21	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
22	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
23	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
24	13/08/18 20:22		General View													Load JPG	<input checked="" type="checkbox"/>			
25	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
26	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
27	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
28	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
29	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
30	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
31	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
32	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
33	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			
34	13/08/18 20:23		General View													Load JPG	<input checked="" type="checkbox"/>			

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
36	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
37	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
38	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
39	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
40	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
41	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
42	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
43	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
44	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
45	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
46	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
47	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
48	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
49	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
50	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
51	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
52	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
53	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
54	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
55	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
56	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
57	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
58	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
59	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
60	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
61	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
62	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
63	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
64	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
65	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
66	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
67	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
68	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
69	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
70	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
71	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
72	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
73	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
74	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
75	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
76	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
77	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
78	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
79	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
80	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
81	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
82	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
83	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
85	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
86	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
87	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
88	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
89	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
90	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
91	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
92	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
93	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
94	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
95	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
96	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
97	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
98	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
99	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
100	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
101	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
102	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
103	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
104	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
105	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
106	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
107	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
108	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
109	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
110	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
111	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
112	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
113	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
114	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
115	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
116	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
117	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
118	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
119	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
120	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
121	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
122	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
123	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
124	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
125	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
126	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
127	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
128	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
129	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
130	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
131	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
132	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>
133	13/08/18 20:23	General View	 Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
134	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
135	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
136	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
137	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
138	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
139	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
140	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
141	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
142	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
143	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
144	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
145	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
146	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
147	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
148	13/08/18 20:23	General View		Load JPG	<input checked="" type="checkbox"/>
149	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
150	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
151	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
152	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
153	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
154	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
155	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
156	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
157	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
158	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
159	22/08/18 09:51	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/08/18 21:26	TP ESTIMATE - MARKED		Load PDF	
2	14/08/18 21:26	TP GIA REPORT		Load PDF	
3	14/11/18 13:46	LTA AND RENTAL RECEIPT		Load PDF	
4	28/11/18 12:01	LETTER TO INSURED		Load PDF	
5	12/12/18 17:04	WORKSHOP INVOICE		Load PDF	
6	12/12/18 17:04	AUTHORISATION TO ACT FORM		Load PDF	
7	12/12/18 17:04	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	14/08/18 10:34	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</div> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLM2207Y (Insd veh)	Model:	TOYOTA COROLLA 1.5 X
	SGW1314J (TP veh)		AXIO (A)
Date of Accident:	11/08/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	23,612.01	
Final Repair Cost	: \$	8,346.00	
Loss of Use	: \$	days at \$0.00 per day	
Rental (if any)	: \$	1,284.00	12 days
LTA / GIA Search Fee	: \$	7.49	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	9,637.49	

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ 0 _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Tan Lim Motor Pte Ltd	: \$	9,637.49
2)		: \$	
3)		: \$	
4)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

12 Dec
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18014621/UJA3Q2

Date: 12/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100504994
Claimant Vehicle No : SGW1314J **Insured Vehicle No :** SLM2207Y
Date of Loss: 11/08/2018 **Nature of Claim:** TP **Claim No:** 3393787684SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGW1314J**
 Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A) Engine No: 1NZC584034
 Reg. Date: 04/05/2007 (Man. Year: 2007) Chassis No: NZE1416031368
 Colour: Grey Odometer: 179305 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/70 R14 Rear Tyre Size: 185/70 R14
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,817.30	7,073.82	8,743.48	55.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,250.00	3,690.00	2,560.00	40.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,067.30	10,763.82	11,303.48	51.22
Approved Total (Overridden) (S\$)		7,800.00		
(S\$)	22,067.30	7,800.00	14,267.30	64.65
+ GST 7.00/7.00% (S\$)	1,544.71	546.00	998.71	64.65
Nett Amount (S\$)	23,612.01	8,346.00	15,266.01	64.65
+ Car Rental (12.0 x S\$100.00/day + 7.00% GST) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		9,637.49		

INSPECTION

Date of Assignment: 13/08/2018
 Date Inspected: 13/08/2018 Inspected At: Tan Lim Motor Pte Ltd (Defu)
 51 Defu Lane 10
 Singapore 539216

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	720.00 FL	*720.00 FL
2	1		*BOOTLID LOCK	Twisted	99.50 FL	*99.50 FL
3	1		*BOOTLID LOCK STRIKER	Not Necessary	45.80 FL	*- FL
4	1		*BOOTLID AXIO BADGE	Necessary	68.00 FL	*68.00 FL
5	1		*BOOTLID X BADGE	Necessary	38.10 FL	*38.10 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	187.10 FL	*187.10 FL
7	1		*BOOTLID OUTER GARNISH	Bent / Cracked	225.00 FL	*225.00 FL
8	1		*BOOTLID OUTER GARNISH EMBLEM BADGE	Necessary	45.60 FL	*45.60 FL
9	2		*BOOTLID HINGE	Repair	138.00 FL	*- FL
10	4		*BOOTLID RUBBER STOPPER	Not Necessary	48.00 FL	*- FL
11	3		*BOOTLID LOCK CABLE CLIP	Not Necessary	9.00 FL	*- FL
12	1		*BOOTLID INNER TRIM COVER	Not Necessary	299.60 FL	*- FL
13	6		*BOOTLID INNER TRIM COVER CLIP	Not Necessary	18.00 FL	*- FL
14	1		*REAR END PANEL	Badly Dented	599.80 FL	*599.80 FL
15	1		*REAR END PANEL INNER TRIM	Twisted	199.70 FL	*199.70 FL
16	4		*REAR END PANEL INNER TRIM CLIP	Not Necessary	12.00 FL	*- FL
17	1		*REAR BUMPER	Distorted	1,209.00 FL	*566.10 FL
18	2		*REAR BUMPER BRACKET	Dented	197.00 FL	*197.00 FL
19	2		*REAR BUMPER SIDE RETAINER	Bent	109.20 FL	*109.20 FL
20	2		*REAR BUMPER SIDE HOLDER	Not Necessary	91.60 FL	*- FL
21	2		*REAR BUMPER SIDE BRACKET	Not Necessary	73.40 FL	*- FL
22	8		*REAR BUMPER CLIP	Necessary	24.00 FL	*24.00 FL
23	1		*REAR BUMPER END SPLASHIELD COVER	Not Necessary	45.60 FL	*- FL
24	6		*REAR BUMPER END SPLASHIELD COVER CLIP	Not Necessary	18.00 FL	*- FL
25	2		*REAR LAMP	Cracked	799.40 FL	*799.40 FL
26	4		*REAR LAMP CLIP HOLDER	Not Necessary	12.00 FL	*- FL
27	2		*REAR LICENCE PLATE LAMP	Not Necessary	110.00 FL	*- FL
28	1		*REAR LUGGAGE FLOOR PANEL	Repair	949.60 FL	*- FL
29	1		*REAR LUGGAGE FLOOR PANEL TRIMBOARD	Cracked	349.70 FL	*349.70 FL
30	1		*REAR FENDER RH	Repair	848.60 FL	*- FL
31	2		*REAR FENDER INNER TRIM	Deformed / Torn	399.40 FL	*399.40 FL
32	8		*REAR FENDER INNER TRIM CLIP	Not Necessary	24.00 FL	*- FL
33	1		*REAR FENDER AIR VENT RH	Not Necessary	42.80 FL	*- FL
34	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	121.60 FL	*- FL
35	1		*SPARE TYRE CLAMP	Not Necessary	64.70 FL	*- FL
36	1		*REAR EXHAUST BOX	Repair	449.60 FL	*- FL
37	2		*REAR EXHAUST BOX MOUNT	Not Necessary	76.60 FL	*- FL
38	1		*REAR EXHAUST BOX HEAT SHIELD	Repair	99.70 FL	*- FL
39	1		*BONNET	Buckled	897.00 FL	*897.00 FL
40	2		*BONNET HINGE	Repair	132.00 FL	*- FL
41	1		*BONNET LOCK	Twisted	89.50 FL	*89.50 FL
42	2		*BONNET RUBBER STOPPER	Necessary	36.40 FL	*36.40 FL
43	1		*BONNET UNDERSEAL WEATHERSTRIP	Necessary	102.70 FL	*102.70 FL
44	2		*HEADLAMP	Cracked	1,687.80 FL	*1,687.80 FL
45	2		*HEADLAMP CLIP	Not Necessary	25.00 FL	*- FL
46	1		*RADIATOR GRILLE	Broken / Missing	350.60 FL	*350.60 FL
47	1		*RADIATOR GRILLE EMBLEM BADGE	Missing	54.60 FL	*54.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
48	1		*RADIATOR GRILLE BRACE PANEL	Twisted	59.80 FL	*59.80 FL
49	1		*FRONT BUMPER	Dented	455.80 FL	*455.80 FL
50	1		*FRONT BUMPER REINFORCEMENT	Bent	328.90 FL	*328.90 FL
51	1		*FRONT BUMPER ABSORBER FOAM	Torn	95.00 FL	*95.00 FL
52	2		*FRONT BUMPER SIDE RETAINER	Bent	109.40 FL	*109.40 FL
53	10		*FRONT BUMPER CLIP	Necessary	30.00 FL	*30.00 FL
54	1		*FRONT BUMPER LOWER SPLASH COVER	Not Necessary	199.00 FL	*- FL
55	4		*FRONT BUMPER LOWER SPLASH COVER CLIP	Not Necessary	12.00 FL	*- FL
56	2		*HORN	Not Necessary	137.00 FL	*- FL
57	1		*AIRCON CONDENSOR	Not Necessary	1,474.50 FL	*- FL
58	1		*RADIATOR ASSY	Not Necessary	1,758.50 FL	*- FL
59	1		*RADIATOR FAN MOTOR	Not Necessary	538.00 FL	*- FL
60	1		*RADIATOR FAN BLADE	Not Necessary	148.30 FL	*- FL
61	1		*RADIATOR FAN SHROUD	Not Necessary	216.50 FL	*- FL
62	2		*FRONT FENDER	Repair	1,476.00 FL	*- FL
63	2		*FRONT FENDER INNER TRIM	Not Necessary	332.40 FL	*- FL
64	6		*FRONT FENDER INNER TRIM CLIP	Not Necessary	21.00 FL	*- FL
65	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
66	1		*REAR LICENCE PLATE	Bent	80.00 FS	*40.00 FS
67	1		*REAR LUGGAGE FLOOR PANEL INSULATION PADDING	Necessary	150.00 FS	*100.00 FS
68	1		*REAR WINDSCREEN GLASS SEALANT	Not Necessary	200.00 FS	*- FS
69	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
70	1		*RADIATOR COOLANT	Not Necessary	30.00 FS	*- FS
71	1		*FRONT LICENCE PLATE	Cracked	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	20,726.40	9,305.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,909.10	2,231.28
Total Parts (\$\$)	15,817.30	7,073.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEES	New	120.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	30.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	280.00	120.00
4	TO PLACE VEHICLE ON JIG BENCH TO OBTAIN CROSS AND PARALLEL MEASUREMENT AND CORRECT TO MANUFACTURER SPECIFICATION WITH HYDRAULIC PNEUMATIC JACK	New	550.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	150.00	60.00
6	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	220.00	80.00
7	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	150.00	50.00
8	TO DROP REAR EXHAUST BOX AND RENEW THE SAME	New	160.00	0.00
9	TO DISMANTLE AIR-CON ASSY ,REMOVE AND RENEWAL OF PARTS ,VACUUM AND CHARGE-IN GAS	New	180.00	100.00
10	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
11	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,400.00	1,600.00
12	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,800.00	1,600.00
Gross Labour Cost (S\$)			6,250.00	3,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >