

ASS. REC. BY:

REF:

CS/FCI/8014632/K/d302

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

Jurnee Yong

of

FCI

Date/Time:

13/08/2018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLN681T

Insured:

SHC 1357D

at Workshop m/s

Esteem Performance
385 Sir Ming Drive

Tel:

87 990066

Policy No:

Claim No:

D18005593MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 19/07/2018

CA / REV / REP. / REV 24 HRS

IDS

Date/Time:

12:15pm @ 13/8/18

Person Contacted:

Carmen

H.O.D. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLN681T-X
	SHC1357D - NSINC16015238/Hlvbn2 DoA: 13/8/2016
	Part by Part \$ 3,123.81 (Red. 1914.57; 37%)

ASS. REC. BY:

REF: PC1 /

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 88416

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 04 days

Res.: Yes or No

Lum Sum: 1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN8817Yr Regn: 04.17Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: 707 Privsc.c. 1798Colour: A.P. White

A/C: Insured / Std / NI / NA

Sp. Reading: 115117

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTD KB 31FU 503556124Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: DAVARI 195/65R15R: YokoBS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 2 mm


Rear

R/Bal. 6 mmL/Bal. 8 mmL/Bal. 6 mmD.O.A. 19/7/18D.O.I. 13/8/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.



RECEIVED 04 OCT 2018

Date/Time, File Pass to?

☐

: Prell. Report

1) 4/10 Typist☒

: Final Report

Date/Time, File Return to?

2) _____

Report Format: TPLump Sum / I.B.I: (\$ 3123.81)Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + P.S. \$

Fixturs

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

140
50
50
15
245

MOTOR SURVEY ASSIGNMENT

Date	23-07-2018	Our Ref No. D18005593MFSH
Accident Date	19-07-2018	Claim Type. Third Party
Insured Vehicle	SHC1357D	Third Party Vehicle. SLN681T
Survey Location	385 SIN MING DRIVE (INSIDE VICOM)	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 87990066	Fax No. 64510394
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/242619)



PRI Documents



Close



PRI Header Details

Claim No	D18005593MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ESTEEM P
Workshop Name	ESTEEM PERFORMANCE PTE LTD (Contact Person : CARMEN LIM)	Survey Location & Contact Details	385 SIN MING DRIVE (INSIDE VICOM) Mobile: 87990066 , Phone: 64841221 , Fax: 6451039 EmailId: CARMEN@ESTEEMPERF.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC1357D	TP Vehicle No	SLN681T
PRI Recieved Date	10-08-2018 02:50:13 PM	Surveyor Appointed Date	13-08-2018 12:04:08 PM	Surveyor Accept Date	13-08-2018 0

Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	13-08-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18014632/Ktd3

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-08-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1357D	Veh. Inspected	SLN 681T
Policy No.		Coverage (\$)	0.00
Claim No.	D18005593MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	13/08/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	19/07/2018	Inspection Date	13/08/2018
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2018 14:14
Date Of Accident	19/07/2018 20:40
Exact Location Of Accident	KATONG 112 (DROP OFF POINT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN681T
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS HYBRID 1.8 CVT
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	

Driver

Name of Driver	NG HONG GEE
NRIC No	S1582492A
Date Of Birth	09/11/1963
Occupation	OUTDOOR
Date Of Driving Pass	30/06/1986
Driving Experience	32 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98774493
Fax Number	
Contact Number	
EEmail Address	NGHONGGEE2327@GMAIL.COM

Address	HDB RIVERVALE GROVE, 123E RIVERVALE DRIVE. (S)545123 #10-101
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - OPENING DOOR OF VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : P1 GENDER: : MALE
Passenger 2	NAME: : P2 GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was driving along drive way at KATONG MALL (East Coast Rd) when suddenly a passenger from the taxi SHC1357D that was alighting at the drop off point at KATONG MALL open the rear left door & hit onto my SLN0681T right side mirror. I try to avoid & my SLN0681T front left/bottom bumper scratch onto a kerb. No injuries involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	RETRIEVING
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC1357D
Vehicle Make/Model/Colour	HYUNDAI/i40 1.7 CRDI F/L AT ABS AIRBAG 4DR/BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	KWOK QUOK MENG
NRIC/Passport Number	S1239260E
Contact Number	91776257
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

KERB

Vehicle Category

NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may give insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available as stated.
8. Consent under the Personal Data Protection Act (PDPA)
 - (a) I, My Insurer, my witnesses and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to an insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as "Insurers"), the Insurers' lawyers/law firms, the Ministry/Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims, including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the sums as well as on the external cover of photographs/recordings, where;
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX M
REPORTING OFFIC
MOHD FADZLY BIN IS

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Officer

Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I was driving along drive way at KATONG MALL (East Coast Rd) when suddenly a passenger from the taxi SHC1357D that was alighting at the drop off point at KATONG MALL open the rear left door & hit onto my SLN0681T right side mirror. I try to avoid & my SLN0681T front left/bottom bumper scratch onto a kerb. No injuries involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MOHD FADZLY BIN ISMAIL

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

20 July 2018 12:01 pm

Date/Time:

20 July 2018 12:01 pm



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 681 T

Parts	(a) Cost / List Price Items	\$	3,584.50
	Plus/Less 25%	\$	896.13
	Total of Cost / List	\$	2,688.38
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	2,688.38
Labour		\$	2,350.00
Total		\$	5,038.38

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 13/8/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 13/8/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperv.com.sg

Spare Parts

Vehicle No. :	SLN 681 T	Submit By :	Carmen Lim
Make & Model :	TOYOTA PRIUS	Year Manufacture :	2017
Chassis No. :	JTDKB3FU503556124	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (arm)	1			
2	RH wing mirror (signal lamp) <i>cm</i>	1	\$1,374.20		✓
3	RH wing mirror (glass)	1			
4	RH wing mirror (cover) <i>Respray</i>	1	\$87.40		X
5	RH front fender <i>Sn</i>	1	\$868.70		✓
6	RH front fender undershield <i>Sn</i>	1	\$185.64		X
7	RH front fender undershield clip <i>nn</i>	10	\$25.00		X
8	RHF fender wording "HYBRID" <i>nn</i>	1	\$44.17		✓
9	RH front fender quarter garnish <i>Sn</i>	1	\$122.70		✓
10	RHF door glass outer moulding <i>SVC</i>	1	\$121.75		X
11	RH front door stand moulding <i>Ref</i>	1	\$49.74		✓
12	Front bumper <i>Sn</i>	1	\$450.80		X
13	Front bumper clip <i>nn</i>	10	\$40.00		X
14	Front bumper side retainer RH <i>Sn</i>	1	\$107.20		X
15	Front bumper side retainer LH <i>Sn</i>	1	\$107.20		X
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Vehicle No. : SLN 681 T Submit By : Carmen Lim
Make & Model : TOYOTA PRIUS Year of Manufacture : 2017



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLN 681 T

Finalized

Not Authorized

1-13-1

Primary B & Paint

Parts	(a) Cost / List Price Items	\$	3,584.50	2498.41
	Plus/Less 25%	\$	896.13	624.60
	Total of Cost / List	\$	2,688.38	1873.81
	(b) Nett Price Items			
	Less			
	Total of Nett Item			
	(c) Special Nett Items			
Total Parts Cost		\$	2,688.38	
Labour		\$	2,350.00	1750
Total		\$	5,038.38	3123.81 ✓ ok

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

UPK

Survey conducted on

13/8/18

at

14:30

Remarks By Surveyor

(a) The repair of this vehicle is ☒ authorized / is not authorized until further notice.

(b) Recommended Days of Repair : *04* day(s)

(c) Resurvey : Required / ☒ Not Required

(d) Excess : \$

(e) Signature of surveyor

Sc

Date:

13/8/18



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLN 681 T

TOYOTA PRIUS

JTDKB3FU503556124

Submit By :
Year Manufacture :
Engine No. :
Cost / List

Carmen Lim
2017

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
(1)	RH wing mirror (arm)	1			
(2)	RH wing mirror (signal lamp)	1	\$1,374.20		
(3)	RH wing mirror (glass)	1			✓
4	RH wing mirror (cover)	1			
5	RH front fender	1	\$87.40		X
6	RH front fender undershield	1	\$868.70		✓
7	RH front fender undershield clip	1	\$185.64		X
8	RHF fender wording "HYBRID"	10	\$25.00		X
9	RH front fender quarter garnish	1	\$44.17		✓
10	RHF door glass outer moulding	1	\$122.70		✓
11	RH front door stand moulding	1	\$121.75		X
12	Front bumper	1	\$49.74		✓
13	Front bumper clip	1	\$450.80		X
14	Front bumper side retainer RH	10	\$40.00		X
15	Front bumper side retainer LH	1	\$107.20		X
16		1	\$107.20		X
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

2498.41

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

SLN 681 T

Make & Model :

TOYOTA PRIUS

Chassis No. :

JTDKB3FU503556124

Submit By :

CARMEN LIM

Year Manufacture :


2017

Engine No. :

Cost / List**Supplementary**

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH Front Door Frame Moulding <i>nd</i>	1	\$38.90	✓	
2		1			
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge



1250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014632/Ktd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-10-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 1357D	Veh. Inspected	SLN 681T
	Policy No.	D-18088936MFSH	Coverage (\$)	0.00
	Claim No.	D18005593MFSH	Excess (\$)	0.00
	Assign From	JOANNE YONG	Assign Date	13/08/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA PRIUS (A)	c.c	1798
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTDKB3FU503556124	Colour	METALLIC PEARL WHITE
	Odometer	115117	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	DAVANTI	8 mm
	L/H Front Tyre	195/65 R15	DAVANTI	8 mm
	R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	19/07/2018	Inspection Date	13/08/2018
	Survey held at	385 SIN MING DRIVE		
	Repairer	ESTEEM PERFORMANCE PTE LTD		
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 681T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RH WING MIRROR (SIGNAL LAMP) }	CRACKED	1,374.20	1,374.20
1	RH WING MIRROR (ARM) }		-	-
1	RH WING MIRROR (GLASS) }		-	-
1	RH WING MIRROR (COVER)	RESPRAY SEE LABOUR	87.40	-
1	RH FRONT FENDER	BENT	868.70	868.70
1	RH FRONT FENDER UNDERSHIELD	SERVICEABLE	185.64	-
10	RH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	25.00	-
1	RHF FENDER WORDING "HYBRID"	NECESSARY	44.17	44.17
1	RH FRONT FENDER QUARTER GARNISH	MISSING	122.70	122.70
1	RHF DOOR GLASS OUTER MOULDING	SERVICEABLE	121.75	-
1	RH FRONT DOOR STAND MOULDING	DENTED	49.74	49.74
1	FRONT BUMPER	SERVICEABLE	450.80	-
10	FRONT BUMPER CLIP	NOT NECESSARY	40.00	-
1	FRONT BUMPER SIDE RETAINER RH	SERVICEABLE	107.20	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	107.20	-
1	RH FRONT DOOR FRAME MOULDING (ADDITIONAL)	DENTED	38.90	38.90
	LESS 25% DISCOUNT		-905.85	-624.60
			2,717.55	1,873.81
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RHF FENDER,FRONT BUMPER,RHF WINDSCREEN PILLAR,RH QUARTER PANEL,RHF DOOR,RH SIDE MIRROR).		1,000.00	500.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RHF FENDER,FRONT BUMPER,RHF WINDSCREEN PILLAR,RH QUARTER PANEL,RHF DOOR,RH SIDE MIRROR).INCLUSIVE OF THE REPAINT OF RH WING MIRROR (COVER).		1,200.00	700.00
	TO CHECKWIRING.		50.00	20.00
	TO TUFF COAT.		100.00	30.00
			2,350.00	1,250.00

Report Ref No. CS/FCI18014632/Ktd3e2



GRAND TOTAL		5,067.55	3,123.81
RECOMMENDED COST OF REPAIRS			3,123.81

Report Ref No. CS/FCI18014632/Ktd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.