

2/1/2002

ASS. REC. BY:

REF: CS/CTI/8014645/Ksd3/n2

Special Instruction:

Survivor: Kenneth
memmen

ASSIGNMENT (Office)

From (Person): Irene Jay

of CTI

Date/Time: 13/8/18 @ 4:53pm

Estimated Cost:

Bill to:

OD WS / TP RES / OD RES / EVA / INV / MV7CS

To Inspect Vehicle No: SKV 9973 L

Insured: SJK 8007C

at Workshop m/s: Tong Luek

Tel: 8250 0088

of 160 Sin Ming Drive #07-01

Policy No: DMHCSN1745801700

Claim No: SNM18D03703C02

Sum Insured:

Excess:

Make of Veh:

D.O.A. 25/7/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up?

14/8/2018

H.O.D. Endorsement:

Date/Time: 5:29pm @ 13/8/18

Person Contacted:

candice

Vehicle IN OUT

Date/Time	Action/Instruction	Estimate
	SKV 9973L - NA/CTI 18 013728 / K1	DUA: 25/7/18
	SJK 8007C - NA/CTI 18 013728 / K1	DUA: 25/7/18

(08/11/13) wef

REF: CTI

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: 14/08/18

Estimated Cost: _____

OD: TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKV 9973L

at Workshop m/s Tong Luck

of 160 Sin Ming Drive # 07-01

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Wp

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKV 9973L Yr Regn: 10/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen DS5 c.c. 1560

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 56727 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: V17FK159110805516599

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: _____
R: 225/50R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front R/Bal. 8 mm

Rear R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 25/7/18 D.O.I. 14/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>15/8</u>	<u>File pass to Catherine</u>
<u>25/08/18</u>	<u>Confirmed P/P \$2,536.10 @ 3 days with Kenneth. (\$1,894.00 Red - 43%)</u>

Date/Time, File Pass to? : Preli. Report

Days Of Repair: 3

1) 25/08/18 : Final Report
Typist

Resurvey No. of Trip: 2

Date/Time, File Return to?

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
<u>220</u>	
TOTAL	

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ 2,536.10 P/P)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18014645/Ksd3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 13-08-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 8007C	Veh. Inspected	SKV 9973L
Policy No.	DMHCSN1745801700	Coverage (\$)	0.00
Claim No.	SNM18D03703C02	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAY)	Assign Date	13/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	25/07/2018	Inspection Date	14/08/2018
Survey held at	TONG LUCK AUTO PL 160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Aug 2018		13 Aug 2018 16:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	M/S VOULEZ CARS, Co. Reg. No.: -								
Main Claimant:	DAIMLER FLEET MANAGEMENT SINGAPOTE PTE LTD								
Vehicle Reg. No.:	SKV9973L	Date of Loss:	25/07/2018 18:00 - :59						
Claim Type:	TP / SNM18D03703C02	Policy/Cover Note No.:	DMHCSN1745801700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJK8007C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/08/2018]								
Adj Asg. Remarks:	NO EST, ASSIGN KENNETH KONG AS SJE.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



TONG LUCK AUTO PTE LTD.

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO :

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 25/07/2018

TP VEH REG NO : SJK8007C

ESTIMATE

NO : QUOT201808-000019(00)

DATE : 10/08/2018

POLICY NO : 999995580

VEH REG NO : SKV9973L

MAKE/MODEL : CITROEN DS5 1.6I E-HDI ETG6

CHASSIS NO : VF7KF9HD8DS516599

ENGINE NO : 10JBFT0042936

REG. DATE : 2013

NOT IN THE SHED

Resurvey B & paint

3 days

Estimate Repair Cost to Vehicle No : SKV9973L

Description	Quantity	Unit Price	Amount
		S\$	S\$
LIST PRICE			
1 Rear bumper	1	900.00	900.00 ✓
2 Rear bumper reinforcement	1	400.00	400.00 ✓
3 Rear bumper retainer - RH	1	152.00	152.00 7X
4 Rear bumper tow cover	1	89.00	89.00 ✓
5 Rear bumper clips	15	5.00	75.00 ✓
6 Rear bumper reverse sensor	1	220.00	220.00 ✓
7 Rear bumper reverse sensor seal	6	5.00	30.00 ✓
8 Rear bumper lower spoiler	1	325.00	325.00 ✓
9 Rear bumper lower spoiler clips	8	5.00	40.00 ✓
10 Rear exhaust chrome pipe - RH	1	358.00	358.00 7X
			2,589.00
		Less 10%	258.90
			2,330.10
LABOUR			
11 To panel beat and straighten RH rear chassis frame, taillamp panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 300
12 To remove and refit rear bumper sensor and reset faulty code	1	100.00	100.00 300
13 To check and rectify wiring system	1	80.00	80.00 150
14 To spray same on affected area	1	800.00	800.00 300
15 To apply rust-proofing on replaced and repaired panels.	1	120.00	120.00 X
			2,100.00

TOTAL S\$ 4,430.10

ADD GST @ 7% 310.11

GRAND TOTAL S\$ 4,740.21

SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED FORTY AND CENTS TWENTY-ONE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD
1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN :

YOUR REF NO :

CLAIM TYPE : THIRD PARTY

TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE

ACCIDENT DATE : 25/07/2018

TP VEH REG NO : SJK8007C

ESTIMATE

NO : QUOT201808-000019(00)

DATE : 10/08/2018

POLICY NO : 999995580

VEH REG NO : SKV9973L

MAKE/MODEL : CITROEN DS5 1.6I E-HDI ETG6

CHASSIS NO : VF7KF9HD8DS516599

ENGINE NO : 10JBFT0042936

REG. DATE : 2013

NOT WITHHELD
Repair B4 paint
3 days

Estimate Repair Cost to Vehicle No : SKV9973L

Description	Quantity	Unit Price	Amount
			<u>SS</u>
LIST PRICE			SS
1 Rear bumper	1	900.00	900.00 ✓
2 Rear bumper reinforcement	1	400.00	400.00 ✓
3 Rear bumper-retainer-RH	1	152.00	152.00 ✗
4 Rear bumper tow cover	1	89.00	89.00 ✓
5 Rear bumper clips	15	5.00	75.00 ✓
6 Rear bumper reverse sensor	1	220.00	220.00 ✓
7 Rear bumper reverse sensor seal	6	5.00	30.00 ✓
8 Rear bumper lower spoiler	1	325.00	325.00 ✓
9 Rear bumper lower spoiler clips	8	5.00	40.00 ✓
10 Rear exhaust-chrome-pipe - RH	1	358.00	358.00 ✗
			2,589.00
			Less 10%
			2,330.10
LABOUR			
11 To panel beat and straighten RH rear chassis frame, taillamp panel, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00 300 ✓
12 To remove and refit rear bumper sensor and reset faulty code	1	100.00	100.00 50 ✓
13 To check and rectify wiring system	1	80.00	80.00 15 ✓
14 To spray same on affected area	1	800.00	800.00 300 ✓
15 To apply rust-proofing on replaced and repaired panels. (end panel)	1	120.00	120.00 ✗
			2,100.00 705
TOTAL			SS 4,430.10
ADD GST @ 7%			310.11
GRAND TOTAL			SS 4,740.21

SINGAPORE DOLLAR FOUR THOUSAND SEVEN HUNDRED FORTY AND CENTS TWENTY-ONE ONLY

\$ 2,536.10 ✓
7%
180.33
\$ 2,716.43

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118014645/KSD3N2

Date: 26/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSN1745801700
Claimant Vehicle No :	SKV9973L	Insured Vehicle No :	SJK8007C
Date of Loss:	25/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03703C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV9973L	Engine No:	10JBFT0042936
Make & Model:	CITROEN DS5, 1.6 I-HDI ETG (A)	Chassis No:	VF7KF9HD8DS516599
Reg. Date:	14/10/2015 (Man. Year: 2013)	Odometer:	56727 km
Colour:	Metallic Grey		
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,330.10	1,871.10	459.00	19.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	665.00	1,435.00	68.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,430.10	2,536.10	1,894.00	42.75
+ GST 7.00/7.00% (S\$)	310.11	177.53	132.58	42.75
Nett Amount (S\$)	4,740.21	2,713.63	2,026.58	42.75

INSPECTION

Date of Assignment:	13/08/2018	
Date Inspected:	14/08/2018 Inspected At:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	3.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 26 Sep 2018)	
Parts:	N/A	CITROEN DS5 1.6 I-HDI ETG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKV9973L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Buckled	900.00 FL	*900.00 FL	
2	1		*REAR BUMPER REINFORCEMENT	Bent	400.00 FL	*400.00 FL	
3	1		*REAR BUMPER RETAINER-RH	Serviceable	152.00 FL	*- FL	
4	1		*REAR BUMPER TOW COVER	Dented	89.00 FL	*89.00 FL	
5	15		*REAR BUMPER CLIPS	Necessary	75.00 FL	*75.00 FL	
6	1		*REAR BUMPER REVERSE SENSOR	Shorted	220.00 FL	*220.00 FL	
7	6		*REAR BUMPER REVERSE SENSOR SEAL	Necessary	30.00 FL	*30.00 FL	
8	1		*REAR BUMPER LOWER SPOILER	Dented	325.00 FL	*325.00 FL	
9	8		*REAR BUMPER LOWER SPOILER CLIPS	Necessary	40.00 FL	*40.00 FL	
10	1		*REAR EXHAUST CHROME PIPE-RH	Repair	358.00 FL	*- FL	
					Sub Total (\$\$)	2,589.00	2,079.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	258.90	207.90
					Total Parts (\$\$)	2,330.10	1,871.10

F=Franchise part L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND STRAIGHTEN RH REAR CHASSIS FRAME, TAILLAMP PANEL, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,000.00	300.00
2	TO REMOVE AND REFIT REAR BUMPER SENSOR AND RESET FAULTY CODE	New	100.00	50.00
3	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	15.00
4	TO SPRAY SAME ON AFFECTED AREA	New	800.00	300.00
5	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	120.00	-
Gross Labour Cost (\$\$)			2,100.00	665.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >