



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

Not Authorized
Work
The photo, Behn
for ity.
5-day
13/8/18

EQ INSURANCE

DATE : 08-08-2018

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX
SINGAPORE 069110

VEHICLE NO. : SKW6968S

ACCIDENT DATE : 07-08-2018 07:45

THIRD PARTY REF. : GBD3666P

ATTN: EQ INSURANCE

ESTIMATE COST OF REPAIR TO VEICLE SKW6968S HONDA VEZEL 1.5 SA

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	REAR BOOT COVER	300/300 560.00 /
2	1	REAR BOOT WINDSCREEN MOULDING	rec 38.00 /
3	1	REAR BOOT VEZEL EMBLEM	rec 38.00 /
4	1	REAR BOOT LOCK	twi/gm 65.00 /
5	1	REAR BOOT RUBBER	twi 50.00 /
6	2	REAR BOOT REFLECTOR@\$165.00	cm 330.00 /
7	1	REAR BOOT GARNISH	11 68.00 x
8	1	REAR BOOT H EMBLEM	11 15.00 x
9	1	REAR BOOT TRIMBOARD	98.00 ?
10	2	REAR BOOT PULL COVER	15.00 ?
11	2	REAR END PANEL	300/300 285.00 /
12	2	REAR END PANEL TOP GARNISH	twi 38.00 /
13	10	REAR SPARE TYRE BOARD	11 160.00 x
14	1	REAR TOOL FOAM	11 115.00 x
15	1	REAR BUMPER	o/pe 185.00 /
16	2	REAR BUMPER SIDE RETAINER@\$11.00	22.00 ?
17	1	REAR BUMPER SIDE@\$85.00	170.00 ?
18	2	REAR BUMPER RELFECTOR@\$38.00	n/s.m 76.00 1pc
19	10	REAR BUMPER CLIP@\$1.50	rec 15.00 ?
20	2	REAR LAMP@\$250.00	500.00 ?
			2,843.00
ADD 20 %			568.60
TOTAL (A)			3,411.60

SPECIAL NETT ITEMS

1 1 REAR WINDSCREEN GUM

rec 40.00 /



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : SKW6968S
ACCIDENT DATE : 07-08-2018 07:45
THIRD PARTY REF. : GBD3666P

#	QTY	PARTS DESCRIPTION
2	1	REAR WINDSCREEN FILM
3	1	REAR BOOT CHROME
4	1	REAR BUMPER CHROME
5	1	REAR BUMPER LOWER SKIT
6	1	REAR REVERSE SENSOR
7	1	REAR END PANEL TOP GARNISH CHROME
8	1	SOUND PROOF <i>Ta'igale</i>

TOTAL (C)

AMOUNT (SG\$)

<i>11</i>	200.00	<i>X</i>
<i>20</i>	300.00	<i>✓</i>
<i>20</i>	400.00	<i>300</i>
	480.00	<i>?</i>
<i>Shut</i>	300.00	<i>200</i>
<i>Tu</i>	350.00	<i>300</i>
	300.00	<i>?</i>

2,370.00

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00	<i>20</i>
2	1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00	<i>✓</i>
3	1	TO REMOVE/REFIT REAR FENDER INNER GARNISH & ETC	150.00	<i>60</i>
4	1	TO REMOVE ALL NECESSARY AFFECTE PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	880.00	<i>600</i>
5	1	SPRAYPAINTING CHARGES	980.00	<i>700</i>

TOTAL (D)

2,140.00

ESTIMATE TOTAL

7,921.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: