

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0904/2018/KS
Date : 8-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AXA Insurance Singapore Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

Hi Adrian,
4 days ok - Carrine

Attn: Motor Claims Dept
Tel: 6880 4602 - Fax 6880 4838

Owner's Name : Koh Khai Yang
Address : 20F Watten Rise
Singapore 287386
Telephone : HP + 65 93632003
Type of Claim : Own Damage Claim
Policy No. : GA345250/0
Vehicle No : **SJW 988 K**
Model Code : Audi Q7 3.0 TFSI QU
Model / Year : May-16
Engine No : CRE050525
Chassis No : WAUZZZ4M1GD009689
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Apr-16
Place of Accident : Sengkang Blk 411 Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SJW 988 K.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear kick lid sensor. Calibrate park assistance.	S/N	\$ 480.00	\$ 480.00
2	To dismantle and renew rear bumper.Re-organise rear crash management components . Reinstall all parts removed.		\$ 1,200.00	\$ 800.00
3	To respray rear bumper, rear lower spoiler, both wheel arch covers, rhs rear fender and		\$ 3,600.00	\$ 3,000.00
4	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,472.00</u>	<u>\$ 4,472.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SJW 988 K.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER TOP	\$ 1,061.00	
2	REAR BUMPER MID	\$ 1,645.00	
3	REAR BUMPER FIXING PARTS	\$ 178.00	
4	REAR BUMPER SPOILER	\$ 1,095.00	
5	SPOILER	\$ 92.00	
6	GUIDE SECTION	\$ 54.00	
7	REAR PARKING AID SENSOR	\$ 421.00	
8	REAR PARKING AID SENSOR SEAL RING	\$ 14.00	
9	REAR BUMPER TAILLIGHT RH	\$ 313.00	\$ 313.00
10	REAR WHEEL ARCH COVER LH / RH	2 \$ 662.00	\$ 661.00
11	"Q7" EMBLEM	\$ 83.00	\$ 82.70
12	"AUDI" EMBLEM	\$ 108.00	\$ 107.50
13	"TFSI" EMBLEM	\$ 83.00	\$ 82.70
14	"QUATTRO" EMBLEM	\$ 83.00	\$ 82.70
15	ADHESIVE packing	\$ 15.00	\$ 14.50
16	REAR NO PLATE	S/N \$ 25.00	
17	SUNDRIES	\$ 300.00	\$ 8.40
TOTAL SPARE PARTS CHARGES		: \$ 6,232.00	\$ 1,352.50
TOTAL LABOUR CHARGES		: \$ 5,472.00	\$ 4,472.00
GRAND TOATL		: \$ 11,704.00	\$ 5,824.50

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.