

ASS. REC. BY:

REF: CS/CTI18014697 / Utd3ⁿ²

Special Instruction:

Survivor:

Muhren

ASSIGNMENT (Office)

From (Person):

Hwang Shiang Yi

of

CTI

Date/Time:

14/6/18 @ 9:07am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLX 5601P

Insured:

GBC 539Z

at Workshop m/s

Trans Eurokers

Tel:

63957877

of

12 Sungai Kadut Ave

Policy No:

DMCVSN101171800

Claim No:

SNM18D03886C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 07/08/2018

CA / REV / REP. / REV 24 HRS

kup

H.O.D. Endorsement:

Date/Time:

10:06am @ 14/6/18

Person Contacted:

vion

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLX 5601P - X

GBC 539Z - CCG / CTI18010766 / Aven3

DOA: 11/06/18

15/6/18 -

4:29pm called vion vehicle still not in

(08/11/13) wef

REF:

CAI

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLX5601P

at Workshop m/s Trans En

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GLA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLX5601P Yr Regn: 3, 18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA 1

Make: Mazda 6 c.c. 1998

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 9350 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM66L1071J0139446

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mm

L/Bal. 2 mm

D.O.A. 7/8/18

Survey held at

Rear

R/Bal. 2 mm

L/Bal. 2 mm

D.O.I. 28/8/18

Des. of Damages: Frt / Rear / O/S / M/S / U/C / Rooftop or

O/S R/L.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7720.12 CO

4/12/18 contact final by 7720.12 with Catherine.
(Ref: 4944.360.3926)

RECEIVED 07 DEC 2018

Date/Time, File Pass to?

☐ : Prel. Report☒ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B. (\$) TP 7720.12

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

220



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18014697/Utd3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 14-08-2018	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBC 539Z	Veh. Inspected	SLX 5601P
Policy No.	DMCVSN1011711800	Coverage (\$)	0.00
Claim No.	SNM18D03886C02	Excess (\$)	0.00
Assign From	HWANG SHIANG YI)	Assign Date	14/08/2018
2. Vehicle Particulars & Condition			
Make & Model	c.c		0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/08/2018	Inspection Date	28/08/2018
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Aug 2018		14 Aug 2018 09:07 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	GOLDWIND SERVICES PTE LTD , Co. Reg. No.: 201326729N		
Main Claimant:	KESHGALA RAMANJANEYALU SUDHAKAR , ID: S7469818B		
Vehicle Reg. No.:	SLX5601P	Date of Loss:	07/08/2018 19:00 - :59
Claim Type:	TP / SNM18D03886C02	Policy/Cover Note No.:	DMCVSN1011711800 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC539Z	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave, 729648 Sungei Kadut - Tel: 63602845		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 24/08/2018]		
Driver/Custodian (Insured):	MOHD FADEL BIN ZAIN (51 / Male), NRIC: S1751683C, Tel: +6591977037		
Adj Asg. Remarks:	EST \$12,664.98, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2018 14:42
Date Of Accident	07/08/2018 19:45
Exact Location Of Accident	CARPARK BLK 309B DECK 2B AMK 31
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLX5601P
Insured/Policyholder	
Name Of Registered Owner	KESHGALA RAMANJANEYALU SUDHAKAR
NRIC No	S7469818B
Email Address	SUDHAKARBAB@YAHOO.COM
Mobile Phone No	(LOCAL) +65-97267027
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MAZDA
Model	6-2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	KESHGALA RAMANJANEYALU SUDHAKAR
NRIC No	S7469818B
Date Of Birth	24/10/1974
Occupation	INDOOR
Date Of Driving Pass	23/03/2018
Driving Experience	0 YEAR AND 4 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97267027
Fax Number	
Contact Number	OFFICE-NOPHONE
Email Address	SUDHAKARBAB@YAHOO.COM

Address	BLK 309A ANG MO KIO STREET 31 #08-349
Postcode	562309
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC539Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MOHD KADEL
NRIC/Passport Number	
Contact Number	91977037
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 10/08/2016

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Trans Eurokars Pte Ltd

5 Ubi Cbse


Singapore 408605

Tel: 6744 3003 / 6749 4333

Fax: 6744 0680

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SLX 5601 P

ACCIDENT DATE: 07/08/2018

CONTACT NUMBER: 97267027

ACCIDENT TIME: 19:45

EMAIL: Sudhakarbab@yahoo.co.in

LOCATION: Car park, blk 309B, deck 2B, Ang mo kio 31.

Vehicle GBC 539Z ; Name of driver: Mohd Kader

Type of vehicle: Nissan Van E25 driven no. 9197-7037

Above vehicle hit my parked vehicle and written an apologize letter attached as proof.

Need to claim from their Insurance.

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE: () CLAIM OWN POLICY (X) CLAIM THIRD PARTY () REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 10/08/2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

[Signature]
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9818B
Vehicle Details	
Vehicle No.:	SLX5601P
Vehicle to be Exported:	No
Intended De-registration Date:	29 Aug 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA6 SEDAN 2.0 AT EXECUTIVE EU6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	PE21056165
Chassis No.:	JM6GL1071J0139446
Maximum Power Output:	121.0 kW (162 bhp)
Open Market Value:	\$20,925.00
Original Registration Date:	29 Mar 2018
First Registration Date:	29 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$21,295.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Mar 2028
PARF Rebate Amount:	\$15,971.00
Intended COE Rebate Details	
COE Expiry Date:	28 Mar 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$37,343.00
Total Rebate Amount:	\$53,314.00

The information contained herein is correct as at 29 Aug 2018

OK



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



(TP)

CHINA TAIPING INSURANCE P/L		NAME : Mr Keshgala Ramanjaneyalu Sudhakar		WIP : 21270	
3 ANSON ROAD		ADDRESS : 309A Ang Mo Kio Street 31		EXCESS :	
#16-00 SPRINGLEAF TOWER		#08-349		DATE: 11-Aug-18	
SINGAPORE 079909		Singapore 562309			
ATTN. : MOTOR CLAIMS		TEL : 97267027			
FAX :					
VEH NO :	SLX5601P	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6GL1071J0139446	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	29-Mar-18	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY	REVISED	PRICES		
1	FRONT BUMPER <i>Dis</i>	1	MGMV8-50-031CBB	✓	\$ 1,154.10
2	RETAINER RHS <i>3x1</i>	1	MGHP9-50-0T1B	✓	\$ 16.20
3	CLIP, FRONT BUMPER <i>1x1</i>	6	MC274-50-133	✓	\$ 21.00
4	FASTENER, FRONT BUMPER <i>1x1</i>	2	MB45A-56-146A	✓	\$ 5.60
5	GROMMET, FRONT BUMPER <i>1x1</i>	2	MGHP9-50-025	✓	\$ 5.40
6	RIVET, FRONT BUMPER <i>1x1</i>	6	MGHP9-50-355	✓	\$ 27.60
7	RIVET, FRONT BUMPER <i>1x1</i>	8	M5515-51-833	✓	\$ 30.40
8	FRONT FENDER RHS <i>3x1</i>	1	MGHP9-52-111A	✓	\$ 365.40
9	STAY RHS, FENDER <i>1x1</i>	1	MGHY9-52-10YD	✓	\$ 51.60
10	MUDGUARD RHS <i>Dis</i>	1	MGHP9-56-130K	✓	\$ 108.80
11	FASTENER, MUDGUARD <i>1x1</i>	20	MB45A-56-146A	✓	\$ 56.00
12	HEADLAMP RHS <i>Scr/cr</i>	1	MGML8-51-031E	✓	\$ 3,209.30
13	CORD SHORT RHS, HEADLAMP <i>1x1</i>	1	MGMG9-51-0K6	✓	\$ 201.30
14	CLIP, HEADLAMP <i>1x1</i>	2	MFB01-50-133C	✓	\$ 7.60
15	RIVET, HEADLAMP <i>1x1</i>	1	MB092-51-833	✓	\$ 3.30
16	WASHER TANK <i>1x1</i>	1	MGHR1-67-481	✓	\$ 104.50
17	PIPE, WASHER TANK <i>1x1</i>	1	MGHR1-67-500	✓	\$ 27.00
18	FRONT WHEEL RIM RHS <i>1x1</i>	1	M9965-07-7570	✓	\$ 1,277.10
19	FRONT TYRE RHS <i>Scr</i>	1			\$ 400.00
TOTAL PARTS					\$ 7,072.20
LESS 10%					\$ 707.22
TOTAL PARTS COST					\$ 6,364.98
Labour Description					
1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			990 \$ 1,980.00

2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.	1260	\$ 1,890.00
3	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	120	NETT \$ 120.00
4	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	120	NETT \$ 560.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	120	\$ 250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
8		TO SUPPLY BRILA PREMIUM COATING	400	NETT \$ 800.00
9	MZ-BR-SUNDRI	SUNDRIES.	NET 30	NETT \$ 100.00

TOTAL LABOUR	\$ -	\$ 6,300.00
TOTAL PARTS	\$ -	\$ 6,364.98
TOTAL	\$ -	\$ 12,664.98
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature

Not Authorized
26/11
5/12
28/8/18
The Phil. Sec. party.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS



(TP)

CHINA TAIPING INSURANCE P/L 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Keshgala Ramanjaneyalu Sudhakar ADDRESS: 309A Ang Mo Kio Street 31 #08-349 Singapore 562309 TEL: 97267027		WIP: 21270 EXCESS: DATE: 11-Aug-18	
VEH NO:	SLX5601P	DATE IN:		CONTACT PERSON:	Vion 63957877
CHASSIS NO:	JM6GL1071J0139446	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA6	DATE REG.:	29-Mar-18	POLICY NO.:	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	FRONT BUMPER	Dis	1	✓	\$ 1,154.10
2	RETAINER RHS	Ref	1	✓	\$ 16.20
3	CLIP, FRONT BUMPER	Ref	6	✓	\$ 21.00
4	FASTENER, FRONT BUMPER	Ref	2	✓	\$ 5.60
5	GROMMET, FRONT BUMPER	Ref	2	✓	\$ 5.40
6	RIVET, FRONT BUMPER	Ref	6	✓	\$ 27.60
7	RIVET, FRONT BUMPER	Ref	8	✓	\$ 30.40
8	FRONT FENDER RHS	Scd 50	1	✓	\$ 365.40
9	STAY RHS, FENDER	Ref	1	✓	\$ 51.60
10	MUDGUARD RHS	Dis	1	✓	\$ 108.80
11	FASTENER, MUDGUARD	Ref	20	✓	\$ 56.00
12	HEADLAMP RHS	Scn	1	✓	\$ 3,209.30
13	CORD SHORT RHS, HEADLAMP	11	1	✓	\$ 201.30
14	CLIP, HEADLAMP	Ref	2	✓	\$ 7.60
15	RIVET, HEADLAMP	Ref	1	✓	\$ 3.30
16	WASHER TANK		1	✓	\$ 104.50
17	PIPE, WASHER TANK		1	✓	\$ 27.00
18	FRONT WHEEL RIM RHS	n 1	1	✓	\$ 1,277.10
19	FRONT TYRE RHS	607	1	✓	\$ 400.00
TOTAL PARTS					\$ 7,072.20
LESS 10%					\$ 707.22
TOTAL PARTS COST					\$ 6,364.98
Labour Description					
1	M2-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.			990 \$ 1,980.00

2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.	1260	\$	1,890.00
3	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING. 50 100	NETT	\$	120.00
4	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT. 11 X	NETT	\$	560.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. 11 X		\$	250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING. 120		\$	250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS. 150		\$	350.00
8		TO SUPPLY BRILA PREMIUM COATING 400	NETT	\$	800.00
9	MZ-BR-SUNDRI	SUNDRIES. 30	NETT	\$	100.00
			TOTAL LABOUR	\$ -	\$ 6,300.00
			TOTAL PARTS	\$ -	\$ 6,364.98
			TOTAL	\$ -	\$ 12,664.98
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ -	
			GST 7%	\$ -	\$ -
			GRAND TOTAL	\$ -	\$ -

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

Not Authorised
LHL
S. J.
28/8/18
The Phil Bedbury.



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
FINALISED COST OF REPAIRS



(TP)

CHINA TAIPING INSURANCE P/L		NAME :	Mr Keshgala Ramanjaneyalu Sudhakar	WIP :	21270
3 ANSON ROAD		ADDRESS :	309A Ang Mo Kio Street 31	EXCESS :	
#16-00 SPRINGLEAF TOWER			#08-349	DATE:	11-Aug-18
SINGAPORE 079909			Singapore 562309		
ATTN. :	MOTOR CLAIMS	TEL :	97267027		
FAX :					
VEH NO :	SLX5601P	DATE IN :		CONTACT PERSON :	Vion 63957877
CHASSIS NO :	JM6GL1071J0139446	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6	DATE REG.:	29-Mar-18	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MGMV8-50-031CBB	\$ 1,154.10	\$ 1,154.10
2	1	MGHP9-50-0T1B	\$ 16.20	\$ 16.20
3	6	MC274-50-133	\$ 21.00	\$ 21.00
4	2	MB45A-56-146A	\$ 5.60	\$ 5.60
5	2	MGHP9-50-0Z5	\$ 5.40	\$ 5.40
6	6	MGHP9-50-355	\$ 27.60	\$ 27.60
7	8	M5515-51-833	\$ 30.40	\$ 30.40
8	1	MGHP9-52-111A	\$ 365.40	\$ 365.40
9	1	MGHY9-52-10YD	\$ 51.60	\$ 51.60
10	1	MGHP9-56-130K	\$ 108.80	\$ 108.80
11	20	MB45A-56-146A	\$ 56.00	\$ 56.00
12	1	MGML8-51-031E	\$ 3,209.30	\$ 3,209.30
13	1	MGMG9-51-0K6		\$ 201.30
14	2	MFB01-50-133C	\$ 7.60	\$ 7.60
15	1	MB092-51-833	\$ 3.30	\$ 3.30
16	1	MGHR1-67-481	\$ 104.50	\$ 104.50
17	1	MGHR1-67-500		\$ 27.00
18	1	M9965-07-7570		\$ 1,277.10
19	1			\$ 400.00
TOTAL PARTS			\$ 5,166.80	\$ 7,072.20
LESS 10%			\$ 516.68	\$ 707.22
TOTAL PARTS COST			\$ 4,650.12	\$ 6,364.98

Labour Description

1	MZ-BR-FRONT7	TO REPLACE FRONT BUMPER AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 990.00	\$ 1,980.00
2	MZ-SP-SFRT07	TO RESPRAY FRONT BUMPER AND FRONT FENDER.	\$ 1,260.00	\$ 1,890.00

3	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.		\$ 120.00
4	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	\$ 120.00	\$ 560.00
5	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 120.00	\$ 250.00
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 150.00	\$ 350.00
8		TO SUPPLY BRILA PREMIUM COATING	\$ 400.00	\$ 800.00
9	MZ-BR-SUNDRI	SUNDRIES.	\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 3,070.00 \$ 6,300.00
			TOTAL PARTS	\$ 4,650.12 \$ 6,364.98
			TOTAL	\$ 7,720.12 \$ 12,664.98
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ 7,720.12
			GST 7%	\$ 540.41 \$ -
			GRAND TOTAL	\$ 8,260.53 \$ -

REMARKS:

5 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18014697/UTD3N2

Date: 11/12/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1011711800
Claimant Vehicle No :	SLX5601P	Insured Vehicle No :	GBC539Z
Date of Loss:	07/08/2018	Nature of Claim:	TP
		Claim No:	SNM18D03886C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX5601P	Engine No:	PE21056165
Make & Model:	MAZDA 6, 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A)	Chassis No:	JM6GL1071J0139446
Reg. Date:	29/03/2018 (Man. Year: 2017)	Odometer:	9350 km
Colour:	Brown		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Toyo 8 mm	Rear Left Side:	Toyo 8 mm
Front Right Side:	Toyo 8 mm	Rear Right Side:	Toyo 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,464.98	4,680.12	1,784.86	27.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,200.00	3,040.00	3,160.00	50.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,664.98	7,720.12	4,944.86	39.04
+ GST 7.00/7.00% (S\$)	886.55	540.41	346.14	39.04
Nett Amount (S\$)	13,551.53	8,260.53	5,291.00	39.04

INSPECTION

Date of Assignment:	14/08/2018	
Date Inspected:	14/08/2018 Inspected At:	Trans Eurokars Pte Ltd (Sungei Kadut) 12 Sungei Kadut Ave Singapore 729648
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Dec 2018)
Parts:	143	MAZDA 6 2.0 4-DOOR SEDAN 2.0L SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX5601P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,154.10 FL	*1,154.10 FL
2	1		*RETAINER RHS	Bent	16.20 FL	*16.20 FL
3	6		*CLIP,FRONT BUMPER	Necessary	21.00 FL	*21.00 FL
4	2		*FASTENER,FRONT BUMPER	Necessary	5.60 FL	*5.60 FL
5	2		*GROMMET,FRONT BUMPER	Necessary	5.40 FL	*5.40 FL
6	6		*RIVET,FRONT BUMPER	Necessary	27.60 FL	*27.60 FL
7	8		*RIVET,FRONT BUMPER	Necessary	30.40 FL	*30.40 FL
8	1		*FRONT FENDER RHS	Badly Dented	365.40 FL	*365.40 FL
9	1		*STAY RHS,FENDER	Necessary	51.60 FL	*51.60 FL
10	1		*MUDGUARD RHS	Distorted	108.80 FL	*108.80 FL
11	20		*FASTENER MUDGUARD	Necessary	56.00 FL	*56.00 FL
12	1		*HEADLAMP RHS	Scratched/Cracked	3,209.30 FL	*3,209.30 FL
13	1		*CORD SHORT RHS,HEADLAMP	Not Necessary	201.30 FL	*- FL
14	2		*CLIP,HEADLAMP	Necessary	7.60 FL	*7.60 FL
15	1		*RIVET,HEADLAMP	Necessary	3.30 FL	*3.30 FL
16	1		*WASHER TANK	Deformed	104.50 FL	*104.50 FL
17	1		*PIPE,WASHER TANK	Not Necessary	27.00 FL	*- FL
18	1		*FRONT WHEEL RIM RHS	Not Necessary	1,277.10 FL	*- FL
19	1		*FRONT TYRE RHS	Serviceable	400.00 FL	*- FL
20	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,172.20	5,196.80
- List Item Discount on L Items 10.00/10.00% (\$\$)	707.22	516.68
Total Parts (\$\$)	6,464.98	4,680.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER AND FRONT FENDER.REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	1,980.00	990.00
2	TO RESPRAY FRONT BUMPER AND FRONT FENDER	New	1,890.00	1,260.00
3	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	-
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	120.00
5	TO CARRY-OUT BODY CAVITY PRESERVATION	New	250.00	-
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	250.00	120.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	350.00	150.00
8	TO SUPPLY BRILA PREMIUM COATING	New	800.00	400.00
Gross Labour Cost (\$\$)			6,200.00	3,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >