

CASE OWNER:

CC

4, Asm 180

14700, N 24302

LKK:

IDAC:

62823

ASSIGNMENT

DOI:

14/8/18

Date / Time:

13/8/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKZ 1690J

Name of Insured:

Yn Gan Xiang. VINCENT

Insured Tel No.:

HP:

Excess Sec II : S\$

D.O.A.:

8/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SYM 00RLR

Policy No.:

GA1485291

Make / Model:

MISJAN

Place of Accident:

Bukit PUS

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

Sub 9590B

INSRS:
WSP:
Tel:
Liability:
RMKS:Kia
AutomotiveINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

Sub 9590B - X: SKZ 1690J - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

20/8/18

confirm accident details. inform TP claim
refer send outCecilia
waiting for Elite to
accept car.

21/8/19

26/8/19
- Pending mandate approval.
- offer G/L \$7750/- (pending acceptance).
- settle @ G/L \$7750/- (send pending on in).
- in G/L pass Admin to close.

24/8/19

PRELIMINARY ADVICE

Date/Time:

16/8

Sent By:

Jm

FINALIZATION

Date/Time:

Confirm with:

Confirm by: NAZ

Repair Cost:

LC

S\$ 6700/-

(5 days)

Reduction:

\$7096.25 % 51

Email

Call

FINAL SETTLEMENT

Date/Time:

21/8/19 3.29pm

Confirm with:

CHISH

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

37

If NO or B 28, Ass. Lia:

Repair Cost:

(W/GST)

S\$

7169.00

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

560.00

(\$ 80 x 7 days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$

91.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

7760.00

Global Sum S\$:

7770.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7750.00

Name 1:

Elite Automotive Pte Ltd

Payee 2: (Strike if N/A)

S\$

-

Name 2:

-

Payee 3: (Strike if N/A)

S\$

-

Name 3:

-

COPY SENT
29/8/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

TP
\$350/-

Surveyor

NA2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Elite Auto

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 35K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLB 9590B Yr Regn: 22 DEC 2009

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 2.0 c.c. 1,984

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 299 028 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZZ8K2AA064136

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245 / 40 R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or SILVERSTONE (F), KUMHO (R)

Front: 6 mm Rear: 5 mm

R/Bal. 6 mm L/Bal. 5 mm

D.O.A. 8/8/18 D.O.I. 14/8/18

Survey held at ELITE AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

19/8/19 FINALIZED LUMP SUM REPAIR \$6,700.00 / 5 REPAIR DAYS (Red = \$7056.25 / 51%)

* 5 repair days + 3 PRS + 1 Sunday = 9 days.

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$) \$ + RS \$

☐ : Interview (\$) Photos

☐ : Tech. Invs (\$) Others

☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLB9590B

Vehicle Model : Audi A4

Chassis Number : WAUZZZ8K2AA064136

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID	1	\$ 1,500 1625.05 <i>ARC / DD</i>
2	BOOT LID "AUDI" LOGO	1	\$ 93.65 <i>ARC</i>
3	"A4" EMBLEM	1	\$ 72.30 <i>ARC</i>
4	"MTM" EMBLEM	1	\$ 75.00 <i>ARC</i>
5	"2.0T" EMBLEM	1	\$ 72.30 <i>ARC</i>
6	"QUATTRO" EMBLEM	1	\$ 72.30 <i>ARC</i>
7	BOOT LID LAMP (LH & RH)	2	\$ 1,000 1288.50 <i>X CHERA</i>
8	BOOT LID LOCK	1	\$ 159.35 <i>? / DD</i>
9	TAIL LAMP (LH & RH)	2	\$ 1,400 1553.10 <i>X SOT / CRK</i>
10	TAIL LAMP LOWER BRACKET (LH & RH)	2	\$ 32.70 <i>? / CRK</i>
11	BOOT LID INNER TRIM	1	\$ 255.15 <i>? / CRK</i>
12	BOOT LID INNER TRIM CLIPS	10	\$ 50.00 <i>? / NEC</i>
13	REAR BUMPER	1	\$ 1,200 1360.25 <i>CRK</i>
14	REAR BUMPER CENTRE GRILLE	1	\$ 186.15 <i>? / CRK</i>
15	REAR BUMPER LOWER LID	1	\$ 272.00 <i>? / CRK</i>
16	REAR BUMPER REINFORCEMENT	1	\$ 458.65 <i>? / BT</i>
17	END PANEL	1	\$ 1331.65 <i>? X R</i>
18	END PANEL UPPER GARNISH	1	\$ 136.45 <i>? / DEF</i>
19	END PANEL UPPER GARNISH CLIPS	10	\$ 50.00 <i>? / NEC</i>
20	EXHAUST PIPE	1	\$ 1252.40 <i>? X R</i>
21	EXHAUST MOUNTING	2	\$ 121.10 <i>? X SVL</i>
7,086 \$			10518.05

Discount Less 10% \$ 1051.81
List Prices Total \$ 9,466.25

6,377.40

S/N	Special Nett Items:	Qty	
1	REVERSE SENSOR	2	\$ 390 780.00 <i>per</i>
2	REAR NUMBER PLATE WITH HOLDER	1 set	\$ 60.00 <i>X M</i>
Special Nett Total		390	\$ 840.00
Spare Part's Total Price			\$ 840.00

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLB9590B

Vehicle Model : Audi A4

Chassis Number : WAUZZZ8K2AA064136

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS, TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR REAR LUGGAGE PANEL, REINFORCEMENT; TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	S 1500.00 800
2	TO SPRAY PAINTING ON: BOOT LID (INNER, OUTER), REAR BUMPER, END PANEL, REAR LUGGAGE, FLOOR PANEL.	S 1500.00 600
3	TO REMOVE & TRANSFER BOOT LID SERVICEABLE ATTACHMENTS TRIMMINGS.	S 100.00 50
4	TO DRILL SENSORS HOLES, REPLACE SENSOR AND TEST FUNCTION.	S 120.00 50
5	TO REMOVE & INSTALL REAR LUGGAGE.	S 80.00 50
6	TO DIAGNOSE, CHECK & RESET FAULT CODES AFTER ACCIDENT REPAIRS.	S 150.00 60

Labour Total S 3450.00

Parts & Labour Total S 13756.25

PARTS \$7,086
LESS 10% \$6,377.40

SINER \$ 390.00

LABOUR \$1,610.00

TOTAL \$8,377.40

LESS 20% LIS \$6,701.92

L1STOTAL \$6,700.00

5

NAZ LKK
14/8/18 1700

4/5

3 DAYS

AFTER REPAIR PHOTO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	998A
Vehicle Details	
Vehicle No.:	SLB9590B
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Jul 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 2.0 TFSI QU S-TRONIC (SUNROOF)
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	CDN074771
Chassis No.:	WAUZZZ8K2AA064136
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$48,116.00
Original Registration Date:	22 Dec 2009
First Registration Date:	22 Dec 2009
Transfer Count:	1
Actual ARF Paid:	\$48,116.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2019
PARF Rebate Amount:	\$24,058.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2019
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$19,801.00
COE Rebate Amount:	\$793.00
Total Rebate Amount:	\$24,851.00

The information contained herein is correct as at 26 Jul 2019

OK



Service Request Details

Claim

S8M00RLR

Reference

None 

Loss Date

August 8, 2018

Request Date

August 13, 2018

Due Date

August 20, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

13082018 @ 2.04pm
Christy veh in
Elite Automotive
280 Woodlands Ind Park E5 #01-17
arrange 14082018

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLB9590B

Make

TPVD AUDI

Model

A4-2.0 TFSI QU S-TRONIC (A)

Service Address

...

Primary Contact/Insured

YU GANGXANG VINCENT
BLK 314 SHUNFU ROAD, #03-120, 570314, Singapore
94383559

Claim Handler

CHAN Kian Chuan
6568804269
kianchuan.chan@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

[New Message](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 21/8/2019

Survey Details:

Date of loss	8-Aug-18
Date of appointment	13-Aug-18
Date of survey	14-Aug-18
Location of survey	ELITE AUTOMOTIVE

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SLB9590B
Make and Model	AUDI A4 2.0 TFSI QU S-TRONIC - 1984cc
Date of registration	22-Dec-09
Excess	
Market Value	\$ 35,000.00
Parf Rebate	\$ 29,140.00
Nett Loss	\$ 5,860.00

Repair details:

Initial Estimate	13,756.25
------------------	-----------

Proposed/Revised repair cost:

Parts	\$ 6,767.40
Check items (estimate)	\$ -
Labour	\$ 1,610.00
Total	\$ 8,377.40
Lump Sum(if applicable)	\$ 6,700.00

Number of days for repair	<u>5 days</u>
---------------------------	---------------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

05 RECOMMENDED REPAIR DAYS + 3 PRS + 1 SUNDAY = 9DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 7,169.00	W/GST
Loss of use	\$ 900.00	9days x \$100
Loss of rental	\$ -	
Loss of income	\$ -	
LTA search fees	\$ 31.00	
Others	-	
Proposed Total	8100	



<MANDATE IA> - S8M00RLR {ACCIDENT INVOLVING SKZ 1690J(OI) & SLB 9590B(TP) ON 08/08/2018}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27: INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8100.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS. - CECILIA

Reply



**Re:<MANDATE IA> - S8M00RLR {ACCIDENT INVOLVING
SKZ 1690J(OI) & SLB 9590B(TP) ON 08/08/2018}**

Type

Question

Message

TO OFFER LOU \$80 @ 7DAYS =\$560 OTHERS AS PROPOSED.

Reply

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands (S) 757322

Tel : 63397378/ 86606722 Fax: 63397475

Reg No: 201700196D GST Reg No: 201700196D

Date : 15/08/2019

OUR REF : TP/SLB 9590B/19

M/S : AXA INSURANCE PTE LTD

8 SHENTON WAY

#27-01

SINGAPORE 068811

Statement Of Claim On Veh No : SLB 9590B**MODEL : AUDI A4****LUMP SUM OF REPAIR****INCLUDING SUPPLY OF PARTS & LABOUR**

PANEL BEATING & SPRAY PAINTING		\$6,700.00
	7%GST	\$588.00
		\$7,169.00
LOSS OF USE (\$150 X 16 DAYS)		\$2,400.00
*PRE-REPAIR INSPECTION		
*INCLU WEEKEND		
*POST REPAIR		
LTA SEARCH		\$2.00
TP REPORT		\$29.00
		<u>\$9,600.00</u>



GST.Reg.No: 201700196D

Hotline: 8660 6722 Tel: 6339 7378 Fax: 6339 7475 Email: elite.automotive13@gmail.com

Date : 22/8/2019

Email : _____ Mobile : _____ Home/Office Tel : _____

Customer Signature & Company Stamp



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM18014700/Nga3s2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: KIAN CHUAN		Date : 30-08-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 1690J	Veh. Inspected	SLB 9590B	
Policy No.	GA148529/1	Coverage (\$)	0.00	
Claim No.	S8M00RLR	Excess (\$)	0.00	
Assign From	KIAN CHUAN	Assign Date	13/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A4 2.0	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WAUZZZ8K2AA064136	Colour	WHITE	
Odometer	299028	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/40 R18	SILVERSTONE	6 mm	
L/H Front Tyre	245/40 R18	SILVERSTONE	6 mm	
R/H Rear Tyre	245/40 R18	KUMHO	5 mm	
L/H Rear Tyre	245/40 R18	KUMHO	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2018	Inspection Date	14/08/2018	
Survey held at	ELITE AUTOMOTIVE 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS SINGAPORE 757322			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 9590B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID (CONSISTENT)	DENTED	1,625.05	1,500.00
1	BOOT LID "AUDI" LOGO (CONSISTENT)	NECESSARY	93.65	93.65
1	"A4" EMBLEM (CONSISTENT)	NECESSARY	72.30	72.30
1	"MTM" EMBLEM (CONSISTENT)	NECESSARY	75.00	75.00
1	"2.0T" EMBLEM (CONSISTENT)	NECESSARY	72.30	72.30
1	"QUATTRO" EMBLEM (CONSISTENT)	NECESSARY	72.30	72.30
2	BOOT LID LAMP (LH & RH) (CONSISTENT)	CRACKED	1,288.50	1,000.00
1	BOOT LID LOCK (CONSISTENT)	DENTED	159.35	159.35
2	TAIL LAMP (LH & RH) (CONSISTENT)	CRACKED	1,553.10	1,400.00
2	TAIL LAMP LOWER BRACKET (LH & RH) (CONSISTENT)	CRACKED	32.70	32.70
1	BOOT LID INNER TRIM (CONSISTENT)	CRACKED	255.15	255.15
10	BOOT LID INNER TRIM CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	REAR BUMPER (CONSISTENT)	CRACKED	1,360.25	1,200.00
1	REAR BUMPER CENTRE GRILLE (CONSISTENT)	CRACKED	186.15	186.15
1	REAR BUMPER LOWER LID (CONSISTENT)	CRACKED	272.00	272.00
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	458.65	458.65
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	1,331.65	-
1	END PANEL UPPER GARNISH (CONSISTENT)	DEFORMED	136.45	136.45
10	END PANEL UPPER GARNISH CLIPS (CONSISTENT)	NECESSARY	50.00	50.00
1	EXHAUST PIPE (CONSISTENT)	TO REPAIR SEE LABOUR	1,252.40	-
2	EXHAUST MOUNTING (CONSISTENT)	SERVICEABLE	121.10	-
	LESS 10% DISCOUNT		-1,051.80	-708.60
			9,466.25	6,377.40
SPECIAL NETT ITEMS				
4	REVERSE SENSOR (SN) (CONSISTENT)	DEFORMED 2PCS ONLY	780.00	390.00
1	SET REAR NUMBER PLATE WITH HOLDER (SN) (CONSISTENT)	NOT NECESSARY	60.00	-
			840.00	390.00

Report Ref No. CC4/ASM18014700/Nga3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS, TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR REAR LUGGAGE PANEL, REINFORCEMENT; TO REPLACE DAMAGED PARTS AS LISTED ABOVE. INCLUSIVE OF THE REPAIR OF END PANEL AND EXHAUST PIPE.		1,500.00	800.00
	TO SPRAY PAINTING ON: BOOT LID (INNER, OUTER), REAR BUMPER, END PANEL, REAR LUGGAGE, FLOOR PANEL.		1,500.00	600.00
	TO REMOVE & TRANSFER BOOT LID SERVICEABLE ATTACHMENTS TRIMMINGS.		100.00	50.00
	TO DRILL SENSORS HOLES, REPLACE SENSOR AND TEST FUNCTION.		120.00	50.00
	TO REMOVE & INSTALL REAR LUGGAGE.		80.00	50.00
	TO DIAGNOSE, CHECK & RESET FAULT CODES AFTER ACCIDENT REPAIRS.		150.00	60.00
			3,450.00	1,610.00
	GRAND TOTAL		13,756.25	8,377.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,700.00

Report Ref No. CC4/ASM18014700/Nga3s2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.