ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17, Harvest @ Woodlands Singapore 757322 Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLB9590B Vehicle Model : Audi A4

Chassis Number: WAUZZZ8K2AA064136

Estimated Repair Cost

S/N	Parts Description		Qty	List Price
1	BOOT LID		1	\$ 1625.05 XX
2	BOOT LID "AUDI" LOGO		1	\$ 93.65 NCC
3	"A4" EMBLEM		1	\$ 72.30 (ARC
4	"MTM" EMBLEM		1	\$ 75.00 TARC
5	"2.0T" EMBLEM		1	\$ 72.30 - MC
6	"QUATTRO" EMBLEM		1	\$ 72.30
7	BOOT LID LAMP (LH & RH)		2	\$ 1288.50 XCHC
8	BOOT LID LOCK		1	\$ 159.35 ?
9	TAIL LAMP (LH & RH)		2	\$ 1553.10 X SV C
10	TAIL LAMP LOWER BRACKET (LH & RH)		2	\$ 32.70 ?
11	BOOT LID INNER TRIM		1	\$ 255.15 ?
12	BOOT LID INNER TRIM CLIPS		10	\$ 50.00 ?
13	REAR BUMPER		1	\$ 1360.25 CRA
14	REAR BUMPER CENTRE GRILLE		1	\$ 186.15
15	REAR BUMPER LOWER LID		1	\$ 272.00 ?
16	REAR BUMPER REINFORCEMENT		1	\$ 458.65 ?
17	END PANEL		1	\$ 1331.65 ?
18	END PANEL UPPER GARNISH		1	\$ 136.45 ?
19	END PANEL UPPER GARNISH CLIPS		10	\$ 50.00
20	EXHAUST PIPE		1	\$ 1252.40 ?
21	EXHAUST MOUNTING		2	\$ 121.10
				\$ 10518.05
		Discount Less	10%	\$ 1051.81
		List Prices Total		\$ 9,466.25

S/N	Special Nett Items:	Qty	,
1	REVERSE SENSOR	4	\$ 780.00 (ot
2	REAR NUMBER PLATE WITH HOLDER	1 set	\$ 60.00
	Special Nett Tota	1	\$ 840.00
	Spare Part's Total Price	e	\$ 840.00

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17, Harvest @ Woodlands Singapore 757322 Tel: 6339 7378 Fax: 6339 7475

Vehicle Number: SLB9590B Vehicle Model: Audi A4

Chassis Number: WAUZZZ8K2AA064136

S/N	Labour Descriptions	Charges		
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END	\$	1500.00 you	
	ATTACHMENTS & FITTINGS TO ENABLE REPAIRS, TO		<i>i</i>	
	CUT & WELD WHERE NECESSARY; TO STRAIGHTEN			
	& REPAIR REAR LUGGAGE PANEL,			
	REINFORCEMENT; TO REPLACE DAMAGED PARTS			
	AS LISTED ABOVE.			
2	TO SPRAY PAINTING ON: BOOT LID (INNER, OUTER),	\$	1500.00 400	
	REAR BUMPER, END PANEL, REAR LUGGAGE, FLOOR		,00	
	PANEL.			
3	TO REMOVE & TRANSFER BOOT LID SERVICEABLE	\$	100.00	
	ATTACHMENTS TRIMMINGS.			
,	TO DRIVE GENCORG HOLES DERI A CE SENSOR AND	¢	12000 50	
4	TO DRILL SENSORS HOLES, REPLACE SENSOR AND	\$	120.00	
	TEST FUNCTION.			
5	TO REMOVE & INSTALL REAR LUGGAGE.	S	80.00	
		-		
6	TO DIAGNOSE, CHECK & RESET FAULT CODES	\$	150.00 60	
	AFTER ACCIDENT REPAIRS.			
	Labour Total	\$	3450.00	
	Labour Total	4	5.150.00	
	Parts & Labour Total	\$	13756.25	
	_			

NAZ LKK 14/8/18 1700 APTER REPAIR PHOTO LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- · To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- · Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: