

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, S068811

Email: motor.survey@axa.com.sg

TEL: 6880 4741(Hotline) FAX: 6880 4740/6880 4838

ATTN: Motor Claim Department

Estimate No: EST0000685

Date: 14 Aug 2018

Policy No: P2156823

Veh Reg No: SMC6516U

Make/Model: HYUNDAI ELANTRA AD
1.6 GLS AT (AMS)

Your Ref No: SMC6516U

Claim Type: Third Party

Accident Date: 11-08-2018

Chassis No: KMHD841CMJU685787

Engine No: G4FGJU685787

Reg. Date: 14-07-2018

Not Allowed
the Ins. Policy.
14/8/18
SL.

Estimate Repair Cost to Vehicle No :SMC6516U

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
HYUNDAI ELANTRA 1.6 GLS AT (AMS)				
List Price				
1 Rear Boot <i>2nd/3rd</i>	1,582.000	1 PC	1,582.00	—
2 Rear Boot Lock <i>2nd/3rd</i>	139.0000	1 PC	139.00	—
3 Rear Boot Lock Catch <i>11</i>	36.0000	1 PC	36.00	X
4 Rear Boot Rubber <i>2nd/1</i>	129.0000	1 PC	129.00	—
5 Rear Boot Emblem (ELANTRA) <i>2nd</i>	48.0000	1 PC	48.00	—
6 Rear Boot Emblem (S) <i>2nd</i>	20.0000	1 PC	20.00	—
7 Rear Boot Centre Logo <i>2nd</i>	39.0000	1 PC	39.00	—
8 Rear Boot Hinge <i>2</i>	111.0000	2 PC	222.00	X
9 Rear Boot Reflector Lamp <i>2nd one o/s</i>	331.0000	2 PC	662.00	?
10 Rear Boot Lock Handle Sensor	180.0000	1 PC	180.00	?
11 Rear Boot Inner Cover Board <i>11</i>	240.0000	1 PC	240.00	X
12 Rear Boot Inner Cover Board Clipse <i>11</i>	5.5000	8 PC	44.00	X
13 Rear Taillamp Outer	382.0000	2 PC	764.00	?
14 Rear Taillamp Inner	299.0000	2 PC	598.00	?
15 Rear Tail Lamp Clipse <i>11</i>	8.0000	2 PC	16.00	X
16 Rear End Panel <i>3.2500</i>	491.0000	1 PC	491.00	—
17 Rear End Panel Top Garnish	69.8000	1 PC	69.80	?
18 Rear End Panel Top Garnish Clipse	6.5000	3 PC	19.50	?
19 Rear Spare Tyre Top Cover Board <i>11</i>	311.0000	1 PC	311.00	X
20 Rear Bumper <i>2.5</i>	459.5000	1 PC	459.50	—
21 Rear Bumper Reinforcement	329.5000	1 PC	329.50	?
22 Rear Bumper Side Retainer <i>3rd</i>	41.0000	2 PC	82.00	—
23 Rear Bumper Reflector <i>2nd one</i>	47.0000	2 PC	94.00	126
24 Rear Bumper Lower Pad <i>2nd/10.1</i>	280.1000	1 PC	280.10	—
25 Rear Bumper Under Cover LH	89.0000	1 PC	89.00	?
26 Rear Bumper Clipse <i>2nd</i>	5.5000	10 PC	55.00	?
27 Rear Number Plate Lamp	28.0000	2 PC	56.00	?
			7,055.40	
	Less 20%		1,411.08	5,644.32
Special Net				
28 Rear Bumper Sensor <i>2nd</i>	300.0000	1 SET	300.00	200
29 Rear Number Plate <i>2nd</i>	50.0000	1 PC	50.00	40

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6841 9095 Email: focus.autopteltd@yahoo.com.sg

GST:200712509E RCB NO:201004495R

M/S : AXA Insurance Singapore Pte Ltd
8 Shenton Way, #27-01 AXA Tower, S068811

Email: motor.survey@axa.com.sg

TEL: 6880 4741(Hotline) FAX: 6880 4740/6880 4838

ATTN: Motor Claim Department

Your Ref No: SMC6516U

Claim Type: Third Party

Accident Date: 11-08-2018

Estimate No: EST0000685

Date: 14 Aug 2018

Policy No: P2156823

Veh Reg No: SMC6516U

Make/Model: HYUNDAI ELANTRA AD
1.6 GLS AT (AMS)

Chassis No: KMHD841CMJU685787

Engine No: G4FGJU685787

Reg. Date: 14-07-2018

Estimate Repair Cost to Vehicle No :SMC6516U

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
			350.00	350.00
Labour				
30 Panel Beating	1,200.000	1 PC	1,200.00	800
31 Check Wiring	80.0000	1 PC	80.00	30
32 To Spray Rust Proofing	80.0000	1 PC	80.00	60
33 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
34 To Spray Painting	950.0000	1 PC	950.00	920
			2,390.00	2,390.00
Total				S\$ 8,384.32

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND THREE HUNDRED EIGHTY FOUR AND CENTS THIRTY TWO

For FOCUS AUTO PTE LTD
Focus Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Auto Bay

#02-50 Singapore 417883

Tel: 66349695

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: