

12/03/2002

ASSIGNED BY:

REF: CS/ALH18014713 / Kthb

Special Instruction:

SUPERVISOR:

Kenneth

ASSIGNMENT (Office)

From (Person):

Mariesa

of

ALH

Date/Time: 11/08/2018 11:48am

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GZ 1311B

Insured:

SJJ 97718J

at Workshop m/s

Siong Lee Motor

Tel:

6456 1255.

of

160 Sin Ming Drive #02-07

Policy No:

Claim No:

Sum Insured:

Excess:

D.O.A.

11-08-2018

Make of Veh:

(Client's Record)

15082018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'wp'

Date/Time: 11/08/2018 11:55am

Person Contacted:

Kwee Pin

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

estimate not yet done arrange on 15082018

GZB 111B - X

SJJ 97718J - NA / 4P10015754 / CL

DOA: 15082018

Confirm Lump Sum \$63001- , 6days (Red: 5553.52!46%)  
 (Red:

(08/11/13) wef

ASS. REC. BY:

REF:

AIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: 15/8/2018

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GZ 1311B

at Workshop m/s: Siong Lee Motor

of 160 Sin Ming Drive # 02-07

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Estimate not yet done.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 12/15 <sup>1 up</sup>

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: GZ 1311B Yr Regn: 12 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Ty Dyno c.c. 2986

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 749785 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFU1F34Y203011167

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: mic 185 R14XD

R: Yoko 155 R12 X81D

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 11/8/18

Rear

R/Bal. 22 mm


L/Bal. 22 mm

D.O.I. 15/8/18

Survey held at ✓

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



Date / Time Action / Instruction

16/8 File pass to Catherine

RECEIVED 14 FEB 2019

Date/Time, File Pass to?



: Preli. Report

1) 14/2 Typist

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6Resurvey No. of Trip: 1

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

6300/-25020




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CS/AIG18014713/Ktb	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 14-08-2018	
		Code : AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SJJ 9778J	Veh. Inspected	GZ 1311B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MARIESA	Assign Date	14/08/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	11/08/2018	Inspection Date	15/08/2018
Survey held at	160 SIN MING DRIVE #02-07		
Repairer	SIONG LEE MOTOR		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

- Pre repair inspection request - GZ1311B VS SJJ9778J (OI) DOA: 11/08/2018

From: Abu Kassim, Noor Mariesa  
To: admin-a@lkkauto.com, assignments@lkkauto.com  
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Chin, Lee-Ying, Md Ishak, Mohd Imran, Lim, Sheng Yang, Supramaniam, Darshene, Chan, Yoke Shi, Azlan, Syazairdina, Mithoosingh, Aashweenje  
Sent: Tuesday, 14 August, 2018 11:48:39 AM  
Attachments:  tmsE804.tif

Hi,

Please refer to the enclosed request from **Cheonghoh Law Corporation**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign Mohammed Rasul as Single Joint Expert as requested.

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (867191-D)

Menara Worldwide, Level 12, 19B Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

NoorMariesa.AbuKassim@aig.com | www.aig.com

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: mail@cheonghoh.sg

To: NoorMariesa.AbuKassim@aig.com

Cc: Lily.Tan@aig.com, Andy-SY.Fong@aig.com, Baljit.Kaur@aig.com, Lee-Ying.Chin@aig.com, Imran.Ishak@aig.com, ShengYang.Lim@aig.com, YokeShi.Chan@aig.com, Syazairdina.Azlan@aig.com, Aashweenjeet.Kaur.Mithoosingh@aig.com

Subject: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SJJ9778J AND GZ1311B ON 11/08/2018 (Oref: LCH.Ig/SMSL-80719.18)

Date: Tue, 14 Aug 2018 03:11:05 +0000

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client hereby nominate Mohammed Rasul of LKK Auto Consultants Pte Ltd named in list to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be informed that our client's vehicle, GZ 1311 B is currently laying at our client's workshop, Siong Lee Motor, 160 Sing Ming Drive #02-07 AutoCity Singapore 575722.

Contact Person

: Mr Tan / Ms Kwee Pin

Telephone: 6453 1255

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 14 Aug 2018, at 9:28 AM, Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com> wrote:

Without Prejudice

Your Reference : LCH.Ig/SMSL-80719.18

Our Reference : SJJ9778J

Dear Sir/Madam,

We refer to your Notice of Accident dated 13/8/2018

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motorsurveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Fong Soon Yee	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd

Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

<tmpE804.tif>

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/08/2018 18:11
Date Of Accident	11/08/2018 17:25
Exact Location Of Accident	PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GZ1311B
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN BROS GAS SUPPLY
Co Reg No	36674400C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98003866
Alternative Phone No	OFFICE-64551169

### Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5088120160-01
Cover Note Number	

### Driver

Name of Driver	LI GANG
Passport No/FIN	G3261840K
Date Of Birth	13/05/1987
Occupation	OUTDOOR
Date Of Driving Pass	16/05/2016
Driving Experience	2 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98003866
Fax Number	
Contact Number	OFFICE-64551169
Email Address	NOEMAIL

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

TAN BROS GAS SUPPLY

Policyholder's Signature

Date & Time: 12/8/18 3:50 PM

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12/8/18 3:50 PM

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:





松 利 摩 哆  
**SIONG LEE MOTOR**

Sin Ming Industrial Estate  
Block 12 Sector B #01-73 Singapore 575656  
Tel: 6457 0410, 6453 3478 Fax: 6552 0692

Company Reg. No.: 100839/00J

We specialise in repairing all kinds of vehicles and pre-inspection servicing.  
We also undertake accident insurance claims for our customers.

14 August 2018

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAN BROS GAS SUPPLY

H/P: 6455 1169

*Not Authorised  
L1 Sing 883006  
Remy Ate Pater  
6day*

Dear Sirs / Madam,

A Incident Claim for Vehicle No.GZ 1311 B, Involving Vehicle No.SJJ 9778 J.  
Accident on 11 AUGUST 2018, AT PIE.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE
1	TAILLAMP <i>also oil Ser</i>	2PCS	\$ 520.20
2	TAILLAMP BRACKET	2PCS	\$ 354.40
3	TAILGATE	1PC	\$ 1,680.20
4	TAILGATE SAFETY LOCK	2PCS	\$ 380.60
5	TAILGATE STICKER "70 KM/H"	1PC	\$ 10.00
6	TAILGATE STICKER 'DANGER HIGHLY FLAMMABLE'	1PC	\$ 100.00
7	TAILGATE STICKER 'FLAMMABLE GAS'	1PC	\$ 100.00
8	TAILGATE WOOD	3PCS	\$ 600.00
9	TAILGATE STOPPER	2PCS	\$ 220.69
10	TAILGATE STOPPER PILLAR	2PCS	\$ 288.20
11	REAR DECK FRONT PANEL WITH FRAME <i>882.00</i>	1SET	\$ 2,800.00
12	REAR DECK FRONT PANEL WOOD	1PC	\$ 200.00
13	REAR EXHAUST BOX	1PC	\$ 780.45
14	REAR EXHAUST BOX MOUNTING	1PC	\$ 98.61
15	REAR CROSS MEMBER	1PC	\$ 580.60
16	ENGINE MOUNTING	2PCS	\$ 286.60
17	GEAR BOX MOUNTING	1PC	\$ 143.30
	LESS 20%	25%	\$ (1,828.77)
	TOTAL AMOUNT		\$ 7,315.08



NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	REAR NUMBER PLATE	1PC	\$ 12 30.00
2	REAR NUMBER PLATE BRACKET	1PC	\$ 12 182.20
3	REAR NUMBER PLATE LAMP	2PCS	\$ 75 150.00
TOTAL SPECIAL NETT PRICE			\$ 362.20

LABOUR :		
1	LABOUR TO SPRAY PAINT	\$ 700 880.00
2	LABOUR TO PANEL BEATING	\$ 700 800.00
3	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	\$ 250.00
4	LABOUR TO DISMANTLE AND REFIX REAR DECK WOOD.	\$ 500 800.00
5	LABOUR TO DISMANTLE REAR DECK FOR CHANGING DECK FRONT PANEL.	\$ 300 400.00
6	LABOUR TO DISMANTLE AND REFIX ENGINE MOUNTINGS AND REAR EXHAUST BOX.	\$ 350.00
TOTAL LABOUR		\$ 3,480.00
TOTAL AMOUNT		\$ 11,157.28

THANK YOU

FROM:

**SIONG LEE MOTOR**

Mr Tan Leng Huat

11893.52

4765.43  
240.15  
352.20  
2420



松 利 摩 哆  
**SIONG LEE MOTOR**

Sin Ming Industrial Estate  
Block 12 Sector B #01-73 Singapore 675656  
Tel: 6457 0410, 6453 3478 Fax: 6552 0892

Company Reg. No.: 100936100J

We specialise in repairing all kinds of vehicles and pre-inspection servicing.  
We also undertake accident insurance claims for our customers.

17 August 2018

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: TAN BROS GAS SUPPLY

H/P: 6455 1169

Dear Sirs / Madam,

Accident Claim for Vehicle No.GZ 1311 B, Involving Vehicle No.SJJ 9778 J.  
Accident on 11 AUGUST 2018, AT PIE.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE
1	CABIN REAR CENTER GLASS	1PC	\$ CM 450.00 ✓
2	CABIN REAR CENTER GLASS RUBBER	1PC	\$ 160.15 320.30 ✓
	<b>TOTAL LIST PRICE</b>		\$ <b>770.30</b> ✓
	<b>LESS 20% 25%</b>		\$ <b>(154.06)</b> ✓
	<b>TOTAL AMOUNT</b>		\$ <b>616.24</b>

	<b>LABOUR :</b>		
1	LABOUR TO REMOVE AND REFIX CABIN REAR CENTER	\$	80.00 ✓
	<b>TOTAL LABOUR</b>	\$	<b>80.00</b>
	<b>TOTAL AMOUNT</b>	\$	<b>696.24</b>

THANK YOU

FROM:

**SIONG LEE MOTOR**

Mr Tan Leng Huat



松 利 摩 哆  
**SIONG LEE MOTOR**

Sin Ming Industrial Estate  
Block 12 Sector B #01-73 Singapore 575656  
Tel: 6457 0410, 6453 3478 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.  
We also undertake accident insurance claims for our customers.

14 August 2018

ATTN: MOTOR CLAIM DEPARTMENT

**ATTN: TAN BROS GAS SUPPLY**

**H/P: 6455 1169**

*Not Authorised  
11 Sep 87  
Penny After Paint  
6 days*

Dear Sirs / Madam,

**Accident Claim for Vehicle No.GZ 1311 B, Involving Vehicle No.SJJ 9778 J.**  
**Accident on 11 AUGUST 2018, AT PIE.**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	SUPPLEMENTARY PARTS REPLACEMENT	QTY	LIST PRICE	
1	TAILLAMP <i>also Mr. Old Ser</i>	2PCS	\$ 520.20	✓
2	TAILLAMP BRACKET	2PCS	\$ <i>015 R1</i> 354.40	✓
3	TAILGATE	1PC	\$ <i>R1</i> 1,680.20	✓
4	TAILGATE SAFETY LOCK	2PCS	\$ <i>015 D11</i> 380.60	✓
5	TAILGATE STICKER "70 KM/H"	1PC	\$ <i>Mr</i> 10.00	✓
6	TAILGATE STICKER 'DANGER HIGHLY FLAMMABLE'	1PC	\$ <i>Mr</i> 100.00	✓
7	TAILGATE STICKER 'FLAMMABLE GAS'	1PC	\$ <i>Mr</i> 100.00	✓
8	TAILGATE WOOD	3PCS	\$ <i>Mr</i> 600.00	✓
9	TAILGATE STOPPER	2PCS	\$ <i>015 GA</i> 220.69	✓
10	TAILGATE STOPPER PILLAR	2PCS	\$ <i>015 R1</i> 288.20	✓
11	REAR DECK FRONT PANEL WITH FRAME	1SET	\$ <i>R1</i> 2,800.00	✓
12	REAR DECK FRONT PANEL WOOD	1PC	\$ <i>Mr</i> 200.00	✓
13	REAR EXHAUST BOX	1PC	\$ <i>R1</i> 780.45	✓
14	REAR EXHAUST BOX MOUNTING	1PC	\$ <i>Mr</i> 98.61	✓
15	REAR CROSS MEMBER	1PC	\$ <i>R1</i> 580.60	✓
16	ENGINE MOUNTING	2PCS	\$ 286.60	✓
17	GEAR BOX MOUNTING	1PC	\$ 143.30	✓
	<b>TOTAL LIST PRICE</b>		<b>\$ 9,143.85</b>	
	<b>LESS 20%</b>	<i>25%</i>	<b>\$ (1,828.77)</b>	
	<b>TOTAL AMOUNT</b>		<b>\$ 7,315.08</b>	

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	REAR NUMBER PLATE	1PC	\$ 12 30.00 2012
2	REAR NUMBER PLATE BRACKET	1PC	\$ 12 182.20 ✓
3	REAR NUMBER PLATE LAMP	2PCS	\$ 215 150.00 ✓
	<b>TOTAL SPECIAL NETT PRICE</b>		<b>\$ 362.20</b>

	LABOUR :	
1	LABOUR TO SPRAY PAINT	\$ 700 880.00
2	LABOUR TO PANEL BEATING	\$ 700 800.00
3	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	\$ 250.00 901
4	LABOUR TO DISMANTLE AND REFIX REAR DECK WOOD.	\$ 500 800.00
5	LABOUR TO DISMANTLE REAR DECK FOR CHANGING DECK FRONT PANEL.	\$ 300 400.00
6	LABOUR TO DISMANTLE AND REFIX ENGINE MOUNTINGS AND REAR EXHAUST BOX.	\$ 350.00 7
	<b>TOTAL LABOUR</b>	<b>\$ 3,480.00</b>
	<b>TOTAL AMOUNT</b>	<b>\$ 11,157.28</b>

THANK YOU

FROM:


**SIONG LEE MOTOR**

Mr Tan Leng Huat

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	16 Aug 2018 <a href="#">Edit Reg</a>		14 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$6,300.00</b> <a href="#">Edit Estimates</a>	<b>S\$6,300.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	NGUI CHOON KONG, ID: S6876261H		
Main Claimant:	TAN BROS GAS SUPPLY, Co. Reg. No.: 36674400C		
Vehicle Reg. No.:	GZ1311B	Date of Loss:	11/08/2018 17:00 - :59 [151 Months and 21 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1223216782SG	Policy/Cover Note No.:	2100385358-03 (Comprehensive)
Vehicle Reg. No. (Insured):	SJJ9778J	Policy No. (Claimant):	
		Excess:	
Repairer:	Siong Lee Motor (HQ) Sin Ming Industrial Estate, Block 12 Sector B #01-73, 575656 Sin Ming - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 28/08/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG (20/08/2018): Request To Upload TP GIA Report

### ALL ASSOCIATED TASKS ☐

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

**\*GZ1311B (1223216782SG)**  
**[SJJ9778J]**  
**TP**  
**TAN BROS GAS SUPPLY**  
**Aug 11 2018 5:25PM**  
**[NGUI CHOON KONG]**  
**Siong Lee Motor**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser ▼		
Photos/Images															3 per page ▼			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
2	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
3	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
4	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
5	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
6	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
7	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
8	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
9	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
10	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
11	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
12	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
13	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
14	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
15	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
16	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
17	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
18	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
19	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
20	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
21	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
22	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
23	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
24	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
25	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
26	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
27	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
28	14/02/19 11:23	General View														Load JPG	<input checked="" type="checkbox"/>			
29	14/02/19 11:24	Reinspection Photo														Load JPG	<input checked="" type="checkbox"/>			
Documentation															1 per page ▼			<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print			
1	14/02/19 16:00	SUPPLEMENTARY														Load PDF				
No	Finalized On	AIG Asia Pacific Insurance Pte, Ltd. (SG)														Thumbnail	Print			
1	20/08/18 09:23	OI GIA REPORT														Load PDF				

## Documents Checklist

**DOCUMENTS CHECKLIST**

Reset

Save

Print

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18014713/KTBS2  
Date: 14/02/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100385358-03  
Claimant Vehicle No: GZ1311B Insured Vehicle No: SJJ9778J  
Date of Loss: 11/08/2018 Nature of Claim: TP Claim No: 1223216782SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GZ1311B  
Make & Model: TOYOTA DYNA 1.5T, 3.0 (A) Engine No: 5L5618700  
Reg. Date: 21/12/2005 (Man. Year: 2005) Chassis No: JTFUF34Y203011167  
Colour: Blue Odometer: 749785 km  
Engine Capacity: 2986 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185 R14X8 Rear Tyre Size: 155 R12X8 (D)  
Front Left Side: Michelin 8 mm Rear Left Side: Yokohama 2/2 mm  
Front Right Side: Michelin 8 mm Rear Right Side: Yokohama 2/2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,293.52	5,357.78	2,935.74	35.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	2,490.00	1,070.00	30.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,853.52</b>	<b>7,847.78</b>	<b>4,005.74</b>	<b>33.79</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>6,300.00</b>		
<b>(S\$)</b>	11,853.52	6,300.00	5,553.52	46.85
<b>+ GST 7.00/7.00% (S\$)</b>	829.75	441.00	388.75	46.85
<b>Nett Amount (S\$)</b>	<b>12,683.27</b>	<b>6,741.00</b>	<b>5,942.27</b>	<b>46.85</b>

## INSPECTION

Date of Assignment: 14/08/2018  
Date Inspected: 15/08/2018 Inspected At: 160 SIN MING DRIVE #02-07  
Estimated Period of Repair: 6.0 days Repairer: Siong Lee Motor

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*TAILLAMP	N/s Cracked / O/s Scratched	520.20 FL	*520.20 FL
2	1		*TAILLAMP BRACKET	O/s Bent	354.40 FL	*177.20 FL
3	1		*TAILGATE	Bent	1,680.20 FL	*1,680.20 FL
4	1		*TAILGATE SAFETY LOCK	O/s Distorted	380.60 FL	*190.30 FL
5	1		*TAILGATE STICKER 70KM/H	Necessary	10.00 FL	*10.00 FL
6	3		*TAILGATE WOOD	Serviceable	600.00 FL	*- FL
7	1		*TAILGATE STOPPER	O/s Cut	220.69 FL	*110.35 FL
8	1		*TAILGATE STOPPER PILLAR	O/s Bent	288.20 FL	*144.10 FL
9	1		*SET REAR DECK FRONT PANEL WITH FRAME	Bent	2,800.00 FL	*982.00 FL
10	1		*REAR DECK FRONT PANEL WOOD	Cracked	200.00 FL	*200.00 FL
11	1		*REAR EXHAUST BOX	Bent	780.45 FL	*780.45 FL
12	1		*REAR EXHAUST BOX MOUNTING	Torn	98.61 FL	*98.61 FL
13	1		*REAR CROSS MEMBER	Bent	580.60 FL	*580.60 FL
14	2		*ENGINE MOUNTING	Cracked	286.60 FL	*286.60 FL
15	1		*GEAR BOX MOUNTING	Cracked	143.30 FL	*143.30 FL
16	1		*TAILGATE STICKER DANGER HIGHLY FLAMMABLE	Necessary	80.00 FS	*40.00 FS
17	1		*TAILGATE STICKER FLAMMABLE GAS	Necessary	80.00 FS	*40.00 FS
18	1		*REAR NUMBER PLATE	Bent	30.00 FS	*20.00 FS
19	1		*REAR NUMBER PLATE BRACKET	Bent	182.20 FS	*182.20 FS
20	2		*REAR NUMBER PLATE LAMP	Missing	150.00 FS	*150.00 FS
21	1		*CABIN REAR CENTER GLASS	Cracked	450.00 FL	*450.00 FL
22	1		*CABIN REAR CENTER GLASS RUBBER (50%)	Necessary	256.24 FS	*160.15 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,172.29</b>	<b>6,946.26</b>
<b>- List Item Discount on L Items 20.00/25.00% (\$\$)</b>	<b>1,878.77</b>	<b>1,588.48</b>
<b>Total Parts (\$\$)</b>	<b>8,293.52</b>	<b>5,357.78</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR TO SPRAY PAINT.	New	880.00	700.00
2	LABOUR TO PANEL BEATING.	New	800.00	700.00
3	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS.	New	250.00	90.00
4	LABOUR TO DISMANTLE AND REFIX REAR DECK WOOD.	New	800.00	500.00
5	LABOUR TO DISMANTLE REAR DECK FOR CHANGING DECK FRONT PANEL.	New	400.00	300.00
6	LABOUR TO DISMANTLE AND REFIX ENGINE MOUNTINGS AND REAR EXHAUST BOX.	New	350.00	150.00
7	LABOUR TO REMOVE AND REFIX CABIN REAR CENTER.	New	80.00	50.00
<b>Gross Labour Cost (S\$)</b>			<b>3,560.00</b>	<b>2,490.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >