



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: India International Insurance Pte Ltd (HQ)
Comfort Transportation Pte Ltd

Singapore

Claimant Insurer: MS First Capital Insurance Ltd

LLK
Marcus
14/08/18
0950h0

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP009082018
Policy No:		Date of Loss:	13/08/2018
Vehicle Reg. No.:	SH1525D	Driveable?	YES
Pa At Fault:	UNKNOWN		
Driver (TP):	GOH CHENG CHEE		

Make/Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Vehicle Reg. Date:	02/04/2015
Vehicle Colour:	YELLOW/BLACK	Gen Condition:	GOOD
Engine No:	2ZRR780832	Chassis No:	JTDKN36U001931386
Odometer:	535997 KM		

Paint Type:		Nett Item Discount:	10.00 %
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		

Description of Accident/Loss

ON 13/08/2018 AT ABOUT 1310HR, I WAS DRIVING MY VEHICLE (A: SH1525D) ALONG JURONG WEST STREET 24 GOING TO CORPORATION PRIMARY SCHOOL. UPON REACHING THE SCHOOL, I STOPPED MY VEHICLE WITH HAZARD LIGHT AT ROAD SIDE OF THE OPPOSITE SCHOOL AND CHANGE THE BALANCE WITH MY PASSENGER. SUDDENLY THE VEHICLE (B: SHD4582U) WHICH WAS REVERSED OUT FROM THE SCHOOL AND HOT ONTO MY VEHICLE'S FRONT RIGHT PORTION. AFTER THE ACCIDENT, I FELT UNWELL.

VEHICLE A (SH1525D) - 1 FEMALE ADULT PASSENGER ON BOARD.

VEHICLE B (SHD4582U) - NO PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

Parts	7,532.75
Miscellaneous Items	10.00
Labour	1,410.00
Paintwork Labour	1,000.00
Towing	0.00

Gross Total (S\$) **9,952.75**
+ GST 7.00% (S\$) **696.69**

Nett Amount (S\$)

10,649.44**This claim is handled by: LAM WEI SHONG***Generated using Merimen e-Claims Internet Estimation & Adjusting System*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2018)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Tan Lim Motor Pte Ltd/SH1525D/13/08/2018 18:13	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*front support panel	25.00	0.00	*1,223.70 FL
2	1		*front support panel top cover	25.00	0.00	*232.00 FL
3	6		*front support panel top cover clips	25.00	0.00	*27.00 FL
4	1		*right headlamp	25.00	0.00	*3,278.30 FL
5	1		*front bumper	25.00	0.00	*499.80 FL
6	1		*right front bumper tow cover	25.00	0.00	*45.00 FL
7	1		*front bumper reinforcement	25.00	0.00	*575.00 FL
8	1		*front bumper reinforcement absorber foam	25.00	0.00	*125.00 FL
9	1		*front bumper lower beam	25.00	0.00	*236.10 FL
10	1		*right front bumper lower beam bracket	25.00	0.00	*45.00 FL
11	1		*right front bumper lower beam garnish	25.00	0.00	*115.00 FL
12	1		*front bumper side retainers	25.00	0.00	*95.00 FL
13	1		*right front bumper indication light	25.00	0.00	*125.00 FL
14	1		*front bumper lower centre air grille	25.00	0.00	*168.00 FL
15	1		*front bumper emblem badge	25.00	0.00	*78.00 FL
16	3		*front bumper emblem badge clips	25.00	0.00	*13.50 FL
17	1		*right front bumper air guide top	25.00	0.00	*51.90 FL
18	1		*right front bumper air guide bottom	25.00	0.00	*65.00 FL
19	6		*front bumper air guide clips	25.00	0.00	*27.00 FL
20	1		*front bumper lower splashshield cover	25.00	0.00	*178.20 FL
21	6		*front bumper lower splashshield cover clips	25.00	0.00	*27.00 FL
22	1		*front bumper upper centre air grille	25.00	0.00	*331.90 FL
23	1		*front bumper motorised air deflector	25.00	0.00	*498.90 FL
24	1		*front bumper motorised air deflector motor	25.00	0.00	*165.00 FL
25	1		*front bumper upper weatherstrip	25.00	0.00	*123.60 FL
26	3		*front bumper upper weatherstrip clips	25.00	0.00	*13.50 FL
27	1		*windscreen washer tank	25.00	0.00	*180.10 FL
28	1		*windscreen washer tank filler neck	25.00	0.00	*46.80 FL
29	1		*outdoor temperature sensor	25.00	0.00	*240.80 FL
30	1		*right front fender	25.00	0.00	*723.40 FL
31	1		*right front fender inner liner	25.00	0.00	*172.20 FL
32	4		*right front fender inner liner clips	25.00	0.00	*18.00 FL
33	1		*right front fender air guide	25.00	0.00	*79.80 FL
34	3		*right front fender air guide clips	25.00	0.00	*13.50 FL
35	1		*front licence plate	0	0.00	*80.00 FS
36	1		*front licence plate garnish	25.00	0.00	*99.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

10,017.00

- List Item Discount on L Items (\$\$)

2,484.25

Total Parts (\$\$)

7,532.75

Tan Lim Motor Pte Ltd/SH1525D/13/08/2018 18:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (\$\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New 700	1,000.00
Labour Items			
2	To check electrical lighting concerned.	New 20	60.00
3	To rust-proofing of the affected areas.	New 30	200.00
4	To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	New 17 X	150.00
5	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New 600	1,000.00
Gross Labour Cost (\$\$)			2,410.00

Tan Lim Motor Pte Ltd/SH1525D/13/08/2018 18:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display (damaged parts) during resurvey
- Parts price are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-4329.90
less 252
3247.42 -
1360
4607.42
confirmed 15/08/18
[Signature]