

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : AXA INSURANCE S'PORE PTE LTD  
8 SHENTON WAY  
#27-01 AXA TOWER  
SINGAPORE 068811

**Registration No** : SJY2466B

**Chassis No** : MRHFC1660JT000037

**Model** : CIVIC 1.5 TURBO VTIS YM2018

**Owner's Name** : HONG WEICHENG

**Ins Policy No.** :

**Date of Accident** : 10/8/2018

**Document No.** : SQT18003350 **Page** 1

**Date** : 13. Aug 2018

**Customer No.** : WZA006

**Svc Advisor** : ANIKKA LAI SWEE KAM

**Engine No** : L15B73621209

**Date | Time** : 13. Aug 2018 8:09:49 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

| Item            | Description                                                                                                                                                                       | Qty | Unit Price | Disc % | Amount  | 0% GST Amount | Amount incld GST |
|-----------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|------------|--------|---------|---------------|------------------|
|                 | TP DIRECT SETTLEMENT (J/NO: )<br>OWNER: HONG WEI CHENG<br>OWNER INSURER: AVIVA<br>ACC DATE: 10/08/2018<br>SURVEYED BY:<br>DATE:<br>REF NO:<br>TP INSURER: AXA<br>TP VEH: SDS8596Y |     |            |        |         |               |                  |
| 71101-TEA-T00ZZ | FACEFR.BUMPER                                                                                                                                                                     | 1   | 579.90     | 25     | 434.92  | 30.44         | 465.36           |
| 71103-TEA-T10   | GARNISHR.FR.BUMPER SIDE                                                                                                                                                           | 1   | 13.80      | 25     | 10.35   | 0.72          | 11.07            |
| 71108-TEA-T10   | GARNISHL.FR.BUMPER SIDE                                                                                                                                                           | 1   | 13.80      | 25     | 10.35   | 0.72          | 11.07            |
| 71193-TEA-T01   | SPACERR.FR.BUMPER SIDE                                                                                                                                                            | 1   | 10.40      | 25     | 7.80    | 0.55          | 8.35             |
| 71198-TEA-T01   | SPACERL.FR.BUMPER SIDE                                                                                                                                                            | 1   | 10.40      | 25     | 7.80    | 0.55          | 8.35             |
| 71102-TBA-A00   | GRILLEFR.BUMPER LOWER                                                                                                                                                             | 1   | 67.70      | 25     | 50.77   | 3.55          | 54.32            |
| 71130-TEA-T00   | BEAM COMPFR.BUMPER                                                                                                                                                                | 1   | 335.80     | 25     | 251.85  | 17.63         | 269.48           |
| 91505-TM8-003   | CLIPBUMPER                                                                                                                                                                        | 22  | 2.00       | 25     | 33.00   | 2.31          | 35.31            |
| Sum Item        |                                                                                                                                                                                   |     |            |        | 806.84  | 56.47         | 863.31           |
| BOSUN           | SUNDRIES                                                                                                                                                                          | 1   | 100.00     |        | 100.00  | 7.00          | 107.00           |
| BKBU01R         | REMOVE & RENEW FR BUMPER.                                                                                                                                                         | 1   | 1000.00    |        | 1000.00 | 70.00         | 1070.00          |
| BP01R           | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.<br>(1P)                                                                                                                             | 1   | 800.00     |        | 800.00  | 56.00         | 856.00           |
| Sum Labor       |                                                                                                                                                                                   |     |            |        | 1900.00 | 133.00        | 2,033.00         |

Survey By

Date &amp; Time

Excess

Total Amount 2,706.84 189.47 2,896.31

Total (Inclusive of GST) 2,896.31