

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/09123/2018/PH
Date : 10-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Teng Siok Ting
Address : Blk 1B Pine Grove
#09-08
Singapore 591001
Telephone : HP +65 91264643
Type of Claim : Own Damage claims
Policy No. : 2100445404-02
Vehicle No : **SKX 9408 S**
Model Code : Audi A3 SEDAN 1.4
Model / Year : Dec-15
Engine No : CZC 294933
Chassis No : WAUZZZ8V6G1040506
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Aug-18
Place of Accident : Bukit Timah Road between Mayne Road & Makenize Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 9408 S.

<u>S/N</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendation</u>
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper and rhs headlight. Re-organise front crash management components. Reinstall all parts removed.	\$ 1,200.00 500.	
3	To respray front bumper.	\$ 800.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>2,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SFC 13-B.**

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
1	BUMPER COVER <i>Refer d</i>	\$ 1,739.00	✓
2	FIXING PARTS FOR BUMPER <i>Not</i>	\$ 161.00	+
3	COVER TRIM - LH/RH <i>?</i>	2 \$ 280.00	+
4	PULL STRAP <i>Not</i>	4 \$ 175.00	+
5	GUIDE SECTION - RH <i>?</i>	\$ 33.00	+
6	AIR GUIDE GRILLE - RH <i>?</i>	\$ 95.00	?
7	RADIATOR GRILLE <i>not included</i>	\$ 573.00	✓
8	COVER FOR RADIATOR GRILLE <i>Not</i>	\$ 86.00	+
9	FOAM FILLER PIECE <i>Not</i>	\$ 117.00	+
10	SIDE REINFORCEMENT <i>Not</i>	\$ 633.00	+
11	COVER <i>Not</i>	\$ 48.00	+
12	HIGH VOLTAGE' STICKER <i>Not</i>	\$ 12.00	+
13	HEADLIGHT FOR GAS DISCHARGE LAMP - RH <i>Not</i>	\$ 1,764.00	+
14	LIFT CYLINDER FOR HEADLIGHT WASHER - RH <i>?</i>	\$ 174.00	?
15	CAR PLATE <i>Not</i>	\$ 25.00	✓
16	SUNDRIES <i>?</i>	\$ 300.00	?
SUB- TOTAL SPARE PARTS		\$ 6,215.00	

8767

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name
Surveyed Date
Authorised Date
Excess Cost
Liability
Remarks

: Adrian Wong
: 14/08/18
:
:
:
: Authorised Repairs, 030mgs

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant