

ASS. REC BY: Adrian Ling

REF:

CC3 / ALH18014731 / Aqber

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No

1700061930

Claims No.

8457245690 SC

Sum Insured:

Excess:

600 15/8/18

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bail. or Market Value:

105K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

24/8/18

days

Res.:

Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLT4436C

Yr Regn:

2017 / Oct

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3

C.C.

999.

Colour:

Red.

A/C:

Insured / Std / NI / NA

Sp. Reading

3027.

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAU2228VOJ1017472.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

205/55R16-

R:

205/55R16.

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A

D.O.I

12/08/18

Survey held at

Premium.

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

OD AIG.

SLT 4436C - X

RECEIVED 16 MAY 2019

14/5/18 @ 5.12pm revert to Victor via Meimian.

15/5/18 @ 11.57am Victor informed C/A via Meimian.

15/5/18 @ 4.59pm Informed George C/A B 6X & 600 by email.

20/5/18 @ 2.40pm 2nd revert to Victor via Meimian. (Supplementary)

21/2/18 @ 2.45pm 3rd revert to Victor via Meimian. (Supplementary 1 & 2).

16/4/19 @ 8.26am Victor informed C/A at \$34055.64 via Meimian

16/4/19 @ 1.57pm confirmed with Carvine final fig \$34055.64, 20 days (Red B 12921.36, 28

Date/Time, File Pass to?



Prel. Report

Days Of Repair:

24

1) 16/5/19



Final Report

Resurvey No. of Trip:

1

Survey Fee:

700

Transportation:

5 x 100 = 500

Picnic

Others

10

TOTAL

210

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

MER-01)

Lump Sum / L.B.I. (\$

34055.64

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 16 April 2019 1:51 PM
To: Carrine Leong; SUR; nora.khai@premiumauto.com.sg
Cc: jiyee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLT4436C - OD AIG - SURVEYED 14 AUG 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$34,055.64 before excess \$600.00 & GST and 24 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 29 March 2019 11:37 AM
To: Carrine Leong <carrine.leong@premiumauto.com.sg>; SUR <sur@lkkauto.com>; nora.khai@premiumauto.com.sg
Cc: jiyee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLT4436C - OD AIG - SURVEYED 14 AUG 18

Dear Nora,

As spoken with you.

Kindly advise whether you agree to take out the part of 'LUGGAGE COMPARTMENT COVER LH' as it was not approved by insurance office.

Please let us have your conclusion as we need get approval on repair cost from insurance.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Thursday, 21 February 2019 3:58 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: jiyee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLT4436C - OD AIG - SURVEYED 14 AUG 18
Importance: High

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Aug 2018 11:28	Cim Veh Model Changed		[] Merimen Administrator
2	13 Aug 2018 11:28	Cim Created	Reg No: SLT4436C, Policy No: 1700061930, Acct Date: 2018/08/11, Claim Type: S C, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), Ins.Status => Notification, Created from SAS:MPA118103831	[I] Merimen Administrator
3	14 Aug 2018 15:06	Cim Registration Modified	SetJ.Type:3->0, Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	14 Aug 2018 15:06	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	14 Aug 2018 15:06	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	14 Aug 2018 15:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/24	[A] CATHERINE CHONG KAI LING
7	14 Aug 2018 15:06	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	14 Aug 2018 15:06	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	14 Aug 2018 15:06	Cim Veh Model Changed	(205280) AUDI A3 999cc TFSI (A).	[A] CATHERINE CHONG KAI LING
10	14 Aug 2018 15:06	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	14 Aug 2018 17:06	Adj Rpt Initiated		[A] SHIAU CHAN
12	14 Aug 2018 17:06	Insured Phone No Updated	[None] -> [+6598155489]	[A] SHIAU CHAN
13	14 Aug 2018 17:06	Cim Dtl Modified	Driver Name: CHOK YEE TIN REGINA -> CHOK YEE TIN REGINA (ZHOU YUTI.	[A] SHIAU CHAN
14	14 Aug 2018 17:06	Cim Dtl Modified	JPJ Reg. Date: -> 2017/10/30.	[A] SHIAU CHAN
15	14 Aug 2018 17:06	Cim Details Notified		[A] SHIAU CHAN
16	14 Aug 2018 17:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/08/24	[A] SHIAU CHAN
17	14 Aug 2018 17:17	Adj Mandate Request	Cur.Req:32364.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	15 Aug 2018 10:20	Cim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Dally Amri, Mimi Zarina
19	15 Aug 2018 10:20	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	15 Aug 2018 11:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/24, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	15 Aug 2018 11:57	Adj Mandate Set	Approved:28903.00:Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
22	30 Aug 2018 14:47	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/08/24	[A] SHIAU CHAN
23	30 Aug 2018 14:48	Adj Mandate Request	Cur.Req:38031.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
24	07 Sep 2018 13:33	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/08/24, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
25	07 Sep 2018 13:33	Adj Mandate Set	Maintained:Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
26	21 Dec 2018 14:42	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/08/24	[A] SHIAU CHAN
27	21 Dec 2018 14:44	Adj Mandate Request	Cur.Req:34055.64:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY & CHECK ITEMS.	[A] SHIAU CHAN
28	31 Jan 2019 10:07	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/08/24, Mandate Remarks: Refer to case mail.	[I] Koh, Victor-CK
29	31 Jan 2019 10:07	Adj Mandate Set	Maintained:Refer to case mail.	[I] Koh, Victor-CK
30	27 Mar 2019 16:25	Adj Mandate Request	Cur.Req:34055.64:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY AP PROVE ON SUPPLEMENTARY & CHECK ITEMS.	[A] SHIAU CHAN

 AUDIT TRAIL

No.	On	Audit	Remarks	By
31	28 Mar 2019 08:21	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2018/08/24, Mandate Remarks: Luggage compartment cover LH damage not consistent to take out.	[I] Koh, Victor-CK
32	28 Mar 2019 08:21	Adj Mandate Set	Maintained:Luggage compartment cover LH damage not consistent to take out.	[I] Koh, Victor-CK
33	11 Apr 2019 12:07	Adj Mandate Request	Cur.Req:34055.64:According to our surveyor, please refer to the newly uploaded photos 75-81 of LUGGAGE COMPARTMENT COVER LH in Merimen System.	[A] SHIAU CHAN
34	16 Apr 2019 08:26	Adj Mandate Set	Approved:34055.64.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1887188	14/08/2018 17:06	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLT4436C		10.70

View Sent Message

This mail is associated with :

***SLT4436C (8457245690SG)**

OD

Aug 11 2018 12:30PM

[CHOK YEE TIN REGINA (ZHOU YUTING REGINA)]

Premium Automobiles Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 11/04/2019 12:06 PM.

To AIG_SG; Victor_KohCK

Subject Re: Alert - Adj Mandate Maintained - SLT4436C - Claim Handler: Dally Amri, Mimi Zarina

Dear Victor,

According to our surveyor, please refer to the newly uploaded photos 75-81 in Merimen System.

Thanks & Regards,

Shiau Chan (Ms)

LKK Auto Consultants Pte Ltd

Tel: 6256 3561

<-- Original Message -->

From: AIG_SG

To: LKK_HQ

Sent On: 28/03/2019 08:21 AM

Subject: Alert - Adj Mandate Maintained - SLT4436C - Claim Handler: Dally Amri, Mimi Zarina

Maintained:Luggage compartment cover LH damage not consistent to take out.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

*SLT4436C (84572456905G)
OD

Aug 11 2018 12:30PM
[CHOK YEE TIN REGINA (ZHOU YUTING REGINA)]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/03/2019 08:21 AM.
To LKK_HQ
Subject Alert - Adj Mandate Maintained - SLT4436C - Claim Handler: Dally Amri, Mimi Zarina

Maintained:Luggage compartment cover LH damage not consistent to take out.

Please see newly uploaded photos 75-81.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

***SLT4436C (8457245690SG)**

OD

Aug 11 2018 12:30PM

[CHOK YEE TIN REGINA (ZHOU YUTING REGINA)]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 31/01/2019 10:21 AM.
To LKK_HQ
CC victor-ck.koh@aig.com; Andy-SY.Fong@aig.com
Subject Consistency of the supplementary parts.

Hi,

Kindly justify why the luggage compartment cover LH/RH is allow to replace. Photos 61-62 clearly show it was cut and not damage by accident. Photos 65-66 close up damage area located at which area. General photo dosent seem to be damage.

End panel - Does photo 68, 70 damage area belong to the end panel or the tail lamp panel? Also additional labour to replace end panel should be at 1.5 days (conjunctive repair) if replace.

Kindly revert on above queries.

Regards
Victor Koh

DOCUMENTS SUMMARY

There are no documents.

LH

Luggage Compartment Cover
photo 7690

RH

Luggage Compartment Cover
photo-7695

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 21 Dec 2018

Preliminary Advice

Vehicle No	: SLT4436C	Accident Date	: 11/08/2018
Make	: AUDI A3	Policy No.	: 1700061930
Assignment Date	: 14/08/2018	Excess	: S\$600.00
Date of Inspection	: 14/08/2018	Est. Duration of Repair	: 24.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,977.00	(ESTIMATE \$39,270.00 + SUPPLEMENTARY 1 \$5,667.00 + SUPPLEMENTARY 2 \$2,040.00)
Revised Amount	:S\$	34,055.64	(INCLUSIVE OF SUPPLEMENTARY & CHECK ITEMS)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	34,055.64	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	50,044.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,956.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY & CHECK ITEMS.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 30 Aug 2018

Preliminary Advice

Vehicle No	: SLT4436C	Accident Date	: 11/08/2018
Make	: AUDI A3	Policy No.	: 1700061930
Assignment Date	: 14/08/2018	Excess	: S\$600.00
Date of Inspection	: 14/08/2018	Est. Duration of Repair	: 24.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,937.00	(ESTIMATE \$39,270.00 + SUPPLEMENTARY \$5,667.00)
Revised Amount	:S\$	34,253.00	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	3,778.00	(INCLUSIVE OF SUPPLEMENTARY)
Total	:S\$	38,031.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	50,044.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,956.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAuto)

From: Koh, Victor-CK <Victor-CK.Koh@aig.com>
Sent: Tuesday, 4 September 2018 12:01 PM
To: SUR
Cc: Fong, Andy-SY
Subject: SLT4436C/ OD / 8457245690SG

Hi

Supplementary labour 1 in excess additional 3 day labour is reasonable. Kindly amend.
Also kindly advise where is 'D' pillar located in this saloon vehicle?
Supplementary labour 2 should be already included in estimate labour 3. Kindly take out.

Thanks & Regards

Victor Koh
AIG
Claims Technical Controller
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120
Tel +65 6419 1785 | Fax +65 68357416
Victor-ck.koh@aig.com | www.aig.com

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 15 August 2018 4:59 PM
To: Claims Dept; SUR
Subject: RE: OD CLAIMS FOR SLT 4436 C

Dear George,

As instructed by our client AIG Insurance, please proceed to repair the insured vehicle **SLT 4436C (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 15 August 2018 11:19 AM
To: Claims Dept <claims@premiumauto.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: OD CLAIMS FOR SLT 4436 C

Dear George,

Please be informed that we are still pending for insurance mandate approval. Once approve, we will send you an email.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 15 August 2018 11:08 AM
To: SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIMS FOR SLT 4436 C

Dear all,

Any update for the approval?

Vehicle is in our premises.

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	13 Aug 2018 11:28	Cim Veh Model Changed		[I] Merimen Administrator
2	13 Aug 2018 11:28	Cim Created	Reg No: SLT4436C. Policy No: 1700061930, Acct Date: 2018/08/11. Claim Type: S C. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118103831	[I] Merimen Administrator
3	14 Aug 2018 15:06	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[I] CATHERINE CHONG KAI LING
4	14 Aug 2018 15:06	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[I] CATHERINE CHONG KAI LING
5	14 Aug 2018 15:06	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	14 Aug 2018 15:06	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/24	[A] CATHERINE CHONG KAI LING
7	14 Aug 2018 15:06	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	14 Aug 2018 15:06	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	14 Aug 2018 15:06	Cim Veh Model Changed	(205280) AUDI A3 999cc TFSI (A).	[A] CATHERINE CHONG KAI LING
10	14 Aug 2018 15:06	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	14 Aug 2018 17:06	Adj Rpt Initiated		[A] SHIAU CHAN
12	14 Aug 2018 17:06	Insured Phone No Updated	[None] -> [+6598155489]	[A] SHIAU CHAN
13	14 Aug 2018 17:06	Cim Dtl Modified	Driver Name: CHOK YEE TIN REGINA -> CHOK YEE TIN REGINA (ZHOU YUTI.	[A] SHIAU CHAN
14	14 Aug 2018 17:06	Cim Dtl Modified	JPJ Reg. Date: -> 2017/10/30.	[A] SHIAU CHAN
15	14 Aug 2018 17:06	Cim Details Notified		[A] SHIAU CHAN
16	14 Aug 2018 17:15	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/08/24	[A] SHIAU CHAN
17	14 Aug 2018 17:17	Adj Mandate Request	Cur.Req:32364.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	15 Aug 2018 10:20	Cim Registration Modified	Init.Est.->5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Dally Amri, Mimi Zarina
19	15 Aug 2018 10:20	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
20	15 Aug 2018 11:57	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/08/24. Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
21	15 Aug 2018 11:57	Adj Mandate Set	Approved:28903.00:Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK

Date From



Date To



Audit Type

None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1887188	14/08/2018 17:06	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLT4436C		10.70

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 14 Aug 2018

Preliminary Advice

Vehicle No	: SLT4436C	Accident Date	: 11/08/2018
Make	: AUDI A3	Policy No.	: 1700061930
Assignment Date	: 14/08/2018	Excess	: S\$0.00
Date of Inspection	: 14/08/2018	Est. Duration of Repair	: 24.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	39,270.00
Revised Amount	:S\$	28,903.00
Check Items (Estimated)	:S\$	3,461.00
Total	:S\$	32,364.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	105,000.00
COE / PARF Rebate	:S\$	50,044.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,956.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5302C
Vehicle Details	
Vehicle No.:	SLT4436C
Vehicle to be Exported:	No
Intended De-registration Date:	14 Aug 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	CHZ562767
Chassis No.:	WAUZZZ8V0J1017472
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$23,900.00
Original Registration Date:	30 Oct 2017
First Registration Date:	30 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$15,460.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2027
PARF Rebate Amount:	\$11,595.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,761.00
COE Rebate Amount:	\$38,449.00
Total Rebate Amount:	\$50,044.00

The information contained herein is correct as at 14 Aug 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/08/2018 09:43
Date Of Accident	11/08/2018 12:30
Exact Location Of Accident	HOTEL ROYAL @ QUEENS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT4436C
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	CHOK YEE TIN REGINA (ZHOU YUTING REGINA)
NRIC No	S8015302C
Email Address	REG_CHOK@YAHOO.COM
Mobile Phone No	(LOCAL) +65-98155489
Alternative Phone No	OFFICE-98155489

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI 8V
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700061930
Cover Note Number	

Driver

Name of Driver	CHOK YEE TIN REGINA
NRIC No	S8015302C
Date Of Birth	30/05/1980
Occupation	INDOOR
Date Of Driving Pass	15/12/2001
Driving Experience	16 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98155489
Fax Number	
Contact Number	
Email Address	REG_CHOK@YAHOO.COM

Address	21 LORONG LEW LIAN #03-03
Postcode	536467
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


REVERSED INTO CARPARK WALL

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

reversed into carpark wall

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:

Date & Time: 15/5 8:49

Driver's Signature _____

(if driver is not the policyholder)

Date & Time: 13/9 9:45

PHIA CHOON HUEN ©

Reporting Centre Personnel's Signature

Name: PAUL GREEN MURPHY

NRIC/TIN No: 57702630

Premium Automobiles Pte Ltd



Head Office
 200 Ang Mo Kio Street
 Singapore 560020
 Telephone: (65) 4346 1111
 Telex: (87) 6471 373

Service & Parts Centre
 11 Ulu Road 1
 Singapore 408606
 Telephone: (65) 4364 2121
 Telex: (87) 6471 118

Collision Damage Repair Centre
 24 Brine Street
 Singapore 120017
 Telephone: (65) 4364 2121
 Telex: (87) 6471 118

Third Party Direct Settlement / Own Damage Claim - Acknowledgement Letter

Premium Automobiles Pte Ltd received your instructions to assist you to submit a Third Party - Direct Settlement or Own Damage Claim. We hereby advise you on the following claims procedure:

1. We will assist you to submit your GIA report, estimates and any necessary documentation needed for the claim process.
2. You are required to allow the Third Party surveyor to carry out pre-repair survey of your vehicle to ascertain the damages incurred during the accident at any time and in any case at least 2 clear working days before commencement of the repairs.
3. We will attend to the surveyor on your behalf during the assessment and you are not required to be present however it is permitted should you wish to participate.
4. Premium Automobiles will carry out the repairs to your vehicle as per Surveyor's approval and recommendations.
5. Premium Automobiles will carry out the repairs to your vehicle only upon your insurer approval.
6. The period to establish the liability differs on case-to-case basis, subject to the how the accident between you and the 3rd Party occurred.
7. Premium Automobiles does not have any control over the period taken, however we will continue to follow up your case and we will render any information to assist and expedite your claim.
8. Premium Automobiles do not have any control over the 3rd Party insurers' decision and conclusion. In the event, liability is disputed by the 3rd Party insurers or you are unable to agree to the 3rd Party insurers' position/offer on liability, we would advise you to revert this claim to one under Own Damage and make the claim directly from your insurers to expedite the repairs. In this event, please be advised that you will be liable to pay the excess due under your own insurance policy and your No Claim Bonus may be adversely affected as a result. This action allows you to seek recovery of your uninsured losses later. Please be further advised that your insurer's surveyor may take additional time to survey the vehicle for the purpose of a Own Damage Claim.
9. You may wish to seek legal advice should the Third Party insurer's decision be unfavorable however we do not encourage for such purposes. You may refer to Fiddo for your claim resolutions or settlement. The costs of such service shall be solely borne by you.
10. After clearance of the liability with the Third Party insurers, you have the option to choose to claim Loss of Use or may opt for Costs of Rental Car during the period of repair. The rates provided in Third party Direct Settlement Claim are based on the Benchmark rate issued by the Subordinate Courts NIMA ("Non Injury Motor Claims") Protocol. The number of days claimable during the repair period is strictly subjected to the surveyor's recommendation of the number of days required for repairs, not while vehicle is in workshop in consideration of the downtime for parts order, availability of aluminum body/palette bench, etc. relating to repair needs.
11. Premium Automobiles do not provide any courtesy car for your period of repairs / rental. (For Third Party Direct Settlement Claim or for Own Damage Claim), Rental from day one accident is at your own risk.
12. If you would like Premium Automobiles to assist in claiming for Rental Claim you are required to submit your Rental Invoice and we will do the necessary.
13. Premium Automobiles will not under any circumstance be held responsible for the difference of the loss of use payable by the Third Party insurers and the actual number of days of loss of use as we will not compromise the quality over the repair period as recommended by the surveyor.
14. You will render your fullest cooperation to sign on the Satisfaction and/or Discharge Voucher(s) following the completion of the repairs and in any time required for the closure of your claim and to authorize the payment by the Third Party/Own insurers to us for our repair costs, failing in which we will recover the full cost of repairs, legal costs and disbursements and all other incidental losses against your good self.
15. Please be advised that the Satisfaction and/or Discharge Voucher(s) are required to be signed by the owner of the vehicle at the point of collection of the repaired vehicle, failing which we shall reserve our rights to exercise our right of lien over the vehicle. In the event that the owner of the vehicle is unable to collect the vehicle personally, the owner will need to authorize the collection (by way of a letter of authority) and the appointed person shall bear such letter of authority with a photo ID at the time of collection. Such a person must also be authorized by the owner to sign the Satisfaction and/or Discharge Voucher(s) on behalf of the owner. Please note in this regard that the insurers may subsequently require more documents to be signed for the release of payment to us.
16. For the avoidance of doubt, the repairs are deemed satisfactory carried out if no defect is raised upon collection of the vehicle, if such defect would have been apparent upon visual examination. For defects not apparent upon visual examination, you may raise the defect to us in writing within the next 7 days from the date of collection of the vehicle, beyond which we shall not be liable for the same. Kindly be advised that the period of warranty for replaced parts is limited to 2 years and the warranty period for workmanship is limited to 6 months. We shall not be liable for damage to the vehicle occurring after delivery of the repaired vehicle.
17. Please note that this service is an extension of our good service to you and if the Third Party Direct Settlement and/or Own Damage Claim should fail for any reason whatsoever, we shall reserve our rights to look to you for an indemnity and payment of the repair costs incurred.
18. In the event that the repair costs is invoiced to you and payment is not received from you within 14 days, we reserve the right to levy additional late payment interest at the rate of 10% per annum from the date of the invoice.

By signing below you hereby acknowledge that you have been advised of the claims procedure by our Claims Advisor and you are agreeable to the same. You hereby authorize Premium Automobiles Pte Ltd to proceed with the Third Party Claim - Direct Settlement/ Own Damage and the repairs to your vehicle and to submit, resolve, sign all necessary documents in connection with the accident stated below. Premium Automobiles Pte Ltd will assure you of the best duty of care and workmanship in the repairs carried out.

Please select one of the followings (please tick ✓) :-

- ☒ Own Damage Claim (Excess Applicable)
☐ Recovery
☐ Third Party Direct Settlement
☐ Possible Dispute Liability / Reject Case
☐ Gate May Drag
☐ No of days claimable for LOU/OL subject strictly to surveyor's recommendation

Signature

Owner/Driver Name

Vehicle Number

Accident Date & Time

Third Party Vehicle No.

dl
 CHOW YEE TIN ROYINA
 SLT 4936C
 11/5/18 12 30 PM
 /

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





ENDORSEMENT SCHEDULE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Policy No. : 1700061930
Period of Insurance : 30 Oct 2017 to 29 Oct 2018

Endorsement No. : 000000000180493
Issued Date : 13 Feb 2018

ABOUT THE POLICYHOLDER

Name of Policyholder : CHOK YEE TIN REGINA (ZHUO YUTING REGINA)
Address : 21 LORONG LEW LIAN
03-03 CHERRY HILL CONDOMINIUM
SINGAPORE 536467
Occupation/Nature of Business : Manager/Director/Management

ABOUT THE VEHICLE

Registration No. : SLT4436C
Chassis No. : WAUZZZ8V0J1017472
Seating Capacity : 5
First Year of Registration : 2017
Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Hire Purchase Company/Employer's Loan : MayBank
Engine Capacity/Tonnage : 999.00 CC
Engine No. : CHZ562767
Body Type : Sedan

ABOUT THE COVER

Sum Insured : Market Value
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive :
Off Peak Car : No
Insuring with COE/PAFF : Yes

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Other Key Policy Benefits :

Act of God, Strike, Riots and Civil Commotions, PA to Authorised Driver / Unnamed Passengers- \$10000, Dealer + AIG Authorised Workshops, PA Insured- \$100000, Fixture and Accessories (Cosmetic)- \$5000, Solar Film- \$1150, New For Old (36 months), Loss of Use, In-Car Camera Excess Waiver, Glass Roof/ Moon Roof/ Sun Roof/ Panoramic Glass Roof, NCD Protector

ENDORSEMENT REMARK

It is hereby declared and agreed that with effect from 19/01/2018:

1) NCD Details : Update NCD on Policy with AIG

Declared Previous Insurer: AXA INSURANCE SINGAPORE PTE LTD

Declared NCD: 50%

Verified NCD: 50%

With the update in Claims/NCD details, premium and/or excess are revised. Refer to details stated above.
Subject otherwise to the Terms, Exclusion and Conditions of this Policy.

Endorsement effective from: 19-Jan-2018. All other terms and conditions remain unchanged.

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8015302C



CHOK YEE TIN REGINA
(ZHUO YUTING REGINA)

卓玉婷

Chinese

Chinese

30-05-1980

Female

Country of Birth

SINGAPORE

3382847



NRIC No. S8015302C



21 LIORING LEW LIAN #03-03
SINGAPORE 530467

NRIC No. S8015302C

Date: 18/07/2015

Valid Until: 11-08-2003

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

PASS DATA

15 Dec 2003

Class 3 Motor Cars and Motor Tractors the weight of which includes driver and not exceed 3500 kilograms



License No. S8015302C

NP 425A

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number S8015302C

Valid

CHOK YEE TIN REGINA
(ZHUO YUTING REGINA)

Valid Date: 30 May 1980

Valid Date: 19 Jul 2003



NP 425A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0923/2018/nk
Date : 13-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Chok Yee Tin Regina
Address : 21 Lorong Lew Lian
#03-03
Singapore 536467
Telephone : HP +65 98155489
Type of Claim : Own Damage claims
Policy No. : 1700061930
Vehicle No : **SLT 4436 C**
Model Code : Audi A3 SEDAN 1.0 TFSI QU
Model / Year : Oct-17
Engine No : CHZ 562767
Chassis No : WAUZZZ8V0J1017472
Mileage :
Date In : 13-Aug-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Aug-18
Place of Accident : Hotel Royal @ Queens

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 4436 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	✓
2	To renew both 1/4 glass and rear windscreen to facilitate fender renewal.	S/N	\$ 900.00	✓
3	To remove and transfer rear lid's convenience lock sytem, wire harness for taillights and rear wiper assy.	S/N	\$ 480.00	✓
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 1,400.00	✓
5	To remove and reinstall rear seat, back rest , hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbaq etc.	S/N	\$ 1,400.00	✓
SUB LABOUR CHARGES		:	\$ 4,460.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 4436 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
6	To dismantle and renew rear bumper and rear lid. Cut out and reweld both side rear fender. Reorganise rear crash managements components. Reinstall all parts removed.	S 7,800.00	6500 Excluding Rear Panel.
7	To respray rear bumper, rear lid, both side rear fender, sill panel, rear lid hinges, drain panel, roof channel, door entrances and end panneling. To carry out stone chip treatment and joint sealer works.	S 7,000.00	3850
8	To carry out diagnostic checks.	S/N S 192.00	
SUB LABOUR CHARGES		: <u><u>S 19,452.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Deformed</i>	\$ 1,697.00	✓ 1359.60
2	REAR BUMPER FIXING PARTS <i>per m</i>	\$ 166.00	✗
3	REAR ADAPTER WHEEL HOUSING LINERS LH / RH <i>not per m</i>	\$ 64.00	✗
4	REAR BUMPER GUIDE SECTION LH / RH <i>per m</i>	2 \$ 28.00	✗
5	REAR BUMPER LOCKING MECHANISM	2 \$ 50.00	✗
6	REAR BUMPER SPOILER <i>per m</i>	\$ 206.00	✗
7	REAR BUMPER LIGHT REFLECTOR LH / RH <i>per m</i>	2 \$ 70.00	✗
8	REAR RENFORCEMENT BEAM <i>Not Nec</i>	\$ 501.00	? ✗
9	REAR BUMPER BRACKET LH / RH <i>per m</i>	2 \$ 47.00	✗
10	REAR BUMPER GUIDE SECTION LH / RH <i>per m</i>	2 \$ 114.00	✗
11	REAR SENSOR INNER / OUTER <i>per m</i>	2 \$ 421.00	✗
12	REAR BUMPER SEAL RING <i>per m</i>	4 \$ 14.00	✗
13	REAR LID <i>Distorted</i>	\$ 2,310.00	✓ 1848
14	REAR LID ATTACHEMENTS PARTS <i>per m</i>	\$ 253.00	✓ 113.85
15	REAR LID HINGES LH / RH <i>Bent</i>	2 \$ 448.00	✓ 358.40
16	REAR LID GASKET <i>per m</i>	\$ 176.00	✓ 140.40
17	REAR LID LOCK STRIKER <i>Not nec</i>	\$ 44.00	? ✗
18	REAR LID LOCK <i>Jammed</i>	\$ 170.00	✓ 136
19	REAR LID LOCK COVER <i>Not nec</i>	\$ 7.00	? ✗
20	PUSH BUTTON FOR LID LOCK <i>Not nec</i>	\$ 159.00	? ✗
SUB- TOTAL SPARE PARTS		\$ 6,945.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	STOP BUFFER <i>Not Nec</i>	2 S	30.00 ? X
22	PACKING ADHESIVE <i>re</i>	S	15.00 ✓ 11.60
23	AUDI LOGO <i>re</i>	S	108.00 ✓ 86
24	A3' CHROME EMBLEM <i>re</i>	S	83.00 ✓ 66.16
25	TFSTI' CHROME EMBLEM <i>re</i>	S	83.00 ✓ 66.16
26	SECTIONAL PART LH / RH <i>Dented</i>	2 S	4,012.00 ✓ 3207.60
27	REAR WINDSCREEN <i>re</i>	S	704.00 ? 563.70 ✓
28	REAR WINDSCREEN PRIMER <i>re</i>	2 S	37.00 ✓ 29.12
29	REAR QUARTER GLASS LH / RH <i>Not Nec</i>	2 S	1,004.00 ? 802.40 ✓
30	REAR QUARTER TRIM STRIPS REAR LH / RH <i>re</i>	2 S	776.00 X
31	REAR QUARTER GLASS CLIPS <i>re</i>	8 S	104.00 ✓ X
32	REAR LID TRIM PANEL <i>re</i>	S	273.00 ? 218.40 ✓
33	REAR CROSS PANEL TRIM <i>re</i>	S	135.00 ? 107.60 ✓
34	LED TAILLIGHT OUTER LH / RH <i>crack</i>	2 S	1,460.00 ✓ 1168
35	TAILLIGHT TRIM LH / RH <i>crack</i> <i>Not Nec</i>	2 S	52.00 <i>not</i> ? X
36	LED TAILLIGHT INNER LH / RH <i>crack</i>	2 S	1,460.00 ✓ 1168
37	TAILLIGHT TRIM LH / RH <i>re</i>	2 S	52.00 ? X
38	NO PLATE <i>Best</i>	S/N S	25.00 ✓
39	ACYRLIC SEALER <i>re</i>	S/N S	360.00 ✓
40	CAVITY WAX <i>re</i>	S/N S	280.00 ✓
SUB PARTS CHARGES		:	\$ 11,053.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
41	STONE CHIP	S/N \$ 360.00	✓
42	METAL FILLER POWDER	S/N \$ 560.00	✓
43	REAR WINDSCREEN SEALANT	S/N \$ 200.00	✓
44	1/4 GLASS SEALANT	S/N \$ 200.00	✓
45	SUNDRIES	\$ 500.00	? 158.55 ✓
TOTAL SPARE PARTS		: \$ 19,818.00	
TOTAL LABOUR CHARGES		: \$ 19,452.00	
GRAND TOTAL		: \$ 39,270.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

36279 60

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adnan King

Surveyed Date

: 14/08/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 24 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dep Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0923/2018/NK 23-Aug-18 CHANG 1 of 1 SLT 4436 C Audi A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To cut out and weld rear outer, inner rear end panels and connecting plates. Repair lhs rear D-pillar reinforcement.	\$ 2,700.00	* 700
2	To retrofit rear lid reverse camare. S/N	\$ 1,300.00	* 509
Parts			
1	REAR LID RETAINER FOR WARNING TRIANGLE	\$ 51.00	X 40.48
2	REAR LID ANTI-THEFT GUARD COVER	\$ 30.00	DE 23.72
3	REAR LID HINGE COVER - LH/RH	\$ 14.00	cl 1.88
4	REAR LID CABLE GUIDE	\$ 61.00	cl 48.16
5	REAR LID CLOSING ELEMENT	\$ 54.00	DE 42.72
6	REAR CROSS PANEL - OUTER	\$ 317.00	DE 253.60
7	REAR CROSS PANEL REINFORCEMENT - INNER	\$ 645.00	BT 515.60
8	REAR CROSS PANEL CONNECTING PLATE - LH/RH	\$ 252.00	na 201.60
9	REAR LID LED LICENCE PLATE LIGHT	\$ 187.00	CPA / na 149.28
10	REAR END PANEL WELD SCREW SET	\$ 26.00	na 20.72
11	REAR LID STOP BUFFER	\$ 30.00	na 20.64
GRAND TOTAL :		\$ 5,667.00	


 23/08/18 @ 1610

For Premium Automobiles Pte Ltd




 Authorised Signature



Audi

ETKA - Order Form

Order Form:

SLT4436C-WIP20910

18:44

20.08.2018

R2 by Kiam

Editor:

Item Description	Remark	Model	Qty	SGD	D
BV5 863 887 AN CA9 VIN: WAUZZZ8V0J1017472 Luggage compartment trim Black Stock : 0	-? te left	PR-1X0, 1X5+ QX1, QX5+1X0+ 4X3	1	676,00	
BV5 862 888 E CA9 VIN: WAUZZZ8V0J1017472 Luggage compartment trim Black Stock : 0	-? te right	PR-1X0+4X3	1	676,00	
BV0 827 586 B Push button for electric lid lock actuator	-?		1	1181,00	
BV5 867 975 G CA9 VIN: WAUZZZ8V0J1017472 Rear lid trim panel Black Stock : 0	-?	PR-1T2, 1T3, 1T4+5C0, 5C1	1	273,00	
ETO 860 285 VIN: WAUZZZ8V0J1017472 Retainer for warning triangle Location : FF06-C-4 Stock : 0	-supp	PR-1T2, 1T3, 1T4, 1T8	1	50,60	
BV5 827 569 VIN: WAUZZZ8V0J1017472 Anti-theft guard cover Stock : 0	-supp inner		1	39,90	
BV5 827 373 VIN: WAUZZZ8V0J1017472 Stop Rear lid Location : 8B03-C-6 Stock : +2.00	left		1	6,10	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>detached</i>	\$ 1,697.00	✓
2	REAR BUMPER FIXING PARTS <i>new</i>	\$ 166.00	✗
3	REAR ADAPTER WHEEL HOUSING LINERS LH / RH <i>new</i>	\$ 64.00	✗
4	REAR BUMPER GUIDE SECTION LH / RH <i>new</i>	\$ 28.00	✗ (RA) ✓
5	REAR BUMPER LOCKING MECHANISM	\$ 50.00	✗ ✓
6	REAR BUMPER SPOILER <i>new</i>	\$ 206.00	✗
7	REAR BUMPER LIGHT REFLECTOR LH / RH <i>new</i>	\$ 70.00	✗
8	REAR RENFORCEMENT BEAM	\$ 501.00	?
9	REAR BUMPER BRACKET LH / RH <i>new</i>	\$ 47.00	✗
10	REAR BUMPER GUIDE SECTION LH / RH <i>new</i>	\$ 114.00	✗
11	REAR SENSOR INNER / OUTER <i>new</i>	\$ 421.00	✗
12	REAR BUMPER SEAL RING <i>new</i>	\$ 14.00	✗
13	REAR LID <i>Distorted</i>	\$ 2,310.00	✓
14	REAR LID ATTACHEMENTS PARTS <i>new</i>	\$ 253.00	✓
15	REAR LID HINGES LH / RH <i>Bent</i>	\$ 448.00	✓
16	REAR LID GASKET <i>new</i>	\$ 176.00	✓
17	REAR LID LOCK STRIKER	\$ 44.00	?
18	REAR LID LOCK <i>Jammed</i>	\$ 170.00	✓
19	REAR LID LOCK COVER	\$ 7.00	✗ (d) ✓
20	PUSH BUTTON FOR LID LOCK	\$ 159.00	?
SUB- TOTAL SPARE PARTS		\$ 6,945.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	STOP BUFFER ?	2 \$	30.00 ?
22	PACKING ADHESIVE re	\$	15.00 ✓
23	AUDI LOGO	\$	108.00 ✓
24	A3' CHROME EMBLEM	\$	83.00 ✓
25	TFSI' CHROME EMBLEM	\$	83.00 ✓
26	SECTIONAL PART LH / RH Dented	2 \$	4,012.00 ✓
27	REAR WINDSCREEN ?	\$	704.00 ?
28	REAR WINDSCREEN PRIMER re	2 \$	37.00 ✓
29	REAR QUARTER GLASS LH / RH ?	2 \$	1,004.00 ?
30	REAR QUARTER TRIM STRIPS REAR LH / RH 2 re	2 \$	776.00 ✓
31	REAR QUARTER GLASS CLIPS re	8 \$	104.00 ✓
32	REAR LID TRIM PANEL ?	\$	273.00 ? OK ✓
33	REAR CROSS PANEL TRIM ?	\$	135.00 ?
34	LED TAILLIGHT OUTER LH / RH cracked	2 \$	1,460.00 ✓
35	TAILLIGHT TRIM LH / RH Cracked ?	2 \$	52.00 4000? Cut ✓
36	LED TAILLIGHT INNER LH / RH cracked	2 \$	1,460.00 ✓
37	TAILLIGHT TRIM LH / RH ?	2 \$	52.00 ? Cut ✓
38	NO PLATE Bent	S/N \$	25.00 ✓
39	ACYRLIC SEALER } re	S/N \$	360.00 ✓
40	CAVITY WAX	S/N \$	280.00 ✓
SUB PARTS CHARGES		:	<u>\$ 11,053.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
41	STONE CHIP	S/N \$ 360.00	✓
42	METAL FILLER POWDER	S/N \$ 560.00	✓
43	REAR WINDSCREEN SEALANT	S/N \$ 200.00	✓
44	1/4 GLASS SEALANT	S/N \$ 200.00	✓
45	SUNDRIES	\$ 500.00	?
TOTAL SPARE PARTS		: \$ 19,818.00	
TOTAL LABOUR CHARGES		: \$ 19,452.00	
GRAND TOTAL		: \$ 39,270.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0923/2018/nk
Date : 13-Aug-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Adrian
24 days - ok - /b - 12 Nov 18

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Chok Yee Tin Regina
Address : 21 Lorong Lew Lian
#03-03
Singapore 536467
Telephone : HP +65 98155489
Type of Claim : Own Damage claims
Policy No. : 1700061930
Vehicle No : **SLT 4436 C**
Model Code : Audi A3 SEDAN 1.0 TFSI QU
Model / Year : Oct-17
Engine No : CHZ 562767
Chassis No : WAUZZZ8V0J1017472
Mileage :
Date In : 13-Aug-18
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Aug-18
Place of Accident : Hotel Royal @ Queens

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 4436 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	\$ 280.00
2	To renew both 1/4 glass and rear windscreen to facilitate fender renewal.	S/N \$	900.00	\$ 900.00
3	To remove and transfer rear lid's convenience lock sytem, wire harness for taillights and rear wiper assy.	S/N \$	480.00	\$ 480.00
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$	1,400.00	\$ 1,400.00
5	To remove and reinstall rear seat, back rest , hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$	1,400.00	\$ 1,400.00
SUB LABOUR CHARGES		:	<u>\$ 4,460.00</u>	<u>\$ 4,460.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLT 4436 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
			\$ 4,460.00
6	To dismantle and renew rear bumper and rear lid. Cut out and reweld both side rear fender. Reorganise rear crash managements components. Reinstall all parts removed. <i>(With rear lid/rr bumper replaced - added \$500.00)</i>	\$ 7,800.00	\$ 6,500.00
7	To respray rear bumper, rear lid, both side rear fender, sill panel, rear lid hinges, drain panel, roof channel, door entrances and end panelling. To carry out stone chip treatment and joint sealer works.	\$ 7,000.00	\$ 3,850.00
8	<i>Added labour charges - see attached</i>	\$ 4,000.00	\$ 2,500.00
9	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
	SUB LABOUR CHARGES	: \$ 23,452.00	\$ 17,502.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER	\$ 1,697.00	\$ 1,357.60
2	REAR BUMPER FIXING PARTS	\$ 166.00	
3	REAR ADAPTER WHEEL HOUSING LINERS LH / RH	2 \$ 64.00	
4	REAR BUMPER GUIDE SECTION LH / RH	2 \$ 28.00	
5	REAR BUMPER LOCKING MECHANISM	2 \$ 50.00	
6	REAR BUMPER SPOILER	\$ 206.00	
7	REAR BUMPER LIGHT REFLECTOR LH / RH	2 \$ 70.00	
8	REAR RENFORCEMENT BEAM	\$ 501.00	
9	REAR BUMPER BRACKET LH / RH	2 \$ 47.00	
10	REAR BUMPER GUIDE SECTION LH / RH	2 \$ 114.00	
11	REAR SENSOR INNER / OUTER	2 \$ 421.00	
12	REAR BUMPER SEAL RING	4 \$ 14.00	
13	REAR LID	\$ 2,310.00	\$ 1,848.00
14	REAR LID ATTACHEMENTS PARTS	\$ 253.00	\$ 113.85
15	REAR LID HINGES LH / RH	2 \$ 448.00	\$ 358.40
16	REAR LID GASKET	\$ 176.00	\$ 140.40
17	REAR LID LOCK STRIKER	\$ 44.00	
18	REAR LID LOCK	\$ 170.00	\$ 136.00
19	REAR LID LOCK COVER	\$ 7.00	
20	PUSH BUTTON FOR LID LOCK	\$ 159.00	
SUB- TOTAL SPARE PARTS		\$ 6,945.00	\$ 3,954.25

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
			\$	3,954.25
		c/f		
21	STOP BUFFER	2 \$	30.00	
22	PACKING ADHESIVE	\$	15.00	\$ 11.60
23	AUDI LOGO	\$	108.00	\$ 86.00
24	A3' CHROME EMBLEM	\$	83.00	\$ 66.16
25	TFSI' CHROME EMBLEM	\$	83.00	\$ 66.16
26	SECTIONAL PART LH / RH	2 \$	4,012.00	\$ 3,209.60
27	REAR WINDSCREEN	\$	704.00	\$ 563.20
28	REAR WINDSCREEN PRIMER	2 \$	37.00	\$ 29.12
29	REAR QUARTER GLASS LH / RH	2 \$	1,004.00	\$ 802.40
30	REAR QUARTER TRIM STRIPS REAR LH / RH	2 \$	776.00	
31	REAR QUARTER GLASS CLIPS	8 \$	104.00	
32	REAR LID TRIM PANEL	\$	273.00	\$ 218.40
33	REAR CROSS PANEL TRIM	\$	135.00	\$ 107.60
34	LED TAILLIGHT OUTER LH / RH	2 \$	1,460.00	\$ 1,168.00
35	TAILLIGHT TRIM LH / RH	2 \$	52.00	
36	LED TAILLIGHT INNER LH / RH	2 \$	1,460.00	\$ 1,168.00
37	TAILLIGHT TRIM LH / RH	2 \$	52.00	
38	NO PLATE	S/N \$	25.00	\$ 25.00
39	ACYRLIC SEALER	S/N \$	360.00	\$ 360.00
40	CAVITY WAX	S/N \$	280.00	\$ 280.00
	SUB PARTS CHARGES	:	\$ 11,053.00	\$ 12,115.49

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLT 4436 C

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
			\$	12,115.49
41	STONE CHIP	S/N	\$ 360.00	\$ 360.00
42	METAL FILLER POWDER	S/N	\$ 560.00	\$ 560.00
43	REAR WINDSCREEN SEALANT	S/N	\$ 200.00	\$ 200.00
44	1/4 GLASS SEALANT	S/N	\$ 200.00	\$ 200.00
45	Added parts - see attached		\$ 3,707.00	\$ 2,959.60
47	SUNDRIES		\$ 500.00	\$ 158.55
	TOTAL SPARE PARTS	:	\$ 23,525.00	\$ 16,553.64
	TOTAL LABOUR CHARGES	:	\$ 23,452.00	\$ 17,502.00
	GRAND TOTAL	:	\$ 46,977.00	\$ 34,055.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0923/2018/NK 23-Aug-18 CHANG 1 of 1 SLT 4436 C Audi A3 SEDAN 1.0 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	To cut out and weld rear outer, inner rear end panels and connecting plates. Repair lhs rear D-pillar reinforcement.	\$ 2,700.00	\$ 2,000.00
2	To retrofit rear lid reverse camare. S/N	\$ 1,300.00	\$ 500.00
Parts		\$ 4,000.00	\$ 2,500.00
1	REAR LID RETAINER FOR WARNING TRIANGLE	\$ 51.00	\$ 40.48
2	REAR LID ANTI-THEFT GUARD COVER	\$ 30.00	\$ 23.92
3	REAR LID HINGE COVER - LH/RH	\$ 14.00	\$ 10.88
4	REAR LID CABLE GUIDE	\$ 61.00	\$ 48.16
5	REAR LID CLOSING ELEMENT	\$ 54.00	\$ 42.72
6	REAR CROSS PANEL - OUTER	\$ 317.00	\$ 253.60
7	REAR CROSS PANEL REINFORCEMENT - INNER	\$ 645.00	\$ 515.60
8	REAR CROSS PANEL CONNECTING PLATE - LH/RH	\$ 252.00	\$ 201.60
9	REAR LID LED LICENCE PLATE LIGHT	\$ 187.00	\$ 149.28
10	REAR END PANEL WELD SCREW SET	\$ 26.00	\$ 20.72
11	REAR LID STOP BUFFER	\$ 30.00	\$ 20.64
12	Reverse camera <i>Dayd</i>	\$ 688.00	\$ 550.40
13	Luggage compt cover LHS/RHS <i>Rehand.</i>	\$ 1,352.00	\$ 1,081.60
MATERIALS		\$ 3,707.00	\$ 2,959.60
LABOUR		\$ 4,000.00	\$ 2,500.00
LABOUR :		\$ 7,707.00	\$ 5,459.60

For Premium Automobiles Pte Ltd

Adrian Ling
sls

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLT 4436 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0923/2018/MAS

15 May 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLT 4436 C, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no. **SLT 4436 C**, claimant, **Ms. Chok Yee Tin Regina**, please find the related document per attached.

1. A copy of the Original invoice no. 85013737 – S\$35,797.53
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLT 4436 C

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119838
Main Telephone: 6386 2223
Main Telefax: 6471 3735

Alexandre Service Centre
281 Alexandra Road
Singapore 119838
Telephone: 6386 2223
Telefax: 6471 3735

Ubi Service Centre
55 Ubi Road 1
Singapore 408723
Telephone: 6386 2223
Telefax: 6471 3735

Customer Service
Service Appointment
Your Breakdown Service
Email: customers.care@premiumauto.com.sg

6366 2323
9828 1235

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 1 10:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013737 Date : 07/05/2019 Order : SLT4436C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLT4436C (V 35645)	Regn Date: 30/10/2017	Mileage: 3030	WIP No.: 20910
Model: A3 SEDAN 1.0 TFSI 8VWANG	Chassis: WAUZZZ8V0J1017472	Engine: CHZ 562767	Dept: U
VS8 No.:			
You have been assisted by :- UB-Jiayee (87)			

		Details	Qty	Unit Price	Amount
S	SUBLET	N: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	N: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	N: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	280.00	1.00	280.00
S	BODYWORK	N: TO RENEW BOTH 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL	900.00	1.00	900.00
S	BODYWORK	N: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAILLIGHT AND REAR WIPER ASSY.	480.00	1.00	480.00
S	BODYWORK	N: TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	1400.00	1.00	1,400.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6828 1238

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 2 10:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013737 Date : 07/05/2019 Order : SLT4436C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLT4436C (V 35645) Regn Date: 30/10/2017 Mileage: 3830 WIP No.: 20910
Model: A3 SEDAN 1.0 TFSI 8VWANG Chassis: WAUZZZ8V0J1017472 Engine: CHZ 562767 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS, DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID, CUT OUT AND REMELD BOTH SIDE REAR FENDER, REORGANISE REAR CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	6500.00	1.00	6,500.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER, REAR LID, BOTH SIDE REAR FENDER, SILL PANEL, ROOF CHANNEL AND END PANELLING, TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS	3850.00	1.00	3,850.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M:	1960.00	1.00	1,960.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6336 2223
Main Telex: 6471 2133

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6336 2223
Telex: 6471 2133

Ubi Service Centre
55 Ubi Road 1
Singapore 408713
Telephone: 6188 2713

Customer Service
Service Appointment
Service Breakdown Service
(Email)

6336 2233
6336 1233
customer.care@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 3 10:37

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013737
Date : 07/05/2019
Order : SLT4436C
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLT4436C (V 35645) Regn Date: 30/10/2017 Mileage: 3030 WIP No.: 20910
Model: A3 SEDAN 1.0 TFSI 8VWANG Chassis: WAUZZZ8V0J1017472 Engine: CHZ 562767 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (87)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO SUPPLY ACRYLIC SEALER, CAVITY WAX, STONE CHIP, METAL FILLER POWDER, REAR WINDSCREEN SEALANT AND 1/4 GLASS SEALANT M:	2000.00	1.00	2,000.00
S	BODYWORK	TO CUT OUT AND WELD REAR OUTER, INNER REAR END PANELS AND CONNECTING PLATES, REPAIR LHS REAR D-PILLAR REINFORCEMENT M:	500.00	1.00	500.00
X	A0V59452568	TO RETROFIT REAR LID REVERSE CAMARE (AIR) (SK) TRIM (21/00/	1.00	25.10	20.00
X	A0V5863887ANCA9	006407/ (VOR) (GER) LIN	1.00	676.00	540.80
X	A0V5863888K CA9	006407/ (VOR) (GER) LIN	1.00	676.00	540.80
X	A0V5827569	006407/ (VOR) (GER) ANT	1.00	29.90	23.92
X	A0V5827377A	(SK) STOP	2.00	6.10	9.76
X	A0V5827310	(AIR) (SK) CLIP (21/00/	2.00	1.30	2.00
X	A0V5971821	006407/ (VOR) (GER) CON	2.00	30.10	48.16
X	A0V5827207	006431/ (V) (B) PLATE (0	2.00	26.70	42.72
X	A0V5809838	SUBPART	1.00	2006.00	1,604.80
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2222
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2222
Telefax: 6471 3733

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6888 2333
Telefax: 6888 2333

Customer Service
Service Appointment
Your Breakdown Service
Email: customer.care@premiumauto.com.sg

6346 2222
6828 1218

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 4 10:37

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013737
Date : 07/05/2019
Order : SLT4436C
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLT4436C (V 35645)

Regn Date: 30/10/2017

Mileage: 3030

WIP No.: 20910

Model: A3 SEDAN 1.0 TFSI 8VWANG

Chassis: WAUZZZ8V0J1017472

Engine: CHZ 562767

Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee

(87)

		Details		Qty	Unit Price	Amount
X	ABV5809837	SUBPART (FRIDAY-SEA)	Less 020%	1.00	2006.00	1,604.00
X	ABV5945091	TAIL LIGHT	Less 020%	1.00	730.00	584.00
X	ABV5945092	TAIL LIGHT	Less 020%	1.00	730.00	584.00
X	ABV59450930	TAIL LIGHT	Less 020%	1.00	730.00	584.00
X	ABV59450940	TAIL LIGHT	Less 020%	1.00	730.00	584.00
X	ABV5845297K NVB	SIDE WINDO	Less 020%	1.00	501.50	401.20
X	ABV5845298K NVB	SIDE WINDO	Less 020%	1.00	501.50	401.20
X	ABV5827025F	LID	Less 020%	1.00	2310.00	1,848.00
X	ABV5827705E	WTHRSTRIP	Less 020%	1.00	175.50	140.40
X	ABV58679756 CA9	(AIR) (SK) TRIM PANEL (	Less 020%	1.00	273.00	218.40
X	ABV5813331TB	REINFORCEM	Less 020%	1.00	644.50	515.60
X	ABV5813307	REAR APRON	Less 020%	1.00	317.00	253.60
X	ABV5845501E NVB	REARWINDOW	Less 020%	1.00	704.00	563.20
X	ABV5807067G GRU	COVER	Less 020%	1.00	1697.00	1,357.60
X	AN 10261501	FUSE (5A) SMALL (REQ1)	Less 020%	1.00	1.80	1.44
X	A000979950	TAPE	Less 020%	1.00	15.40	12.32
X	ZT-09	A38V PA CABLE SET	Less 020%	1.00	65.00	52.00
X	ZT-10	A38V PA REVERSE CAME	Less 020%	1.00	688.00	550.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 3733

Uti Service Centre
55 Uti Road 1
Singapore 159938

Customer Service
Service Appointment
Your Breakdown Service
Email: customerscare@premiumauto.com.sg

6386 2223
9828 1235

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 10:37

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013737
Date : 07/05/2019
Order : SLT4436C
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLT4436C (V 35645)

Regn Date: 30/10/2017

Mileage: 3830

WIP No.: 20910

Model: A3 SEDAN 1.0 TFSI 8VWANG

Chassis: WAUZZZ8V0J1017472

Engine: CHZ 562767

Dept: U

VS0 No.:

You have been assisted by :- UB-Jiayee

(87)

		Details		Qty	Unit Price	Amount
X	ABV5807975A	CATCH	Less 020%	2.00	24.90	39.84
X	ABV5807571A	GUIDE	Less 020%	1.00	13.40	10.72
X	ABV5807572A	GUIDE	Less 020%	1.00	13.40	10.72
X	ABX0853737A 222	INSCRIPTION 'TFSI'	Less 020%	1.00	82.70	66.16
X	ABP0853741 222	INSCRIPTION 'A3'	Less 020%	1.00	82.70	66.16
X	ABV7853742 222	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	ABV5827301C	HINGE	Less 020%	1.00	224.00	179.20
X	ABV5827302C	HINGE	Less 020%	1.00	224.00	179.20
X	A4H0827520	COVER	Less 020%	1.00	6.10	4.88
X	A4G0827127	006407/(V0R) (BER) STD	Less 020%	2.00	2.60	4.16
X	A4H0827505A	LATCH	Less 020%	1.00	170.00	136.00
X	ABX0827499	BUFFER	Less 020%	2.00	15.00	24.00
X	ABV5827374	STOP	Less 020%	1.00	6.10	4.88
X	ABV5827232	COVER(AIR) (SK) (21/08)	Less 020%	1.00	6.80	5.44
X	ABV5827373	STOP	Less 020%	1.00	6.10	4.88
X	ABD0853419F	PACKING	Less 020%	1.00	14.50	11.60
X	ABV5827231 989	COVER	Less 020%	1.00	6.80	5.44
X	ABT0827310A	(AIR(SK)) CLIP (21/08/	Less 020%	2.00	1.30	2.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159038
Main Telephone: 6806 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159038
Telephone: 6806 2223
Telefax: 6471 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408733
Telephone: 6886 2333

Customer Service
Service Appointment
Breakdown Service
Email: customers.care@premiumauto.com.sg

6366 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 6 10:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013737 Date : 07/05/2019 Order : SLT4436C Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLT4436C (V 35645)	Regn Date: 30/10/2017	Mileage: 3030	WIP No.: 20910
Model: A3 SEDAN 1.0 TFSI BVMANG	Chassis: WAUZZZ8V0J1017472	Engine: CHZ 562767	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (07)			

		Details		Qty	Unit Price	Amount
X	A0K9805673C	SPEED NUT	Less 020%	4.00	1.10	3.52
X	A0P4627951A	PLUG	Less 020%	2.00	1.70	2.72
X	A4G5827797	STOP	Less 020%	2.00	4.20	6.72
X	A0T0660285	(AIR) (SK) BRACKET (21/	Less 020%	1.00	50.60	40.48
X	A5M943021	(AIR) (SK) LIC PL LIG	Less 020%	2.00	93.30	149.28
X	A0V5945255B	TRIM	Less 020%	1.00	25.10	20.08
X	AD 00920002	PRIMER (DG)	Less 020%	2.00	18.20	29.12
X	A0V5945253B	TRIM	Less 020%	1.00	25.10	20.08
X	A0V5945254B	TRIM	Less 020%	1.00	25.10	20.08
X	A0V5863471A 4PK	TRIM	Less 020%	1.00	134.50	107.60
X	A0V5813543	PLATE	Less 020%	1.00	126.00	100.80
X	A0V5813544	PLATE	Less 020%	1.00	126.00	100.80
X	AN 91029902	(AIR) (SK) BOLT (21/00/	Less 020%	10.00	1.10	8.80
X	AN 90945402	BOLT	Less 020%	3.00	1.30	3.12
X	AN 91017602	BOLT	Less 020%	10.00	1.10	8.80

Parts 14,568.64	Sub-Total	33,455.64
Labour 0.00	7% GST	2,341.89
Sublet 19,467.00	Grand Total	35,797.53
Menus 0.00		
Lubricant 0.00		



8/5

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLT 4436 C

Norah Khai
6768 9828
6841 1183

Body Repair
PA/OD/0923/2018/GW
11 September 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 Sedan 1.0 TFSI S Tronic
Vehicle Chassis No. : WAUZZZ8V0J1017472
Vehicle Regn No. : SLT 4436 C
Vehicle Mileage : 3029 KM
Vehicle Owner : M^S Chok Yee Tin Regina (Zhou YuTing Regina)
Certificate No : 1700061930
Policy Excess : S\$642.00 (Inclusive GST)
Accident Date : 11 of August 2018
Place : Hotel Royal & Queens
Repair Cost : \$ 35,797.53
WIP No. : 20910
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 5/09/18
Date : 1000

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : CHOK YEE TIN REGINA (ZHUO YUTING REGINA)
 Period of Insurance : 30 Oct 2017 To 29 Oct 2018
 Engine No. : CHZ562767
 Chassis No. : WAUZZZ8V0J1017472

Vehicle No. : SLT4436C
 Policy No. : 1700051930
 Endorsement No. :
 Issued Date : 30 Oct 2017

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
 Engine Capacity/Tonnage : 999.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2017
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

*You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 160) and Section 85 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

CHOK YEE TIN REGINA (ZHUO YUTING REGINA) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408559 53562323

For other Approved Reporting Centres/Audited Repairers, please contact our 24-hour accident emergency hotline at +65 6338 5200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 160), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

6504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

Cheng Sian Yee

3582847

NRIC No: S8015302C



21 LORONG LEE LIAN A03-03
SINGAPORE 530467

NRIC No: S8015302C Date: 18/07/2015

Place of Birth: 11-08-2003

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 2 Motor Cars and Motor Tractors the weight of which (unladen does not exceed 2000 kilograms)

15 Dec 2001

Place of Birth: 11-08-2003

License No: S8015302C

NR 428A

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8015302C



CHOK YEE TIN REGINA
(ZHUO YUTING REGINA)

Chinese: 卓玉婷

Chinese: CHINESE

Date of Birth: 30-05-1980

Gender: F

Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE

DRIVING LICENCE:



License Number: S8015302C

CHOK YEE TIN REGINA
(ZHUO YUTING REGINA)

Date of Issue: 30 May 1990

Valid Until: 19 Jul 2003

008662469F

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Aug 2018 17:06		14 Aug 2018 15:06 Edit Adj Rpt	\$34,055.64 Edit Estimates	\$34,055.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CHOK YEE TIN REGINA (ZHOU YUTING REGINA) , ID: S8015302C, Tel: +6598155489								
Vehicle Reg. No.:	SLT4436C	Date of Loss:	11/08/2018 12:00 - :59 [9 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 8457245690SG	Policy/Cover Note No.:	1700061930 (Comprehensive)						
		Excess:	\$600.00						
Repaire:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 24/08/2018]								
Driver/Custodian:	CHOK YEE TIN REGINA (ZHOU YUTING REGINA) (38 / Female) , NRIC: S8015302C, Tel: +6598155489 Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (16/04/2019): Alert - Adj Mandate Approved (\$34055.64) - SLT4436C - Claim Handler: Dally Amri... - AIG_SG (28/03/2019): Alert - Adj Mandate Maintained - SLT4436C - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (31/01/2019): Consistency of the supplementary parts. - AIG_SG (31/01/2019): Alert - Adj Mandate Maintained - SLT4436C - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (07/09/2018): Alert - Adj Mandate Maintained - SLT4436C - Claim Handler: Dally Amri, Mimi Zari... - AIG_SG (15/08/2018): Alert - Adj Mandate Approved (\$28903.00) - SLT4436C - Claim Handler: Dally Amri... - AIG_SG (15/08/2018): SLT4436C / OD / 11/08/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT4436C (8457245690SG)

OD

Aug 11 2018 12:30PM

[CHOK YEE TIN REGINA (ZHOU YUTING REGINA)]

Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser	
Assessment Reports														1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	14/08/18 17:15	Adjuster Immediate Advice												Load HTM		
2	30/08/18 14:47	Adjuster Immediate Advice												Load HTM		
3	21/12/18 14:42	Adjuster Immediate Advice												Load HTM		
Photos/Images														3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print	
1	14/08/18 17:02	General View												Load JPG	☒	
2	14/08/18 17:02	Chassis Number												Load JPG	☒	
3	14/08/18 17:02	General View												Load JPG	☒	
4	14/08/18 17:02	General View												Load JPG	☒	
5	14/08/18 17:02	General View												Load JPG	☒	
6	14/08/18 17:02	General View												Load JPG	☒	
7	14/08/18 17:02	General View												Load JPG	☒	
8	14/08/18 17:02	General View												Load JPG	☒	
9	14/08/18 17:02	General View												Load JPG	☒	
10	14/08/18 17:02	General View												Load JPG	☒	
11	14/08/18 17:02	General View												Load JPG	☒	
12	14/08/18 17:02	General View												Load JPG	☒	
13	14/08/18 17:02	General View												Load JPG	☒	
14	14/08/18 17:02	General View												Load JPG	☒	
15	14/08/18 17:02	General View												Load JPG	☒	
16	14/08/18 17:02	General View												Load JPG	☒	
17	14/08/18 17:02	General View												Load JPG	☒	
18	14/08/18 17:02	General View												Load JPG	☒	
19	14/08/18 17:02	General View												Load JPG	☒	
20	14/08/18 17:02	General View												Load JPG	☒	
21	14/08/18 17:02	General View												Load JPG	☒	
22	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
23	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
24	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
25	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
26	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
27	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
28	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
29	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
30	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
31	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
32	30/08/18 14:43	Reinspection Photo												Load JPG	☒	
33	30/08/18 14:43	Reinspection Photo												Load JPG	☒	

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	30/08/18 14:43	Reinspection Photo		☒
35	30/08/18 14:43	Reinspection Photo		☒
36	30/08/18 14:43	Reinspection Photo		☒
37	30/08/18 14:43	Reinspection Photo		☒
38	30/08/18 14:43	Reinspection Photo		☒
39	30/08/18 14:43	Reinspection Photo		☒
40	30/08/18 14:43	Reinspection Photo		☒
41	30/08/18 14:43	Reinspection Photo		☒
42	30/08/18 14:43	Reinspection Photo		☒
43	30/08/18 14:43	Reinspection Photo		☒
44	30/08/18 14:43	Reinspection Photo		☒
45	30/08/18 14:43	Reinspection Photo		☒
46	30/08/18 14:43	Reinspection Photo		☒
47	30/08/18 14:43	Reinspection Photo		☒
48	30/08/18 14:43	Reinspection Photo		☒
49	30/08/18 14:43	Reinspection Photo		☒
50	30/08/18 14:43	Reinspection Photo		☒
51	30/08/18 14:43	Reinspection Photo		☒
52	30/08/18 14:43	Reinspection Photo		☒
53	30/08/18 14:43	Reinspection Photo		☒
54	30/08/18 14:43	Reinspection Photo		☒
55	30/08/18 14:43	Reinspection Photo		☒
56	30/08/18 14:43	Reinspection Photo		☒
57	30/08/18 14:43	Reinspection Photo		☒
58	30/08/18 14:43	Reinspection Photo		☒
59	30/08/18 14:43	Reinspection Photo		☒
60	30/08/18 14:43	Reinspection Photo		☒
61	30/08/18 14:43	Reinspection Photo		☒
62	30/08/18 14:43	Reinspection Photo		☒
63	30/08/18 14:43	Reinspection Photo		☒
64	30/08/18 14:43	Reinspection Photo		☒
65	30/08/18 14:43	Reinspection Photo		☒
66	30/08/18 14:43	Reinspection Photo		☒
67	30/08/18 14:43	Reinspection Photo		☒
68	30/08/18 14:43	Reinspection Photo		☒
69	30/08/18 14:43	Reinspection Photo		☒
70	30/08/18 14:43	Reinspection Photo		☒
71	30/08/18 14:43	Reinspection Photo		☒
72	30/08/18 14:43	Reinspection Photo		☒
73	30/08/18 14:43	Reinspection Photo		☒
74	30/08/18 14:43	Reinspection Photo		☒
75	10/04/19 13:48	Reinspection Photo		☒
76	10/04/19 13:48	Reinspection Photo		☒
77	10/04/19 13:48	Reinspection Photo		☒
78	10/04/19 13:48	Reinspection Photo		☒
79	10/04/19 13:48	Reinspection Photo		☒
80	10/04/19 13:48	Reinspection Photo		☒
81	10/04/19 13:48	Reinspection Photo		☒
82	10/04/19 13:48	Reinspection Photo		☒
83	10/04/19 13:48	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	10/04/19 13:48	Reinspection Photo		Load JPG ☒
85	10/04/19 13:48	Reinspection Photo		Load JPG ☒
86	10/04/19 13:48	Reinspection Photo		Load JPG ☒
87	10/04/19 13:48	Reinspection Photo		Load JPG ☒
88	10/04/19 13:48	Reinspection Photo		Load JPG ☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/08/18 17:01	Singapore Accident Statement		Load PDF
2	14/08/18 17:01	Certificate of Insurance		Load PDF
3	14/08/18 17:01	Driver's Driving License		Load PDF
4	14/08/18 17:01	ESTIMATE		Load PDF
5	30/08/18 14:42	SUPPLEMENTARY LIST		Load PDF
6	21/12/18 14:43	REVISED ESTIMATE		Load PDF
7	21/12/18 14:43	REVISED SUPPLEMENTARY LIST 1		Load PDF
8	21/12/18 14:43	SUPPLEMENTARY LIST 2		Load PDF
9	17/05/19 11:19	Workshop Invoice		Load PDF
10	17/05/19 11:19	Discharge Voucher		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/08/18 11:28	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/08/18 11:21	Accident Photo		Load JPG ☒
2	13/08/18 11:21	Accident Photo		Load JPG ☒
3	13/08/18 11:21	Accident Photo		Load JPG ☒
4	13/08/18 11:21	Accident Photo		Load JPG ☒
5	13/08/18 11:21	Accident Photo		Load JPG ☒
6	13/08/18 11:21	Accident Photo		Load JPG ☒
7	13/08/18 11:21	Accident Photo		Load JPG ☒
8	13/08/18 11:21	Accident Photo		Load JPG ☒
9	13/08/18 11:21	Accident Photo		Load JPG ☒
10	13/08/18 11:22	Accident Photo		Load JPG ☒
11	13/08/18 11:22	Accident Photo		Load JPG ☒
12	13/08/18 11:23	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/08/18 09:58	Sketch Plan		Load JPG ☒
2	13/08/18 09:58	Sketch Plan #2		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG18014731/AQBE2

Date: 17/05/2019

REFERENCE

Insured/Claimant: CHOK YEE TIN REGINA (ZHOU YUTING REGINA)

Policy No: 1700061930

Date of Loss: 11/08/2018

Nature of Claim: OD Claim No: 8457245690SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT4436C**
Make & Model: AUDI A3, 999cc TFSI (A) Engine No: CHZ562767
Reg. Date: 30/10/2017 (Man. Year: 2017) Chassis No: WAUZZZ8V0J1017472
Colour: Red Odometer: 3027 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$105,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,777.60	16,553.64	6,223.96	27.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	23,452.00	17,502.00	5,950.00	25.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	46,229.60	34,055.64	12,173.96	26.33
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	45,629.60	33,455.64	12,173.96	26.68
+ GST 7.00/7.00% (S\$)	3,194.07	2,341.89	852.18	26.68
Nett Amount (S\$)	48,823.67	35,797.53	13,026.14	26.68

INSPECTION

Date of Assignment: 14/08/2018

Date Inspected: 14/08/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 24.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Deformed	1,697.00 FS	*1,357.60 FS
2	1	*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
3	2	*REAR ADAPTER WHEEL HOUSING LINERS LH/RH	Not Necessary	64.00 FS	*- FS
4	2	*REAR BUMPER GUIDE SECTION - LH/RH	Not Necessary	28.00 FS	*- FS
5	2	*REAR BUMPER LOCKING MECHANISM	Not Necessary	50.00 FS	*- FS
6	1	*REAR BUMPER SPOILER	Not Necessary	206.00 FS	*- FS
7	2	*REAR BUMPER LIGHT REFLECTOR LH/RH	Not Necessary	70.00 FS	*- FS
8	1	*REAR REINFORCEMENT BEAM	Not Necessary	501.00 FS	*- FS
9	2	*REAR BUMPER BRACKET LH/RH	Not Necessary	47.00 FS	*- FS
10	2	*REAR BUMPER GUIDE SECTION - LH/RH	Not Necessary	114.00 FS	*- FS
11	2	*REAR SENSOR INNER / OUTER	Not Necessary	421.00 FS	*- FS
12	4	*REAR BUMPER SEAL RING	Not Necessary	14.00 FS	*- FS
13	1	*REAR LID	Distorted	2,310.00 FS	*1,848.00 FS
14	1	*REAR LID ATTACHMENT PARTS	Necessary	253.00 FS	*113.85 FS
15	2	*REAR LID HINGE - LH/RH	Bent	448.00 FS	*358.40 FS
16	1	*REAR LID GASKET	Necessary	176.00 FS	*140.40 FS
17	1	*REAR LID LOCK STRIKER	Not Necessary	44.00 FS	*- FS
18	1	*REAR LID LOCK	Jammed	170.00 FS	*136.00 FS
19	1	*REAR LID LOCK COVER	Not Necessary	7.00 FS	*- FS
20	1	*PUSH BUTTON FOR LID LOCK	Not Necessary	159.00 FS	*- FS
21	2	*STOP BUFFER	Not Necessary	30.00 FS	*- FS
22	1	*PACKING ADHESIVE	Necessary	15.00 FS	*11.60 FS
23	1	*AUDI LOGO	Necessary	108.00 FS	*86.00 FS
24	1	*A3 CHROME EMBLEM	Necessary	83.00 FS	*66.16 FS
25	1	*TFSI CHROME EMBLEM	Necessary	83.00 FS	*66.16 FS
26	2	*SECTIONAL PART LH/RH	Dented	4,012.00 FS	*3,209.60 FS
27	1	*REAR WINDSCREEN	Necessary	704.00 FS	*563.20 FS
28	2	*REAR WINDSCREEN PRIMER	Necessary	37.00 FS	*29.12 FS
29	2	*REAR QUARTER GLASS LH/RH	Necessary	1,004.00 FS	*802.40 FS
30	2	*REAR QUARTER TRIM STRIPS REAR LH/RH	Not Necessary	776.00 FS	*- FS
31	8	*REAR QUARTER GLASS CLIPS	Not Necessary	104.00 FS	*- FS
32	1	*REAR LID TRIM PANEL	Deformed	273.00 FS	*218.40 FS
33	1	*REAR CROSS PANEL TRIM	Deformed	135.00 FS	*107.60 FS
34	2	*LED TAILLIGHT OUTER - LH/RH	Cracked	1,460.00 FS	*1,168.00 FS
35	2	*TAILLIGHT TRIM - LH/RH	Not Necessary	52.00 FS	*- FS
36	1	*NO PLATE	Bent	25.00 FS	*25.00 FS
37	1	*ACRYLIC SEALER	Necessary	360.00 FS	*360.00 FS
38	1	*CAVITY WAX	Necessary	280.00 FS	*280.00 FS
39	2	*LED TAILLIGHT INNER - LH/RH	Cracked	1,460.00 FS	*1,168.00 FS
40	2	*TAILLIGHT TRIM - LH/RH	Not Necessary	52.00 FS	*- FS
41	1	*STONE CHIP	Necessary	360.00 FS	*360.00 FS
42	1	*METAL FILLER POWDER	Necessary	560.00 FS	*560.00 FS
43	1	*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
44	1	*1/4 GLASS SEALANT	Necessary	200.00 FS	*200.00 FS
45	1	*SUNDRIES	Necessary	500.00 FS	*158.55 FS
46	1	*REAR LID RETAINER FOR WARNING TRIANGLE	Deformed	40.48 FS	*40.48 FS
47	1	*REAR LID ANTI-THEFT GUARD COVER	Deformed	23.92 FS	*23.92 FS
48	2	*REAR LID HINGE COVER - LH/RH	Cut	10.88 FS	*10.88 FS
49	2	*REAR LID CABLE GUIDE	Cut	48.16 FS	*48.16 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*REAR LID CLOSING ELEMENT	Deformed	42.72 FS	*42.72 FS
51	1		*REAR CROSS PANEL - OUTER	Dented	253.60 FS	*253.60 FS
52	1		*REAR CROSS PANEL REINFORCEMENT - INNER	Bent	515.60 FS	*515.60 FS
53	2		*REAR CROSS PANEL CONNECTING PLATE - LH/RH	Necessary	201.60 FS	*201.60 FS
54	2		*REAR LID LED LICENCE PLATE LIGHT	Cracked / Missing	149.28 FS	*149.28 FS
55	1		*REAR END PANEL WELD SCREW SET	Necessary	20.72 FS	*20.72 FS
56	3		*REAR LID STOP BUFFER	Necessary	20.64 FS	*20.64 FS
57	1		*REVERSE CAMERA	Damaged	550.40 FS	*550.40 FS
58	1		*LUGGAGE COMPT COVER LHS/RHS	Deformed	1,081.60 FS	*1,081.60 FS
Total Parts (S\$)					22,777.60	16,553.64

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	New	280.00	280.00
2	TO RENEW BOTH 1/4 GLASS AND REAR WINDSCREEN TO FACILITATE FENDER RENEWAL.	New	900.00	900.00
3	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM, WIRE HARNESS FOR TAILLIGHTS AND REAR WIPER ASSY.	New	480.00	480.00
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	New	1,400.00	1,400.00
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	New	1,400.00	1,400.00
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND REWELD BOTH SIDE REAR FENDER. REORGANISE REAR CRASH MANAGERMENTS COMPONENTS. REINSTALL ALL PARTS REMOVED.	New	7,800.00	6,500.00
7	TO RESPRAY REAR BUMPER, REAR LID, BOTH SIDE REAR FENDER, SILL PANEL, REAR LID HINGES, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES AND END PANELLING. TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.	New	7,000.00	3,850.00
8	TO CARRY OUT DIAGNOSTIC CHECKS.	New	192.00	192.00
9	TO CUT OUT AND WELD REAR OUTER, INNER REAR END PANELS AND CONNECTING PLATES. REPAIR LHS REAR D-PILLAR REINFORCEMENT.	New	2,700.00	2,000.00
10	TO RETROFIT REAR LID REVERSE CAMERA.	New	1,300.00	500.00
Gross Labour Cost (S\$)			23,452.00	17,502.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >