

INSURANCE

INS. CASE OWNER

CC 2 / UP 4707, Kjbh

LKK
IDAC

Surveyor:

Kenneth

DOI:

ASSIGNMENT

12/8/18

Date / Time:

12/8/18

Registered in Merimen:

4/8/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SL6 5825A

Name of Insured:

UP

Insured Tel No.:

HP:

Excess Sec II : \$

D.O.A.:

6/8/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ABDUL KAHMAN BIN SAUEN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

2167746074649

Policy No.:

ANNA 5147

Make / Model:

FA

Place of Accident:

Alk G Ennos KESKENT

OI GIA REPORT (YES / NO):

YES

TP GIA REPORT (YES / NO)

YES

Insured Liability:

%

Final ? Yes / No

410 205K



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans Cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/8/18
DUN

410 205K

410 205K

REJECTED VIDEO SHOWED
TP REVERSED & HIT OUR
PARKED / STATIONARY VEH.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: EMAIL NP

Confirm by:

Email ☐ Call ☐

Email ☐ Call ☐

If NO or B 28, Ass. Lia:

TP REVERSED

COMPONENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

\$

(

days) Reduction:

%

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

NIL

Repair Cost:

\$

Loss of Rental (LOR):

\$

(

days)

VIDEO

Loss of Use (LOU):

\$

(

\$

x

days)

Loss of Income (LOI):

\$

(

\$

x

days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GLA/TA Search

\$

Medical:

\$

Disbursement:

\$

(e.g. Tow/ Independent)

Legal Cost

\$

Total:

\$

Global Sum \$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$

Name 1:

Payee 2: (Strike if N.A.)

\$

Name 2:

Payee 3: (Strike if N.A.)

\$

Name 3:

ASS. REC. BY:

REF:

A/GI

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

314D 205K

Yr Regn:

10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Renault Latitude

c.c.

1995

Colour:

M. White / A/L

A/C:

Insured / Std / NI / NA

Sp. Reading

449700

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VF1 ABL 15 AUG 28 2381

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order

Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modl:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Giti

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

6/8/18

D.O.L.

13/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14/8

File pass to Catherine
2990.94

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - R.S. \$1

Fixtures

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/LCR18014737/Kjb3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 14-08-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 5825A	Veh. Inspected	SHD 205K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/08/2018	Inspection Date	13/08/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 205K**AAD1808-031***Not Authorized*
*Resurvey B4 point**\$2990.84*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

SHD 205K

VF1ABL15AUC282381

RENAULT

LATITUDE

6.8.2018

AIG**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>By</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>pull out</i> <i>Sm</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sm</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>0.17</i> 135.97	✓
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sm</i> 44.99	} X
9	1 BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61	
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	
14	1 BOOT FINISHER	\$	<i>Sm</i> 470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>rr</i> 225.36	
19	1 BOOT BADGE	\$	<i>rr</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>Sm</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>Sm</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sm</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81	

Trans-cab Auto Services Pte Ltd

AAD1808-031

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD 205K

30	1 FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	}
31	1 WHEELARCH REAR LH	\$	<i>Sh</i>	543.47	
32	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sh</i>	671.45	
33	1 FENDER PANEL REAR RH	\$	<i>R</i>	3,299.13	
34	1 WHEELARCH REAR RH	\$	<i>Sh</i>	543.47	
35	1 TAILLAMP RH	\$	<i>Sh</i>	552.55	
36	1 TAILLAMP PANEL RH	\$	<i>R</i>	986.70	
37	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i>	1,471.77	
38	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sh</i>	404.56	
39	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	
40	1 SPARE WHEEL PANEL TRIM	\$	<i>Sh</i>	612.21	
41	1 EXHAUST REAR	\$	<i>R</i>	7,489.05	
42	1 EXHAUST CAP REAR	\$	<i>Sh</i>	230.49	
43	1 CHASSIS PANEL REAR RH	\$	<i>R</i>	3,766.43	
44	1 KUCKLE ARM REAR RH L70Y	\$	<i>Sh</i>	736.67	
45	1 BRAKE DISC REAR L70Y	\$	<i>Sh</i>	525.91	
46	1 WHEEL HUB NUT L70Y	\$	<i>Sh</i>	51.11	
47	1 WHEEL HUB CAP L70Y	\$	<i>Sh</i>	57.82	
48	1 ABS SENSOR REAR RH L70Y	\$	<i>Sh</i>	255.75	
49	1 REAR AXLE L70Y	\$	<i>Sh</i>	4,167.03	
50	1 AXLE ARM RH L70Y	\$	<i>Sh</i>	117.22	
51	1 LOWER ARM REAR RH L70Y	\$	<i>Sh</i>	905.99	
52	1 ABSORBER REAR	\$	<i>Sh</i>	389.75	
53	1 STABILIZER BAR REAR RH	\$	<i>Sh</i>	604.65	
54	1 BRAKE CALIPER REAR RH	\$	<i>Sh</i>	1,300.67	
55	1 WHEEL HOUSING PANEL REAR RH	\$	<i>R</i>	4,682.09	
56	1 CHASSIS PANEL REAR RH	\$	<i>R</i>	3,766.43	
TOTAL		\$		54,985.76	
10%		\$		5,498.58	
		\$		49,487.19	

Specical Nett

1 1SET PARKING AID	\$	<i>Shon</i>	700.00	<i>Goosa</i>
2 1SET REAR BUMPER CLIP	\$	<i>R</i>	66.00	—
3 1SET BUMPER BRACKET CTR CLIP	\$	<i>R</i>	33.00	—
4 1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>R</i>	10.00	X
5 1SET BUMPR RETAINER RH CLIP RR	\$	<i>R</i>	20.00	X
6 1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>R</i>	10.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-031

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 205K

7 1SET BUMPR RETAINER CLIP LH RR	\$	20.00	}
8 1SET BUMPER LOWER REAR RIVET	\$	22.00	
9 1SET BUMPER LOWER REAR CLIP	\$	66.00	
10 1 EXHAUST MOUNTING REAR	\$	17.82	
11 1SET BOOT FINISHER CLIP	\$	24.20	
12 1 BOOT STICKER "Trans-cab"	\$	30.00	
13 1 BOOT STICKER "6555-3333"	\$	30.00	
14 1 BOOT INNER TRIM CLIP	\$	45.00	
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	35.00	
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	35.00	
17 1 FENDER INNER TRIM CLIP LH	\$	28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	28.00	
19 1 TAILLAMP CLIP RH	\$	5.00	
20 1 TAILLAMP CLIP LH	\$	5.00	
21 2 REAR WINDSCREEN SELANT	\$	80.00	
22 1 WINDSCREEN MOULDING	\$	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	} X
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	
25 1 SPARE TYRE	\$	330.00	
26 1 RIGHT REAR TYRE	\$	330.00	
27 1 RIGHT REAR TYRE RIM	\$	380.00	

TOTAL \$ 2,935.02

TOTAL PARTS \$ 52,422.21

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	2200
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	2000
To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	600

Trans-cab Auto Services Pte Ltd**AAD1808-031**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 205K

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To transfer of rear door fittings, attachment and perform water seepage test.	\$	380.00	X

TOTAL \$ 12,540.00**Over All Total \$ 64,962.21****LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(PART-BY-PART)**Repair Days****20 DAYS****2 days**

Acknowledged by Repairer

Signature:

Date:

Joy Irene (LKKAuto)

From: Ng, Hai-Chuan <Hai-Chuan.Ng@aig.com>
Sent: Wednesday, 29 August 2018 9:50 AM
To: Vivian Lau (LKKAuto); Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: Claim No: 29633460345G

Dear all,

Video footage has been uploaded into Merimen.

Please proceed to reject the TP claim.

Thank you.

Regards,

Ng Hai Chuan
AIG
Senior Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way AIG Building #08-16 Singapore 079120

Tel +(65)6419 1994| Fax +68357416

Hai-Chuan.Ng@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Tuesday, 4 September 2018 5:28 PM
To: 'Jasmine Tan'; 'Ng Wai Yin'
Cc: Admin A; Kenneth Kong (LKKAuto)
Subject: SLG 5825A AND SHD 205K ON 06.08.2018
Attachments: Video - Accident (46).MP4

WITHOUT PREJUDICE

Dear Jasmine,

We refer to the subject.

We regret to inform you that based on video evidence (attached), we are unable to look into your claim.

Video showed your driver reversed his vehicle and hit our parked/stationary vehicle.

Best Regards,
Joy Irene | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Aug 2018 Edit Reg		13 Aug 2018 00:00 Edit Adj Rpt	S\$2,990.94 Edit Estimates	S\$2,990.94 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHD205K	Date of Loss:	06/08/2018 11:00 - :59 [34 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2963346034SG	Policy/Cover Note No.:	0999994801 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLG5825A	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ng, Hai-Chuan] Hai-Chuan.Ng@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 24/08/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHD205K (2963346034SG)
[SLG5825A]
TP
TRANS-CAB SERVICES PTE LTD
Aug 6 2018 11:00AM
[LCRF PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Video										1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	29/08/18 09:48	Video - Accident From: SC - Reg. No: SLG5825A, Claimant: LCRF PTE LTD						 Load MP4			
Assessment Reports										1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	16/08/18 09:26	Accident Statement From: SC - Reg. No: SLG5825A, Claimant: LCRF PTE LTD						 Load HTM			
Photos/Images										3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	04/09/18 17:28	General View						 Load JPG	☒		
2	04/09/18 17:28	General View						 Load JPG	☒		
3	04/09/18 17:28	General View						 Load JPG	☒		
4	04/09/18 17:28	General View						 Load JPG	☒		
5	04/09/18 17:28	General View						 Load JPG	☒		
6	04/09/18 17:28	General View						 Load JPG	☒		
7	04/09/18 17:28	General View						 Load JPG	☒		
8	04/09/18 17:28	General View						 Load JPG	☒		
9	04/09/18 17:28	General View						 Load JPG	☒		
10	04/09/18 17:28	General View						 Load JPG	☒		
11	04/09/18 17:28	General View						 Load JPG	☒		
Documentation										1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	14/08/18 19:04	TP ESTIMATE- MARKED						 Load PDF			
2	14/08/18 19:04	TP GIA REPORT						 Load PDF			
3	04/09/18 17:28	REJECTION EMAIL						 Load PDF			
4	04/09/18 17:28	MANDATE TO REJECT						 Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18014737/KJB3Q2

Date: 14/09/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994801
Claimant Vehicle No : SHD205K **Insured Vehicle No :** SLG5825A
 Date of Loss: 06/08/2018 Nature of Claim: TP Claim No: 2963346034SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD205K**
 Make & Model: RENAULT LATITUDE, 2.0 D dCi (A) Engine No: M9R8839C002969
 Reg. Date: 02/10/2015 (Man. Year: 2015) Chassis No: VF1ABL15AUC282381
 Colour: Metallic White/Red Odometer: 449700 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Giti 9 mm Rear Left Side: Giti 9 mm
 Front Right Side: Giti 9 mm Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,422.19	2,510.94	49,911.25	95.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,920.00	480.00	12,440.00	96.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	65,342.19	2,990.94	62,351.25	95.42
+ GST 7.00/7.00% (S\$)	4,573.95	209.37	4,364.58	95.42
Nett Amount (S\$)	69,916.14	3,200.31	66,715.83	95.42
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 13/08/2018
 Date Inspected: 13/08/2018 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Bent	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Distorted	135.97 FL	*135.97 FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
14	1		*BOOT FINISHER	Serviceable	470.06 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT REFLECTOR LAMP LH	Serviceable	493.35 FL	*- FL
17	1		*BOOT REFLECTOR LAMP RH	Serviceable	493.35 FL	*- FL
18	1		*BOOT BADGE RENAULT	Not Necessary	225.36 FL	*- FL
19	1		*BOOT BADGE	Not Necessary	225.36 FL	*- FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	1		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
31	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
32	1		*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- FL
33	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
34	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
35	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
36	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
37	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
38	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
39	1		*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
40	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
41	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
42	1		*EXHAUST CAP REAR	Serviceable	230.49 FL	*- FL
43	1		*CHASSIS PANEL REAR RH	Repair	3,766.43 FL	*- FL
44	1		*KNUCKLE ARM REAR RH L70Y	Serviceable	736.67 FL	*- FL
45	1		*BRAKE DISC REAR L70Y	Serviceable	525.91 FL	*- FL
46	1		*WHEEL HUB NUT L70Y	Serviceable	51.11 FL	*- FL
47	1		*WHEEL HUB CAP L70Y	Serviceable	57.82 FL	*- FL
48	1		*ABS SENSOR REAR RH L70Y	Serviceable	255.75 FL	*- FL
49	1		*REAR AXLE L70Y	Serviceable	4,167.03 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*AXLE ARM RH L70Y	Serviceable	117.22 FL	*- FL
51	1		*LOWER ARM REAR RH L70Y	Serviceable	905.99 FL	*- FL
52	1		*ABSORBER REAR	Serviceable	389.75 FL	*- FL
53	1		*STABILIZER BAR REAR RH	Serviceable	604.65 FL	*- FL
54	1		*BRAKE CALIPER REAR RH	Serviceable	1,300.67 FL	*- FL
55	1		*WHEEL HOUSING PANEL REAR RH	Repair	4,682.09 FL	*- FL
56	1		*CHASSIS PANEL REAR RH	Repair	3,766.43 FL	*- FL
57	1		*SET PARKING AID	Shorted	700.00 FS	*600.00 FS
58	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
59	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
60	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
61	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
62	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
63	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
64	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
65	1		*SET BUMPER LOWER REAR CLIP	Not Necessary	66.00 FS	*- FS
66	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
67	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
68	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS
69	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS
70	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
71	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
72	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
73	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
74	1		*FENDER INNER TRIM CLIP LH	Not Necessary	28.00 FS	*- FS
75	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
76	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
77	2		*REAR WINDSCREEN SELANT	Not Necessary	80.00 FS	*- FS
78	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
79	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
80	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
81	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS
82	1		*RIGHT REAR TYRE	Serviceable	330.00 FS	*- FS
83	1		*RIGHT REAR TYRE RIM	Serviceable	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	57,920.76	2,712.27
- List Item Discount on L Items 10.00/10.00% (\$\$)	5,498.57	201.33
Total Parts (\$\$)	52,422.19	2,510.94

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	4,200.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
14	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
Gross Labour Cost (S\$)			12,920.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >