

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0930/2018/PH
Date : 14-Aug-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Huang Yi Ping
Address : Blk 961 Hougang Avenue 9
#02-576
Singapore 530961
Telephone : HP +65 97426086
Type of Claim : Third Party Claim
Policy No. : DHOM12003431800
Vehicle No : **SKT 2782 C**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : May-15
Engine No : CZC 253801
Chassis No : WAUZZZ8V3F1130582
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Aug-18
Place of Accident : Blk 701A Tampines ST 71 Multi Storey Carpark

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax**Estimated Labour Charges for Accident Vehicle SKT 2782 C.**

S/N	Nature of Jobs	Estimated Charges	Surveyor's commendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer Assy.	S/N \$ 360.00	✓
2	To remove and transfer aircon condensor, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,000.00	X
3	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed. ✓	\$ 4,500.00	1250 .
4	To respray front bumper, lhs front fender and bonnet. ✓ X	\$ 2,200.00	1100
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,252.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 2782 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER COVER <i>Distorted</i>	\$ 1,739.00	✓
2	FRONT BUMPER FIXING PARTS <i>see u</i>	\$ 161.00	x.
3	FRONT BUMPER COVER TRIM LH / RH <i>see u</i>	2 \$ 280.00	x
4	FRONT BUMPER CLOSING ELEMENT <i>3 see u</i>	\$ 140.00	x
5	FRONT BUMPER GUIDE SECTION LH	\$ 33.00	x.
6	AIR GUIDE GRILLE LH <i>Missing</i>	\$ 95.00	✓
7	RADIATOR GRILLE <i>3 see u</i>	\$ 573.00	x
8	RADIATOR GRILLE COVER	\$ 86.00	x
9	FOAM FILLER PIECE <i>cracked</i>	\$ 117.00	✓
10	REINFORCEMENT BEAM <i>Bent</i>	\$ 633.00	✓
11	SUNDRIES <i>see u</i>	\$ 300.00	x
12	SIGNAL HORN LH <i>?</i>	\$ 177.00	?
13	FRONT FENDER LH <i>see u</i>	\$ 746.00	x
14	FRONT FENDER ATTACHMENT PARTS <i>3 see u</i>	\$ 62.00	x
15	FRONT FENDER BRACE LH	\$ 84.00	x.
16	BONNET <i>Dented</i>	\$ 2,755.00	✓
17	BONNET ATTACHMENT PARTS <i>?</i>	\$ 141.00	?
18	EDGE PROTECTION <i>3 see u ?</i>	\$ 24.00	?
19	CATCH HOOK LH / RH <i>not u</i>	2 \$ 133.00	x
20	HEADLIGHT LH <i>cracked</i>	\$ 1,764.00	✓
SUB - TOTAL SPARE PARTS		\$ 10,043.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 2782 C.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	HEADLIGHT DISCHARGE LAMP <i>new</i>	\$ 394.00	*
22	HEADLIGHT CONTROL UNIT <i>new</i>	\$ 1,018.00	*
23	HEADLIGHT POWER MODULE	\$ 503.00	*
24	LIFT CYLINDER LH ?	\$ 174.00	?
25	LIFY CYLINDER WATER HOSE <i>new</i>	\$ 164.00	*
26	LOCK CARRIER <i>new</i>	\$ 638.00	*
27	LOCK CARRIER AIR GUIDE LH	\$ 20.00	*
28	RADIATOR COOLANT <i>new</i>	\$ 133.00	*
29	FRONT NO PLATE	S/N \$ 25.00	*
30	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 13,412.00
TOTAL LABOUR CHARGES		:	\$ 8,252.00
GRAND TOTAL		:	\$ 21,664.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim -
Surveyed Date : 16/08/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant