

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YP4218H1180717

Estimate

Customer

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 13-08-18

Address Motor Claims Department

Vehicle No: YP4218H

78 Shenton Way #07-16

Model/Make: Mitsubishi Fuso

AIG Building

Singapore 079120

FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Safety Guard Railing <i>cut</i>	\$ 1,500.00	1000.00 <i>N</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 380.00	250
	To putty & spray painting & including touch up paint on accident affected	\$ 300.00	11 X

Total Parts & Labour of estimate for damaged vehicle

\$ 2,180.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

Not Approved
RM
2/3 @ 1000/-
2/3
14/8/18

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: