

14/8/18

14/8/20

Intersection of Kocher Rd & North Bridge

	%	Final ? Yes / No
Insured Liability		X

RMES

Others:

### 13) Survey Ice

Name 3



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417881

ROB No: 532927931 - Tel: 6744 1730 / 731 - Fax: 6744 5346 - Email: liushbro@gmail.com

Invoice/Ref No: YP4218H180717

**Estimate****Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 13-08-18

Address: Motor Claims Department

Vehicle No: YP4218H

78 Shenton Way #07-16

Model/Make: Mitsubishi Fuso

AIG Building Singapore 079120

FM65FM2RDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Safety Guard Railing <i>5x1</i>	\$ 1,500.00	1000.00 <i>N</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 380.00	250
	To putty & spray painting & including touch up paint on accident affected	\$ 300.00	11 X

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 2,180.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

*not allowed!*  
*2/3*  
*2/3 \$1000/-*  
*2/3*  
*14/8/18*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No 100% modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
 Signature:  
 Date:

## Hsiao Tong (LKKAuto)

**From:** Md Noor, Norsiah <Norsiah.MdNoor@aig.com>  
**Sent:** Thursday, 6 December 2018 1:47 PM  
**To:** Hsiao Tong (LKKAuto)  
**Subject:** RE: <Seek Instruction> Your Ref: 5143093712S \*Our Ref: CC6/AIG18014747/Upa3  
[ACCIDENT INVOLVING SJY 8401Z(OI) & YP 4218H(TP) ON 17/07/2018]

Dear Hsiao Tong,

Please proceed to reject third party claim.

Please also confirm with insured & third party on the time of the accident. Thanks

By clicking to the delivery of this report at the bottom and to copies of the report being made available online.

### ACCIDENT STATEMENT

17/07/2018 12:32  
17/07/2018 01:50  
JUNCTION OF ROCHOR ROAD AND NORTH BRIDGE ROAD  
SINGAPORE

### DETAILS OF OWN VEHICLE

SJY8401Z

By clicking to the delivery of this report at the bottom and to copies of the report being made available online.

### ACCIDENT STATEMENT

Report 18/07/2018 19:02  
Accident 17/07/2018 16:15  
Location Of Accident ROCHOR ROAD AND NTH BRIDGE ROAD  
Date of Loss SINGAPORE

### DETAILS OF OWN VEHICLE

Registration Number YP4218H  
Policyholder

Kind regards  
Norsiah

Norsiah Md Noor  
AIG  
Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419-1606 | Fax +(65) 6835-7417  
[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]  
**Sent:** Thursday, December 06, 2018 12:24 PM  
**To:** Md Noor, Norsiah  
**Subject:** RE: <Seek Instruction> Your Ref: 5143093712S \*Our Ref: CC6/AIG18014747/Upa3 [ACCIDENT INVOLVING SJY 8401Z(OI) & YP 4218H(TP) ON 17/07/2018]

Hi Norsiah,

We refer to our below email.

Kindly advise if we may proceed to reject third party claim.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Saturday, 3 November 2018 10:35 AM  
**To:** Md Noor, Norsiah (Norsiah.MdNoor@aig.com) <Norsiah.MdNoor@aig.com>  
**Subject:** RE: <Seek Instruction> Your Ref: 5143093712S \*Our Ref: CC6/AIG18014747/Upa3 [ACCIDENT INVOLVING SJY 8401Z(OI) & YP 4218H(TP) ON 17/07/2018]

Hi Norsiah,

We refer to our below email.

Kindly let us have your instruction.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)

**Sent:** Saturday, 13 October 2018 1:07 PM

**To:** Md Noor, Norsiah ([Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com)) <[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com)>

**Subject:** RE: <Seek Instruction> Your Ref: 5143093712S \*Our Ref: CC6/AIG18014747/Upa3 [ACCIDENT INVOLVING SJY 8401Z(OI) & YP 4218H(TP) ON 17/07/2018]

Hi Norsiah,

We refer to our below email.

Kindly let us have your instruction.

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hsiao Tong (LKKAuto)

**Sent:** Saturday, 15 September 2018 12:37 PM

**To:** Md Noor, Norsiah ([Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com)) <[Norsiah.MdNoor@aig.com](mailto:Norsiah.MdNoor@aig.com)>

**Subject:** <Seek Instruction> Your Ref: 5143093712S \*Our Ref: CC6/AIG18014747/Upa3 [ACCIDENT INVOLVING SJY 8401Z(OI) & YP 4218H(TP) ON 17/07/2018]

Your Ref: **5143093712S**

Our Ref: CC6/AIG18014747/Upa3

Dear Sirs,

**ACCIDENT INVOLVING SJY 8401Z(OI) & YP 4218H(TP) ON 17/07/2018**

We refer to the above matter.

Third party reported that he was on the 3<sup>rd</sup> lane of 4 lanes road. Our insured was on his left. When the traffic light turned green third party moved forward to make a left turn as his vehicle is long. Our insured wanted to make a left turn and both vehicles came too close and resulted the collision.

OI reported that he stopped and waiting for traffic light at lane 1. When the traffic light turned green, he moved slowly to make a left turn. Suddenly third party who was on his right had turned left and resulted the collision. Please note that third party was on the lane which only allow to go straight.

We attached here with a copy of accident location from google map. Third party was on the 2<sup>nd</sup> left lane and he is not supposed to turn left.\

In view of this, we are intending to reject third party claim.

**For your comments/ instruction please.**

Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Hsiao Tong (LKKAUTO)

**From:** Hsiao Tong (LKKAUTO)  
**Sent:** Saturday, 15 December 2018 9:41 AM  
**To:** 'Susan Low'  
**Subject:** Your Ref: YP4218H180717 \*Our Ref: CC6/AIG18014747/Upa3 [ACCIDENT INVOLVING SJY 8401Z(AIG) & YP 4218H ON 17/07/2018]  
**Attachments:** Statement of SJY 8401Z.pdf; Accident\_Location.pdf

Your Ref: **YP4218H180717** Without Prejudice  
Our Ref: CC6/AIG18014747/Upa3

Dear Sirs/Madam,

### ACCIDENT INVOLVING SJY 8401Z(AIG) & YP 4218H ON 17/07/2018

We refer to the above matter.

Attached is a copy of our insured accident report and accident location from google map for your easy reference. Based on both parties report, your client was driving on 2<sup>nd</sup> left lane, made a left turn and collided onto our insured vehicle. From the accident location, your client was on the 2nd left lane and he is not supposed to turn left. We are of the view that our insured is not liable for the accident.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Meantime, the time of accident should be 01:50hrs instead of 16:15hrs as reported by your client. Kindly assist to amend the time of accident Thank you.

#### Our Insured GIA Report

I/We undertake to the accuracy of this report as the vehicle and its driver in this report were insured under this policy.

##### ACCIDENT STATEMENT

17/07/2018 12:32  
17/07/2018 01:50  
JUNCTION OF ROCHOR ROAD AND NORTH BRIDGE ROAD  
SINGAPORE

##### DETAILS OF OWN VEHICLE

SJY8401Z

#### Your Client's GIA Report

By submitting to the accuracy of this report as the vehicle and its driver in this report were insured under this policy.

##### ACCIDENT STATEMENT

Report 18/07/2018 19:02  
Accident 17/07/2018 16:15  
Location Of Accident ROCHOR ROAD AND NTH BRIDGE ROAD  
Date of Loss SINGAPORE

##### DETAILS OF OWN VEHICLE

Registration Number YP4218H

Policyholder

Thank you.



Best Regards,

**Hsiao Tong, Chew** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6742-3197 | email: [chewht@lkkauto.com](mailto:chewht@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Our Ref: YP4218H180717

Date: 24/08/2018

Your Ref:

AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way #07-16  
Chartis Building  
Singapore 079120

Attn: Motor Claims Department

Dear Sir / Madam

**TRAFFIC ACCIDENT ALONG ROCHOR ROAD AND NORTH BRIDGE ROAD  
INVOLVING YP4218H AND SJY8401Z ON 17/07/2018**

We/I, **Messers Goldbell Leasing Pte Ltd** (Nric / ROC No: **199001196N**), the registered owners of m/vehicle – **YP4218H** at all material times of the above accident. Our/my vehicle was surveyed by "AIG Asia" authorized appraiser and we/I based our/my on his recommendation for **S\$1,000-00** being the repair for **02** Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle **SJY8401Z** when the same was involved in the aforesaid accident with our/my m/vehicle – **YP4218H**.

We/I whereby you are the insurers of m/vehicle **SJY8401Z** and the driver / owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle – **YP4218H** has suffered loss and damage as follows:

(a) Cost of repairs	S\$	1,000-00
(b) LOU for pre-repair notice 02 days @\$120-00 (7545 cc Box Lorry)		240-00
(c) LOU Fee for 02 days @\$120-00		240-00
(d) GIA / LTA search fee		2-00

<b>Total Amount</b>	<b>S\$</b>	<b>1,482-00</b>
---------------------	------------	-----------------

We/I enclose herewith copies of the supporting documents for vehicle no. **YP4218H** as follows:-

- (i) Motor Accident Report;
- (ii) Repair Invoices;

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu's Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank you.

Yours faithfully,

\_\_\_\_\_  
The owner of m/vehicle **YP4218H**  
Messers Goldbell Leasing Pte Ltd  
cc. Liu's Bro Auto Engrg Ws

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: YP4218H180717

**Final Bill**

<b>Customer</b>		<b>Date:</b>	13-08-18
<b>Name:</b>	AlG Asia Pacific Insurance Pte Ltd	<b>Vehicle No:</b>	YP4218H
<b>Address:</b>	Motor Claims Department	<b>Model/Make:</b>	Mitsubishi Fuso
	78 Shenton Way #07-16		FM65FM2RDEB
	AlG Building Singapore 079120		

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Safety Guard Railing	\$ 1,500.00	\$ -
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 380.00	\$ -
	To putty & spray painting & including touch up paint on accident affected	\$ 300.00	\$ -

Total Parts & Labour of estimate for damaged vehicle	\$ 2,180.00
--	-------------

Total amount in Lump Sum Basis for repaired vehicle	\$ 1,000.00
---	-------------

SDLS: One Thousand Only



M/s Liu's Brother Auto Engrg Wks



# GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No. M400017735

## Third Party Insurer Enquiry

Our Ref No: GR-18-124293  
Date of Request 14/08/2018

Your Ref No: Online Purchase

LIU'S BROTHER AUTO WORKSHOP  
1 Kaki Bukit Ave 6 #01-01  
Auto Bay@Kaki Bukit  
Singapore 417883

Dear Sir/Madam,

Enquiry Date 14/08/2018  
Enquiry By Susan Low Siew Yian  
TP Vehicle No. SJY8401Z  
Accident Date 17/07/2018

### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJY8401Z	AIG Asia Pacific Insurance Pte. Ltd.	04/07/2018-03/07/2019	65-6419-3000

Thank You

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jul 2018 <a href="#">Edit Reg</a>		14 Aug 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,000.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,000.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	TAY TIEN WHUI (ZHENG ZHANWEI), ID: S8100725Z								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	YP4218H	Date of Loss:	17/07/2018 00:00 - :59 [22 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5143093712SG	Policy/Cover Note No.:	1800079214 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJY8401Z	Policy No. (Claimant):	D-18090757MFCV						
		Excess:							
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by <b>MdNoor, Norsiah</b> ] Norsiah.MdNoor@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 24/08/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (15/08/2018): Request To Upload TP GIA Report</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*YP4218H (5143093712SG)  
 [SJY8401Z]  
 TP  
 GOLDBELL LEASING PTE LTD  
 Jul 17 2018 12:00AM  
 [TAY TIEN WHUI (ZHENG ZHANWEI)]  
 Liu's Brother Auto Engineering Workshop

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/08/18 17:29	<b>Accident Statement</b> <small>From: SC • Reg. No: SJY8401Z, Claimant: TAY TIEN WHUI (ZHENG ZHANWEI)</small>	Load HTML	
<b>Photos/Images</b>			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/08/18 17:42	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	14/08/18 17:42	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
4	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
5	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
6	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
7	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
8	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
9	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
10	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
11	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
12	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
13	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
14	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
15	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
16	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
17	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
18	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
19	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
20	14/08/18 17:43	General View	Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/08/18 12:04	TP GIA REPORT	Load PDF	
2	15/09/18 12:28	Accident_Location	Load PDF	
3	15/09/18 12:36	TP ESTIMATE_MARKED	Load PDF	
4	15/12/18 09:41	Email from AIG dd 061218	Load PDF	
5	15/12/18 09:41	Email to TP_reject dd 151218	Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

## Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18014747/UPA3Q2

Date: 24/06/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800079214  
 Claimant Vehicle No: YP4218H Insured Vehicle No: SJY8401Z  
 Date of Loss: 17/07/2018 Nature of Claim: TP Claim No: 5143093712SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: YP4218H  
 Make & Model: MITSUBISHI FUSO, 7.5 D FM65FM2RDEB (M) Engine No: 6M60208342  
 Reg. Date: 08/09/2016 (Man. Year: 2015) Chassis No: FM65FMA20110  
 Colour: White Odometer: 110548 km  
 Engine Capacity: 7545 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 11 R22.5 Rear Tyre Size: 11 R22.5 (D)  
 Front Left Side: Triangle 6 mm Rear Left Side: Triangle 6/6 mm  
 Front Right Side: Triangle 6 mm Rear Right Side: Triangle 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,500.00	1,000.00	500.00	33.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	680.00	250.00	430.00	63.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,180.00</b>	<b>1,250.00</b>	<b>930.00</b>	<b>42.66</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
<b>Nett Amount (S\$)</b>	<b>2,180.00</b>	<b>1,000.00</b>	<b>1,180.00</b>	<b>54.13</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

## INSPECTION

Date of Assignment: 14/08/2018  
 Date Inspected: 14/08/2018 Inspected At: Liu's Brother Auto Engineering Workshop (HQ)  
 BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT  
 Singapore 417883

Estimated Period of Repair: 2.0 days



---

**Adjuster:** MARCUS CHUA**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH SAFETY GUARD RAILING	Bent	1,500.00 FS	*1,000.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					1,500.00	1,000.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	380.00	250.00
2	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	300.00	0.00
Gross Labour Cost (\$\$)			680.00	250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >