

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

13-Aug-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30A REGN NO: SHB 8058 B

1 pc	Front bumper <i>X Repair</i>	\$	811.11
1 pc	Front bumper emblem <i>X</i>	\$	27.80
2 pcs	Front n/s & o/s side bracket @ \$32.51 <i>X</i>	\$	65.02
1 pc	Front n/s fender <i>X Repair</i>	\$	514.02
1 pc	Front n/s fender signal lamp @ \$32.10 <i>X</i>	\$	32.10
1 pc	Front n/s rim @ \$246.00 <i>X</i>	\$	246.00
		\$	1,696.05
	<i>Front x/s door X repair</i>	Less 20%	\$ 339.21
		\$	1,356.84

S/NETT

1 set	Front bumper clips <i>X</i>	\$	48.00
1 pc	Front n/s fender sticker <i>/</i>	\$	30.00
1 set	n/s door stickers <i>/</i>	\$	100.00

Sundry

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

\$ ~~50.00~~ *20*

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front bumper, front n/s fender, front n/s door, etc.

\$ ~~120.00~~ *X*

To putty and spray painting on front bumper, front n/s fender, front n/s door

\$ ~~850.00~~ *400*

To apply rustproofing on the repaired and replaced panels.

\$ ~~600.00~~ *540*

\$ ~~120.00~~ *X*
\$ 3,274.84

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

- LKK Auto Consultants hereby certify that the repairer of the following:
- To display damaged parts before and after repair
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Kalir 10/11/14
13/8/18 16:42
2 dr
PIP
After Repair