

Surveyor:

K8L

DOI:

ASSIGNMENT

13/8/2018

Date / Time:

13/8/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

6Y8995L

Name of Insured:

AL'FRESCO CUTE SYSTEM P/L

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

10/8/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Ganesan Sathyanathan

Driver Tel No.:

82848679

(V/L: YES / NO)

Claim No.:

Srm 180 2086/102

Policy No.:

Dm EVS 1541241702

Make / Model:

7-byma

Place of Accident:

Slip Rd & Amy Ave

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHB 9522 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans, cab



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

NM 041 17004200 / 14 ; 04/13/17

23/8
AshwSHB 9522 X - 03/10/17 03:36 PM / Kpa3n2 ; 04/13/17
6Y8995L - NM 041 17004200 / 14 ; 04/13/17
- NM 041 17004200 / 14 ; 04/13/17

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

7 AMER 09-04-19

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

17/8

Sent By:

K8L

FINALIZATION

Date/Time:

Confirm with:

Confirm by: K8L

Repair Cost:

45 \$52,800

(2 days)

Reduction:

86 %

Email

Call

FINAL SETTLEMENT

Date/Time:

29/08/19

Confirm with:

WH YIN

Email

Call

Final Liability:

% 100

(Assessed / Assessed) BOLA S/N No. : NL

If NO or B 28, Ass. Lia:

Repair Cost:

2/451 \$52,996.00

OLD TURN TOO CLOSE TO SHIP

Loss of Rental (LOR):

\$538.63

(4.5 days) x 75.25

Loss of Use (LOU):

\$5

(\$ x 4.5 days)

Loss of Income (LOI):

\$525.40

(\$50 x 4.5 days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☒

[Tick only one]

GIA/LTA Search

\$57.44

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$53,567.12

Global Sum \$5:

\$5,560.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$53,560.00

Name 1:

TRANG-CAB AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
17/9/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$100.00

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details	
Vehicle No.:	5HB9522X
Vehicle to be Exported:	Yes
Intended De-registration Date:	10 Aug 2018
Vehicle Make:	CHEVROLET
Vehicle Model:	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour:	Red
Manufacturing Year:	2011
Engine No.:	Z20S1462215K
Chassis No.:	KL1LA69RJBB123785
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,971.00
Original Registration Date:	29 Jan 2013
First Registration Date:	29 Jan 2013
Transfer Count:	0
Actual AFE Paid:	\$13,971.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jan 2021
PARF Rebate Amount:	\$9,779.00

COE Expiry Date:	28 Jan 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$60,655.00
COE Rebate Amount:	\$18,689.00
Total Rebate Amount:	\$28,468.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHB 9522X**AAD1808-062***Not Authaised*
11 Sep 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9522X

KL1LA69RJBB123785

CHEVROLET

EPICA 2.0

10.8.2018

CHINA TAIPING**PART****LIST**

1	1	Front Bumper	\$	<i>CM</i> 1,202.00 ✓
2	1	Front Bumper Lower Absorber	\$	<i>SL</i> 180.00 X
3	1	Front Bumper Reinforcement	\$	<i>R</i> 356.00 X
4	1	Front Bumper Retainer RH	\$	<i>DIR</i> 102.00 ✓
5	1	Front Bumper Retainer LH	\$	<i>SL</i> 102.00 X
6	1	Front Bumper Lower Grille	\$	<i>SL</i> 78.00 X
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37 X
8	1	Front Bumper Bracket LH	\$	<i>R</i> 10.00 X
9	1	Front Bumper Bracket RH	\$	<i>R</i> 10.00 X
10	1	Bumper Fog Lamp Cover RH	\$	<i>SL</i> 32.40 X
11	1	Bumper Fog Lamp Cover LH	\$	<i>SL</i> 32.40 X
12	1	Headlamp RH	\$	<i>BRO</i> 816.00 ✓
13	1	Headlamp RH inner panel	\$	<i>R</i> 611.16 X
14	1	Front Fender RH	\$	<i>B</i> 837.60 ✓
15	1	Front Fender Liner RH	\$	<i>SL</i> 47.00
16	1	Front Fender Inner Wheel House Panel RH	\$	<i>R</i> 1,437.00
17	1	Front Shock Absorber Assy RH	\$	<i>SL</i> 216.17
18	1	Front Shock Absorber Top Mounting RH	\$	<i>SL</i> 48.32
19	1	Front Lower Arm RH	\$	<i>SL</i> 283.00
20	1	Front Knuckle Arm RH	\$	<i>SL</i> 230.00
21	1	Front Hub Unit	\$	<i>SL</i> 376.00
22	1	Front Disc Brake RH	\$	<i>SL</i> 157.55
23	1	Front Strut Bar Bracket RH	\$	<i>R</i> 235.01
24	1	Front Stabilizer Bar	\$	<i>SL</i> 234.00
25	1	Front Stabilizer Bar Link RH	\$	<i>SL</i> 51.79
26	1	Front Stabilizer Bar Bracket RH	\$	<i>R</i> 105.75
27	1	Front Stabilizer Bar Bush RH	\$	<i>SL</i> 66.00
28	1	Front Beam A - Impact RH	\$	<i>R</i> 214.00
29	1	Bonnet Panel	\$	<i>R</i> 1,250.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1808-062**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9522X

30	1	Horn Unit (Low Tone)	\$	53.46	} X
31	1	Horn Unit (High Tone)	\$	53.46	
32	1	Front Support Panel Assy	\$	1,222.32	
33	1	Front brace panel	\$	134.37	
34	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	62.00	
35	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	51.00	
36	1	TANK, WIPER HOSE	\$	21.00	
37	1	Radiator Assembly (Radiator A	\$	618.00	

TOTAL	\$	11,671.13
10%	\$	1,167.11
	\$	10,504.02

Specical Nett

1	1 Set	Front Fender Liner clip LH	\$	30.00	} X
2	1 Set	Louver Cowl Top clip	\$	30.00	
3	1	Front right tyre rim	\$	380.00	
4	1	Front right tyre	\$	300.00	
5	2	Bonnet stopper	\$	15.00	
6	6	Bonnet under weatherstrip seal clips	\$	30.00	
7	10	Bonnet insulator clip	\$	30.00	

TOTAL \$ 815.00**TOTAL PARTS \$ 11,319.02****LABOUR**

To Check Electrical Lighting Concerned.	\$	170.00	200/
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	400/

Trans-cab Auto Services Pte Ltd**AAD1808-062**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9522X

Putty and spray painting of the affected portion.	\$	3,200.00	<i>4001</i>
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 440.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>↪</i> 380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>↪</i> 380.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>↪</i> 380.00	<i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>↪</i> 170.00	<i>X</i>
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	<i>↪</i> 170.00	<i>X</i>

TOTAL \$ 8,790.00**Over All Total \$ 20,109.02****Repair Days**~~10 DAYS~~*2 days***LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 20 August, 2018 5:20 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GY8995L (OI : CTI - SNM18D03887C02) and SHB9522X (TP : LKK REF - CC3/CTI18014751/Kea3) on 10/08/2018
Attachments: LeeSZ_SNM18D03887C01-GY8995L-LKKDirectSettlementAccidentLtr_CLCR95.595.pdf; MNA118103739-GY8995L.pdf
Follow Up Flag: Follow up
Flag Status: Completed
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Elaine Cheong

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Friday, 17 August, 2018 2:41 PM
To: Claims Dept of CTI
Cc: Lucas Lee; Elaine Cheong; Asher Sng (LKKAUTO); Hsiao Tong (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving GY8995L (OI : CTI - TBA) and SHB9522X (TP : LKK REF - CC3/CTI18014751/Kea3) on 10/08/2018



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D03887/C01/5**

Date : **20 AUGUST 2018**

via Ordinary & Registered Mail

**AL'FRESCO ELITE SYSTEM PTE LTD
NO.23 KAKI BUKIT ROAD 4
#01-16/17 SYNERGY@KB
SINGAPORE 417801**

Dear Sir / Madam

**ACCIDENT INVOLVING GY8995L AND SHB9522X ON 10 AUGUST 2018
ALONG SLIP ROAD TOWARDS SIMS AVE**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SHB9522X**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : ASHER

Ref : CC3/CTI18014751/KEA3

Contact No : 68416051

via Email : ASHER@LKKAUTO.COM

CC : Agent - (AN0215A) - SEAGULL AGENCY

F01/LKKDS-2013

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Monday, 1 April 2019 4:10 PM
To: claims@transcab.com.sg
Cc: 'Jasmine Tan'; 'Ng Wai Yin'
Subject: ACCIDENT INVOLVING GY 8995L & SHB 9522X ON 10/08/2018
Attachments: OI SKETCH PLAN.pdf

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: AAD1808-062
Our Ref: CC3/CTI18014751/Kea3

Dear Sirs,

ACCIDENT INVOLVING GY 8995L & SHB 9522X ON 10/08/2018

We refer to the above matter.

Please be informed that liability is unclear for this matter. Our insured driver reported that your client rear ended our insured vehicle. Enclosed herewith in this email is a copy of our insured's accident report for your perusal.

We are in a course of investigating into the circumstances of the accident. After verifying further with our OI we will revert with our opinion on the cause of the accident. Kindly do not refer to any party for legal assistance until you heard further from us.

Meanwhile, we would like to request a copy of video footage/witness statement/scene photos(if any) in order for us to look into the matter.

We shall revert upon hearing from you.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC3/CTI18014751/Kha3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 18-09-2019	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 8995L	Veh. Inspected	SHB 9522X	
Policy No.	DMCVSN1541241702	Coverage (\$)	0.00	
Claim No.	SNM18D03887C02/5	Excess (\$)	0.00	
Assign From		Assign Date	13/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET EPICA (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	KL1LA69RJBB123785	Colour	WHITE / RED	
Odometer	712662	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GITI	6 mm	
L/H Front Tyre	195/65 R15	GITI	6 mm	
R/H Rear Tyre	195/65 R15	GITI	3 mm	
L/H Rear Tyre	195/65 R15	GITI	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	10/08/2018	Inspection Date	13/08/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9522X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	CRACKED	1,202.00	1,202.00
1	FRONT BUMPER LOWER ABSORBER	SERVICEABLE	180.00	-
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	356.00	-
1	FRONT BUMPER RETAINER RH	DISTORTED	102.00	102.00
1	FRONT BUMPER RETAINER LH	SERVICEABLE	102.00	-
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	78.00	-
1	FRONT BUMPER LOWER STIFFENER	TO REPAIR SEE LABOUR	134.37	-
1	FRONT BUMPER BRACKET LH	TO REPAIR SEE LABOUR	10.00	-
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	10.00	-
1	BUMPER FOG LAMP COVER RH	SERVICEABLE	32.40	-
1	BUMPER FOG LAMP COVER LH	SERVICEABLE	32.40	-
1	HEADLAMP RH	BROKEN	816.00	816.00
1	HEADLAMP RH INNER PANEL	TO REPAIR SEE LABOUR	611.16	-
1	FRONT FENDER RH	BENT	837.60	837.60
1	FRONT FENDER LINER RH	SERVICEABLE	47.00	-
1	FRONT FENDER INNER WHEEL HOUSE PANEL RH	TO REPAIR SEE LABOUR	1,437.00	-
1	FRONT SHOCK ABSORBER ASSY RH	SERVICEABLE	216.17	-
1	FRONT SHOCK ABSORBER TOP MOUNTING RH	SERVICEABLE	48.32	-
1	FRONT LOWER ARM RH	SERVICEABLE	283.00	-
1	FRONT KNUCKLE ARM RH	SERVICEABLE	230.00	-
1	FRONT HUB UNIT	SERVICEABLE	376.00	-
1	FRONT DISC BRAKE RH	SERVICEABLE	157.55	-
1	FRONT STRUT BAR BRACKET RH	TO REPAIR SEE LABOUR	235.01	-
1	FRONT STABILIZER BAR	SERVICEABLE	234.00	-
1	FRONT STABILIZER BAR LINK RH	SERVICEABLE	51.79	-
1	FRONT STABILIZER BAR BRACKET RH	TO REPAIR SEE LABOUR	105.75	-

Report Ref No. CC3/CTI18014751/Kha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT STABILIZER BAR BUSH RH	SERVICEABLE	66.00	-
1	FRONT BEAM A-IMPACT RH	TO REPAIR SEE LABOUR	214.00	-
1	BONNET PANEL	TO REPAIR SEE LABOUR	1,250.00	-
1	HORN UNIT (LOW TONE)	SERVICEABLE	53.46	-
1	HORN UNIT (HIGH TONE)	SERVICEABLE	53.46	-
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	1,222.32	-
1	FRONT BRACE PANEL	TO REPAIR SEE LABOUR	134.37	-
1	WINDSCREEN WASHER TANK (RESERVOIR A-W/SHIELD)	SERVICEABLE	62.00	-
1	WINDSCREEN WASHER TANK MOTOR (PUMP W/SWA)	SERVICEABLE	51.00	-
1	TANK,WIPER HOSE	SERVICEABLE	21.00	-
1	RADIATOR ASSEMBLY (RADIATOR A)	SERVICEABLE	618.00	-
	LESS 10% DISCOUNT		-1,167.11	-295.76
			10,504.02	2,661.84
	SPECIAL NETT ITEMS			
1	SET FRONT FENDER LINER CLIP LH (SN)	NOT NECESSARY	30.00	-
1	SET LOUVER COWL TOP CLIP (SN)	NOT NECESSARY	30.00	-
1	FRONT RIGHT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT RIGHT TYRE (SN)	SERVICEABLE	300.00	-
2	BONNET STOPPER (SN)	SERVICEABLE	15.00	-
6	BONNET UNDER WEATHERSTRIP SEAL CLIPS (SN)	NOT NECESSARY	30.00	-
10	BONNET INSULATOR CLIP (SN)	NOT NECESSARY	30.00	-
			815.00	-
	LABOUR			
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT,FRONT BUMPER LOWER STIFFENER,FRONT BUMPER BRACKET LH,FRONT BUMPER BRACKET RH,HEADLAMP RH INNER PANEL,FRONT FENDER INNER WHEEL HOUSE PANEL RH,FRONT STRUT BAR BRACKET RH,FRONT STABILIZER BAR BRACKET RH,FRONT BEAM A-IMPACT RH,BONNET PANEL,FRONT SUPPORT PANEL ASSY AND FRONT BRACE PANEL.		3,500.00	400.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,200.00	400.00
	TO REMOVE AND REFIT FRONT AND REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	440.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF BONNET FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
			8,790.00	820.00
	GRAND TOTAL		20,109.02	3,481.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,800.00

Report Ref No. CC3/CT118014751/Kha3n2

KSC

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.