

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9522X**AAD1808-062***Not Notified
1/Rep &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9522X

KL1LA69RJB123785

CHEVROLET

EPICA 2.0

10.8.2018

CHINA TAIPING**PART****LIST**

1	1	Front Bumper	\$	<i>CM</i> 1,202.00	✓
2	1	Front Bumper Lower Absorber	\$	<i>SL</i> 180.00	X
3	1	Front Bumper Reinforcement	\$	<i>R</i> 356.00	X
4	1	Front Bumper Retainer RH	\$	<i>Dir</i> 102.00	✓
5	1	Front Bumper Retainer LH	\$	<i>SL</i> 102.00	X
6	1	Front Bumper Lower Grille	\$	<i>SL</i> 78.00	X
7	1	Front Bumper Lower Stiffener	\$	<i>R</i> 134.37	X
8	1	Front Bumper Bracket LH	\$	<i>R</i> 10.00	X
9	1	Front Bumper Bracket RH	\$	<i>R</i> 10.00	X
10	1	Bumper Fog Lamp Cover RH	\$	<i>SL</i> 32.40	X
11	1	Bumper Fog Lamp Cover LH	\$	<i>SL</i> 32.40	X
12	1	Headlamp RH	\$	<i>Brd</i> 816.00	✓
13	1	Headlamp RH inner panel	\$	<i>R</i> 611.16	X
14	1	Front Fender RH	\$	<i>Brd</i> 837.60	✓
15	1	Front Fender Liner RH	\$	<i>SL</i> 47.00	} X
16	1	Front Fender Inner Wheel House Panel RH	\$	<i>R</i> 1,437.00	
17	1	Front Shock Absorber Assy RH	\$	<i>SL</i> 216.17	
18	1	Front Shock Absorber Top Mounting RH	\$	<i>SL</i> 48.32	
19	1	Front Lower Arm RH	\$	<i>SL</i> 283.00	
20	1	Front Knuckle Arm RH	\$	<i>SL</i> 230.00	
21	1	Front Hub Unit	\$	<i>SL</i> 376.00	
22	1	Front Disc Brake RH	\$	<i>SL</i> 157.55	
23	1	Front Strut Bar Bracket RH	\$	<i>R</i> 235.01	
24	1	Front Stabilizer Bar	\$	<i>SL</i> 234.00	
25	1	Front Stabilizer Bar Link RH	\$	<i>SL</i> 51.79	
26	1	Front Stabilizer Bar Bracket RH	\$	<i>R</i> 105.75	
27	1	Front Stabilizer Bar Bush RH	\$	<i>SL</i> 66.00	
28	1	Front Beam A - Impact RH	\$	<i>R</i> 214.00	
29	1	Bonnet Panel	\$	<i>R</i> 1,250.00	

Trans-cab Auto Services Pte Ltd

AAD1808-062

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9522X

30	1	Horn Unit (Low Tone)	\$	53.46	}	X
31	1	Horn Unit (High Tone)	\$	53.46		
32	1	Front Support Panel Assy	\$	1,222.32		
33	1	Front brace panel	\$	134.37		
34	1	Windscreen Washer Tank (Reservoir A-W/Shield)	\$	62.00		
35	1	Windscreen Washer Tank Motor (Pump Wswa)	\$	51.00		
36	1	TANK, WIPER HOSE	\$	21.00		
37	1	Radiator Assembly (Radiator A	\$	618.00		

TOTAL	\$	11,671.13
10%	\$	1,167.11
	\$	10,504.02

Special Nett

1	1 Set	Front Fender Liner clip LH	\$	30.00	}	X
2	1 Set	Louver Cowl Top clip	\$	30.00		
3	1	Front right tyre rim	\$	380.00		
4	1	Front right tyre	\$	300.00		
5	2	Bonnet stopper	\$	15.00		
6	6	Bonnet under weatherstrip seal clips	\$	30.00		
7	10	Bonnet insulator clip	\$	30.00		

TOTAL \$ 815.00**TOTAL PARTS \$ 11,319.02****LABOUR**To Check Electrical Lighting Concerned. \$ 170.00 *2cl*Panel beating, knocking and straightening the
necessary portion, remove and renewal of parts, adjust
and realign the same \$ 3,500.00 *400cl*

Trans-cab Auto Services Pte Ltd**AAD1808-062**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 9522X

Putty and spray painting of the affected portion.	\$	3,200.00	<i>4001</i>
To Remove And Refit Front And Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 440.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>7</i> 380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>5</i> 380.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>5</i> 380.00	<i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>5</i> 170.00	<i>X</i>
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	<i>5</i> 170.00	<i>X</i>

TOTAL \$ 8,790.00**Over All Total \$ 20,109.02****Repair Days****10 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: