

ASS. REC. BY:

REF:

CS/FCI18014752/Kvd3/12

Special Instruction:

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Srene ler

of

FCI

Date/Time: 14/8/18 @ 3:43pm

Estimated Cost:

Bill to:

OD TP WS TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW698Y

Insured:

SHD 4539X

at Workshop m/s

Ah Lim Motor

Tel:

6483 1244

of

176 Sir Ming Drive #05-12

Policy No:

Claim No:

D18066026MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

08/08/18

Insp: AMK Ah Lim motor 15/8/18 @ 10:30am

CA / REV / REP. / REV 24 HRS

DS

H.O.D. Endorsement:

Date/Time:

4pm @ 14/8/18

Person Contacted:

Zila

Vehicle IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

SJW 698Y - X

SHD 4539X - X

16/8/18

Email preli revised to FCI

19/11 @ 4965.18 Ccabin (Red 542062, 5790) (No LS)

(08/11/13) wef

REF: FCI

ASS. REC. BY:

ASSIGNMENT

From: Date: 15/8/18

Estimated Cost:

On TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJW 698 Y

at Workshop m/s Ah Lim Motor

of No. 10 AMK Ind. Park 2A #01-09

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record) 10.30am

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$ 79k

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1. B. % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJW 698 Y Yr Regn: 06, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo S60 c.c. 1566

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 67814 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: YV11FS84ABF2365224

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 8/8/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

16/8 15k pass to Catherine

RECEIVED 20 NOV 2018

19/11/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 19/11 - typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

TOTAL

Report Format: CWS

Lump Sum / I.B.I. (\$) 4965.19

170

50

50

19

289



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18014752/Kvd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 14-08-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4539X	Veh. Inspected	SJW 698Y
Policy No.		Coverage (\$)	0.00
Claim No.	D18006026MFSH	Excess (\$)	0.00
Assign From	CWS (SERENE LER)	Assign Date	14/08/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	08/08/2018	Inspection Date	15/08/2018
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAVA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18006026MFSH

Our ref: CS/FCI18014752/Kvd3

Date : 16/8/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SJW 698Y


We thank for your instruction on 14/8/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15/8/2018 at the premises of M/s AH LIM MOTOR COMPANY and have the following to report:-

Workshop Estimate Amount	: S\$9,885.77
Revised Estimate Amount	: S\$4,465.15
"Check" Items Amount	: S\$348.66
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	10-08-2018	Our Ref No. D18006026MFSH
Accident Date	08-08-2018	Claim Type. Third Party
Insured Vehicle	SHD4539X	Third Party Vehicle. SJW698Y
Survey Location	176 SIN MING DRIVE #05-12 SIN MING AUTOCARE	
Contact Person.	ZILA	
Contact No.	64831244/ 0	Fax No. 64836170
Survey Type	DIRECT SETTLEMENT: EST. COR \$10,577.77	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AH LIM MOTOR COMPANY	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/243212)



PRI Documents



Close



PRI Header Details

Claim No	D18006026MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & AH LIM M THUAN LING !
Workshop Name	AH LIM MOTOR COMPANY (Contact Person : ZILA)	Survey Location & Contact Details	176 SIN MING DRIVE #05-12 SIN MING AUTOCARE Mobile: 0 , Phone: 64831244 , Fax: 64836170 EmailId: ZILA@AHLIMMOTOR.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT: EST. COR \$10,577.77		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD4539X	TP Vehicle No	SJW698Y
PRI Recieved Date	13-08-2018 05:57:28 PM	Surveyor Appointed Date	14-08-2018 10:44:24 AM	Surveyor Accept Date	14-08-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	14-08-2018	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 16 August 2018 2:08 PM
To: 'Claim Workflow System'
Cc: Sereneler@msfirstcapital.com.sg; SUR
Subject: RE: SURVEY ASSESSMENT - D18006026MFSH/1, SJW 698Y
Attachments: SJW 698Y PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SJW 698Y
Date of survey: 15/8/2018
Number of days : 3 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 14 August 2018 3:48 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: Sereneler@msfirstcapital.com.sg; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006026MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer arrange on 15/08/2018.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 14 August 2018 3:42 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: Sereneler@msfirstcapital.com.sg; cwsmotorclaims@msfirstcapital.com.sg
Subject: PRI: SURVEY ASSESSMENT - D18006026MFSH/1

Please find below link to download document
[Jobsheet_D18006026MFSH_TPD1.pdf](#)

Dear Sir/Mdm,

We refer to the above reference.
Please find attached the necessary documents for survey.
Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



AVG

This email has been checked for viruses by AVG antivirus software.
www.avg.com

Veron Chen (LKKAUTO)

From: muihong@ahlimmotor.com.sg
Sent: Wednesday, 14 November 2018 5:32 PM
To: Kenneth Kong (LKKAUTO); Veron Chen (LKKAUTO)
Subject: Draft Finalisation - SJW698Y
Attachments: Draft Finalisation - SJW698Y.pdf

Dear Mr Kenneth

Pls see attached the Draft Finalisation – SJW698Y for your approval.

Pls advise.

Thanks

Regards

Kee Mui Hong
Ah Lim Motor @ AMK
No. 10 Ang Mo Kio Ind Pk 2A
#01-09 AMK Autopoint
Singapore 568047
Tel : 64831244 Fax : 64836170

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

5650H

Vehicle Details

Vehicle No.:

SJW698Y

Vehicle to be Exported:

No

Intended De-registration Date:

08 Aug 2018

Vehicle Make:

VOLVO

Vehicle Model:

S60 D2

Primary Colour:

Black

Manufacturing Year:

2015

Engine No.:

D4162T3256385

Chassis No.:

YV1FS84ABF2365224

Maximum Power Output:

84.0 kW (112 bhp)

Open Market Value:

\$26,106.00

Original Registration Date:

27 Jun 2015

First Registration Date:

27 Jun 2015

Transfer Count:

0

Actual ARF Paid:

\$13,549.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

26 Jun 2025

PARF Rebate Amount:

\$10,161.00

Intended COE Rebate Details

COE Expiry Date:

26 Jun 2025

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$66,000.00

COE Rebate Amount:

\$45,430.00

Total Rebate Amount:

\$55,591.00

The information contained herein is correct as at 08 Aug 2018

OK



Contact us at
 Hotline: (65) 6532 2888
 E-mail: CustomerService@DirectAsia.com

YOUR POLICY SCHEDULE

This document forms part of your contract with us and should be read together with your Certificate of Insurance and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Car Insurance

Policy number	: MT/00283456/02
Period of cover	: Policy begins 27/06/2018 00:00 and runs until 26/06/2019 23:59
Premium	: S\$ 1,488.56 (inclusive of GST)
Own Damage Excess	: S\$ 100.00 (before any applicable GST)
Windscreen Excess	: S\$ 100.00 (before any applicable GST)
Vehicle Details	
Vehicle Registration	: SJW698Y
Make and model	: Volvo S60 Diesel D2
Year of registration	: 2015
Finance company / Hire purchase	: Citibank
Is your car modified? (Modifications are according to LTA guidelines)	: No
Chassis number	
	: YV1FS84ABF2365224
Car usage	: Private and Business Use
Policyholder	
Policyholder	: Chow, Thuan Ling Shirley
Mailing Address	: 501 ANG MO KIO AVENUE 5, 09-3700, Singapore 560501
E-mail Address	: shirleychowtl@yahoo.com.sg
Mobile Number	: 98197045
No Claims Discount (NCD)	: 50%
Main Driver Details	
Main Driver	: Chow, Thuan Ling Shirley
Date of Birth	: 08/12/1970
Marital Status	: Married
Gender	: Female
Occupation	: Civil servants : management
Certificate of Merit	: Yes
Years of valid driving licence	: > 5
Important Note: This policy covers any authorised drivers.	
Young and/ or Inexperienced Driver (YIED): refers to any driver who is below the age of 30 or holds a driving licence for less than 2 years.	

Direct Asia Insurance (Singapore) Pte Ltd
 88 South Bridge Road Singapore 058716
 www.DirectAsia.com

Company Registration No: 200327616



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHOW THUAN LING SHIRLEY
BLK 501 ANG MO KIO AVE 5
#09-3700
SINGAPORE 560501

Estimate No: MC0913342
Date: 13 Aug 2018
Policy No: MT/00283456/02
Veh Reg No: SJW698Y
Make/Model: VOLVO S60 D2

ATTN:

Your Ref No: SJW698Y
Claim Type: Third Party — MS 1st cap
Accident Date: 08/08/2018
TP Veh Reg No: SHD4539X

Not Authorized
Resurvey BY claim 3 days
1-B.1

Estimate Repair Cost to Vehicle No :SJW698Y

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 REAR BOOT	1 PC	2,484.80	X
2 REAR BOOT LOGO (VOLVO) CTR	1 PC	99.50	X
3 REAR BOOT LOGO (S60) LH	1 PC	90.80	X
4 REAR BOOT LOGO (D2) RH	1 PC	90.80	X
5 REAR BOOT INSULATOR CLIPS	12 PC	79.20	X
6 REAR BOOT LOCK	1 PC	433.70	X
7 TAILAMP RH	1 PC	387.40	2X
8 REAR BUMPER	1 PC	1,440.70	✓
9 REAR BUMPER SIDE RETAINERS	2 PC	115.20	4 + 57.60 ✓
10 REAR BUMPER CLIPS	12 PC	66.00	✓
11 REAR BUMPER TOW COVER RH	1 PC	73.90	✓
12 REAR BUMPER REINFORCEMENT WITH BRACKET	1 PC	1,380.20	✓
13 REAR BUMPER CTR GARNISH (CTR)	1 PC	90.70	✓
14 REAR BUMPER SIDE REVERSE SENSOR	1 PC	388.00	194 ✓
15 REAR BUMPER SIDE REVERSE SENSOR HOLDER - CHECK PRICE	1 PC	34.60	0.00 ? ✓
16 REAR BUMPER LOWER LIP	1 PC	486.40	✓
17 REAR BUMPER LOWER LIP REVERSE SENSOR	1 PC	388.00	194 ✓
18 REAR BUMPER LOWER LIP REVERSE SENSOR HOLDER - CHECK PRICE	2 PC	34.60	0.00 ? ✓
		8,095.30	
Less 10%		809.53	7,285.77
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
20 TO RESET REAR BOOT MOTOR, REVERSE SENSOR CTR, SIDE	1 PC	400.00	801
21 TO REMOVE & REINSTALL/REPLACE REAR BUMPER SIDE REVERSE SENSOR, LOWER LIP CTR REVERSE SENSOR	1 PC	180.00	801
22 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	180.00	X
23 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RR BUMPER REINFORCEMENT & BRACKET TO KNOCK & REPAIR END PANEL, REFER FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	3001
24 TO SPRAY RR BOOT, RR BUMPER, REAR BUMPER CTR GARNISH, END PANEL, RR BUMPER REINFORCEMENT & BRACKET, REAR FENDER LH & RH.	1 PC	900.00	4001
		2,600.00	2,600.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHOW THUAN LING SHIRLEY
BLK 501 ANG MO KIO AVE 5
#09-3700
SINGAPORE 560501

Estimate No: MC0913342
Date: 13 Aug 2018
Policy No: MT/00283456/02
Veh Reg No: SJW698Y
Make/Model: VOLVO S60 D2

ATTN:
Your Ref No: SJW698Y
Claim Type: Third Party
Accident Date: 08/08/2018
TP Veh Reg No: SHD4539X

Estimate Repair Cost to Vehicle No :SJW698Y

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
	10,385.81	Total	SS 9,885.77
		Add GST @ 7%	692.00
		Total Amount Payable	SS 10,577.77

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED SEVENTY SEVEN AND CENTS SEVENTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHOW THUAN LING SHIRLEY
BLK 501 ANG MO KIO AVE 5
#09-3700
SINGAPORE 560501

Estimate No: MC0913342
Date: 13 Aug 2018
Policy No: MT/00283456/02
Veh Reg No: SJW698Y
Make/Model: VOLVO S60 D2

ATTN:

Your Ref No: SJW698Y
Claim Type: Third Party
Accident Date: 08/08/2018
TP Veh Reg No: SHD4539X

LKK
1030

Not Notarized
Resurvey 1-B.1
10:40am
3 days

Estimate Repair Cost to Vehicle No :SJW698Y

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BOOT	1 PC	2,484.80	X
2 REAR BOOT LOGO (VOLVO) CTR	1 PC	99.50	X
3 REAR BOOT LOGO (S60) LH	1 PC	90.80	X
4 REAR BOOT LOGO (D2) RH	1 PC	90.80	X
5 REAR BOOT INSULATOR CLIPS	12 PC	79.20	X
6 REAR BOOT LOCK	1 PC	433.70	X
7 TAILAMP RH	1 PC	387.40	7
8 REAR BUMPER	1 PC	1,440.70	✓
9 REAR BUMPER SIDE RETAINERS	2 PC	115.20	✓
10 REAR BUMPER CLIPS	12 PC	66.00	✓
11 REAR BUMPER TOW COVER RH	1 PC	73.90	✓
12 REAR BUMPER REINFORCEMENT WITH BRACKET	1 PC	1,380.20	✓
13 REAR BUMPER CTR GARNISH (CTR)	1 PC	90.70	✓
14 REAR BUMPER SIDE REVERSE SENSOR	1 PC	388.00	✓
15 REAR BUMPER SIDE REVERSE SENSOR HOLDER - CHECK PRICE	2 PC	0.00	2 photo
16 REAR BUMPER LOWER LIP	1 PC	486.40	✓
17 REAR BUMPER LOWER LIP REVERSE SENSOR	1 PC	388.00	✓
18 REAR BUMPER LOWER LIP REVERSE SENSOR HOLDER - CHECK PRICE	2 PC	0.00	7 photo
		8,095.30	
Less 10%		809.53	7,285.77
LABOUR			
19 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	201
20 TO RESET REAR BOOT MOTOR, REVERSE SENSOR CTR, SIDE	1 PC	400.00	801
21 TO REMOVE & REINSTALL/REPLACE REAR BUMPER SIDE REVERSE SENSOR, LOWER LIP CTR REVERSE SENSOR	1 PC	180.00	801
22 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	180.00	X
23 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RR BUMPER REINFORCEMENT & BRACKET. TO KNOCK & REPAIR END PANEL, REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	900.00	3001
24 TO SPRAY RR BOOT, RR BUMPER, REAR BUMPER CTR GARNISH, END PANEL, RR BUMPER REINFORCEMENT & BRACKET, REAR FENDER LH & RH.	1 PC	900.00	4001
		2,600.00	2,600.00





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : CHOW THUAN LING SHIRLEY
BLK 501 ANG MO KIO AVE 5
#09-3700
SINGAPORE 560501

Estimate No: MC0913342
Date: 13 Aug 2018
Policy No: MT/00283456/02
Veh Reg No: SJW698Y
Make/Model: VOLVO S60 D2

ATTN:
Your Ref No: SJW698Y
Claim Type: Third Party
Accident Date: 08/08/2018
TP Veh Reg No: SHD4539X

Estimate Repair Cost to Vehicle No :SJW698Y

Description	Quantity	List Price	Amount
		S\$	S\$
		Total	S\$ 9,885.77
		Add GST @ 7%	692.00
		Total Amount Payable	S\$ 10,577.77

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED SEVENTY SEVEN AND CENTS SEVENTY SEVEN ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : CHOW THUAN LING SHIRLEY
BLK 501 ANG MO KIO AVE 5
#09-3700
SINGAPORE 560501

Claim No: MC0913342
No: MF0911403
Date: 23 Oct 2018
Policy No: MT/00283456/02
Veh Reg No: SJW698Y
Make/Model: VOLVO S60 D2

ATTN:

Your Ref No: SJW698Y
Claim Type: Third Party
Accident Date: 08/08/2018
TP Veh Reg No: SHD4539X

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJW698Y

Description	Quantity	List Price S\$	Amount S\$
SPARE PARTS			
1 REAR BUMPER	1 PC	1,440.70	
2 REAR BUMPER SIDE RETAINER RH	1 PC	57.60	
3 REAR BUMPER CLIPS	12 PC	66.00	
4 REAR BUMPER TOW COVER RH	1 PC	73.90	
5 REAR BUMPER REINFORCEMENT WITH BRACKET	1 PC	1,380.20	
6 REAR BUMPER CTR GARNISH (CTR)	1 PC	90.70	
7 REAR BUMPER SIDE REVERSE SENSOR	1 PC	194.00	
8 REAR BUMPER SIDE REVERSE SENSOR HOLDER	2 PC	34.60	
9 REAR BUMPER LOWER LIP	1 PC	486.40	
10 REAR BUMPER LOWER LIP REVERSE SENSOR	1 PC	194.00	
11 REAR BUMPER LOWER LIP REVERSE SENSOR HOLDER	2 PC	34.60	
12 REAR BUMPER LOWER LIP CENTRE GARNISH <i>Replaced</i>	<i>nd/lh</i> 1 PC	486.40	(A) X
		4,539.10	
	Less 10%	453.91	4,085.19
LABOUR			
13 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	20.00	
14 TO RESET REAR BOOT MOTOR, REVERSE SENSOR CTR, SIDE	1 PC	80.00	
15 TO REMOVE & REINSTALL/REPLACE REAR BUMPER SIDE REVERSE SENSOR, LOWER LIP CTR REVERSE SENSOR	1 PC	80.00	
16 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RR BUMPER REINFORCEMENT & BRACKET. TO KNOCK & REPAIR END PANEL, REFER FENDER LH & RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	
17 TO SPRAY RR BOOT, RR BUMPER, REAR BUMPER CTR GARNISH, END PANEL, RR BUMPER REINFORCEMENT & BRACKET, REAR FENDER LH & RH.	1 PC	400.00	
		880.00	880.00

AH LIM
No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

DRAFT FINALISATION

M/S : CHOW THUAN LING SHIRLEY
BLK 501 ANG MO KIO AVE 5
#09-3700
SINGAPORE 560501

Claim No: MC0913342
No: MF0911403
Date: 23 Oct 2018
Policy No: MT/00283456/02
Veh Reg No: SJW698Y
Make/Model: VOLVO S60 D2

ATTN:

Your Ref No: SJW698Y
Claim Type: Third Party
Accident Date: 08/08/2018
TP Veh Reg No: SHD4539X

DRAFT FINALISATION

Repair Cost to Vehicle No (For Finalization):SJW698Y

Description	Quantity	List Price	Amount
		SS	SS
		Total	SS 4,965.19
		Less Excess	SS 0.00
		Amount Before GST	SS 4,965.19
		Add GST @ 7%	347.56
		Total Amount Payable	SS 5,312.75

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND THREE HUNDRED TWELVE AND CENTS SEVENTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 15/08/2018

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170
AUTHORISED SIGNATURE



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : CHOW THUAN LING SHIRLEY
BLK 501 ANG MO KIO AVE 5
#09-3700
SINGAPORE 560501

Estimate No: MC0913342
Date: 30 Aug 2018
Policy No: MT/00283456/02
Veh Reg No: SJW698Y
Make/Model: VOLVO S60 D2

ATTN:

Your Ref No: SJW698Y
Claim Type: Third Party
Accident Date: 08/08/2018
TP Veh Reg No: SHD4539X

Estimate Repair Cost to Vehicle No :SJW698Y

Description	Quantity	List Price SS	Amount SS
Supplementary Parts to Repair			
SPARE PARTS			
1 REAR BUMPER LOWER LIP CENTRE GARNISH	DD / cut 1 PC	486.40	
		486.40	
	Less 10%	48.64	437.76
		Total	SS 437.76
		GST Amount	SS 30.64
		Total Amount Payable	SS 468.40

The above vehicle was surveyed by KENNETH KONG -LKK on 15/08/2018

For AH LIM MOTOR COMPANY

AUTHORISED SIGNATURE



Photo taken by Simon 30/8/18
Email Photo Back



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18014752/Kvd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 27-11-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 4539X	Veh. Inspected	SJW 698Y	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18006026MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO S60 (A)	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	YV1FS84ABF2365224	Colour	METALLIC BLACK	
Odometer	67814	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R16	MICHELIN	4 mm	
L/H Front Tyre	215/55 R16	MICHELIN	4 mm	
R/H Rear Tyre	215/55 R16	MICHELIN	4 mm	
L/H Rear Tyre	215/55 R16	MICHELIN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2018	Inspection Date	15/08/2018	
Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 698Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT	TO REPAIR SEE LABOUR	2,484.80	-
1	REAR BOOT LOGO (VOLVO) CTR	NOT NECESSARY	99.50	-
1	REAR BOOT LOGO (S60) LH	NOT NECESSARY	90.80	-
1	REAR BOOT LOGO (D2) RH	NOT NECESSARY	90.80	-
12	REAR BOOT INSULATOR CLIPS	NOT NECESSARY	79.20	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	433.70	-
1	TAILLAMP RH	NOT NECESSARY	387.40	-
1	REAR BUMPER	BUCKLED	1,440.70	1,440.70
2	REAR BUMPER SIDE RETAINERS	O/S DISTORTED	115.20	57.60
12	REAR BUMPER CLIPS	NECESSARY	66.00	66.00
1	REAR BUMPER TOW COVER RH	MISSING	73.90	73.90
1	REAR BUMPER REINFORCEMENTWITH BRACKET	BENT	1,380.20	1,380.20
1	REAR BUMPER CTR GARNISH (CTR)	BUCKLED	90.70	90.70
2	REAR BUMPER SIDE REVERSE SENSOR	SHORTED (1 PC ONLY)	388.00	194.00
2	REAR BUMPER SIDE REVERSE SENSOR HOLDER	NECESSARY	34.60	34.60
1	REAR BUMPER LOWER LIP	DISTORTED	486.40	486.40
2	REAR BUMPER LOWER LIP REVERSE SENSOR	SHORTED (1 PC ONLY)	388.00	194.00
2	REAR BUMPER LOWER LIP REVERSE SENSOR HOLDER	NECESSARY	34.60	34.60
1	REAR BUMPER LOWER LIP CENTRE GARNISH (ADDITIONAL)	DENTED / CUT	486.40	486.40
	LESS 10% DISCOUNT		-865.09	-453.91
			7,785.81	4,085.19
LABOUR				
	TO DISCONNECT AND CHECK ELECTRICALWIRING,WIRE SOCKETS AND ETC.TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,TEST AND RECTIFY FOR PROPER FUNCTIONING.		40.00	20.00
	TO RESET REAR BOOT MOTOR,REVERSE SENSOR CTR,SIDE.		400.00	80.00

Report Ref No. CS/FCI18014752/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Reg. No. 199007150N GST Reg. No. 199007150N

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REINSTALL/REPLACE REAR BUMPER SIDE REVERSE SENSOR,LOWER LIP CTR REVERSE SENSOR.	NOT NECESSARY	180.00	80.00
	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.		180.00	-
	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD RR BUMPER REINFORCEMENT & BRACKET.TO KNOCK & REPAIR END PANEL,REAR FENDER LH & RH INNER PANELS AND AFFECTED AREAS.TO REFIT LISTED PARTS BACK SAME.INCLUSIVE OF THE REPAIR OF REAR BOOT AND REAR BOOT LOCK.		900.00	300.00
	TO SPRAY RR BOOT,RR BUMPER,REAR BUMPER CTR GARNISH,END PANEL,RR BUMPER REINFORCEMENT & BRACKET,REAR FENDER LH & RH.		900.00	400.00
			2,600.00	880.00
GRAND TOTAL			10,385.81	4,965.19
RECOMMENDED COST OF REPAIRS				4,965.19

Report Ref No. CS/FC118014752/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.