

Woon Meng Motor Pte Ltd

Office : 140 Upper Bukit Timah Road, #03-15 Beauty World Plaza, Singapore 588176

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

hongpai Insurance

TP CLAIM

To : India International Insurance Pte Ltd
Motor Claims Dept

Date : 02 Jan 2015

Dear Sirs :

Fax : 6224 4174

RE : ESTIMATE COST FOR TOYOTA LIEACE 5DR - GY3123U
ACCIDENT INVOLVING GY3123U & SHB8382P ON 29/12/2014

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Front bonnet. <i>ht</i>	1pc	
2	Front bonnet lock. <i>ht</i>	1pc	
3	Front bonnet hinge @\$53.ea. <i>ht</i>	2pcs	
4	Front bonnet side rubber o/s. <i>wt</i>	1pc	
5	Air cleaner box. <i>aw</i>	1pc	
6	Front wiper garnish. <i>de</i>	1pc	
7	Front fender @\$ <i>bt</i>	2pcs	
8	Front fender lamp @\$?	2pcs	
9	Front fender garnish o/s. <i>de</i>	1pc	
10	Front mudflat @\$ <i>x</i>	1pc	
11	Front fender side mirror garnish n/s. <i>aw</i>	1pc	
12	Front door n/s. <i>ht</i>	1pc	
13	Front door hinge n/s @\$?	2pcs	
14	Front door chek n/s. ?	1pc	
15	Front door lock n/s. <i>x</i>	1pc	
16	Front bumper beam. <i>ht</i>	1pc	
17	Front bumper. <i>wt</i>	1pc	
18	Front bumper reinforcement. <i>ht</i>	1pc	
Balance Carried Forward			\$ -

Balance Carried Forward

19	Front bumper retainer @\$38ea. <i>new</i>	2pcs
20	Front bumper fog lamp cover @\$ <i>new</i>	2pcs
21	Front headlamp @\$ <i>new</i>	2pcs
22	Front headlamp grille @\$ <i>new</i>	2pcs
23	Front side lamp @\$ <i>new</i>	2pcs
24	Front center grille. <i>new</i>	2pcs
25	Emblem. <i>new</i>	1pc
26	Clips @\$5ea. <i>new</i>	10pcs
27	Front support panel. <i>new</i>	1pc
28	Front support base panel. <i>new</i>	1pc
29	Front radiator. <i>new</i>	1pc
30	Front radiator fan cowling. <i>new</i>	1pc
31	Front radiator fan blade. <i>new</i>	1pc
32	Front radiator fan motor. <i>new</i>	1pc
33	Front air con condenser. <i>new</i>	1pc
34	Front wheel house @\$ <i>LH-RX, RY-16</i>	2pcs
35	Horn. <i>old</i>	1pc
36	Wiper tank. <i>del</i>	1pc
37	Spare tank. <i>del</i>	1pc
38	Fuel box. <i>del</i>	1pc
39	Top hose. <i>?</i>	1pc
40	Discharge hose. <i>new</i>	1pc
41	Suction hose. <i>new</i>	1pc
42	Air con valve. <i>?</i>	1pc
43	Air con dryer. <i>del</i>	1pc
44	Front windscreen glass. <i>new</i>	1pc
45	Front windscreen moulding. <i>new</i>	1pc
46	Nozzle @\$ <i>?</i>	2pcs
		\$ -
Add 20%		\$ -
47	Front windscreen sealant. <i>new</i>	1pc \$ 40.00
48	Front ERP bracket. <i>new</i>	1pc \$ 15.00
49	Coolant. <i>new</i>	1pc \$ 35.00
50	Front number plate. <i>new</i>	1pc \$ 25.00
Balance Carried Forward		\$ -

Balance Carried Forward

Labour Charge & Misc

Towing fee.

To remove, repair, replace & install damaged

1000

To numbering logo.

X

To R & R front radiator.

100

To R & R air con system.top up air con gas.

\$100

To remove & replace front windscreen glass.

120

To repair & straighten chassis.

200 photo

To remove & install door mechanism }
and for function. }

60

To R & R wiring.

40

To putty & spray painting.

1200

Total

\$ -

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufik 97495749
-wp-
13/8/18 @ 4pm
Resurvey after repair
sur @ (LKK Auto Consultants)
Repair Limit \$5000
of days.