

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8729T

DATE 13/8/2018 11:18

MAKE :

MODEL :

HYUNDAI i40

Whole Right Side

LS

Fz

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Fender (RH) ✓			\$ 619.00
	Front Fender Shield (RH) ?			\$ 169.80
	Rocker Panel Outer Garnish x 2			\$ 483.60
	Front Wheel Hub Cap (RH) ✓			\$ 150.70
	Front Door (RH) x 2			
	SUB TOTAL			\$ 1,423.10
	LESS 20%			\$ 284.62
	DISCOUNTED TOTAL			\$ 1,138.48
	Front Door Comfort Logo (RH) ✓			\$ 75.00
	Front Tyre (RH) x			\$ 216.00
				\$ 291.00
	Labour Charge			
	Panel Beating			\$ 500.00 400
	Spray Painting Charge			\$ 750.00 600
	Tuff Kote			\$ 50.00 20
	FRT Wheel Alignment			\$ 120.00 60
	Towing ✓ \$ 60			
	TOTAL LABOUR			\$ 1,420.00
	ESTIMATE TOTAL			\$ 2,849.48

Nett
Nett

Kelvin 10/11/14
13/8/18 1510hrs
2 hrs
4/5
After Repair photo

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.