(08/11/13)	
Bineur:	Kolvin

REF: CC3 /TM[18014767/Klsbs2

84	PODI GIAIMENT
From: Date:	Veh Nó: SH 6125 S Yr Regn: 25 &p , 200
EstimatedCost	Type: M.Car / M.Cycle / Bus / Van / Lorry / T & / Prime Mover /
ODITP INSITE RESIDE RESIEVA INVIMV	Truck / Trailer or
To Insped Vehicle No:	Make: - Upun In- South co 1991".
at Workshop m/s	Colour BL A/C: Insufed / Std / NI / NA
of	Sp.Reading 5 885/6 T/Radio: Inst Oed / Std / NI / NA
Insured: SUA 7626K	Eng/No:
Policy Na.	CNO: KAHETYIVAAA 793777
Claims No.	Gen. Cond: Good / F# / Poor / Burnt
Sum Insured: . Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or.
Make of Veh;	Modi: Nil / S/Rim / STDON/Rim or
	Tyre Size; F: 215/6.16
(Policy Condition)	R:
Remark: The veh had commenced its N/S	O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of Inspection.	TOYOTYOKO or Werlak
Bal, or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal. mm .
GIA / PR Seen: Consistent? : Yes or No	L/Bal. + mm L/Bal. + mm
Est. Repairs: days Res.: Yes or No	D.O.A. 13/8/12 D.O.I. 14/8/10
Lum Sum: % 3 Val.: Yes or No	Survey held at (DRE (Loyang)
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date: Person Contacted: Vehicle: 1	The U/C / Chassis frame / Body Structure affected due to collision.
Dale / Time Action / Instruction	The 0/0 / Gliassis fiame / Body Structure allected due to complete.
	Total loss Tokio
Scrapped	une comment 4.
	to Repair
91 (1)55 - X	
STA FLOCK - X	(6) (7)
Submit Total Loss as a	he to succommat uneconomical to report
net value - \$ 262.04	RECEIVED 1 6 AUG 2018
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
1) Track : Final Report	Resurvey No. of Trip: / Survey Fee: 250
DaleTine, File Return to?	Transportation:
	dd Fee: :Site Insp (\$)_s+Rs_si
	:Interview (\$) Photos
Report Format: Total Loss	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$)
	TOTAL

OMFORTDELGRO ENGINEERING

nember of COMFORTDELCRO

ComfortDelGro Engineering Pte Ltd

Date/Time: 13.08.2018 16:17 Page : 1

Ceam:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: JC NO: 305199464

MER

R)

COMFORT TRANSPORTATION PTE LTD

7010045

MER NO. 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

P)

JNT GARD NO.

SH 6125S	MILEAGE
MAKE: HYUNDAI	FUEL
MODEL SONATA	13.08.2018 11:25
23.09.2010	TARGET DATE
CHASSIS CODE KMHET41VMAA7	93777 COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 13.08.2018

NATURE: 3P 13.08.18/C

S/NO

LABOR CODE



KED & PASSED OUT BY:		
SERVICE ADVISOR		CUSTOMER'S SIGNATURE
	4	

edgement Slip

SH 6125S

LIMTS

Exit Pass

Vehicle No.:

SH 6125S

Service Advisor

Signature/Date

Name of Service Advisor

Date

To be kept by Security Guard

armed to Service Reception upon collection

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ᠬ	IDE.	мт с	ЭΤΛ	T = 0.	IENT
A	uu	IDE		,,,		

Date Of Report

13/08/2018 14:24

Date Of Accident

13/08/2018 00:45

Exact Location Of Accident

AIRPORT BOULEVARD > T1

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SH6125S

Insured/Policyholder

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

Co Reg No

199303821R

Email Address

FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer

HYUNDAI

Model

SONATA

Exact Purpose for which vehicle was being used at

time of accident

70000460

Are you claiming under your own insurance policy for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

MCOM0015

Cover Note Number

Driver

Name of Driver

TOH YEW CHOON

NRIC No

S0174955B

Date Of Birth

24/04/1953

Occupation

Date Of Driving Pass

OUTDOOR

Date of Diffing 1 at

15/05/1972

Driving Experience

46 YEARS AND 2 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-91286088

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

175 #07-153 BISHAN STREET 13

Postcode

570175

Was driver an employee of the Insured's Company

NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

YES

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME (OTHER)

BISHAN NPC

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SGA7626K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

TAN SWEE MENG VINCENT

NRIC/Passport Number

S7002358Z

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHB2102X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

TAN HOCK CHYE

NRIC/Passport Number

S6802990B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

REAR

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

TAN HOCK CHYE

Approximate Age

Injuries Sustain

NOT SURE

Injured person in which vehicle?

SHB2102X

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

			084/12
			1)5/16/12
			BISGAT
			C DSHB ZU
		TENA NAME	
The RAVIT	Son General far	a Quana TI	
DESCRIBE CIRCUMSTAN	CES OF THE ACCIDENT		
	5181 W.		
		0. nort	#5)
	Refer Police	No.	
	Doga Pove	10015	
	KIL	13	
	1201800		
421	11		124
			4
			-
			/
DECLARATION			Mund
DECLARATION			

Page 4 of 14





Police Station Of Origin:

Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999 -

Report No. T/20180813/2015		1 of 4
	Report No.	T/20180813/2015

4444	DF A TRAFFIC		Treat Second Name	Station Diony No.		
Date/Time Report Made: 13/08/2018 09:19		nade:	Vide Report No.:	Station Diary No. 21		
Informa	nt's Partici	ulars				
Name of Informant: TOH YEW CHOON			Address: APT BLK 175 BISHAN STREET 13 #07-153 SINGAPORE 570175			
ID Type / ID No.: NRIC NO / S0174955B		55B	Contact No.: Home/Office:	Mobile: 91286088		
Nationality: SINGAPORE CITIZEN		EN	Email:			
Sex: Age: Date of Birth: Male 65 24/04/1953			Type of Informant: Driver			
Race: Chinese			Language: Chinese	Institution / School Name:		
Occupation: Taxi driver			Driving Licence Information: Class: 2B.2A,2,3,4,5 Date of Expiry:			

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/08/2018 00:45	Type of Location Straight Road	
Location:			1		
	ULEVARD the left side of the road v			Road Speed Limit:	
Weather: Road Surface Clear Dry				Road Speed Little.	
Traffic Flow: Traffic Control: Dual Carriage Way Not Controlled				Traffic Volume: Heavy	
Type of Collis	ion: le Against - Parked Vehic	le		Anyone conveyed by ambulance:	

Details of V	ehicle Invo	lved	Committee of the	75 FEB. 82		
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
SGA7626K	Car	HONDA	STREAM 1.7	Black	Slightly Damaged	0
SH6125S	Car	HYUNDAI	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO		Slightly Damaged	0
SHB2102X	Car	HYUNDAI	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR	Yellow	Slightly Damaged	0



Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757

Report No. T/20180813/2015

2 of 4

Tel No: 1800-5529999

CONTINUATION OF REPORT

Any Pedestrian Ir	volved: No				
Andread of the second second second second second	No. of Pedestrians Injured: NIL				ing: NA
Driver					
Name	TAN SWEE MENG VINCENT		ID No.		S7002358Z
Related Vehicle	SGA7626K (Car)		Conta	ct No.	NIL
Hospital/Clinic	NIL			of g ce & Date	Class; NIL Date of Expiry: NIL
Date Treatment	NIL:	Date Disch	arge	NIL	
	ted Medical Leave NIL	Degree of I	201100 20		
Driver		5 5 160 150 150 46		235V	
Name	TOH YEW CHOON				S0174955B
Related Vehicle	SH6125S (Car)			ct No.	91286088
Hospital/Clinic	NIL		Class Driving Licent Expiry	g ce &	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	NIL	Date Disch		NIL	
	ted Medical Leave NIL	Degree of I	of Injury NIL		
Driver				Marie I	Mean and the second
Name	TAN HOCK CHYE				S6802990B
Related Vehicle	SHB2102X (Car)			ct No.	NIL
Hospital/Clinic	NIL			of g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disch		NIL	
	ted Medical Leave NIL	Degree of I		NIL	

Brief Details.

On 13/8/2018 at about 0045hrs. My car(SH6125S) was parked and stationary on the 4th lane of airport boulevard towards terminal 3 in a queue of other cars. Suddenly I felt an impact come from the rear of my car, causing my vehicle to collide into the vehicle in front of mine. After coming out to inspect, I found that another car(SGA7626K) had accelerated and collided into the rear bumper of my car. My vehicle had also collided with the vehicle(SHB2102X) in front of mine. All drivers exchanged contact information. I have an in car camera facing forwards and I believe it has recorded the event, it has been seized by traffic police. I am lodging this report as requested by Traffic Police. Report vide: P/20180813/0005/.





Police Station Of Origin: Bishan N.P.C 20 Bishan Street 23 SINGAPORE 579757 Tel No: 1800-5529999 3 of 4 Report No. T/20180813/2015

CONTINUATION OF REPORT

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	3821R
Vehicle No.:	SH61255
Vehicle to be Exported:	Yes
Intended De-registration Date:	14 Aug 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	D4EA9819726
Chassis No.:	KMHET41VMAA793777
Maximum Power Output:	110,0 kW (147 bhp)
Open Market Value:	\$16,133.00
Original Registration Date:	23 Sep 2010
First Registration Date:	23 Sep 2010
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$16,133.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Sep 2018
PARF Rebate Amount: Intended COE Rebate Details	\$9,679.00
COE Expiry Date:	22 Sep 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$25,111.00
COE Rebate Amount:	\$331.00
Total Rebate Amount: Message	\$10,010.00
	be further renewed. The vehicle must be de-registered upon COE expiry or when the

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 14 Aug 2018


ОК

























Sweep Move to V Categories V



Favorites

A Lim Tien Siona

Inbox

Drafts

Sent Items

Deleted Items

Archive

Conversation His

Junk Email

Migrated_Emails

Notes

Unfiled

v Groups

Accident involving SH 6125S (Left abt 35+days) and SGA7626K dated 13.08.18

Doris Lim Puay Noi

To - Lim Tien Siong

Co - Tan Pei Wei, Roger How Keen Meng: - Christine Tay Siew Hway 2

SH6125S.pdf

Download Saye to OneDrive - ComfortDelGro Corporation Limited

Hi Tien Siong

Received with thanks. Will put up T/L.

Regards

Doris Lim

Fleet Safety Department

Comfort Transportation Pte Ltd / Citycab Pte Ltd Hotline: 6550 8768 / DID: 6550 8606 / Fax: 6453 0491

" Think Safety. Drive Safely."

Lim Tien Siong

Tue 14/8/2018 10:34 AM

img-814102221-0001.pdf

Download Save to OneDrive - ComfortDelGro Corporation Limited

Hi Doris,

SH 6125S - Date of Reg: 23.09.2010

NAF against Tokio Marine

Refer to attach - Estimate total at \$ 17,209.86

Surveyed and Recommendation by LKK, Mr Kalvin Ang

- Uneconomical to repair.
- Recommend to scrap.

Can provide the said book value and COE rebate.

Awaits your decision.

Thanks.

Best Regards,

Lim Tien Siong

Taxi Crash Repair / ComfortDelgro Engineering Pte Ltd

Off:62148398 / Fax:65468156

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6125S

Tokio Marine-45 DATE 14/8/2018

ONATA LKK-Kalvin Tyre: Westlike P13

MAKE



Qty	Parts Description/ Labour	Type	Unit Price	A	Mount
	Radiator Grille			S	282.10
	Radiator Grille U Moulding			\$	108.90
	Front Bumper Cover			\$	538.80
	Front Bumper Sponge			\$	136.30
	Front Bumper Reinforcement			S	504.10
	Front Bumper Grille (LH)			5	17.60
	10 00		\$ 22.40	S	44.80
	Front Bumper Bracket Top (LH/RH)		\$ 29.20	1 835	58.40
	Front Bumper Protector (LH/RH)		3 29.20		1,023.00
	Headlamp Support Panel Assy			\$	
	Headlamp (LH)			\$	797.90
	Front Fender (LH)			\$	593.00
	Front Fender Shield (LH)			\$	86.00
	Front Fender Retainer			S	9.20
	SUB TOTAL			s	4,200.10
	LESS 20%			S	840.02
	DISCOUNTED TOTAL			\$	3,360.08
	Front Fender Advertisement Logo (LH)			s	100.00
				s	100.00
	Labour Charge Panel Beating Spray Painting Charge			s s	850.00 750.00
	Wiring Charge			\$	50.00
	Tuff Kote			\$	50.00
	TOTAL LABOUR			S	1,700.00
	ESTIMATE TOTAL		A	s	5,160.08

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*
VEHICLE NO: SH 6125S

MAKE:

LKE - KALVIM

ODEL	: HYUNDAI SONATA Parts Description/ Labour	Type	Uni	it Price	A	mount
Qty	Boot Lid	Турс	-	1	S	1,349.50
	Boot Lid Rubber			- 1	S	110.90
	Boot Lid Lock Upper				S	132.10
	Boot Lid Lock Lower				S	30.30
	Boot Lid Sonata Plate				S	43.60
					\$	24.20
	Boot Lid Hyundai Plate				\$	26.10
	Boot Lid 'H' Emblem				5	22.70
	Boot Lid CRDI Plate		s	230.20	S	460.40
	Boot Lid Lamp (LH/RH)		۵	250.20	S	578.40
	Rear Bumper				\$	483.30
	Rear Bumper Reinforcement				\$	22.00
	Rear Bumper Clip				5	137.40
	Rear Bumper Sponge				S	185.80
	Rear Bumper Under Cover		s	38.00	S	76.00
	Rear Bumper Protector (LH/RH)		S	344.00	S	688.00
	Tail Lamp (LH/RH)		2	344.00	S	391.80
	Rear Panel				\$	95.80
	Rear Panel Garnish				\$	863.00
	Spare Tyre Panel				\$	200.30
	Spare Tyre Panel Cushion				S	135.30
	Rear Towing Hook				\$	1,935.90
	Rear Fender (LH)				S	1,190.50
	Rear Fender Inner Panel (LH)		1		S	74.10
	Rear Fender Inner Lining (LH)				190	37.40
	Rear Tray Lugg Side (RH)				\$ \$	49.40
	Rear Fender Air-Duct		1		\$	180.90
	Rear Fender Trim Board (LH)				5	60.00
	Rear Windscreen Moulding				3	00.00
	SUB TOTAL				\$	9,585.10
	LESS 20%				S	1,917.02
	DISCOUNTED TOTAL				\$	7,668.08
	Boot Lid Comfort Logo & Tel No. Sticker				s	30.00
	Boot Lid Connort Logo & Tel No. Sticker Boot Lid Advertisement Logo				S	100.00
	Rear Bumper Reverse Sensor				S	135.70
	Rear Bumper Reverse Sensor Rear Bumper Advertisement Logo				S	50.00
	Rear Fender Advertisement Logo (LH/RH)		s	100.00	S	200.00
	Rear Fender Advertisement Logo (LH/KH) Rear Fender Comfort Sticker (LH)			100.00	S	30.00
	Rear Windscreen Sealant				S	46.00
					\$	591.70

0.	Doub Book of the Paris	hour	Type	Unit Price	SH 61258	
Qty	Parts Description/ La	10 m	Type	Unit Price	Amour	at
	Labour Charge	ko marine		0.1		
	Panel Beating	(115)		12/2	\$ 2,000	
	Spray Painting Charge	-40)		15/5	\$ 1,250	
	Wiring Charge			1		0,0
	Tuff Kote	VV-VALVUT			\$ 50	0,0
	Towing Charge	-KF FMIIII			\$ 50	0.0
	Remove/Refix Cushion & Uphols	terv Rear			\$ 150	0.0
	Remove/Refix Rear Windscreen C	13			\$ 120	0.0
	Remove/Refix Reverse Sensor					0.0
	Remove Rena Reverse Sensor				, ,-	Y.Y.
		TOTAL LABOUR			\$ 3,790	0.0
	E	STIMATE TOTAL		B	\$ 12,049	9.7
				Total Est. A+B=	17,209) a S
	Kahirelle 14/8/8 1650gr uneconwed &	1020L	the Repa • To resurv • To displa • Parts pri • Third pa • No illegal • Suppler is subje	Consultants hence notificer of the following: by before after spray painting a damaged part(s) during resurces are subject to confirmation to survey is on a "Without Prejul modification(s) is allowed entary item(s) must be resurved to final approval from Insurantiged by Repairer	vey idice" basis	
	fork who					

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Page 2 of 2

	nivision	
17.	Safety	
tetion	Fleet	
OCEST	101	.2016
Trac	NEW	.07
fort	icle	AT 33
8	S	2

Amport ID : ZPICTPL32 DATE : 14.08.2018 TIME : 14:45:47 Co.Code : CTPL Licence Pl.Xo : SH 61255 Old Asset No : 10625836-0 Veh.Model : Hyundai Scrate Reg.Date : 23.09.2010 Accident.Date : 13.09.2016 Accident.Date : 13.09.2018 Veh.Age : 095

Scrap value page Refund S	1.00		9,68	0.00				0.00		9, 661.00	9, 681, 00	
Accum. Dep	21,999.00-	3,226.42-	6,453,00	25,111.00-	00.00	00.00	00.00	0.00	140.00-	56,929.42-	31,818,42-56,929,42-	
Cur. Year Dep	-488.87-	772.70-	143,40-	558.02+	00.00	0.00	0.00	0.00	5.17-	1,265,10-	1,265.10-	
Op.Acc.Dep	21,510,13-	3,154,72-	6,309.60-	24,552.98~	00.00	00'0	00.00	0.00	136.89-	55,664.32-	31,111.34-	
250	22,000,00	3,226.42	16,133,00	25,111.00	00.00	0.00	00.00	00.0	240,03	66,650.42	51,499.42	2
Bal.Dap.Value Asset Desciption 1	Si 61255 HSV 23.09.2010 BASIC COST	SH 61255 MEN 23.09.2010 INDOST DUTY	SH 61255 HSV 23.09.2010 ARF 10052NV816133	SH 61255 HSN 23.09.2010 CCE 801	SH 6125S HSN 23.09.2010 CCE 709 UP		61255 HSN 23.09.2010 FRID	SH 61255 HSM 23.09.2010	SH 51258 HSN 23.09.2010			
Bal .Dep.Walue	0.00	0.00	0.00	0.00	0.00			0.63		00.0	0.0	0.00
Per.Mth.Dep	244.43	35.85	71.70	279.01	0.00	0.00	0.00	0.00	¥,	632.55	353.54	632.55
SA No Bal. Dep. William	0 000	1 000	2 000	3 000	000	5000	0000 9	2000	000		COS Vehicle	
Asset No	10025836	10025836	10025836	10025836	10025836	10025836	9585601	10025836	10025836			

SH 61255

(1) cost of fixi = 66610.42 AKP688= 9679 AKP688= 9679 AKP688= (66610.42 - 9639) + 96 = 593.04 (593.04 X 1) + 9649 = 10272.04 (3) Nell who = 10272.04 - 10010 = \$262.04

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Su	bmitted	Ins Authled	Status		
Main	14 Aug 2018 15:39 Sendback Est	14 Aug 2018 15:42 \$\$10.00	15 Aug 2018 15:14 Edit Adj Rpt	S\$10.00 Edit Estimates	S\$10. View	Security in a		Pending for Surve Report Cancel Case		
	Main	Refe	erence	Claim	Details		Documents		Show All	
CLAIM SU	BFOLDER DET	AILS		The state of the s			Andrew St. W. and Physics			
Insured:	CTPL, Co.	Reg. No.: 199303	821R							
Main Claimant:	CTPL									
Vehicle Reg No.:	SH6125S			Date	of Loss:		18 01:00 - :59 hs and 21 Days Fro	om LTA Reg Da	te (Man Yr)]	
Claim Type	TP / M180	TP / M1803993				MU011843 (Third Party Only) Coverage: 01/12/2017 - 30/11/2018				
Vehicle Reg No. (Insured):	SGA7626K			100000000000000000000000000000000000000	y No. mant):					
				Exce		S\$0.00	15% 55% 85%			
Repairer: Handling		IGro Engineering								
Insurer:	Tokio Marii	ne Insurance Sin	gapore Ltd (HC	Q) - Tel: 6221 611	1 [Har	ndled by Zh	neng Hanyang - 6	5926416]		
Adjuster:	27/08/201		.td (HQ) - Tel: 6	256-3561 [Har	dled by F	KALVIN AN	IG WEI KUN]	Final Rpt	lue	
Adj Asg. Remarks:	PLS. CHECK	CONSISTECNY OF	THE DAMAGE.							
ASSOCIA	TED MAIL REC	EIVED					Vi	ew All Com	pose Case Ma	
There are r	no mail for this c	ase.								
ALL ASSO	CIATED TASK	s⊟				View All	Search Tasks	Create New Ta	sk Complet	
Due Dat	e Priority	Type Task G	roup Subje	ct Handler	Assign	ed By	Completed On	Created	On Done	

Claim Documents

SH6125S (M1803993) [SGA7626K] TP CTPL Aug 13 2018 1:00AM [CTPL] ComfortDelGro Engineering Pte Ltd

Up	load Documents Upk	ad Photos Compose New Letter	View	View in Brow	vser ▼
Ass	essment Reports		1 per	page ▼	•
No.	Finalized On	ComfortDelGra Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	14/08/18 15:42	Repairer Estimates	0	Load HTM	
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)		Thumbnail	Print
1	15/08/18 15:15	Accident Statement From:SC - Reg. No: SGA7626K, Claimant: TNG WEE LOY	0	Load HTM	
Pho	otos/Images		3 per	page ▼	•
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	15/08/18 16:47	General View	0	Load JPG	•
2	15/08/18 16:47	General View	0	Load JPG	•
3	15/08/18 16:47	General View	0	Load JPG	•
4	15/08/18 16:47	General View	0	Load JPG	•
5	15/08/18 16:47	General View	0	Load JPG	•
6	15/08/18 16:47	General View	0	Load JPG	•
7	15/08/18 16:47	General View	0	Load JPG	•
8	15/08/18 16:47	General View	0	Load JPG	•
9	15/08/18 16:47	General View	0	Load JPG	•
10	15/08/18 16:47	General View	0	Load JPG	•
11	15/08/18 16:47	General View	0	Load JPG	•
12	15/08/18 16:47	General View	0	Load JPG	•
13	15/08/18 16:47	General View	0	Load JPG	•
14	15/08/18 16:47	General View	0	Load JPG	•
15	15/08/18 16:47	General View	0	Load JPG	•
16	15/08/18 16:47	General View	0	Load JPG	•
17	15/08/18 16:47	General View	0	Load JPG	•
18	15/08/18 16:47	General View	0	Load JPG	•
19	15/08/18 16:47	General View	0	Load JPG	•
20	15/08/18 16:47	General View	0	Load JPG	•
21	15/08/18 16:47	General View	0	Load JPG	•
22	15/08/18 16:47	General View	0	Load JPG	•
23	15/08/18 16:47	General View	0	Load JPG	•
24	15/08/18 16:47	General View	0	Load JPG	•
25	15/08/18 16:47	General View	0	Load JPG	•
26	15/08/18 16:47	General View	0	Load JPG	•
27	15/08/18 16:47	General View	0	Load JPG	•
28	15/08/18 16:47	General View	0	Load JPG	•
29	15/08/18 16:47	General View	0	Load JPG	•
30	15/08/18 16:47	General View	0	Load JPG	•

Ass	essment Reports		1 per pa	ige ▼	~
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	1	l'humbnail	Print
31	15/08/18 16:47	General View	0	Load JPG	•
32	15/08/18 16:47	General View	0	Load JPG	•
33	15/08/18 16:47	General View	0	Load JPG	•
34	15/08/18 16:47	General View	0	Load JPG	•
35	15/08/18 16:47	General View	0	Load JPG	
36	15/08/18 16:47	General View	0	Load JPG	•
37	15/08/18 16:47	General View	0	Load JPG	~
38	15/08/18 16:47	General View	0	Load JPG	•
39	15/08/18 16:47	General View	0	Load JPG	•
40	15/08/18 16:47	General View	0	Load JPG	•
41	15/08/18 16:47	General View	0	Load JPG	•
42	15/08/18 16:47	General View	ő	Load JPG	•
43	15/08/18 16:47	General View	ō	Load JPG	•
44	15/08/18 16:47	General View	0	Load JPG	•
45	15/08/18 16:47	General View	0	Load JPG	•
46	15/08/18 16:47	General View	0	Load JPG	•
47	15/08/18 16:47	General View	0	Load JPG	•
48	15/08/18 16:47	General View	0	Load JPG	
49	15/08/18 16:47	General View	0	Load JPG	•
50	15/08/18 16:47	General View	0	Load JPG	•
51	15/08/18 16:47	General View	0	Load JPG	•
					•
52	15/08/18 16:47	General View	0	Load JPG	
53	15/08/18 16:47	General View	0	Load JPG	Y
54	15/08/18 16:47	General View	0	Load JPG	•
55	15/08/18 16:47	General View	0	Load JPG	•
56	15/08/18 16:47	General View	0	Load JPG	•
57	15/08/18 16:47	General View	0	Load JPG	•
58	15/08/18 16:47	General View	0	Load JPG	•
59	15/08/18 16:47	General View	0	Load JPG	•
60	15/08/18 16:47	General View	0	Load JPG	•
61	15/08/18 16:47	General View	0	Load JPG	2
62	15/08/18 16:47	General View	0	Load JPG	•
63	15/08/18 16:47	General View	0	Load JPG	•
64	15/08/18 16:47	General View	0	Load JPG	•
65	15/08/18 16:47	General View	0	Load JPG	•
66	15/08/18 16:47	General View	0	Load JPG	•
67	15/08/18 16:47	General View	0	Load JPG	•
Doc	umentation		1 per pa	ige ▼	•
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	1	Thumbnail	
1	14/08/18 15:41	E-filed GIA report		Load PDF	
2	14/08/18 15:41	ESTIMATE		Load PDF	
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Thumbnail	Print

Documents Checklist

Reset Save Print

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Repairer Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/TMI18014767/K1SBS2

Date:

17/08/2018

REFERENCE

Handling Insurer:

Tokio Marine Insurance Singapore Ltd

Policy No:

MU011843

Claimant Vehicle No:

SH6125S

Insured Vehicle No:

SGA7626K

Claim No:

Date of Loss:

13/08/2018

Nature of Claim:

TP

M1803993

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SH6125S

Make & Model:

HYUNDAI SONATA, 2.0 D CRDi Turbo (NF) (A)

Engine No: Chassis No: D4EA9819726

Reg. Date:

23/09/2010 (Man. Year: 2010)

Odometer:

KMHET41VMAA793777 588516 km

Colour: Engine Capacity: Blue

1991 cc

Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

Pre-accident Condition:

Good

CONDITION OF TYRES

Front Tyre Size:

215/60R16

Rear Tyre Size:

215/60R16

Front Left Side:

West Lake 7 mm

Rear Left Side: Rear Right Side: West Lake 7 mm West Lake 7 mm

West Lake 7 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	10.00	10.00	0.00	0.00
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10.00	10.00	0.00	0.00
+ GST 7.00/7.00% (S\$)	0.70	0.70	0.00	0.00
Nett Amount (S\$)	10.70	10.70	0.00	0.00

INSPECTION

Date of Assignment:

15/08/2018 Present Location:

ComfortDelGro Engineering Pte Ltd (Loyang) ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected:

Adjuster:

14/08/2018

Inspected At:

59 Loyang Drive Singapore 508969

Estimated Period of Repair:

KALVIN ANG WEI KUN

0.0 days

Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

\$10,272.04 Book Value : OMV : \$16,133.00 \$9,679.00 PARF Rebate (1) : Quota Premium Paid : \$25,111.00 COE Rebate (2) : \$331.00 Total Rebate (1) + (2) = : \$10,010.00

The total amount incurred will be Market Value \$10,272.04 minus Total Rebate \$10,010.00 = \$262.04 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Aug 2018)

HYUNDAI SONATA 2.0 D CRDi Turbo (NF) (A) (Catalogue:Merimen Singapore 1.0) Parts: 143

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SH6125S)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the Validity:

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount
Mis	cella	neous Items			
1	1	OD/TP Case (Insurer)		10.00	10.00
			Sub Total (S\$)	10.00	10.00

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >