

INS. CASE OWNER:

Jenny.

CC 4/QBE1801

4785, K p6307

LKK:

IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

10/8/18

Date / Time:

14/8/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLB 1188H

Name of Insured:

TAN WAH KONG

Insured Tel No.:

HP:

818/18

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN WEI WEN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

S-VOLVERTI - non road

MOTOR

BEAS BASAH RD SUD KO

TWO LANE HIGHWAY

OI GIA REPORT: YES / NO TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLB 667AP



INSRS:

WSP:

Tel:

Liability:

RMKS:

Kny motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

URGENT

Date/Time

SLB 667AP - X

SLB 1188H - X

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

20/12/18

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup)

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

11/10/18
1/11/18

12/11/18 - Old rear ended tp.

24/12/18 - File pass to experimandale

10/1/19 - File pass to Shu Pei to (1st up).
QBE will handle.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

x

days)

Loss of Use (LOU):

S\$

(

x

days)

Loss of Income (LOI):

S\$

(

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COPY SENT
10/1/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

300.00

REF: QBE

ASSIGNMENT

From Date: 15082018

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SLD 6679P

at Workshop no/s

of Blk 9 8m Ming Ind Est #01-46

Insured

Policy No.

Claims No.


Sum Insured: Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection,



Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date Person Contacted:

Vehicle: IN / OUT

Veh No: SLD 6679P Yr Regn: 06 16

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis A/C 1598

Colour: M. Black A/C Insured / Std / NI / NA

Sp Reading: 12454 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053REH104547251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 205/55R16

R:

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 9 mm

L/Bal: 9 mm

D.O.A: 8/8/18

Survey held at

Rear

R/Bal: 9 mm

L/Bal: 9 mm

D.O.I: 15/8/18

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

16/8 FRM pers to Customer

US \$ 2750 (Reel \$ 2057.49 / 4391)

Date/Time: File Pass to?

☐

Prel. Report

11

☐

Final Report

Date/Time: File Return to?

21

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. S + RE. 21

2. Phone:

3. Other:

4. Total:

Report Format:

Lump Sum / I.B.I. (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Insp (\$)☐ Weekend (\$)

Total:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

QBE INSURANCE (SINGAPORE) PTE LTD

Ref : CC4/QBE18014785/Kpb3

1 RAFFLES QUAY #29-10 SOUTH
TOWERSINGAPORE 048583

Date : 14-08-2018



Code : QBE

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 1188H	Veh. Inspected	SLD 6679P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	14/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	08/08/2018	Inspection Date	15/08/2018
Survey held at	KAY MOTOR BLK 9 SIN MING INDUSTRIAL ESTATE #01-46 SINGAPORE 575644		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Ky
Kenneth. pls advise CAR
Thank You!

KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
Tel: 6458 2283 Fax: 6459 8863
Email: kayautosg@yahoo.com

Lee Choon Keong

14 August 2018

Estimate To Repair Toyota Altis - SLD 6679P

1pc	rear bumper
1pc	rear bumper reinforcement
1pc	rear bumper centre bracket
2pcs	rear bumper side retainer @\$132.35
1pc	rear bumper n/s reflector
1pc	rear boot lid
1pc	rear boot lock
1pc	rear boot n/s lamp
2pcs	rear taillamp @\$381.90
1pc	rear boot "Toyota" emblem
1pc	rear boot "Altis" emblem
1pc	rear end panel

less 25%

1set	reverse sensor
1set	rear bumper clip

To repair & panelbeat rear boot inner panel, straighten rear chassis,
cut/weld & renew rear end panel, dismantle &
fit the above parts.
To putty & spray painting

Not Authorized
1. B. I
Runway Bk painting
6/1 Sep 8 2750k - ok
4-5 days

Bm	\$ 531.75	✓
Bs	327.45	✓
R	181.90	X
Ort	264.70	✓
Ln	121.75	X
Buc	781.45	✓
Ad	277.40	✓
Rn	274.30	X
Ln	763.80	X
Mc	81.10	✓
Mc	76.60	✓
Bs	374.45	✓

4056.65

1014.16

3042.49

short 280.00 sn

rec 35.00 sn

750.00

700.00

Total: \$ 4807.49

Additional:

* rear boot rubber - 175.45

Surry - 15/8/18



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC4/QBE18014785/Kpb3

Date: 16.08.2018

The Motor Claims Department
M/s QBE INSURANCE (INTERNATIONAL) LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SLD6679P

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 15.08.2018 at the premises of M/s Kay Motor and have the following to report:-

Workshop Estimate Amount	: S\$	4,807.49
Revised Estimate Amount	: S\$	2,590.34
"Check" Items Amount	: S\$	1,464.30
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 4-5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

KAY MOTOR
BLOCK 9 SIN MING INDUSTRIAL ESTATE
#01-46
SINGAPORE 575644
Tel: 6458 2283 Fax: 6459 8863
Email: kayautosg@yahoo.com

Not Withheld
1.B.1
Resurvey B4 paint
4-5 days

Lee Choon Keong

14 August 2018

Estimate To Repair Toyota Altis – SLD 6679P

1pc	rear bumper
1pc	rear bumper reinforcement
1pc	rear bumper centre bracket
2pcs	rear bumper side retainer @\$132.35
1pc	rear bumper n/s reflector
1pc	rear boot lid
1pc	rear boot lock
1pc	rear boot n/s lamp
2pcs	rear taillamp @\$381.90
1pc	rear boot "Toyota" emblem
1pc	rear boot "Altis" emblem
1pc	rear end panel

<i>Rr</i>	\$ 531.75	—
<i>Rr</i>	327.45	—
	181.90	?
<i>D.1</i>	264.70	✓
	121.75	?
<i>Bu</i>	781.45	—
<i>Re</i>	277.40	✓
	274.30	?
<i>L</i>	763.80	X
<i>Re</i>	81.10	—
<i>Re</i>	76.60	—
	374.45	?

4056.65

1014.16

3042.49

1set	reverse sensor
1set	rear bumper clip

<i>Shor</i>	280.00	sn	<i>2001A</i>
<i>Re</i>	35.00	sn	—

To repair & panelbeat rear boot inner panel, straighten rear chassis,
cut/weld & renew rear end panel, dismantle &
fit the above parts.

750.00 ?

To putty & spray painting

700.00 *600h*

Total: \$ 4807.49

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC4/QBE18014785/Kpb3

14 NOV 2018

TAN WAH KEONG
115 COMPASSVALE BOW
#01-10
SINGAPORE 544815

Dear Sir/Madam,

ACCIDENT INVOLVING SLB 1188H AND SLD 6679P ON 08/08/2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, QBE INSURANCE (SINGAPORE) PTE LTD to deal with the third party claim against your policy.

We have received a claim from SLD 6679P against your motor insurance policy.

Based on the accident report and accident scenario, liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Chew Nsiao Tong
Case Handler
DID: 6742 3197
FAX: 6741 4108
Email: chewht@lkkauto.com

c.c. *QBE Insurance (Singapore) Pte Ltd*
(Motor Claims Dept)

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Wednesday, 9 January 2019 4:47 PM
To: 'Jenny Toh'
Cc: Admin A
Subject: RE: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Hi Jenny,

We are in the midst of closing our file and will submit report to you by this week.

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)
Sent: Friday, 4 January 2019 4:48 PM
To: 'Jenny Toh' <jenny.toh@qbe.com>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: FW: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Dear Sir / Madam,

Thank you for your email.

Dear Hsiao Tong,

FYNA.

Thank you

To check availability of the case handler, you may contact the undersigned

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh <jenny.toh@qbe.com>
Sent: Friday, 4 January 2019 4:24 PM

To: Shu Pei (LKKAUTO) <shupe@lkkauto.com>

Cc: Jenny Toh <jenny.toh@qbe.com>

Subject: FW: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Our ref: VC011739

Hi Shu Pei

Is the survey report ready?

From: Jenny Toh

Sent: Monday, 29 October 2018 5:51 PM

To: Shu Pei (LKKAUTO) <shupe@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Subject: RE: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Our ref: VC011739

Dear Shu Pei

Please find attached as per requested.

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAUTO) <shupe@lkkauto.com>

Sent: Monday, 29 October 2018 5:43 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Subject: RE: Accident Involving SLB1188H & SLD6679P on 08/08/2018

WITHOUT PREJUDICE

Dear Jenny,

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh <jenny.toh@qbe.com>

Sent: Thursday, 25 October 2018 3:47 PM

To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Our ref: VC011739

Dear Shu Pei

We refer to this matter.

What is the outcome?

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>

Sent: Thursday, 16 August 2018 5:12 PM

To: Jenny Toh <jenny.toh@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: RE: Accident Involving SLB1188H & SLD6679P on 08/08/2018

WITHOUT PREJUDICE

Dear Jenny,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SLD 6679P at M/s Kay Motor.

Enclosed for your perusal is:

- TP's GIA report
- Estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Tuesday, 14 August 2018 11:43 AM

To: 'Jenny Toh' <jenny.toh@qbe.com>; assignments <assignments@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Dear Jenny,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jenny Toh [<mailto:jenny.toh@qbe.com>]

Sent: Tuesday, 14 August, 2018 10:38 AM

To: assignments <assignments@lkkauto.com>

Cc: Jenny Toh <jenny.toh@qbe.com>

Subject: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Our ref: VC011739

Dear Sir

Kindly survey the TP Claim :-

Insured : SLB1188H

TP Vehicle : SLD6679P

Date of accident : 08/08/2018

Contact: as below

Kindly acknowledge receipt.

regards

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225
Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



From: Yahoo! [<mailto:kayautosg@yahoo.com>]
Sent: Tuesday, 14 August, 2018 10:21 AM
To: Jenny Toh <jenny.toh@qbe.com>
Subject: Re: Accident Involving SLB1188H & SLD6679P on 08/08/2018

Dear Ms Jenny,

Thanks you for the e-mail.

We will select M/S LKK Auto Consultants Pte Ltd to survey
our clients' vehicle - SLD 6679P

Kindly arrange for survey soonest possible.

Best Regards
Teresa Lim
Kay Motor
Tel: 6458 2283
Fax: 6459 8863

On Monday, August 13, 2018, 6:31:17 PM PDT, Jenny Toh <jenny.toh@qbe.com> wrote:

Our ref : VC011739

Dear Sir

We refer to your fax dated 13/08/2018

We intent to conduct a full survey of the damage to your client's vehicle. We propose to use one of the motor surveyors named in the attached list:

COMPANY
Appraisal Associates Pte Ltd

Automobile Inspection Services
KM Auto Assessors Pte Ltd
LKK Auto Consultants Pte Ltd
Priority Services
Infiniti Appraisal Service
Quantum Risk Management (S) Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors.

Jenny Toh
Senior Assistant, Claims
QBE Emerging Markets – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1225

Email: jenny.toh@qbe.com
Visit us on the web at www.qbe.com.sg



IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC4/QBE18014785/Kpb3q2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 15-01-2019		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 1188H	Veh. Inspected	SLD 6679P	
Policy No.	8-V0014271-MVA-R001	Coverage (\$)	0.00	
Claim No.	VC011739	Excess (\$)	0.00	
Assign From	JENNY	Assign Date	14/08/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104547251	Colour	METALLIC BLACK	
Odometer	12454	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	9 mm	
L/H Front Tyre	205/55 R16	DUNLOP	9 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	9 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	9 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2018	Inspection Date	15/08/2018	
Survey held at	KAY MOTOR BLK 9 SIN MING INDUSTRIAL ESTATE #01-46 SINGAPORE 575644			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 6679P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	531.75	531.75
1	REAR BUMPER REINFORCEMENT	BENT	327.45	327.45
1	REAR BUMPER CENTRE BRACKET	TO REPAIR SEE LABOUR	181.90	-
2	REAR BUMPER SIDE RETAINER @\$132.35	DISTORTED	264.70	264.70
1	REAR BUMPER N/S REFLECTOR	SERVICEABLE	121.75	-
1	REAR BOOT LID	BUCKLED	781.45	781.45
1	REAR BOOT LOCK	DENTED	277.40	277.40
1	REAR BOOT N/S LAMP	SERVICEABLE	274.30	-
2	REAR TAILLAMP @\$381.90	SERVICEABLE	763.80	-
1	REAR BOOT "TOYOTA" EMBLEM	NECESSARY	81.10	81.10
1	REAR BOOT "ALTIS" EMBLEM	NECESSARY	76.60	76.60
1	REAR END PANEL	BENT	374.45	374.45
1	REAR BOOT RUBBER (ADDITIONAL)	CUT	175.45	175.45
	LESS 25% DISCOUNT		-1,058.03	-722.59
			3,174.07	2,167.76
SPECIAL NETT ITEMS				
1	SET REVERSE SEBSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
			315.00	235.00
LABOUR				
	TO REPAIR & PANELBEAT REAR BOOT INNER PANEL, STRAIGHTEN REAR CHASSIS, CUT/WELD & RENEW REAR END PANEL, DISMANTLE & FIT THE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER CENTRE BRACKET.		750.00	550.00
	TO PUTTY & SPRAY PAINTING.		700.00	600.00
			1,450.00	1,150.00
GRAND TOTAL			4,939.07	3,552.76
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,750.00

Report Ref No. CC4/QBE18014785/Kpb3q2



Report Ref No. CC4/QBE18014785/Kpb3q2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.