

KAY MOTOR  
BLOCK 9 SIN MING INDUSTRIAL ESTATE  
#01-46  
SINGAPORE 575644  
Tel: 6458 2283 Fax: 6459 8863  
Email:kayautosg@yahoo.com

*Not Authorized  
1.B.1  
Resurvey B4 paint  
4-5 days*

Lee Choon Keong

14 August 2018

Estimate To Repair Toyota Altis – SLD 6679P

1pc	rear bumper
1pc	rear bumper reinforcement
1pc	rear bumper centre bracket
2pcs	rear bumper side retainer @\$132.35
1pc	rear bumper n/s reflector
1pc	rear boot lid
1pc	rear boot lock
1pc	rear boot n/s lamp
2pcs	rear taillamp @\$381.90
1pc	rear boot "Toyota" emblem
1pc	rear boot "A;tis" emblem
1pc	rear end panel

<i>Rr</i>	\$ 531.75	—
<i>Rr</i>	327.45	—
	181.90	?
<i>D.1</i>	264.70	—
	121.75	?
<i>Bu</i>	781.45	—
<i>Del</i>	277.40	—
	274.30	?
<i>R</i>	763.80	X
<i>na</i>	81.10	—
<i>na</i>	76.60	—
	374.45	?

4056.65

1014.16

3042.49

1set	reverse sensor
1set	rear bumper clip

<i>Shor</i>	280.00	sn	<i>2000</i>
<i>na</i>	35.00	sn	—

To repair & panelbeat rear boot inner panel, straighten rear chassis,  
cut/weld & renew rear end panel, dismantle &  
fit the above parts.  
To putty & spray painting

750.00 ?

700.00 *600h*

Total: \$ 4807.49

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: