
BIMETA: KONIU KEL: NOT MULS	014795/Klrbn2
ASSI	GNMENT
From: Date:	Veh No: SHO 35142 Yr Regn: 8 4 12 16
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Toi / Prime Mover /
ODITPIWS ITPRESIOD RESIEVATINVIMV	Truck / Trailer or
To Insped Vehicle No:	Make: _ Mush- 240 0.0 /68
at Workslep m/s	Colour Ble AC: Insteed Std NI NA
of .	Sp.Reading 277465 T/Radio: Ins@red / Std / NI / N.
Insured: SLA 7705Z	Eng/No:
Policy Na 500949572 250518 - 240519	CNO: KMHLB414A64093488
Claims No. MT /1007040-002	Gen. Cond: Good / For / Poor / Burnt
Suminswed: . Excess:	Steering: Inoger / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Indier / Jammed / Leaked / Burnt or
Make of Veh;	Modi: Nil / S/Rim / ST& A/Rim or
	Tyre Size; F: 200/60/16
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /
repair at the time of Inspection.	TOYOTYOKO or Hankak
Bal. or Market Value:	Front 2 Rear
IDAC Accident Rport: Consistent? : Yes or No	RVBal. 1 mm R/Bal. 1
GtA / PR Seen:Consistent? : Yes or No	L/Bal. + mm L/Bal. + r
Est. Repairs: days Res.: Yes or No	D.O.A. 13/4/8 0.0.1. 14/8/2
Lum Sum: % 3 Val.: Yes or No	Survey held at (DAE (Loyang)
CA' / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/O	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to colli
SHD 3514Z - 035/LPC18705067/	Klm63 DUA: 1503 18. Inc
SIA 7715Z - X	11
20/8/-1 Sahras 1/P \$4039.39/ 3A	2.
Red: \$6957.99 ,637.	•
PECFIVED 2	3 AUG 201B
INC OCT S TO)
	* 4
- N	,
Date/Time, File Pass to? : Prell. Report	Days Of Repair: 3
1) typist : Final Report	Resurvey No. of Trip: Survey Fee:
DataTime, File Return to?	Transportation;
z) Add	
40	: Interview (\$
Report Format : 1P	
Lump Sum / I.B.I: (\$ 4089.59)	:Weekend (\$)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NS/INC18014795/K1rb NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 14-08-2018 189556 Code: INC4 Policy Particulars :- THIRD PARTY CLAIM 1. SLA 7725Z Veh. Inspected SHD 3514Z Insured Veh. 5100949572 0.00 Policy No. Coverage (\$) 0.00 Claim No. Excess (\$) 14/08/2018 Assign From Assign Date 2. Vehicle Particulars & Condition 0 Make & Model C.C HIDDEN Engine No. Year of Reg. Chassis No. Colour Odometer Steering Brakes Modification General **Conditions of Tyres** 3. Size Make Balance R/H Front Tyre mm L/H Front Tyre mm R/H Rear Tyre mm L/H Rear Tyre mm **Description of Damages** 4. 5. General Information **Accident Date** 13/08/2018 Inspection Date 14/08/2018 COMFORTDELGRO ENGINEERING PTE LTD Survey held at 59 LOYANG DRIVE SINGAPORE 508969 5a. Remarks A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

eBao Tech										Genera	lClaim
Hello, NAC_PAYA_UBI_80	0601						Change	Language	e • Chan	ge Password	• Log Ou
My Desktop	Polic	y Query									
Notice of Loss	Policy N	lo.				Date of Accident			13/08/2018 1	7:07	
	Vehicle	No.(For Motor)	SLA772	5Z		Certifi	cate Number	Ţ			
					B	Search					
	Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
	0	5100949572		LAH JUNYI	S8311635H	GPC	drivo CLASSIC	SLA77252	Z SLA7725Z	25/05/2018	24/05/2019
					C	Continue					

TP Claims against NTUC Income: Follow-Through Survey

1000	lacomo Roforonco	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate		Tentative repair cost
00.	MILATING NEIGHBER MILATING	COMPOST TRANSPORTATION	SHC 8254X	51.5 82885	13/08/2018	\$ 4,074	\$ 951	2,250.00
	MT/1007237-002	CITYCAR PTE LTD	SHB 2334T	SJJ 2802T	13/08/2018	\$ 2,718	3 703	1,930.13
	AAT/1006666 003	NOTATE DANS DE LA CONTRACTION	SHD 6654H	SDM 9111M	09/08/2018	\$ 5,938	1.92 \$	4,450.00
	MAT/1007040-002	COMPOST TRANSPORTATION	SHD 3514Z	SLA 77252	13/08/2018	\$ 10,997	7.38 \$	4,039.39
	A47/1006/000 003	CTITOTA DECITO	SHC 71775	FR 73561	05/08/2018	\$ 3,290	3.60 \$	300.00
1	MIT/ 10004935-002	COMMON TRANSPORTATION	SHA 31741	FB12438G	08/08/2018	\$ 2,322	2.02	550.00
0 1	MIT/1006547-002	CUMPONI INANSPORTATION	SHA 9457G	SU 9702D	09/08/2018	\$ 1,639.23	3.23 \$	1,319.23
	MT/1005643-002	COMFORT TRANSPORTATION	SHA 7917.	SDP 7075G	01/08/2018	\$ 3,936	\$ 00.986,0	1,600.00

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCID	ENT	STAT	HΜ	EN.	т
ACCIL			-11		

Date Of Report

14/08/2018 09:31

Date Of Accident

13/08/2018 08:30

Exact Location Of Accident

PIE TWDS CHANGI AIRPORT.

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHD3514Z

Insured/Policyholder

Country/State of Loss

Name Of Registered Owner

COMFORT TRANSPORTATION PTE LTD

199303821R

Co Reg No **Email Address**

FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No

OFFICE-65508768

Vehicle Particulars

Manufacturer

HYUNDAI

Model

140

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAXI

Insurance Company

Name of Insurance Company

INDIA INTERNATIONAL INSURANCE PTE LTD

Type Of Coverage

THIRD PARTY FIRE AND/OR THEFT

Fleet Policy

YES

Policy Number

MCOM0015

Cover Note Number

Driver

Name of Driver

HENG JOON KWANG

NRIC No

S0233162D

Date Of Birth

07/08/1950

Occupation

OUTDOOR

Date Of Driving Pass

11/06/1969

Driving Experience

49 YEARS AND 2 MONTHS

Gender

MALE

Mobile Number

(LOCAL) +65-83740233

Fax Number

Contact Number

EMail Address

NOEMAIL

Address

527 11-223 HOUGANG AVENUE 6

Postcode

530527

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

Remarks/ Reasons:

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLA7725Z

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LAH JUNYI

NRIC/Passport Number

S8311635H

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBC9090R

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

GOH JINN KAI

NRIC/Passport Number

S7672598E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKE9499D

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NG JOO MIN

NRIC/Passport Number

S1461663B

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

the state of the s		
		(D) SHD 35142
	 40 40 40 + + + + + + + + + 	111111111111111111111111111111111111111
		
		111111111111111111111111111111111111111
		(D) D(H) +1+10-6
	111111111111111111111111111111111111111	(C) (3BC 9090 1
+++++++		
		THE MAN TO KE THAT D
	111111111111111111111111111111111111111	
++++++		
	THE CHEN	×9111111111111111111111111111111111111
	11111111111111111111111111111111111111	
	111111111111	A CONTRACTOR OF A CONTRACTOR O
SCRIBE CIRCUMSTANCES	OF THE ACCIDENT	
2 was trave	sling on PIE Captors	teven road toward
1	F. + 1/1 12 12	1 9 7
TOR PRYOL)	. The traffic is hear	y, and senavee
1 4	ack of cab. the t	behend can Knock
about 10km	on EMS. SHOULD	
into the be	ack of cab. the t	ine/ date is
13.08.201	8 8.30 AM. Another	3 car wart priling
DECLARATION /We declare the foregoing par COMFORT TRANSPOR CO. REG. NO. 19	rticulars are true in every respect.	19/8/12 Mackson Hans CSO FACICSO

Data & Time:

Sketch Plan Pg. 2

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose(s).
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms], which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTL CO REG. NO. 199303821R 6

Policyholder's Signature

Date & Time:

Driver's Signature


(If driver is not the policyholder)


Date & Time:


Jackson Hene


Reporting Centre Personnel's Signature Name:


NRIC/FIN No .:
















REPAIR ESTIMATE*

VEHICLE NO : SHD 3514Z

MAKE :

Nonc

DATE 8/14/2018 10:51

POA: 13-08-18

Weaking Str	: HYUNDAI i40	Type	U	Init Price	A	mount	
Qty	Parts Description/ Labour	Туре		1		1,681.40	6
	Boot Lid Ung				\$	115.80	
	Boot Lid Rubber × rv		\$	178.10	\$	356.20	
	Boot Lid Hinge (LH/RH) × 5	7	5	(#X.#X.+)~:	\$	137.90	
	Boot Lid Lock Upper × f	,			\$	31.70	
	Boot Lid Lock Lower × 5th	, ,			\$	27.50	ě
	Boot Lid Hyundai Plate				\$	27.20	
	Boot Lid 'H' Emblem X	/			\$	41.00	
	BOOK LIG CROTTIALE				\$	556.80	,
	BOOT LIG Lamp (Km)		\$	33.95	5	67.90	
	Licence Lamp (LH/RH)		2	33.33	\$	100.00	
	Trimcover × 5 ^{cc}				\$	172.70	
	Boot Lid Trimboard × 5**			1	5	11.00	
	Boot Lid Trimboard Clips (11pcs) > 47			1	2	85.00	
	Bootlid Moulding			1	\$	41.00	
	Bootlid i40 Emblem				\$	398.00	40
	Bootlid Lower Garnish				\$	603.60	700
	Rear Bumper Och	1			\$	504.35	
	Rear Bumper Reinforcement	1 aur	But	120.00	\$	200000000000000000000000000000000000000	
	Rear Bumper Reinforcement Bracket (LH/RH)	Pr	\$	180.00	100	360.00	
	Real Bulliper Clips	(\$	22.00	
	Rear Bumper Sponge 💢 🛰	(\$	143.40	
	Rear Bumper Under Cover 🗶 🖍	0			\$	225.80	
	Tail Lamp (LH/RH) > > > > C		\$	565.60	0.00	1,131.20	
	Rear Panel 😕 💢				\$	592.30	
	Rear Panel Garnish 🗡 🗡				\$	57.70	
	Rear Panel Lower Panel 🗴 🗸				\$	495.50	
	Exhaust Pipe Insulator (LH)				\$	58.55	
	Exhaust Silencer (LH)				\$	954.00	
	Exhaust Pipe Hanger (LH)				\$	58.55	
	Exhaust Pipe Centre × 5				\$	1,150.30	
	SUB TOTAL				\$	10,208.35	
	LESS 20%				\$	2,041.67	4
	DISCOUNTED TOTAL				\$	8,166.68	A
	Bod Lis compose sticker w -6%.	\$ 3-					
	Boot Lid Advortisement Logo / M				\$		
	Rear No.Plate Rear Bumper Reverse Sensor Rear Bumper Reverse Sensor				\$	25.00	
	Rear Bumper Reverse Sensor	4			\$	135.70	Net
	Rear Fender Advertisement Logo (LH/RH)		\$	100.00	0 \$	200.00	Net
					\$	460.70	_
BITY NO	X X						
	45 III	1/					

VEHICLE NO

: SHD 3514Z

MAKE

: HYUNDAI i40

MODEL Amount **Unit Price** Type Parts Description/Labour Qty Labour Charge 1.000.00 Panel Beating Spray Painting Charge \$ Wiring Charge \$ 50:00 Tuff Kote \$ 120.00 Remove/Refix Reverse Sensor Remove/Refix Exhaust Pipe 2,370.00 TOTAL LABOUR \$ 10,997.38 **ESTIMATE TOTAL** 11027.38 Kehn 10104

14/8/18 1505hs

3 hs

P/P

Betone Paix phas onsultants hence notify LKK Auto C the Repaire arry Ng · To resurvey . To display . Parts price . Third party No illegal mod lication(s) is allowed. Supplementary item(s) must be resurveyed is subject to final approval from insurance 0 · Suppleme Acknowledged by Repairer Signature: This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

DATE 8/14/2018 10:52

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

Date/Time: 14.08.2018 14:25

Page : 1

PR1	ARC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305199914
Team: STOMER	./		REGN NO.: SHD3514Z	MILEAGE
MS	COMFORT TRANSPORTATION PTE 7010045	LTD VAFS	MAKE: HYUNDAI	FUEL E1/2F
STOMER NO. DRESS	383 SIN MING DRIVE Singapore SINGAPORE 575717		MODEL I-40	13.08.2018 17:25
(R)	65508755 (O)		YR OF MANU. 08.09.2016	TARGET DATE
(P) SCOUNT GAR		(B)	CHASSIS CODE KMHLB41UMGU0934	88 COMPLETION DATE/TIME
NATU	RE: 3P 13.08.2018			
NATUI 9/NO			CRIPTION FRONT	T B

	CUSTOMER'S SIGNATURE
X Exit Pass	
Vehicle No.: SHD3514Z	th:
Name of Service Advisor To be kept by Security Guard	Date
	Vehicle No.: SHD3514Z

REPAIR ESTIMATE

Date: 17.08.2018 Time: 09:48:55

Page: 1

COMPA_NY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

: 305199914 JOB NO : SHD3514Z REGN NO : 0000000000 MILEAGE : HYUNDAI MAKE

: I-40 MODEL

: 08.09.2016 DATE OF REGN : 13.08.2018 17:25

DATE/TIME IN : 13.08.2018 ACCIDENT DATE

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0577-G I40VC PANEL ASSY-TRUNK LI 1 1,681.40 20.00 1,345.12 0002 04-O1-0103-0800-G I40VC SYMBOL MARK-TRUNK L 1 27.20 20.00 21.76 0003 28-O1-0103-0005-A (I40/SONATA)REAR BOOT LOG 1 - 15.00 10.00 13.50 1 15.00 10.00 13.50 0004 28-01-0103-0006-A (I40/SONATA)REAR BOOT TEL 1 603.60 20.00 482.88 0006 04-01-0101-0111-G HYUNDAI BUMPER COVER CLIP 10 L = 22.00 20.00 17.60 0007 09-01-9999-0068-A HYUNDAI REVERSE SENSOR AS 1_ 135.70 10.00 122.13 0008 09-01-0103-0104-G I40VC LAMP ASSY-LICENSE P 2 67.90 20.00 54.32 0009 04-01-0103-0743-G I40VC STAY-RR BUMPER RH 1 180.00 20.00 144.00 1 N 25.00 10.00 22.50 NO PLATE(S) 0010 FNPS 0011 04-01-0103-0784-G I40VC MLDG-BACK PANEL 1 , 398.00 20.00 318.40 0012 04-01-0103-0785-G I40VC MLDG-CR PIECE 1 /85.00 20.00 68.00

REPAIR ESTIMATE

Date: 17.08.2018 Time: 09:48:55

Page: 2

COMPAINY: THIRD PARTY'S CLAIMS (CAS)

CUSTON 1ER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO REGN NO MILEAGE

: 305199914 : SHD3514Z : 0000000000

MAKE

: HYUNDAI

MODEL

: 1-40

DATE OF REGN DATE/TIME IN

: 08.09.2016 : 13.08.2018 17:25

ACCIDENT DATE : 13.08.2018

JOB/PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 3,069.15

JOB NATURE

0001 L

ADVERTISEMENT - BOOT LID 0000 L

PANEL BEATING

SPRAYPAINT ON AFFECTED AREA

0002 23-502 WIRING CHARGE

0003 17-01 TUFF COAT ON AFFECTED PARTS.

0004 20-00 REMOVE/REFIX REVERSE SENSOR 0005 L

100.00

400.00

400.00

20.00

20.00

30.00

SUB-TOTAL : 970.00

Date: 17.08.2018 Time: 09:48:55

REPAIR ESTIMATE

Page: 3

COMPA NY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

: 305199914 JOB NO : SHD3514Z REGN NO : 0000000000 MILEAGE : HYUNDAI MAKE

: I-40 MODEL

DATE OF REGN : 08.09.2016 DATE/TIME IN : 13.08.2018 17:25

ACCIDENT DATE : 13,08.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 4,039.15

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE

MVA NAME & SIGNATURE

DATE:

DATE:

COMFORTDELGRO ENGINEERING

Our Job Ref No . 305199914 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 17. Aug. 2018 Date FINALIZATION FORM Fax: LKK To KALVIN Attn : Date of Accident: 13. Aug. 2018 Vehicle Reg No. : SHD3514Z The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-NTUC The repair job shall bill to: The finalized amount shall be: \$3,169.39 2. Spare Parts after List discount (a) \$870.00 (b) Labour Charges \$4,039.39 Total for Part-By-Part Repair Cost (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: Final Lumpsum Repair cost working days. Estimated normal period for repairs: We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days We confirm the estimates and Thank you for your assistance. finalized amount 5. Signature: Signature: Name Name : _ Date 6214 8316 Tel : 6546 8156 Fax For Official Use Only Document Confirm By Remarks Attached (Signature) Amount Item Yes or No YES Rental Rate P/Day Loss of Income Paid Survey Fees LTA Search Fee Medical Fees (on behalf of driver, if applicable) 6 Overrun

Remarks:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ITUC	INCOME INSURA	ANCE CO-OPERATIVE LTD	Ref:	NS/INC1801479	5/K1rbn2
3 BF 405-0 18955) INION HOUSESINGAPORE	Date:	28-08-2018 INC4	
		Policy Particulars	:- THIR	D PARTY CLAIM	
	Insured Veh.	SLA 7725Z	_	nspected	SHD 3514Z
	Policy No.	5100949572	Cover	rage (\$)	0.00
	Claim No.	MT/1007040-002	Exces	ss (\$)	0.00
	Assign From		Assign Date		14/08/2018
2.		Vehicle Parti	iculars	& Condition	
	Make & Model	HYUNDAI 140	c.c		1685
_	Engine No.	HIDDEN	Year of Reg. Colour Steering		2016
	Chassis No.	KMHLB41UMGU093488			BLUE
	Odometer	277468			IN ORDER
: - :	Brakes	IN ORDER	Modif	fication	STANDARD ALLOY RIN
	General	FAIR			
3.		Condit	tions of	Tyres	
		Size	Make		Balance
	R/H Front Tyre	205/60 R16	HANK	OOK	7 mm
	L/H Front Tyre	205/60 R16	HANK	ООК	7 mm
	R/H Rear Tyre	205/60 R16	HANK	OOK	7 mm
	L/H Rear Tyre	205/60 R16	HANK	OOK	7 mm
4.				Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE R	EAR PO	RTION.	
	DAMAGES SEE D	ETAILS.			
5.		Gener	al Infor	mation	SUPERIOR AND DESIGNATION
	Accident Date	13/08/2018	200	ection Date	14/08/2018
	Survey held at	COMFORTDELGRO ENGINE	ERING P	TE LTD	
		59 LOYANG DRIVE SINGAPORE 508969			
5a.			Remark		
	A)THE INSPECTION	ON WAS CONDUCTED ON A"W CE TO YOUR INSTRUCTIONS,	THOUT	PREJUDICE" BASI	S. ED REPAIRS.
	ID)IN ACCURDAN	OF 10 100K HOUROUTONO,		of Repair	

ESTIMATED NORMAL PERIOD FOR REPAIR:

3 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3514Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	DENTED	1,681.40	1,681.40
	BOOT LID RUBBER	SERVICEABLE	115.80	-
112	BOOT LID HINGE (LH/RH) @\$178.10	SERVICEABLE	356.20	
	BOOT LID LOCK UPPER	SERVICEABLE	137.90	-
	BOOT LID LOCK LOWER	SERVICEABLE	31.70	
1	BOOT LID HYUNDAI PLATE	NECESSARY	27.50	27.50
1	BOOT LID "H" EMBLEM	NOT NECESSARY	27.20	=
1	BOOT LID CRDI PLATE	NOT NECESSARY	41.00	1
	BOOT LID LAMP (RH)	GRAZED	556.80	
	LICENCE LAMP (LH/RH) @\$33.95	CRACKED	67.90	67.90
	TRIMCOVER	SERVICEABLE	100.00	-
	BOOT LID TRIMBOARD	SERVICEABLE	172.70	
	BOOT LID TRIMBOARD CLIPS	NOT NECESSARY	11.00	-
	BOOTLID MOULDING	CUT	85.00	85.00
	BOOTLID I40 EMBLEM	NOT NECESSARY	41.00	
	BOOTLID LOWER GARNISH	CRACKED	398.00	398.00
	REAR BUMPER	DEFORMED	603.60	603.60
	REAR BUMPER REINFORCEMENT	SERVICEABLE	504.3	5
	REAR BUMPER REINFORCEMENT BRACKET (LH/RH) @\$180.00	O/S BENT / N/S SERVICEABLE	360.00	0-2-2-2
1 10	REAR BUMPER CLIPS	NECESSARY	22.0	0 22.00
- 177	REAR BUMPER SPONGE	SERVICEABLE	143.4	0
	REAR BUMPER UNDER COVER	SERVICEABLE	225.8	
1 0	2 TAIL LAMP (LH/RH) @\$565.60	SERVICEABLE	1,131.2	0
	1 REAR PANEL	SERVICEABLE	592.3	0
	1 REAR PANEL GARNISH	SERVICEABLE	57.7	0
	1 REAR PANEL LOWER PANEL	SERVICEABLE	495.5	0
1 .	1 EXHAUST PIPE INSULATOR (LH)	SERVICEABLE	58.5	5
1	1 EXHAUST SILENCER (LH)	SERVICEABLE	954.0	0
	1 EXHAUST PIPE HANGER (LH)	SERVICEABLE	58.5	5

Report Ref No. NS/INC18014795/K1rbn2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST PIPE CENTRE	SERVICEABLE	1,150.30	
-	LESS 20% DISCOUNT		-2,041.67	-724.44
			8,166.68	2,897.76
	NETT ITEMS			
1	BOOTLID COMFORT STICKER (N)	NECESSARY	30.00	30.00
	REAR NO PLATE (N)	CRACKED	25.00	25.00
	REAR BUMPER REVERSE SENSOR (N)	SHORTED	135.70	135.70
	LESS 10% DISCOUNT		-	-19.07
			190.70	171.63
	SPECIAL NETT ITEMS			
1	BOOT LID ADVERTISEMENT LOGO (SN)	NECESSARY	100.00	
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @\$100.00 (SN)	SERVICEABLE	200.00	8.
			300.00	100.00
	LABOUR			
	PANEL BEATING.		1,000.00	
	SPRAY PAINTING CHARGE.		1,000.00	1000000
	WIRING CHARGE.		50.00	
	TUFF KOTE.		50.00	
	REMOVE/REFIX REVERSE SENSOR.		120.00	30.00
	REMOVE/REFIX EXHAUST PIPE.	NOT NECESSARY	150.00	
	CANCES AND CONTROL OF THE CONTROL OF		2,370.00	870.00
	GRAND TOTAL		11,027.38	4,039.3
	RECOMMENDED COST OF REPAIRS (CONFIRM			4,039.39

Report Ref No. NS/INC18014795/K1rbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.