

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0462/18
DATE : 04-AUG-2018

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS LING MARIANNE
ADDRESS : BLK 149 SIMEI STREET 1
#04-101
S(520149)
TELEPHONE NO : 98787584

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100494606-01
VEHICLE NO : SKP4760Z
MODEL CODE : JDRNRRZT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20905751B
CHASSIS NO : JN1JANT32Z0002754
MILEAGE : 56784 KM
DATE IN : 04/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER - 9645 0084
ACCIDENT DATE : 03/08/2018

67038691

elmer@fanchong.com

Not Authorised
Marcus Lkle
U: 62583561
15/8/18
Take photo before painting
3-4 days.

Lkk-Hyic Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKP4760Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR BOTH FRT FENDER & BONNET, RENEW RADIATOR SUPPORT & FRT BUMPER <i>390</i>	2800.00	<i>585-</i>
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME <i>250</i>	1200.00	<i>600</i>
3	ZZ/003	RENEW DAMAGED BOTH HEADLAMP	48.00	<i>✓</i>
4	ZZ/004	SUPPLY FRT LICENSE PLATE		
5	ZZ/005	RENEW A/T TRANSMISSION INTER COOLER	<i>17</i> 180.00	<i>X</i>
6	ZZ/006	RENEW AC SYSTEM CONDENSER, VACUUM AND REFILL FREON GAS <i>11</i>	120.00	<i>X</i>
TOTAL LABOUR CHARGES			4348.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKP4760Z

		DAMAGED PARTS & PRICES		
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 SUNDRIES	NPN			50.00 ?
2 FRT LICENCE PLATE	FLP		11	60.00 X
3 LH HEAD LAMP	26060-4CA5D	2352.00	?	
4 LH FENDER WHEEL ARC MOULDING	63861-4CE0A	deluged 170.00	✓	
5 AIR DUCT	16576-4BB0A			367.20 ?
6 A/T TRANSMISSION OIL COOLER	21606-4BA0A		11	240.00 X
7 HOSE FLEXIBLE HIGH A/CON	92490-4CB0B		11	117.70 X
8 CONDENSER ASSY	92100-5HA0A		11	743.20 X
9 RADIATOR FAN MOTOR	21481-4CE0A		11	1008.60 X
10 RH AIR GUIDE	21558-4BB0A		11	40.50 X
11 LH AIR GUIDE	21559-4BB0A			40.50 ?
12 RADIATOR ASSY	21410-4BB0A		11	687.40 X
13 BRACKET RADIATOR MOUNTING LOWER	21579-4BB1A		11	94.50 X
14 BRACKET RADIATOR MOUNTING UPPER	21542-4CE0A		11	81.00 X
15 RADIATOR SUPPORT LOWER	62530-4CE0A	11	353.30	X
16 RADIATOR SUPPORT UPPER	62511-4CE0A	11	233.60	X
17 EMBLEM RAD GRIL-NISSAN	62890-4BA0A		59.70	>
18 GRILLE-RADIATOR	62310-4CE1B		390.30	?
19 LH STAY FRT BUMPER	62211-4CL0A		86.60	?
20 REINFORCEMENT FRT BUMPER	62030-4CL0A		453.10	?
21 ENERGY ABSORBER FRT BUMPER	62090-4CE0A		291.60	?
22 FRT BUMPER LOWER COVER UNDER	62660-4CE0B	11	584.00	X
23 LOWER GRILLE FRONT BUMPER	62254-4CE0A	11	199.50	X
24 LH FOG LAMP GARNISH	62256-4BA0B	on	80.90	✓
25 LOWER CHROME MOULDING FRT BUMPER	62072-4BA0A	all	153.10	✓

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKP4760Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 TOWING HOOK COVER FRT BUMPER	622A0-4CLOA	20.30	?	
27 LH SIDE BRACKET FRT BUMPER	62223-4CLOA	20.90	✓	
28 RH SIDE BRACKET FRT BUMPER	62222-4CLOA	20.90	X	
29 CLIP FRT BUMPER @ SGD \$ 1.20 EACH	01553-10501	7.20	✓	
30 FRT BUMPER	62022-4CE0H	534.70	✓	
SUB TOTAL		6011.70	0.00	3530.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1202.34	0.00	0.00
GRAND TOTAL		4809.36	0.00	3530.60
OVERALL TOTAL		8339.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SKP4760Z

TOTAL LABOUR CHARGES 4348.00
TOTAL SPARE PARTS CHARGES 8339.96

GRAND TOTAL 12687.96 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.