

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0462/18

DATE : 04-AUG-2018

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : MISS LING MARIANNE
ADDRESS : BLK 149 SIMEI STREET 1
#04-101
S(520149)
TELEPHONE NO : 98787584

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100494606-01
VEHICLE NO : SKP4760Z
MODEL CODE : JDRNRRT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20905751B
CHASSIS NO : JN1JANT32Z0002754
MILEAGE : 56784 KM
DATE IN : 04/08/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER - 9645 0084
ACCIDENT DATE : 03/08/2018 67038691

elmer@fanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKP4760Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR BOTH FRT FENDER & BONNET, RENEW RADIATOR SUPPORT & FRT BUMPER	2800.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME	1200.00	
3	ZZ/003	RENEW DAMAGED BOTH HEADLAMP	48.00	
4	ZZ/004	SUPPLY FRT LICENSE PLATE		
5	ZZ/005	RENEW A/T TRANSMISSION INTER COOLER	180.00	
6	ZZ/006	RENEW AC SYSTEM CONDENSER, VACUUM AND REFILL FREON GAS	120.00	
		TOTAL LABOUR CHARGES	4348.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKP4760Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	SUNDRIES	NPN			50.00
2	FRT LICENCE PLATE	FLP			60.00
3	LH HEAD LAMP	26060-4CA5D	2352.00		
4	LH FENDER WHEEL ARC MOULDING	63861-4CE0A	170.00		
5	AIR DUCT	16576-4B80A			367.20
6	A/T TRANSMISSION OIL COOLER	21606-4BA0A			240.00
7	HOSE FLEXIBLE HIGH A/CON	92490-4CB0B			117.70
8	CONDENSER ASSY	92100-5HA0A			743.20
9	RADIATOR FAN MOTOR	21481-4CE0A			1008.60
10	RH AIR GUIDE	21558-4B80A			40.50
11	LH AIR GUIDE	21559-4B80A			40.50
12	RADIATOR ASSY	21410-4B80A			687.40
13	BRACKET RADIATOR MOUNTING LOWER	21579-4B81A			94.50
14	BRACKET RADIATOR MOUNTING UPPER	21542-4CE0A			81.00
15	RADIATOR SUPPORT LOWER	62530-4CE0A	353.30		
16	RADIATOR SUPPORT UPPER	62511-4CE0A	233.60		
17	EMBLEM RAD GRIL-NISSAN	62890-4BA0A	59.70		
18	GRILLE-RADIATOR	62310-4CE1B	390.30		
19	LH STAY FRT BUMPER	62211-4CLOA	86.60		
20	REINFORCEMENT FRT BUMPER	62030-4CLOA	453.10		
21	ENERGY ABSORBER FRT BUMPER	62090-4CE0A	291.60		
22	FRT BUMPER LOWER COVER UNDER	62660-4CE0B	584.00		
23	LOWER GRILLE FRONT BUMPER	62254-4CE0A	199.50		
24	LH FOG LAMP GARNISH	62256-4BA0B	80.90		
25	LOWER CHROME MOULDING FRT BUMPER	62072-4BA0A	153.10		

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKP4760Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 TOWING HOOK COVER FRT BUMPER	622A0-4CLOA	20.30		
27 LH SIDE BRACKET FRT BUMPER	62223-4CLOA	20.90		
28 RH SIDE BRACKET FRT BUMPER	62222-4CLOA	20.90		
29 CLIP FRT BUMPER @ SGD \$ 1.20 EACH	01553-10501	7.20		
30 FRT BUMPER	62022-4CE0H	534.70		
SUB TOTAL		6011.70	0.00	3530.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1202.34	0.00	0.00
GRAND TOTAL		4809.36	0.00	3530.60
OVERALL TOTAL		8339.96		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

