



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2004767
INV Date 07/07/2020
Reference CC4/LPC18014801/Nea3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SJD 1000D
Insured Veh. SMC 2611D
Claim No. 18/18/18/VP05/020830
Policy No. Z18VP05019684
Accident Date 12/08/2018
Inspection Date 15/08/2018

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18014801/Nea3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 07-07-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMC 2611D	Veh. Inspected	SJD 1000D
Policy No.	Z18VP05019684	Coverage (\$)	0.00
Claim No.	18/18/18/VP05/020830	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	14/08/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ESTIMA	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	ACR500057052	Colour	BLACK
Odometer	264858	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R18	PIRELLI	6 mm
L/H Front Tyre	225/45 R18	PIRELLI	6 mm
R/H Rear Tyre	225/45 R18	PIRELLI	6 mm
L/H Rear Tyre	225/45 R18	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/08/2018	Inspection Date	15/08/2018
Survey held at	JAS AUTO SERVICES 6D MANDAI ESTATE #03-02 M-SPACE SINGAPORE 729938		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJD 1000D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED	601.20	601.20
2	REAR BUMPER RETAINER LH/RH @\$40.00	O/S NECESSARY / N/S SERVICEABLE	80.00	40.00
1	REAR END PANEL	SERVICEABLE	854.20	-
1	REAR FENDER (RH) (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-307.08	-128.24
			1,228.32	512.96
<u>SPECIAL NETT ITEMS</u>				
1	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-
1	REVERSE SENSOR (SN)	NECESSARY	120.00	120.00
			220.00	170.00
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS ,ALL RELEVANT ATTACHMENTS ,FITTINGS TO COMMENCE REPAIRS, REPLACE THE DAMAGED PARTS ,REINSTALL & REALIGN ALL NECESSARY PARTS.INCLUSIVE OF THE REPAIR OF REAR FENDER (RH) .		800.00	400.00
	TO PUTTY & RESPRAY PAINT ON THE RELEVANT REPAIRED AREAS.		600.00	400.00
	TO RUST PROOF AFFECTED AREAS WHERE NECESSARY.		90.00	50.00
			1,490.00	850.00
GRAND TOTAL			2,938.32	1,532.96

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,200.00
---	--	--	-----------------

Report Ref No. CC4/LPC18014801/Nea3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJD 1000D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJD 1000D

RE-INSPECTION

