

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0442/18
DATE : 28-JUL-2018

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OWNER'S NAME : MR QUEK HUI CHONG
ADDRESS : BLK 10E BEDOK SOUTH AVE 2
#07-546
S(464010)
TELEPHONE NO : 64497141/97399223

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SDB7986B
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2445707A
CHASSIS NO : SJNFEAJ11UZ019118
MILEAGE : 20853 KM
DATE IN : 28/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 27/07/2018

Tanglin 97495749
wp

14/8/18 @ 12pm

Resurvey after repair.

4 days.

sur @ lkkauto.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDB7986B

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR RH REAR FENDER AND RENEW RH REAR DOOR.	500.00	390.
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	650.00	500.
3	ZZ/003	REMOVE AND INSTALL RH REAR DOOR MECHANISM.	80.00	X
4	ZZ/004	APPLY SEALANT TO RH REAR DOOR.	100.00	X
		TOTAL LABOUR CHARGES	1330.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDB7986B

				DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			50.00	ro
2	RH REAR FENDER ARC MLDG	93828-4EA0A	483.00	<i>cut</i>		
3	RH REAR DOOR PVC MLDG	82870-4EA0A	264.80	<i>cut</i>		
4	R/R DOOR TAPE	82818-4EA0A	29.90	X		
5	R/R DOOR TAPE	82812-4EA0A	29.90	X		
6	DOOR-REAR RH	H2100-HV0MA	1104.80	<i>Ry</i>		
SUB TOTAL			1912.40	0.00	50.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			382.48	0.00	0.00	
GRAND TOTAL			1529.92	0.00	50.00	
OVERALL TOTAL			1579.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDB7986B

TOTAL LABOUR CHARGES 1330.00
TOTAL SPARE PARTS CHARGES 1579.92

GRAND TOTAL 2909.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.