


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB440H
Ref. No : TAX/08/18/2045
Reg. Date : 16/07/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : KAMARUDIN BIN YUSOPE
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 10/08/2018 06:30:00 PM
Accident Reported Date / Time : 11/08/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 10/08/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097481
Special Instruction to ARC,if any :
TOWED \$40 / SLE3072D
Prepared Date : 11/08/2018 09:01:11 AM



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905746990

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 845.00	0.00
Total Spray Painting Charges	: 1,872.00	0.00
Total Material Charges	: 7,691.35	7,691.35
Other Charges	: 876.00	0.00
TOTAL	: 11,284.35	0.00
Lum Sum Total	: 11,300.00	0.00
No. of Repair Days	: 6.00 4.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 11/08/2018 01:01:59 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 11/08/2018 01:01:59 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 8/11/2018 1:02:19 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	845.00	0.00
Total Labour	845.00 800	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00 200	0.00
TO RESPRAY FRONT SUPPORT PANEL	180.00 100	0.00
TO RESPRAY FRONT FENDER RH	378.00 200	0.00
TO RESPRAY RIM	180.00 100	0.00
TO RESPRAY FRONT FENDER LH	378.00 200	0.00
TO REPSRAY FRONT HOOD	378.00 200	0.00
Total Spray Painting & Panel Beating	1,872.00 1,000	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00 40	0.00
TO CHECK WIRING AND SYSTEM FUNCTION	80.00 50	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00 X 11	0.00
TO TOP UP A/C GAS	120.00 20	0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00 60	0.00
TO REPLACE SUNDRY PARTS	100.00 X 11	0.00
TO WASH AND VACUUM	60.00 X 11	0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00 50	0.00
TO REMOVE AND REFIT TYRE	120.00 50	0.00
Total Other Costs	876.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NA2 LKK
13/8/18 1015

LIS

4 DAYS

AFTER REPAIR PHOTO

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No <i>/CRA</i>
90467-07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No <i>/CRA</i>
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace	No <i>/CRA</i>
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No <i>/CRA</i>
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace	No <i>/CRA</i>
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace	No <i>/CRA</i>
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace	No <i>/CRA</i>
53293-47040		6505574	DEFLECTOR, RADIATOR RH	1	83.50	25.00	62.62	Replace	Replace	No <i>/CRA</i>
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace	No <i>/CRA</i>
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <i>/CRA</i>
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No <i>/CRA</i>
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace	No <i>/CRA</i>
82113-47180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace	No <i>/CRA</i>
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace	No <i>/CRA</i>
81511-47050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace	No <i>/CRA</i>
81519-47060			BRACKET, FR TURN	1	58.20	25.00	43.65	Replace	Replace	No <i>/CRA</i>
81519-47050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Replace	No <i>/CRA</i>
81519-47060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Replace	No <i>/CRA</i>
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No <i>/CRA</i>
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace	No <i>/CRA</i>
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace	No <i>/CRA</i>
53113-47040			GRILLE RADIATOR LOWER NO.2	1	94.60	25.00	70.95	Replace	Replace	No <i>/CRA</i>
76851-47020		6505616	BUMPER LIP FRT	1	139.60	25.00	104.70	Replace	Replace	No <i>/CRA</i>
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace	No <i>/CRA</i>
51410-12105			UNDER COVER CENTER	1	448.30	25.00	336.22	Replace	Replace	No <i>/CRA</i>
38710-17150			TUBE & ACCESSORY	1	631.90	25.00	473.92	Replace	Replace	No <i>/CRA</i>
5315-17140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace	No <i>/CRA</i>
5319-17120			WIPER WASHER INLET	1	36.90	25.00	27.67	Replace	Replace	No <i>/CRA</i>
5330-7010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Replace	No <i>/CRA</i>

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
85330 60180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Replace	No ?
53201- 47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace	No ?
53801- 47050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace	No X R
75374- 47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No / REC
53876- 47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace	No / REC
53851- 47040			FENDER LINER PAD, FR WHEEL. RH	1	49.30	25.00	36.97	Replace	Replace	No / SCR
42611-- 47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace	No X R
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace	No X nn
81130- 47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No / SCR
53802- 47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace	No X SVL
75374- 47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No / REC
53301- 47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace	No / BT
53410- 47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace	No ?
53420- 47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace	No ?
TOTAL MATERIALS								9,614.27	9,614.19	
TOTAL MATERIALS(Discounted)							7,691.35	7,691.35		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									