

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**Telefax**

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/0914/2018/PH  
**Date** : 10-Aug-18

**Vehicle IN workshop. Kindly arrange for survey.**

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Tan Shen Lek  
**Address** : Blk 79D Toa Payoh Central  
#17-47  
Singapore 314079  
**Telephone** : HP +65 97877551  
**Type of Claim** : Own Damage claims  
**Policy No.** : 1800088788  
**Vehicle No** : **SMD 1109 P**  
**Model Code** : Audi A4 SEDAN 2.0 TFSI  
**Model / Year** : Aug-18  
**Engine No** :- CVK 063736  
**Chassis No** : WAUZZZF40JA186949  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 7-Aug-18  
**Place of Accident** : Duxton Road carpark

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

**Telefax****Estimated Labour Charges for Accident Vehicle SMD 1109 P.**

<b>S/N</b>	<b>Nature of Jobs</b>	<b>Estimated Charges</b>	<b>Surveyor's Recommendation</b>
1	To remove and transfer rear parking aid and rear lid kick sensor.	S/N \$ 360.00 ✓	
2	To dismantle and renew rear bumper.	\$ <del>900.00</del> 500	
3	To respray rear bumper.	\$ <del>800.00</del> 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 2,252.00</b>	

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

**Material List for Accident Vehicle Regn No. <sup>SDM1109P</sup>~~85C113B~~**

		<b>Damage Parts &amp; Prices</b>	
<b>S/N</b>	<b>Parts Description</b>	<b>S/NETT</b>	<b>REMARKS</b>
1	BUMPER COVER <i>rebuild</i>	\$ 1,907.00	✓
2	FIXING PARTS FOR BUMPER	\$ 63.00	✗
3	SECURING STRIP	\$ 191.00	✗
4	SPOILER	\$ 216.00	✗
5	REAR LIGHT REFLECTOR - LH/RH	2 \$ 70.00	✗
6	BUMPER CARRIER	\$ 786.00	✗
7	SEAL	2 \$ 24.00	✗
8	GUIDE SECTION - LH/RH	2 \$ 76.00	✗
9	GUIDE SECTION - LH/RH	2 \$ 38.00	✗
10	SENSOR - REAR INNER/OUTER	2 \$ 421.00	✗
11	SUNDRIES ?	\$ 300.00	?
<b>TOTAL SPARE PARTS</b>		<b>: \$ 4,092.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 2,252.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 6,344.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

**Telefax**

**Name**

: Adrian King

**Surveyed Date**

:

15/08/18

**Authorised Date**

:

**Excess Cost**

:

**Liability**

:

**Remarks**

:

~~Not~~ Authorised Repairs, 03 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Please Note**

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant