

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 17 Aug 2018

Preliminary Advice

Insured Vehicle No : GBF6504T

TP Vehicle No : SLL3655K

Make : TOYOTA HARRIER

Date of Inspection : 16/08/2018

Inspection At : Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Accident Date : 08/08/2018

Assignment Date : 14/08/2018

Est. Duration of Repair : 3 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,929.00 (PENDING SOME PARTS PRICES)
Revised Amount	:S\$	999.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	999.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.