



**Bedok Motor Engineering Pte Ltd**  
30 Defu Lane 9 Singapore 539270  
<http://www.bedokmotor.com>  
[enquire@bedokmotor.com](mailto:enquire@bedokmotor.com)  
+65 6286 3032

Estimate To Repair PA8727P KING LONG XMQ6118KM

Chassis No : LA6R1HSJ98B101732

| S/No                            | Quantity | Description                                            | Amount      |
|---------------------------------|----------|--------------------------------------------------------|-------------|
| <u>LIST ITEMS</u>               |          |                                                        |             |
| 1                               | 1pc      | Front wheel mudguard R/h <i>2d/3rd</i>                 | \$ 1,219.42 |
| 2                               | 1pc      | Front wheel mudguard Inner liner <i>11</i>             | \$ 299.46   |
| 3                               | 1pc      | Side luggage compartment door R/h No. 1 <i>10/12/1</i> | \$ 1,109.42 |
| 4                               | 1pc      | Side luggage compartment door R/h No. 2 <i>10/12/1</i> | \$ 694.24   |
|                                 |          |                                                        | \$ 3,322.54 |
| Less 10%                        |          |                                                        | \$ 332.25   |
|                                 |          |                                                        | \$ 2,990.29 |
| <u>LABOUR &amp; MISC CHARGE</u> |          |                                                        |             |
| 1                               |          | Panel beating and renewal of the necessary parts.      | \$ 1,500.00 |
| 2                               |          | Putty and spray painting of the affected areas.        | \$ 1,900.00 |
| 3                               |          | To redo accent stripe sticker double colors.           | \$ 800.00   |
|                                 |          |                                                        | \$ 4,200.00 |
| Total                           |          |                                                        | \$ 7,190.29 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*not allowed*

*2/5 \* 4300/-*

*The photo after rep-*

*15/8/18*

*Handy*

*P- 3023.08*  
*102*  
*2720.77*  
*5420.77*