

CS. P.C. BY:

REF:

CS3 / SPF18014838 / R19657

Special Instruction:

Surveyor:

Rasall

ASSIGNMENT (Office)

From (Person):

Abdul Rahman

of

SPF

Date/Time:

15082018

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 5316S

Insured:

GZ 3154A

at Workshop m/s

Autofriend Services

Tel:

6268 2065.

of

27A Jumbo Port Road # 01-15

Policy No:

Claim No:

AEMD / 105 / 009 / 2018 / 097

Sum Insured:

Excess:

Make of Veh:

D.O.A.

07082018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

23082018

H.O.D. Endorsement:

Date/Time:

15082018 1209pm

Person Contacted:

Mrs. Lee

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

GY 5316S - X

GZ 3154A - X

22/9/18

Submit DAF - US \$2500, 4 days.

Report Format : BAR #
Lump Sum / I.B.I. (\$) 250 1250

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS3/SPF18014838/R1qb

ACCIDENT CLAIM SECTION
(SINGAPORE POLICE FORCE)

1 MOUNT PLEASANT ROAD

BLK 8 OLD POLICE ACADEMYSINGAPORE 298333

Date : 15-08-2018



Code : SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GZ 3154A	Veh. Inspected	GY 5316S
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/097	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	15/08/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/08/2018	Inspection Date	23/08/2018
Survey held at	AUTOFRIEND SERVICES 27A #01-15 JURONG PORT ROAD SINGAPORE 619101		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.



SINGAPORE POLICE FORCE

SPF Accidents Claims Section
Automotive Engg & Mgmt Div
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Your Ref : GY 5316 S

Our Ref : AEMD/105/009/2018/097

Tel: 64784840

Fax: 64784848

Date : 15 Aug 2018

LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 # 01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir,

**ACCIDENT INVOLVING GOVT VEHICLE GZ 3154A AND OTHER VEHICLE GY 5316 S ON
7 Aug 2018**

We refer to the above matter.

- 2 Kindly arrange for an Inspection of vehicle no. **GY 5316 S** at Autofriend Services, 27A Jurong Port Road, #01-15/27 Singapore 619101.
- 3 For appointment kindly contact Mrs Lee at Tel: 62683065/ 62613287
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours faithfully,


Frankie Thay
Safe Driving Manager
for ASST DIRECTOR

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/08/2018 13:15
Date Of Accident	07/08/2018 23:30
Exact Location Of Accident	BLK 33 TEBAN GARDENS RD OPEN CARPARK LOT TG7
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY5316S
Insured/Policyholder	
Name Of Registered Owner	THOMSON CATERING & ENTERPRISES P/L
Co Reg No	199804699W
Email Address	SALES@THOMSONCATERING.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62657532

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5006523365-13
Cover Note Number	

Driver

Name of Driver	SANKARRAJ SARAVANAN
Passport No/FIN	G6905194X
Date Of Birth	16/04/1986
Occupation	OUTDOOR
Date Of Driving Pass	26/09/2012
Driving Experience	5 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82205166
Fax Number	
Contact Number	OFFICE-62657532
Email Address	NOEMAIL

Address BLK 33 TEBAN BARDENS ROAD
 #07-270
 Postcode 600033
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLIDED INTO PARKED VEHICLE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name HONG KAH SOUTH NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 510 JURONG WEST STREET 52 , POSTCODE: 640510 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-5648999 - FAX NO: 66655797
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT

Attachment(s)


Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GZ3154A
 Vehicle Make/Model/Colour PICK-UP / POLICE VEHICLE
 Details Of Properties RIGHT REAR
 Vehicle Category GOVERNMENT
 Name of Driver NA
 NRIC/Passport Number
 Contact Number NA
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

Sketch Plan #2

SKETCH PLAN



(A) My vehicle #: 6453165

⑩ 7P vehicle: GZ3154A.

BLK 33 Teban Gardens S Rel

open car park also 3 T.G.F.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Postar Police Report

7/20180808/2144

DECLARATION

I/We declare the foregoing particulars are true in every respect

Polysynoder's Signature
Date & Time:

Driver's Signal: "It's better to see the car before the driver."

Reporting Centre Personnel: Signature

VAN / LORRY (Frt)

Front Portion

Vehicle No: 4Y 53165

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	654.00	CUT ✓	
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover	128.00	SLR ✓	
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp	211.10	BR ✓	
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille			
1022	991328	Frt Grille Emblem			
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel	LH 175.00	DD ✓	
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp	78.20	BR ✓	
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2048	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			
1		Labour			
1		Paintwork & materials			300.00
2		Labour			400.00

No of Items:

Assessor:

T. K. K. K.
31/8/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGINEERING & MGT DIVISION Ref: CS3/SPF18014838/R1qbs2

ACCIDENT CLAIM SECTION(SINGAPORE POLICE Date: 03-10-2018
FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD
POLICE ACADEMY SINGAPORE 298333



ATTN: ABDUL RAHMAN

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GZ 3154A	Veh. Inspected	GY 5316S
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/097	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	15/08/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN URVAN 5DR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JN1MG4E25Z0713130	Colour	WHITE
Odometer	588135 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	165R15C	GREEN MAX	6 mm
L/H Front Tyre	165R15C	GREEN MAX	6 mm
R/H Rear Tyre	165R15C	GREEN MAX	6 mm
L/H Rear Tyre	165R15C	GREEN MAX	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/08/2018	Inspect Date / Time	23/08/2018 (03:12 PM)
Survey held at	AUTOFRIEND SERVICES 27A #01-15 JURONG PORT ROAD SINGAPORE 619101		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. GY 5316S

Qty	Description of Parts	Condition	Recommended (\$)
<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	CUT	654.00
1	FRT LH BUMPER FOG LAMP COVER	SCRATCHED	128.00
1	FRT LH BUMPER FOG LAMP	BROKEN	211.10
1	FRT CORNER PANEL LH	DENTED	175.00
1	FRT LH SIDE LAMP	BROKEN	78.90
1	FRT LH DOOR (NPA)	TO REPAIR SEE LABOUR	-
	LESS 30% DISCOUNT		-374.10
			872.90
<u>LABOUR</u>			
	PAINTWORK & MATERIALS.		300.00
	LABOUR. INCLUSIVE OF THE REPAIR OF FRT LH DOOR.		400.00
			700.00
GRAND TOTAL			1,572.90
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CS3/SPF18014838/R1qbs2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.