



新友合汽车私人有限公司
SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
 Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
 Specialise in Insurance Claims and General Motor Repair Work

Co./GST Regn. No. 200921075G

14-Aug-18

THIRD PARTY CLAIM

Third Party Vehicle No : SHA 6911 G

Date of Accident : 13/08/2018

MR FAN SIEW CHEONG

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF REPAIR TO TOYOTA VIOS 1.5 E (M): SKD 3467 R

A) Chassis No : MR053HY9305265496

B) Date of Registration : 21 Nov 2011

S/No.	Pc/s	Item(s) :-		
1	1	Boot lid	595.00	BT
2	1	Boot lid lock	100.00	BUC
3	1	Toyota Emblem	50.80	rec
4	1	Vios	48.00	rec
5	1	E	40.00	rec
6	1	Weatherstrip	200.00	BT
7	2	Taillamp @ \$298.00	596.00	CRA
8	1	Rear bumper	435.00	CRA
9	4	Rear bumper clip @ \$5.00	20.00	rec
10	2	Rear bumper side holder @ \$100.00	200.00	X 2H \$100
11	1	Rear end panel	645.00	PD
12	1	Rear end panel garnish	235.00	CRA
13	1	Spare tyre top cover	145.00	TORN
			3,309.80	
		Less Discs : 25% -	827.45	
			2,482.35	
		<u>Special Nett Item(s) :-</u>		
14	1	Reverse sensor	200.00	malfunction
		Balance C/F:-	2,682.35	



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Specialise in Insurance Claims and General Motor Repair Work

16-Aug-18

THIRD PARTY CLAIM

Third Party Vehicle No : SHA 6911 G

Date of Accident : 13/08/2018

MR FAN SIEW CHEONG

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF REPAIR TO TOYOTA VIOS 1.5 E (M): SKD 3467 R

A) Chassis No : MR053HY9305265496

B) Date of Registration : 21 Nov 2011

S/No. Pc/s Item(s) :-

1	2	Rear combination lamp body @ \$28.00	56.00	/ DD
1	2	Rear bumper reflector @ \$125.50	251.00	/ CRA
			<u>307.00</u>	
		Less Discs : 25% -	76.75	
			<u><u>230.25</u></u>	



新友合汽车私人有限公司
SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
 Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
 Specialise in Insurance Claims and General Motor Repair Work

Co./GST Regn. No. 200921075G

14-Aug-18

THIRD PARTY CLAIM

Third Party Vehicle No : SHA 6911 G

Date of Accident : 13/08/2018

MR FAN SIEW CHEONG

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF REPAIR TO TOYOTA VIOS 1.5 E (M): SKD 3467 R

A) Chassis No : MR053HY9305265496

B) Date of Registration : 21 Nov 2011

S/No. Pc/s Item(s) :-

		\$
	Balance B/F:-	2,682.35
Labour Charges :		
a)	To remove and refit rear end panel garnish, spare tyre top cover, fender inner trimx2	80.00 ⁸⁰
b)	To remove and refit rear boot mechanism	60.00 ⁵⁰
c)	To antirust the affected portion	80.00 ⁴⁰
d)	To remove and refit rear boot lid, rear bumper, tail lamp x2 cut and weld rear end panel, panel beat tail lamp panel, floor panel, rear fender LH	800.00 ⁶⁰⁰
e)	To putty and spray paint rear bumper, rear end panel, rear floor panel, boot lid in & out, tail lamp panel x2	1,000.00 ⁸⁰⁰
		----- 4,702.35
	GST (7%) :-	329.16
	Total :-	----- <u>5,031.51</u>

NAZ LKK
 15/8/18 1700
 4-5 days
 P/P

67418434

Naz@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: