



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981

Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Co./GST Regn. No. 200921075G

Specialise in Insurance Claims and General Motor Repair Work

14-Aug-18

THIRD PARTY CLAIM

Third Party Vehicle No : SHA 6911 G

Date of Accident : 13/08/2018

MR FAN SIEW CHEONG

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF REPAIR TO TOYOTA VIOS 1.5 E (M): SKD 3467 R

A) Chassis No : MR053HY9305265496

B) Date of Registration : 21 Nov 2011

<u>S/No.</u>	<u>Pc/s</u>	<u>Item(s) :-</u>	
1	1	Boot lid	595.00
2	1	Boot lid lock	100.00
3	1	Toyota Emblem	50.80
4	1	Vios	48.00
5	1	E	40.00
6	1	Weatherstrip	200.00
7	2	Taillamp @ \$298.00	596.00
8	1	Rear bumper	435.00
9	4	Rear bumper clip @ \$5.00	20.00
10	2	Rear bumper side holder @ \$100.00	200.00
11	1	Rear end panel	645.00
12	1	Rear end panel garnish	235.00
13	1	Spare tyre top cover	145.00
			<hr/>
			3,309.80
		Less Discs : 25% -	827.45
			<hr/>
			2,482.35
		<u>Special Nett Item(s) :-</u>	
14	1	Reverse sensor	200.00
		Balance C/F:-	<hr/>
			2,682.35



新友合汽车私人有限公司

SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981

Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg

Co./GST Regn. No. 200921075G

Specialise in Insurance Claims and General Motor Repair Work

14-Aug-18

THIRD PARTY CLAIM

Third Party Vehicle No : SHA 6911 G

Date of Accident : 13/08/2018

MR FAN SIEW CHEONG

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

ESTIMATED COST OF REPAIR TO TOYOTA VIOS 1.5 E (M): SKD 3467 R

A) Chassis No : MR053HY9305265496

B) Date of Registration : 21 Nov 2011

S/No. Pc/s Item(s) :-

		\$
	Balance B/F:-	2,682.35
Labour Charges :		
a)	To remove and refit rear end panel garnish, spare tyre top cover, fender inner trimx2	80.00
b)	To remove and refit rear boot mechanism	60.00
c)	To antirust the affected portion	80.00
d)	To remove and refit rear boot lid, rear bumper, tail lamp x2 cut and weld rear end panel, panel beat tail lamp panel, floor panel, rear fender LH	800.00
e)	To putty and spray paint rear bumper, rear end panel, rear floor panel, boot lid in & out, tail lamp panel x2	1,000.00
		<u>4,702.35</u>
	GST (7%) :-	329.16
	Total :-	<u><u>5,031.51</u></u>