

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z**AAD1808-082***Not Authorized
L/Smp @ 3450/h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5529Z

VF1ABL15AUC278870

RENAULT

LATITUDE

11.8.2018

LONPAC

		PART		LIST	
1	1	BUMPER COVER FRT	\$	<i>hulanz.m</i> 1,259.42 ✓	
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 ✓	
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 ✓	
4	1	BUMPER RETAINER FRT LH	\$	<i>mis</i> 151.41 ✓	
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	}
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21	
12	1	BUMPER BEAM FRT	\$	<i>SL</i> 914.08	
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61	
14	1	RADIATOR GRILLE	\$	<i>SL</i> 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36	
16	1	RADIATOR GRILLE FRAME	\$	<i>SL</i> 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>SL</i> 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>SL</i> 89.79	
19	1	FRONT BRACE PANEL	\$	<i>SL</i> 177.22	
20	1	HORN	\$	<i>SL</i> 314.17	
21	1	HORN BRACKET	\$	<i>SL</i> 40.45	
22	1	HEADLAMP LH	\$	<i>ngum</i> 1,184.43 ✓	
23	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43 X	
24	1	HEADLAMP PANEL FRT LH	\$	<i>SL</i> 152.15 X	
25	1	HEADLAMP PANEL FRT RH	\$	<i>SL</i> 152.15 X	
26	1	BONNET	\$	<i>SL</i> 1,941.63 X	
27	1	BONNET INSULATOR	\$	<i>SL</i> 405.73 X	
28	1	BONNET STRUT LH	\$	<i>SL</i> 88.61 X	

Trans-cab Auto Services Pte Ltd**AAD1808-082**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

29	1	BONNET STRUT RH	\$	88.61	X
30	1	BONNET HINGE LH	\$	348.31	X
31	1	BONNET HINGE RH	\$	348.31	X
32	1	BONNET LOCK	\$	305.48	X
33	1	BONNET CABLE	\$	119.19	X
34	1	BONNET CABLE COVER	\$	161.03	X
35	1	BONNET SEAL OUTER	\$	92.36	X
36	1	BONNET SEAL INNER	\$	157.28	X
37	1	FENDER PANEL FRT LH	\$	783.83	
38	1	WHEELARCH FRT LH	\$	278.84	
39	1	FENDER BRACKET LOWER LH	\$	15.79	
40	1	FENDER INSULATOR LH	\$	130.84	
41	1	FENDER INSULATOR RH	\$	130.84	
42	1	WIPER RESERVOIR	\$	348.25	
43	1	WIPER RESERVOIR NECK	\$	136.11	
44	1	WIPER RESERVOIR MOTOR	\$	270.06	
45	1	AIR CLEANER LOWER	\$	271.26	
46	1	AIR CLEANER HOSE	\$	76.14	
47	1	BASE BATTERY TRAY	\$	363.40	
48	1	AIR CLEANER BOX	\$	464.20	
49	1	TURBO DUCT	\$	1,027.80	
50	1	A/C HEATER VALVE	\$	484.50	
51	1	SUBFRAME OUTER FRT	\$	2,652.45	
52	1	SUBFRAME BRACKET OUTER LH	\$	92.36	
53	1	ENGINE UNDERTRAY	\$	564.98	
54	1	A/C CONDENSER	\$	2,020.37	
55	1	A/C CONDENSER GARNISH LH UPPER	\$	39.67	
56	1	A/C CONDENSER GARNISH RH UPPER	\$	39.67	
57	1	A/C CONDENSER GARNISH LH	\$	58.81	
58	1	A/C CONDENSER GARNISH RH	\$	59.60	
59	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	208.39	
60	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	658.72	
61	1	A/C PIPE COMPRESSOR	\$	334.29	
62	1	A/C PIPE	\$	658.72	
63	1	A/C COMPRESSOR	\$	2,684.61	
77	1	AIR COOLER	\$	792.60	
78	1	AIR INTERCOOLER HOSE (LONG)	\$	1,014.13	
79	1	AIR INTERCOOLER HOSE (Short)	\$	375.14	

Trans-cab Auto Services Pte Ltd

AAD1808-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

80	1	TRANSMISSION COOLER	\$	1,219.30
81	1	TRANSMISSION COOLER PAD	\$	17.96
82	1	RADIATOR	\$	1,202.20
83	2	RADIATOR STUD UPPER	\$	14.41
84	2	RADIATOR BUSH UPPER	\$	50.12
85	2	RADIATOR MTG LOWER	\$	55.85
86	1	RADIATOR FAN COWLING	\$	820.54
87	1	RADIATOR FAN MOTOR LH	\$	967.36
88	1	RADIATOR FAN MOTOR RH	\$	1,479.46
89	1	RADIATOR TANK	\$	324.62
90	1	RADIATOR HOSE UPPER	\$	240.56
91	1	RADIATOR HOSE LOWER	\$	491.18
92	1	RADIATOR TANK HOSE	\$	61.18
93	1	AUTO COMPUTER	\$	5,032.17
94	1	INJECTION COMPUTER	\$	4,706.30
95	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52
96	1	STEERING PUMP ELECTRIC L70Y	\$	2,306.90
97	1	STEERING PINION RACK L70Y	\$	4,413.11
98	1	DOOR PANEL FRT LH	\$	2,844.66
99	1	LOWER ARM LH L70Y	\$	685.76
100	1	KUNCKLE ARM LH L70Y	\$	846.98
101	1	ABSORBER FRT LH L70Y	\$	360.54
102	1	AIR CLEANER BOX	\$	464.20
103	1	AIR CLEANER HOSE	\$	175.85
104	1	DOOR HARNESS WIRE LH	\$	2,670.00
105	1	DOOR MIRROR ASSY LH	\$	1,483.40
106	1	DOOR PANEL FRT LH	\$	2,844.66

TOTAL	\$	70,862.14
10%	\$	7,086.21
	\$	63,775.92

Special Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	X
2	1SET	BUMPER CLIP FRT	\$	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	X
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	}	X
7	1	TOW COVER FRT	\$	sn	14.50		
8	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00		
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00		
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00		
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00		
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00		
13	1	Windscreen moulding	\$	nn	100.00		
14	1SET	Front licence plate with holder	\$	sn	80.00		
15	1	Front left tyre	\$	sn	330.00		
16	1	Front left tyre rim	\$	sn	380.00	}	60m
17	1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00		
18	1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00		

TOTAL	\$	1,402.50
TOTAL PARTS	\$	65,178.42

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,400.00	400
Towing Fees.	\$	nn 120.00	X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	600
To rust-proofing of the affected areas.	\$	170.00	300
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X

Trans-cab Auto Services Pte Ltd

AAD1808-082

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5529Z

To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 201
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 X
To lift-up engine with gear box and refit.	\$	440.00 X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	440.00 X
To remove and refit air bag system and reset.	\$	480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 X
To replace, refix and top up coolant for radiator	\$	170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X

TOTAL \$ 16,400.00**Over All Total \$ 81,578.42****Repair Days (LUMP SUM)****20 DAYS**

2 1/2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: