

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 16 Aug 2018

Preliminary Advice

Insured Vehicle No : SKW2997J
TP Vehicle No : SLM7184X
Make : MAZDA 3
Date of Inspection : 15/08/2018
Inspection At : Pegasus Engineering & Trading Pte Ltd (Kian Teck)
74 Kian Teck Road
Singapore 628800

Accident Date : 07/08/2018
Assignment Date : 15/08/2018
Est. Duration of Repair : 5 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesfront O/S and U/C... portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 11,240.80 |
| Revised Amount | :S\$ | 2,824.00 |
| Check Items (Estimated) | :S\$ | 2,434.00 |
| Total | :S\$ | 5,258.00 |
| Lump Sum Repair | :S\$ | |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.