

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

15-Aug-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHD 1138 P

1 pc	Rear bumper	\$	811.11	de
1 pc	Rear bumper sponge	\$	79.20	NN
1 pc	Rear bumper reinforcement	\$	815.64	NN
1 pc	Rear bumper reinforcement centre	\$	79.20	NN
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20	o/s x NN \$	104.40	n/s de
1 pc	Rear bumper n/s reflector @ \$107.50	\$	107.50	NN
1 pc	Rear n/s rim @ \$246.00	\$	246.00	out
		\$	2,243.05	
	Less 20%	\$	448.61	
		\$	1,794.44	

S/NETT

1 set	Rear bumper clips	\$	48.00	new
1 set	Reverse sensor	\$	280.00	NN
1 pc	Rear n/s fender sticker	\$	60.00	new
1 pc	Tyre (MAXXIS) @ \$200	80% \$	200.00	permanet
	Sundry	\$	50.00	20 ✓ NEC
	Towing Fee	\$	50.00	✓
	To check for rear n/s wheel alignment	\$	80.00	✓
	To dismantle and replace reverse sensor and test system	\$	80.00	30
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the same, etc	\$	700.00	300
	To putty and spray painting on the rear bumper, rear n/s fender	\$	400.00	✓
	To apply rustproofing on the repaired and replaced panels	\$	120.00	x
	Total	\$	3,862.44	

LKK Auto Consultants hereby notifies the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts above ESTIMATE
- Parts prices are **ANY UNFORESEEN DAMAGES**
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taylor 97495749
- WP
15/8/18 @ 1655
Resurvey before paint
03 days
sur@lkkauto.com