

Date: 18072017

ASSIGNMENT

Veh No:

13931/Gpa3

Ax

6 Nov 2017

Yew Tee Automobile Tech Pte Ltd

Estimate Report

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61

Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

08/14/2018

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM

Claim Type:	TP	Ref. No:	YTKB/TP/1808/009
Policy No:	83007102	Date of Loss:	11/08/2018
Vehicle Reg. No.:	SDM1360M	Driveable?	no
Driver Age:	0000-00-00	Third Party Vehicle No.:	SKM3767C/GBE3570B/SLG 7674E
Any Injuries?	no	Contact No:	
Insured/Claimant:	ADVANCE LIMO & RENTAL PTE LTD	Driver:	HENG BOON LIANG
Make/Model:	Toyota, Camry -	Vehicle Reg. Date:	14/08/2018
	MR053BK400/BK410	Engine Number:	2AZA641193
Vehicle Colour:	BLACK	Odometer:	
Chassis No:	6T153BK400X076276	Est. Duration of Repair(Day)	10
Total Loss?			

Description of Accident/loss CHAIN COLLISION

Remarks:

Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	7,529.88
Miscellaneous Items	360.00
Labour	1,130.00
Paintwork Labour	980.00
Towing	0.00

Gross Total(S\$):	9,999.88
GST 7.00%(S\$):	699.99
Nett Amount(S\$):	10,699.87

This claim is handled by: Shaun Toh L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not approved
2/8/18
15/8/18
Take photo after repair
(including spare parts)

Estimate Report

08/14/2018

REPAIR DETAILS

Estimates On Parts

50%

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER				
2	1	FRONT BUMPER REINFORCEMENT	591.60	591.60	-25.00	443.70
3	1	FRONT BUMPER INNER SPONGE	377.40	377.40	-25.00	283.05
4	1	FRONT BUMPER SIDE RETAINER LH	182.25	182.25	-25.00	136.69
5	1	FRONT BUMPER SIDE RETAINER RH	161.40	161.40	-25.00	121.05
6	1	BOOT LID	161.40	161.40	-25.00	121.05
7	1	BOOT LID HINGE LH	781.29	781.29	-25.00	585.97
8	1	BOOT LID HINGE RH	121.30	121.30	-25.00	90.98
9	1	BOOT LID LOGO	121.30	121.30	-25.00	90.98
10	1	BOOT LID CAMRY EMBLEM	58.50	58.50	-25.00	43.88
11	1	BOOT LID ALTISE EMBLEM	48.60	48.60	-25.00	36.45
12	1	BOOT LID VVTI EMBLEM	48.60	48.60	-25.00	36.45
13	1	REAR NUMBER PLATE LAMP	35.80	35.80	-25.00	26.85
14	1	REAR OUTER HANDLE GARNISH	238.30	238.30	-25.00	178.73
15	1	BOOT LID REFLECTOR LH	299.40	299.40	-25.00	224.55
16	1	BOOT LID REFLECTOR RH	245.80	245.80	-25.00	184.35
17	1	BOOT LID LOCK	245.80	245.80	-25.00	184.35
18	1	BOOT LID INNER TRIM	182.40	182.40	-25.00	136.80
19	1	REAR BUMPER	474.30	474.30	-25.00	355.73
20	1	REAR BUMPER SIDE RETAINER LH	561.60	561.60	-25.00	421.20
21	1	REAR BUMPER SIDE RETAINER RH	132.10	132.10	-25.00	99.08
22	1	REAR BUMPER REINFORCEMENT	132.10	132.10	-25.00	99.08
23	1	REAR END PANEL	374.45	374.45	-25.00	280.84
24	1	REAR END PANEL TOP GARNISH	781.10	781.10	-25.00	585.83
25	1	REAR TAILLAMP LH	434.25	434.25	-25.00	325.69
26	1	REAR TAILLAMP RH	474.30	474.30	-25.00	355.73
27	1	BOOT LID RUBBER	474.30	474.30	-25.00	355.73
28	1	REAR SPARE TYRE BOARD	231.40	231.40	-25.00	173.55
29	1	BOOT LID DAMPER LH	261.30	261.30	-25.00	195.98
30	1	BOOT LID DAMPER RH	271.40	271.40	-25.00	203.55
31	1	REAR SPARE TYRE PANEL	271.40	271.40	-25.00	203.55
32	1	REAR SMART KEYLESS SENSOR	937.30	937.30	-25.00	702.98
33	1	REAR TAILLAMP LOWER BRACKET LH	171.80	171.80	-25.00	128.85
34	1	REAR TAILLAMP LOWER BRACKET RH	77.80	77.80	-25.00	58.35
34	1	REAR TAILLAMP LOWER BRACKET RH	77.80	77.80	-25.00	58.35
Total Parts (\$\$)						7,529.88

6717.49

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE	40.00	40.00	0.00	40.00
2	1	FRONT BUMPER CLIP	20.00	20.00	0.00	20.00
3	1	REAR NUMBER PLATE	40.00	40.00	0.00	40.00
4	1	BOOT LID INNER TRIM CLIP	25.00	25.00	0.00	25.00
5	1	REAR REVERSE SENSOR	200.00	200.00	0.00	200.00
6	1	REAR BUMPER CLIP	20.00	20.00	0.00	20.00
7	1	REAR END PANEL TOP GARNISH CLIP	15.00	15.00	0.00	15.00
Sub Total (\$\$)						360.00

345

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,100.00	1,100.00	0.00	1,100.00/1000

Gross Labour Cost (\$\$) 1,130.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	40.00	40.00	0.00	40.00 ✓
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	900.00	900.00	0.00	900.00 880

Gross Labour Cost (\$\$) 980.00

< END OF ESTIMATES >

P-6717.49

less 50%

3358.77

S.N 345

labour 1990

5693.74