

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM18014860/Uga3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Date: 06-05-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
Ins	sured Veh.	GBE 3570E	Veh. Inspected	SDM 1360M	
Po	olicy No.	P1849452	Coverage (\$)	0.00	
CI	aim No.	S8M00S3I	Excess (\$)	0.00	
As	ssign From		Assign Date	15/08/2018	
2. Vehicle Particulars & Condition					
Ma	ake & Model	TOYOTA CAMRY (A)	c.c	2362	
En	ngine No.	HIDDEN	Year of Reg.	2009	
Ch	nassis No.	6T153BK400X076276	Colour	BLACK	
Od	dometer	212814	Steering	IN ORDER	
Br	akes	IN ORDER	Modification	SPORTS RIM	
Ge	eneral	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
-	H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/I	H Front Tyre	215/60 R16	DUNLOP	6 mm	
-	H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/I	H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages					
TH	THE VEHICLE SUSTAINED DAMAGES AT THE REAR & FRONT PORTION.				
DA	DAMAGES SEE DETAILS.				
5.	General Information				
Ac	ccident Date	11/08/2018	Inspection Date	15/08/2018	
Su	irvey held at	YEW TEE AUTOMOBILE TECH PL			
		BLK 25 KAKI BUKIT ROAD 4 #01-61 SYNERGY @ KAKI BUKIT SINGAPORE 417800			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	b. Estimate Days of Repair				
ES	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				