

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61

Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1808/009
Policy No:	83007102	Date of Loss:	11/08/2018
Vehicle Reg. No.:	SDM1360M	Driveable?	no
Driver Age:	0000-00-00	Third Party Vehicle No.:	SKM3767C/GBE3570B/SLG 7674E
Any Injuries?	no	Contact No:	
Insured/Claimant:	ADVANCE LIMO & RENTAL PTE LTD	Driver:	HENG BOON LIANG

Make/Model:	Toyota, Camry - MR053BK400/BK410	Vehicle Reg. Date:	14/08/2018
Vehicle Colour:	BLACK	Engine Number:	2AZA641193
Chassis No:	6T153BK400X076276	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	10

Description of Accident/loss CHAIN COLLISION
 Remarks:
 Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	7,529.88
Miscellaneous Items	360.00
Labour	1,130.00
Paintwork Labour	980.00
Towing	0.00
Gross Total(S\$):	9,999.88
GST 7.00%(S\$):	699.99
Nett Amount(S\$):	10,699.87

This claim is handled by: Shaun Toh L M

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not approved
 2 hr
 d/s 7 day
 15/8/18
 Take photo after repair
 including spare parts

REPAIR DETAILS

Estimates On Parts

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>20/20</i>	591.60	591.60	-25.00	443.70 ✓
2	1	FRONT BUMPER REINFORCEMENT <i>7</i>	377.40	377.40	-25.00	283.05 ✓
3	1	FRONT BUMPER INNER SPONGE	182.25	182.25	-25.00	136.69 ✓
4	1	FRONT BUMPER SIDE RETAINER LH <i>3rd</i>	161.40	161.40	-25.00	121.05 ✓
5	1	FRONT BUMPER SIDE RETAINER RH <i>3rd</i>	161.40	161.40	-25.00	121.05 ✓
6	1	BOOT LID <i>3rd/507</i>	781.29	781.29	-25.00	585.97 ✓
7	1	BOOT LID HINGE LH <i>2</i>	121.30	121.30	-25.00	90.98 X
8	1	BOOT LID HINGE RH <i>2</i>	121.30	121.30	-25.00	90.98 X
9	1	BOOT LID LOGO <i>new</i>	58.50	58.50	-25.00	43.88 ✓
10	1	BOOT LID CAMRY EMBLEM <i>new</i>	48.60	48.60	-25.00	36.45 ✓
11	1	BOOT LID ALTISE EMBLEM <i>new</i>	48.60	48.60	-25.00	36.45 ✓
12	1	BOOT LID VVTI EMBLEM <i>new</i>	35.80	35.80	-25.00	26.85 ✓
13	1	REAR NUMBER PLATE LAMP <i>11</i>	238.30	238.30	-25.00	178.73 X
14	1	REAR OUTER HANDLE GARNISH <i>3rd/100</i>	299.40	299.40	-25.00	224.55 ✓
15	1	BOOT LID REFLECTOR LH	245.80	245.80	-25.00	184.35 ✓
16	1	BOOT LID REFLECTOR RH	245.80	245.80	-25.00	184.35 ✓
17	1	BOOT LID LOCK <i>new</i>	182.40	182.40	-25.00	136.80 ✓
18	1	BOOT LID INNER TRIM <i>11</i>	474.30	474.30	-25.00	355.73 X
19	1	REAR BUMPER <i>20/20</i>	561.60	561.60	-25.00	421.20 ✓
20	1	REAR BUMPER SIDE RETAINER LH <i>3rd</i>	132.10	132.10	-25.00	99.08 ✓
21	1	REAR BUMPER SIDE RETAINER RH <i>3rd</i>	132.10	132.10	-25.00	99.08 ✓
22	1	REAR BUMPER REINFORCEMENT <i>20</i>	374.45	374.45	-25.00	280.84 ✓
23	1	REAR END PANEL <i>3rd/100</i>	781.10	781.10	-25.00	585.83 ✓
24	1	REAR END PANEL TOP GARNISH <i>100</i>	434.25	434.25	-25.00	325.69 ✓
25	1	REAR TAILLAMP LH <i>new</i>	474.30	474.30	-25.00	355.73 ✓
26	1	REAR TAILLAMP RH <i>new</i>	474.30	474.30	-25.00	355.73 ✓
27	1	BOOT LID RUBBER <i>100</i>	231.40	231.40	-25.00	173.55 ✓
28	1	REAR SPARE TYRE BOARD <i>100</i>	261.30	261.30	-25.00	195.98 ✓
29	1	BOOT LID DAMPER LH <i>11</i>	271.40	271.40	-25.00	203.55 X
30	1	BOOT LID DAMPER RH <i>11</i>	271.40	271.40	-25.00	203.55 X
31	1	REAR SPARE TYRE PANEL <i>2</i>	937.30	937.30	-25.00	702.98 X
32	1	REAR SMART KEYLESS SENSOR	171.80	171.80	-25.00	128.85 ✓
33	1	REAR TAILLAMP LOWER BRACKET LH	77.80	77.80	-25.00	58.35 ✓
34	1	REAR TAILLAMP LOWER BRACKET RH	77.80	77.80	-25.00	58.35 ✓

6225.79 Total Parts (\$\$) 7,529.88

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE <i>3rd</i>	40.00	40.00	0.00	40.00 ✓
2	1	FRONT BUMPER CLIP <i>new</i>	20.00	20.00	0.00	20.00 ✓
3	1	REAR NUMBER PLATE <i>3rd</i>	40.00	40.00	0.00	40.00 ✓
4	1	BOOT LID INNER TRIM CLIP <i>new</i>	25.00	25.00	0.00	25.00 ✓
5	1	REAR REVERSE SENSOR <i>500/6</i>	200.00	200.00	0.00	200.00 ✓
6	1	REAR BUMPER CLIP <i>new</i>	20.00	20.00	0.00	20.00 ✓
7	1	REAR END PANEL TOP GARNISH CLIP <i>11</i>	15.00	15.00	0.00	15.00 X

Sub Total (\$\$) 360.00

345

Estimates On Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,100.00	1,100.00	0.00	1,100.00 /000
Gross Labour Cost (S\$)						1,130.00

Estimates On Paint Work Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	40.00	40.00	0.00	40.00 ✓
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	900.00	900.00	0.00	900.00 880
Gross Labour Cost (S\$)						980.00

< END OF ESTIMATES >