

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD

PARTICULARS OF CLAIM			
Claim Type:	TP	Ref. No:	YTKB/TP/1808/009
Policy No:	83007102	Date of Loss:	11/08/2018
Vehicle Reg. No.:	SDM1360M	Driveable?	no
Driver Age:	0000-00-00	Third Party Vehicle No.:	SKM3767C/GBE3570B/SLG 7674E
Any Injuries?	no	Contact No:	
Insured/Claimant:	ADVANCE LIMO & RENTAL PTE LTD	Driver:	HENG BOON LIANG
Make/Model:	Toyota, Camry - MR053BK400/BK410	Vehicle Reg. Date:	14/08/2018
Vehicle Colour:	BLACK	Engine Number:	2AZA641193
Chassis No:	6T153BK400X076276	Odometer:	
Total Loss?		Est. Duration of Repair(Day)	10
Description of Accident/loss	CHAIN COLLISION		
Remarks:			
Present Location:	Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB		

COST OF CLAIMS	Amount
Parts	7,529.88
Miscellaneous Items	360.00
Labour	1,130.00
Paintwork Labour	980.00
Towing	0.00
Gross Total(S\$):	9,999.88
GST 7.00%(S\$):	699.99
Nett Amount(S\$):	10,699.87

This claim is handled by: Shaun Toh L M

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER	591.60	591.60	-25.00	443.70
2	1	FRONT BUMPER REINFORCEMENT	377.40	377.40	-25.00	283.05
3	1	FRONT BUMPER INNER SPONGE	182.25	182.25	-25.00	136.69
4	1	FRONT BUMPER SIDE RETAINER LH	161.40	161.40	-25.00	121.05
5	1	FRONT BUMPER SIDE RETAINER RH	161.40	161.40	-25.00	121.05
6	1	BOOT LID	781.29	781.29	-25.00	585.97
7	1	BOOT LID HINGE LH	121.30	121.30	-25.00	90.98
8	1	BOOT LID HINGE RH	121.30	121.30	-25.00	90.98
9	1	BOOT LID LOGO	58.50	58.50	-25.00	43.88
10	1	BOOT LID CAMRY EMBLEM	48.60	48.60	-25.00	36.45
11	1	BOOT LID ALTISE EMBLEM	48.60	48.60	-25.00	36.45
12	1	BOOT LID VVTI EMBLEM	35.80	35.80	-25.00	26.85
13	1	REAR NUMBER PLATE LAMP	238.30	238.30	-25.00	178.73
14	1	REAR OUTER HANDLE GARNISH	299.40	299.40	-25.00	224.55
15	1	BOOT LID REFLECTOR LH	245.80	245.80	-25.00	184.35
16	1	BOOT LID REFLECTOR RH	245.80	245.80	-25.00	184.35
17	1	BOOT LID LOCK	182.40	182.40	-25.00	136.80
18	1	BOOT LID INNER TRIM	474.30	474.30	-25.00	355.73
19	1	REAR BUMPER	561.60	561.60	-25.00	421.20
20	1	REAR BUMPER SIDE RETAINER LH	132.10	132.10	-25.00	99.08
21	1	REAR BUMPER SIDE RETAINER RH	132.10	132.10	-25.00	99.08
22	1	REAR BUMPER REINFORCEMENT	374.45	374.45	-25.00	280.84
23	1	REAR END PANEL	781.10	781.10	-25.00	585.83
24	1	REAR END PANEL TOP GARNISH	434.25	434.25	-25.00	325.69
25	1	REAR TAILLAMP LH	474.30	474.30	-25.00	355.73
26	1	REAR TAILLAMP RH	474.30	474.30	-25.00	355.73
27	1	BOOT LID RUBBER	231.40	231.40	-25.00	173.55
28	1	REAR SPARE TYRE BOARD	261.30	261.30	-25.00	195.98
29	1	BOOT LID DAMPER LH	271.40	271.40	-25.00	203.55
30	1	BOOT LID DAMPER RH	271.40	271.40	-25.00	203.55
31	1	REAR SPARE TYRE PANEL	937.30	937.30	-25.00	702.98
32	1	REAR SMART KEYLESS SENSOR	171.80	171.80	-25.00	128.85
33	1	REAR TAILLAMP LOWER BRACKET LH	77.80	77.80	-25.00	58.35
34	1	REAR TAILLAMP LOWER BRACKET RH	77.80	77.80	-25.00	58.35

Total Parts (\$\$) 7,529.88

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT NUMBER PLATE	40.00	40.00	0.00	40.00
2	1	FRONT BUMPER CLIP	20.00	20.00	0.00	20.00
3	1	REAR NUMBER PLATE	40.00	40.00	0.00	40.00
4	1	BOOT LID INNER TRIM CLIP	25.00	25.00	0.00	25.00
5	1	REAR REVERSE SENSOR	200.00	200.00	0.00	200.00
6	1	REAR BUMPER CLIP	20.00	20.00	0.00	20.00
7	1	REAR END PANEL TOP GARNISH CLIP	15.00	15.00	0.00	15.00

Sub Total (\$\$) 360.00

Estimates On Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00
2	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	1,100.00	1,100.00	0.00	1,100.00
Gross Labour Cost (\$\$)						1,130.00

Estimates On Paint Work Labour						
No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	40.00	40.00	0.00	40.00
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	40.00	40.00	0.00	40.00
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	900.00	900.00	0.00	900.00
Gross Labour Cost (\$\$)						980.00

< END OF ESTIMATES >