

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18014862/T1BA3Q2

Date: 18/08/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant

Vehicle No : SLV4504D

Insured Vehicle No :

SHD528D

Date of Loss: 26/06/2018

Nature of Claim:

TP

Claim No: C0474055

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLV4504D**

Make & Model: NISSAN SYLPHY, 1.6 (A)

Engine No: HR16917307C

Reg. Date: 29/12/2017 (Man. Year: 2017)

Chassis No: MNTBBAB17Z0030949

Colour: Blue

Odometer: 3964 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size:

195/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,794.84	1,313.96	1,480.88	52.99
Miscellaneous Items	0.00	0.00	0.00	
Total Labour	3,170.00	2,109.00	1,061.00	33.47
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,964.84	3,422.96	2,541.88	42.61
+ GST 7.00/7.00% (S\$)	417.54	239.61	177.93	42.61
Nett Amount (S\$)	6,382.38	3,662.57	2,719.81	42.61
+ Loss of Use (8.0 x S\$50.00/day) (S\$)		400.00		
Nett Liability (S\$)		4,062.57		

INSPECTION

Date of Assignment: 10/07/2018

Date Inspected: 20/08/2018 Inspected At:

Tan Chong Motor Sales Pte Ltd (HQ)
911 BUKIT TIMAH ROAD
Singapore 589623

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Aug 2019)
Parts:	143	NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV4504D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAPE-RR DOOR ,RH (CONSISTENT)	Necessary	18.00 FN	*18.00 FN
2	1		*TAPE RR DOOR (CONSISTENT)	Necessary	16.90 FN	*16.90 FN
3	1		*TAPE-RR DOOR ,RH (CONSISTENT)	Necessary	27.90 FN	*27.90 FN
4	1		*SIDE MLDG RH (FRT & REAR) (CONSISTENT)	Not Necessary	505.40 FS	*- FS
5	1		*TAPE RH FRONT DOOR SASH (CONSISTENT)	Necessary	18.00 FN	*18.00 FN
6	1		*TAPE RH FRONT DOOR SASH (CONSISTENT)	Necessary	24.00 FN	*24.00 FN
7	1		*DPPR A FRT (CONSISTENT)	Repair	896.50 FN	*- FN
8	1		*DOOR A RR (CONSISTENT)	Bent	951.90 FN	*951.90 FN
9	1		*LOCK & REMOTE RR DOOR (CONSISTENT)	Not Necessary	236.40 FN	*- FN
10	1		*BRACKET BUMPER RH (CONSISTENT)	Necessary	34.30 FN	*34.30 FN
11	2		*CROMMET -CLIP (CONSISTENT)	Necessary	5.00 FN	*5.00 FN
12	10		*CLIP (CONSISTENT)	Necessary	12.00 FN	*12.00 FN
13	1		*RR BUMPER (CONSISTENT)	Cut	620.90 FN	*620.90 FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	3,367.20	1,728.90
- Nett Item Discount on N Items 20.00/20.00% (S\$)	572.36	345.78
- Add. Disc. on L,N Items 0.00/5.00% (S\$)	0.00	69.16
Total Parts (S\$)	2,794.84	1,313.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PERFORM RUST X3 PANEL TO PROOFING & TREATMENT	New	360.00	240.00
2	APPLY SEALANT X2 PANEL (FRT DOOR RH & RR DOOR RH)	New	200.00	100.00
3	TRANSFER MECHANICAL PART AT FRT DOOR RH & RR DOOR RH SIDE	New	160.00	80.00
4	REPAIR REAR FENDER RH ,ROCKER PANEL RH SIDE,RENEW RR BUMPER ,FRT DOOR RH & RR DOOR RH	New	1,250.00	1,000.00
5	S/PAINT FRT DOOR RH ,RR DOOR RH ,ROCKER PANEL RH ,RR FENDER RH & RR BUMPER COVER	New	1,200.00	800.00
Gross Labour Cost (\$)			3,170.00	2,220.00
- 0.00/5.00% Labour Discount (\$)			0.00	111.00
Gross Labour after Discount (\$)			3,170.00	2,109.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >