

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0275/2018
DATE : 06-JUL-2018

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR VEERAMANI NAGARAJ
ADDRESS : 73 PASIR RIS GROVE
#12-24
S(518206)
TELEPHONE NO : 98202641

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-SHD528D
VEHICLE NO : SLV4504D
MODEL CODE : BDTARCZB17EWA----K
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2017
ENGINE NO : HR16917307C
CHASSIS NO : MNTBBAB17Z0030949
MILEAGE : 1 KM
DATE IN : 06/07/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 26/06/2018

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

6/7/2018

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

Tanfiah 97495729
'wp'

20/8/18 @ 3pm

* Resurvey before paint
sur @ lkk auto.com

7 days

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV4504D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RPI	PERFORM RUST X3 PANEL TO PROOFING & TREATMENT	360.00	240
2	SEALI	APPLY SEALANT X2 PANEL(FRT DOOR RH& RR DOOR RH) RESEAL NECESSARY AREA E/\$100	200.00	100
3	ZZ/001	TRANSFER MECHANICAL PART AT FRT DOOR RH & RR DOOR RH SIDE E/\$80	160.00	80
4	ZZ/002	REPAIR REAR FENDER RH,ROCKER PANEL RH SIDE, RENEW RR BUMPER ,FRT DOOR RH & RR DOOR RH	1250.00	1250
5	ZZ/003	S/PAINT FRT DOOR RH,RR DOOR RH,ROCKER PANEL RH, RR FENDER RH & RR BUMPER COVER	1200.00	800
TOTAL LABOUR CHARGES			3170.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV4504D

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	TAPE-RR DOOR,RH	82816-3SB0A	18.00	rec ✓
2	TAPE RR DOOR	82812-3SB0A	16.90	na ✓
3	TAPE-RR DOOR,RH	82818-3SB0A	27.90	na ✓
4	SIDE MLDG RH (FRT & REAR)	G6840-3ST0A		505.40 Q NN
5	TAPE RH FRONT DOOR SASH	80818-3SB0B	18.00	na ✓
6	TAPE RH FRONT DOOR SASH	80816-3SB0B	24.00	na ✓
7	DOOR A FRT	H010M-3SBMA	896.50	bt XR
8	DOOR A RR	H210M-3SBMA	951.90	bt ✓
9	LOCK & REMOTE RR DOOR	82500-3SB0A	236.40	Q NN
10	BRACKET BUMPER RH	85226-3ST1A	34.30	na ✓
11	CROMMET-CLIP(2X2.5)	63846-5V000	5.00	na ✓
12	CLIP(10X1.2)	01553-10501	12.00	na ✓
13	RR BUMPER	85022-3ST4H	620.90	cut ✓
SUB TOTAL			2861.80	0.00 505.40
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			572.36	0.00 0.00
GRAND TOTAL			2289.44	0.00 505.40
OVERALL TOTAL			2794.84	

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLV4504D

TOTAL LABOUR CHARGES	3170.00
TOTAL SPARE PARTS CHARGES	2794.84

GRAND TOTAL	5964.84 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the
affected vehicle. Should we require further labour
charges & spare parts in the process of repairs, we
shall inform you accordingly.